

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO18006179/	Gbe2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623				22-05-2018	
			Code:	SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	PA 7251B	Veh. Inspected		FBG 8770Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD1801438/NSW	Excess (\$)		0.00
	Assign From	GRACE TEO	Assig	n Date	03/04/2018
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FAZER	c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		SILVER
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	110/70-17	PIRELL	.l	5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	140/70-17	PIRELL	.l	5 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REABODY.			TION, O/S AND N/S	
5.	. General Information				
	Accident Date	02/04/2018 Inspect Date / Time			05/04/2018 (01:00 PM)
	Survey held at	eld at ASIA MOTORSPORTS SOLUTION PTE LTD			
	568 GEYLANG ROAD SINGAPORE 389514				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMO18006179/Gbe2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.