

D.O.A : 31 MARCH 2018

Not Authorized

02 APRIL 2018

OWNER : LOW LEONG CHAI

REG NO. : SLD 4551 L

MAKE/MODEL : TOYOTA SIENTA

*h/llk
2/5.8
9 day.
4/4/18*
ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear tailgate <i>3odg 20</i>	\$ 1,602.40
2	Rear tailgate dampers <i>11</i>	\$ 482.60 X
1	Rear tailgate inner trim board	\$ 481.90 ?
1	Rear tailgate lamp	\$ 358.00 ?
1	Rear tailgate lock <i>7m/3m</i>	\$ 489.70
1	Rear tailgate logo <i>rec</i>	\$ 58.50
1	Rear tailgate rubber <i>7m</i>	\$ 291.60
1	Rear tailgate emblem <i>me</i>	\$ 43.00
1	Rear tailgate outer garnish	\$ 257.30 ?
2	Rear tailgate number plate lamps <i>11</i>	\$ 97.30 X
2	Rear taillamps	\$ 934.40 ?
1	Rear end panel <i>3odg 20</i>	\$ 820.60
1	Rear end panel inner garnish <i>D.S</i>	\$ 221.50
1	Rear smart keyless sensor	\$ 189.50 ?
2	Rear fenders <i>11</i>	\$ 2,541.00 X
2	Rear fender inner trim boards	\$ 1,391.00 ?
1	Rear bumper <i>D.S</i>	\$ 488.70
2	Rear bumper brackets <i>3od</i>	\$ 197.00
1	Rear bumper centre pad <i>D.S</i>	\$ 225.00
2	Rear bumper reflectors <i>11</i>	\$ 114.00 X
2	Rear bumper reflector outer garnishes <i>n/s de</i>	\$ 361.00 lpc
2	Rear bumper side outer garnishes <i>n/s de</i>	\$ 255.00 lpc
2	Rear bumper side retainers <i>n/s de</i>	\$ 128.80 lpc
1	Rear bumper tow hook cover <i>gned</i>	\$ 55.20
1	Rear floor board <i>AA warped</i>	\$ 381.50 X
1	Rear floor compartment tray	\$ 411.50 ?
1	Rear floor compartment panel	\$ 1,055.00 ?
1	Rear exhaust silencer <i>11</i>	\$ 715.50 X
2	Rear exhaust mountings <i>11</i>	\$ 57.00 X
2	Front headlamps	\$ 3,775.00 ?
1	Front grille	\$ 365.20 ?
1	Front grille chrome moulding	\$ 258.00 ?
1	Front grille logo	\$ 55.00 ?
		\$ 19,148.70

takes photo After repair

c/f:

\$ 19,148.70

1	Front bumper	\$ 20/pc	2,668.00	✓
1	Front bumper centre air grille	\$ 22	94.50	✓
2	Front bumper fog lamp side garnishes	\$ 11	676.00	X
2	Front bumper fog lamps	\$ 11	540.80	X
1	Front bumper inner sponge	\$	81.60	✓
1	Front bumper reinforcement	\$	291.90	✓
2	Front bumper side retainers	\$ 34	141.80	✓
1	Front fender	\$ 11	811.80	X
1	Front fender inner shield	\$ 11	162.60	X
1	Front support panel	\$ 2	911.50	X
1	Front brace panel	\$	68.00	✓
1	Horn	\$ 11	105.50	X
1	Air con condenser	\$ 11	1,361.80	X
1	Radiator	\$ 11	1,846.60	X
		\$	28,911.10	
Less 25%		\$	7,227.78	
		\$	21,683.33	

SPECIAL NETT ITEMS

1	Rear windscreen seal	\$ 24	85.00	30
1	Rear windscreen sealant	\$ 22	80.00	40
1	Rear bumper clip (1 set)	\$	50.00	✓
1	Rear reverse sensor (1 set)	\$ 24	350.00	200
1	Rear reverse camera	\$	480.00	✓
1	Front bumper clip (1 set)	\$ 22	50.00	✓
1	Front number plate with holder	\$ 22	50.00	40
1	Front fender inner shield clip (1 set)	\$ 11	35.00	X
		\$	1,180.00	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	✓
3	To remove and refit inner garnishes.	\$	180.00	80
4	To remove and refit rear reverse sensor.	\$	150.00	50
5	To transfer boot lid mechanism and wiring assembly.	\$ Repair	120.00	X
6	To remove, refit air-con condenser, refill gas & conduct leakage test.	\$ 11	180.00	X
7	To remove and refit rear windscreen glass.	\$	180.00	120
8	To remove, refit and replace exhaust silencer and mountings.	\$ 11	150.00	X
9	To apply undercoating.	\$	200.00	100
10	Panel beating.	\$	2,000.00	1200
11	To re-spray painting on the affected areas.	\$	1,800.00	1600
		\$	5,120.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL :**\$ 27,983.33**

PAGE 2 OF 2

Acknowledged by Repairer

Signature:

Date: