

COMFORTDELGRO ENGINEERING PTE LTD

Date: 03.04.2018

REPAIR ESTIMATE

Time: 10:57:26

Page: 1

Ag Asia - CP/P
LKK - Kalvin

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305138030
REGN NO : SHC1980D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 20.12.2017
DATE/TIME IN : 03.04.2018 09:40
ACCIDENT DATE : 31.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0782-A HEADLAMP RH ✓ 1 1,388.00 20.00 1,110.40

Front Bumper x replace
Front RH Fender x replace

SUB-TOTAL : 1,110.40

JOB NATURE

0000 L PANEL BEATING-Frt Fender etc
0001 23-502 SPRAYPAINT ON-Frt Bumper etc
0002 17-01 CHECK ALL LIGHTING
0003 20-00 TUFF COAT ON AFFECTED PARTS.

~~560.00~~ 200
~~500~~ ~~400.00~~ 400
~~40.00~~ 20
~~40.00~~ x

SUB-TOTAL : 1,040.00

TOTAL : 2,150.40

Limf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin 10/11/18
3/4/18 1110 hrs
2 Days
P/P
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: