

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 02 APR 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 02 APR 2018
NRIC/FIN No.:

MERINA CHIA SAN SAN
Performance Motors Limited
305 Alexandra Road
Sims Darby Performance Centre
Singapore 119941

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my car. In a split second moment it derailed to the right of the garden and fell into a 2 feet ditch. The tow company towed the car away.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 02 APR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

02 APR 2018



SKP3345X - Submitted by: Performance Motors Limited (Alexandra)



1/78. Accident Photo [Linked Accident Report Documents]



2/78. Accident Photo [Linked Accident Report Documents]



3/78. Accident Photo [Linked Accident Report Documents]

SKP3345X - Submitted by: Performance Motors Limited (Alexandra)



4/78: Accident Photo [Linked Accident Report Documents]



5/78: Accident Photo [Linked Accident Report Documents]



6/78: Accident Photo [Linked Accident Report Documents]

SKP3345X - Submitted by: Performance Motors Limited (Alexandra)



7/78: Accident Photo [Linked Accident Report Documents]



8/78: Accident Photo [Linked Accident Report Documents]



9/78: Accident Photo [Linked Accident Report Documents]

SKP3345X - Submitted by: Performance Motors Limited (Alexandra)



10/78: Accident Photo [Linked Accident Report Documents]



11/78: Accident Photo [Linked Accident Report Documents]



12/78: Accident Photo [Linked Accident Report Documents]

Vehicle Owner Particulars

Vehicle Details

Intended PARF Rebate Details

Intended COE Rebate Details

COE Expiry Date:	28 Aug 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,810.00
COE Rebate Amount:	\$46,602.00
Total Rebate Amount:	\$100,422.00

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Passport Country/Region: India
Owner ID:	99833
Vehicle Details	
Vehicle No.:	SKP3345X
Vehicle to be Exported:	No
Intended De-registration Date:	09 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	428i CONVERTIBLE AT D/AB HID NAV HUD
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	B9310771N20B20A
Chassis No.:	WBA3V32070J993033
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$58,200.00
Original Registration Date:	29 Aug 2014
First Registration Date:	29 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$71,760.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2024
PARF Rebate Amount:	\$53,820.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,810.00
COE Rebate Amount:	\$45,878.00
Total Rebate Amount:	\$99,698.00

The information contained herein is correct as at 09 May 2018

OK

4/3/2018

Used bmw 428 Car & Used Cars & Vehicles Singapore - sgCarMart

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Daily Flights to Colombo

Best fares from SGD 385* to Colombo.
Book on the official website.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Beautiful Polo At \$6k Depre & Yearly High Scrap Value...



Remove Road Tax In The
Market, You Owners Can Be Doing
Well From It. Now
Wheeler Dealers 2018 \$50,000



Sort by Date Posted 20 results/page

8 vehicles

bmw 428

New Search

Price Any price Depre Any depre Reg Date Any date Eng Cap Any Veh Type All types
Fuel Any fuel Mileage Any OMV Any Gear Any Gear Past Owners Any
Category All categories Scheme All schemes Dealer Any Dealer Location Any Status Any status

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status



**BMW 4 Series 428i Convertible
Luxury**

\$152,800

\$18,830 /yr

07-Aug-2014

1,997 cc

53,857 km

Sports

Available

90% Loan Available, Low Mileage, Consignment Unit, Powerful And Stylish BMW 428 Convertible In Metallic Grey With Sporty Red Leather Upholstery. Come Test Drive Today For The Unique BMW Driving Experi...

TS Wheeler Capital Pte Ltd

Posted: 27-Mar-2018 Tags: 2014 BMW 428i, BMW 428i, BMW, 428i, Used BMW



**BMW 4 Series 428i Coupe M-
Sport**

\$151,888

\$18,270 /yr

10-Oct-2014

1,997 cc

37,888 km

Sports

Available

Very Low Mileage, Well Maintained, High Perf, 90% Loan Available, Powerful 241Bhp, Under Warranty With Serviced Record, Trade In Welcome

Posted: 17-Mar-2018 Tags: 2014 BMW 428i, BMW 428i, BMW, 428i, Used BMW



**BMW 4 Series 428i Coupe
Sport**

-

N.A

22-Jan-2014

1,997 cc

-

Sports

SOLD

5 Years Or 200000km Agent PML Warranty Till Jan 2019! Comes With Adaptive LED Headlamps, Reverse Camera & Sunroof! Flexible In House Financing Package! 1 Owner With Only 47000Km Done. Accident Free, P...

D'Cars

Posted: 10-Mar-2018 Tags: 2014 BMW 428i, BMW 428i, BMW, 428i, Used BMW



**BMW 4 Series 428i Coupe M-
Sport**

\$135,800

\$17,930 /yr

03-Mar-2014

1,997 cc

-

Sports

Available

Best Priced BMW 428i In The Market, Racy And Eye Catching Unit. Tastefully Done Up With Carbon Fibre Parts, Low Mileage And Well Maintain, Powerful And Aggressive Twin Turbo Charged Engine. Hands Free...

Posted: 09-Mar-2018 Tags: 2014 BMW 428i, BMW 428i, BMW, 428i, Used BMW

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



**BMW 4 Series 428i Gran
Coupe Luxury**

-

N.A

05-Dec-2014

1,997 cc

-

Luxury

SOLD

The Only Certified BMW Sport Version 428 Gran Coupe In Low Engine Capacity And Yet Powerful In Its Category. Clad In Renowned Metallic Imperial R... With Iv White/black Leather Upholstery. Come With B...

ance Premium Selection Limited

Posted: 08-Mar-2018 Tags: 2014 BMW 428i, BMW 428i, BMW, 428i, Used BMW

4/3/2018

Used bmw 428 Car & Used Cars & Vehicles Singapore - sgCarMart



BMW 4 Series 428i Coupe Sport

-

N/A

18-Mar-2014

1,997 cc

-

Sports

SOLD

Fully Agent Service (PML Unit). Mileage Done At 8200Km Per Year Only. Brand New Condition. Beautiful Number Plate. Car Always Park Under Shelters. Very Neat And Clean Interior. This Shall Be The Best ...

Posted: 22-Feb-2018 Tags: 2014 BMW 428i, BMW 428i, BMW 428i, Used BMW



BMW 4 Series 428i Coupe M-Sport

\$140,000

\$18,840 /yr

13-Mar-2014

1,997 cc

99,000 km

Sports

Available

Best Priced BMW 428i In The Market. Racy And Eye Catching Unit. Tastefully Well Maintain. Powerful And Aggressive Twin Turbo Charged Engine. Viewing Appointment Must Be Made In Advance.

Posted: 28-Jan-2018 Tags: 2014 BMW 428i, BMW 428i, BMW 428i, Used BMW



BMW 4 Series 428i Gran Coupe Luxury

-

N/A

22-Dec-2014

1,997 cc

-

Luxury

SOLD

Graded B by **STV**

Rare Gem! 1 Owner With Full (PML) Serviced Since Day 1! Very Low Mileage! Like Brand New! Low Down Payment Available, 100% Approval! 1 Year Extended Premium Warranty Plus Servicing For An Added Peace ...

Hamilton Autohub Pte Ltd

Posted: 26-Jan-2018 Tags: 2014 BMW 428i, BMW 428i, BMW 428i, Used BMW

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, compare rates & car insurance. Find buy used bmw 428, bmw 428 Singapore, used bmw 428 Singapore, used bmw 428, used vehicles Singapore or even buy used bmw 428 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

285, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

03 APR 2018

Estimate No. : b1 46463
Date Estimated : 03/04/2018
Prepared By : Merina Chia San San

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Rupinder Kaur Vohra
18J Queen Astrid Park

Singapore 266820

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3345X	J993033	29/08/2014	428iA-C	0

DESCRIPTION

VALUE

To replace front bumper, front right fender, front left fender, bonnet, right door, left door, rear left fender, right side mirror, left side mirror including attachments etc and to knock out dented area caused by accident

11050 ~~12,750.00~~

To paint front bumper, front left fender, front right fender, bonnet, left door, right door, rear left fender, rear right fender, rear bumper, left skirting, right skirting, left side mirror cover and right side mirror cover

9435 ~~10,484.00~~

To tow accident vehicle to PML workshop.

195.00

To supply front emboss number plate.

83.00

To remove and install front suspension to facilitate the jacking of chassis and mounting of car on celette bench including replace damaged parts.

2257? ~~2,655.00~~

To check steering geometry and conduct wheel alignment according to BMW specification (4x)

1805 ~~2,124.00~~

To replace power steering rack & pinion including to flush system and check leak.

451? ~~581.00~~

To replace tyre and wheel rim including balancing. (4x).

320 ~~376.00~~

To replace both front left and right pneumatic spring strut including program and checks function of ride level height control for proper function.

878? ~~1,033.00~~

To mount accident vehicle on celette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications.

2507 ~~2,950.00~~

To check electrical wiring system at the front and rear sections for proper function including adjustment of

251 ~~298.00~~

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63442773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46463
Date Estimated : 03/04/2018
Prepared By : Merina Chia San San

Page No. : 2 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3345X	J993033	29/08/2014	428iA-C	0

DESCRIPTION

VALUE

headlights.

To replace both left and right headlights including program
and conduct tests for proper function.

903 1,062.00

To carry out body cavity preservation.
(Per panel).6x

500 708.00

To supply tyre. -
Pirelli P7 225/45R18 x 4

70%? 1,400.00

Total Labour 1: 36,646.00

DESCRIPTION

QTY PRIC

VALUE

PLASTIC NUT FOR COARSE THREADED PIN

6 0.80

4.80

HEX SCREW WITH COLLAR M12X1.5X85

1 7.70

7.70

Front axle s

1 1,317.15

1,317.15

RH WISHBONE

1 262.20

262.20

RH TENSION STRUT W/HYDRAULIC MOUNT

1 262.20

262.20

HYDROBEARING

1 102.45

102.45

WHEEL HUB WITH BEARING FRT

1 465.75

465.75

FRT RH CARRIER

1 439.10

439.10

FRT GUIDE SUPPORT

1 232.00

232.00

FRT SPRING STRUT

1 484.55

484.55

RH TIE ROD

1 282.35

282.35

EXCH STEERING BOX ELECTR. (TKP)

1 3,583.40

3,583.40

COMBINATION NUT M14X1.5

1 5.55

5.55

HEX NUT WITH FLANGE

1 2.35

2.35

ALLOY RIM 8JX18 DOUBLE SPK STY 397

4 1,089.10

4,356.40

BONNET

1 1,219.70

1,219.70

FRT LH DOOR

1 1,545.75

1,545.75

FRT RH DOOR

1 1,545.75

1,545.75

REAR LH SIDE PANEL

1 1,524.65

1,524.65

FRT LH 2 SIDE PANEL BRACKET

1 32.15

32.15

FRT RH 2 SIDE PANEL BRACKET

1 32.15

32.15

FRT LH FENDER

1 682.50

682.50

FRT RH FENDER

1 682.50

682.50

FRT LH 1 SIDE PANEL BRACKET

1 32.15

32.15

FRT RH 1 SIDE PANEL BRACKET

1 32.15

32.15

FRT LH 3 SIDE PANEL BRACKET

1 32.15

32.15

FRT RH 3 SIDE PANEL BRACKET

1 32.15

32.15

LH UPPER FRT DOOR HINGE

1 54.65

54.65

RH UPPER FRONT DOOR HINGE

1 54.65

54.65

LH LOWER FRT DOOR HINGE

1 54.65

54.65

RH LOWER FRT DOOR HINGE

1 54.65

54.65

BONNET LH HINGE

1 71.50

71.50

BONNET RH HINGE

1 71.50

71.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1974015594 GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190886 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46463
Date Estimated : 03/04/2018
Prepared By : Merina Chia San San

Page No. : 3 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3345X	J993033	29/08/2014	428iA-C	0

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TOP CARRIER	1	397.45	397.45
DEFORMATION ELEMENT FRT LH	1	107.05	107.05
DEFORMATION ELEMENT FRT RH	1	107.05	107.05
DEFORMATION ELEMENT FRT LH	1	90.85	90.85
DEFORMATION ELEMENT FRT RH	1	90.85	90.85
FRT SHOCK ABSORBER	1	43.05	43.05
SUPPORT FOG LAMP LH	1	37.60	37.60
SUPPORT FOG LAMP RH	1	37.60	37.60
PARTIALLY OPEN GRID LH (SPORTLINE)	1	66.35	66.35
PARTIALLY OPEN GRID RH (SPORTLINE)	1	66.35	66.35
FINISHER ROD CENTRE (SPORTLINE)	1	55.65	55.65
INSERT AIR INLET MIDDLE (LINE/SPORT)	1	114.85	114.85
LH FINISHER (SPORTLINE)	1	119.80	119.80
RH FINISHER (SPORTLINE)	1	119.80	119.80
LICENCE PLATE BASE ECE	1	67.60	67.60
FRT BUMPER PANEL PRIMED (SRA)	1	1,031.90	1,031.90
FLAP TOWING EYE PRIMED	1	42.20	42.20
LH COVER SPRAY NOZZLE PRIMED	1	42.20	42.20
RH COVER SPRAY NOZZLE PRIMED	1	42.20	42.20
FRT LH GRILLE (SPORT)	1	115.65	115.65
FRT RH GRILLE (SPORT)	1	115.65	115.65
INSCRIPTION SIDE (SPORT LINE)	2	45.20	90.40
GROMMET	2	0.75	1.50
PLASTIC NUT	4	0.85	3.40
LH HEATED OUTSIDE MIRROR W/O GLASS	1	923.90	923.90
RH HEATED OUTSIDE MIRROR W/O GLASS	1	923.90	923.90
LH SYSTEM LATCH	1	284.50	284.50
CATCH BRACKET	2	52.25	104.50
FRT RH DOOR LOCK	1	246.75	246.75
FRT DOOR BRAKE	1	75.30	75.30
Door brake,	1	75.30	75.30
LH LOWER PART OF HOOK LOCK	1	85.80	85.80
RH LOWER PART OF HOOK LOCK	1	85.80	85.80
BONNET CATCH BRACKET	1	24.65	24.65
FRT LH DOOR CHANNEL SEALING	1	174.80	174.80
FRT RH DOOR CHANNEL SEALING	1	174.80	174.80
FRT LH DOOR JOINT SEAL	1	41.40	41.40
FRT RH DOOR JOINT SEAL	1	41.40	41.40
LH SEAL MIRROR FOOT OUTER	1	116.85	116.85
RH OUTER MIRROR FOOT SEAL	1	116.85	116.85
LH SEAL OUTER MIRROR TRIANGLE	1	27.00	27.00
Seal	1	27.00	27.00
LH OUTER WEATHERSTRIP (SCHWARZ HGL)	1	123.40	123.40
RH OUTER WEATHERSTRIP (SCHWARZ HGL)	1	123.40	123.40
FRT LH DOOR JOINT SEAL	1	57.40	57.40
FRT RH DOOR JOINT SEAL	1	57.40	57.40
LH CORNER MOULDING HIFI	1	140.70	140.70
RH CORNER MOUDLING HIFI	1	140.70	140.70
LH SEAL A PILLAR	1	86.50	86.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No: 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 498180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528
Fax. 64798501
64798524

LKK Auto Consultants hence notify

the Repairer of the following:

- to survey before/after spray painting

- to display damaged part(s) during resurvey

- to display damaged part(s) subject to confirmation

Third party survey is on a "Without Prejudice" basis

* No illegal modification(s) is allowed

* Supplemental item(s) must be resurveyed and

is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081-X

ESTIMATE

Acknowledged by Repairer

Signature:

Date:

Page No. : 4 of 4

Estimate No. : b1 46463
Date Estimated : 03/04/2018
Prepared By : Merina Chia San San

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3345X	J993033	29/08/2014	428iA-C	0

DESCRIPTION

QTY

PRIC

VALUE

RH SEAL A PILLAR	1	86.50	86.50
FRT BUMPER LOWER MOUNT	1	128.00	128.00
Edge protect	2	101.20	202.40
Sealing	1	24.00	24.00
FRONT ENGINE HOOD SEALING	1	24.95	24.95
LH ENGINE HOOD SEALING	1	13.50	13.50
Sealing	1	13.35	13.35
SEALING SIDE PANEL LH	1	24.05	24.05
SEALING SIDE PANEL RH	1	24.05	24.05
SEAL A PILLAR	2	252.95	505.90
PLAQUE 82MM	1	69.50	69.50
LH BI XENON HEADLIGHT	1	2,135.85	2,135.85
RH BI XENON HEADLIGHT	1	2,135.85	2,135.85
LH FOG LIGHT	1	276.40	276.40
RH FOG LIGHT	1	276.40	276.40
PDC sensor	4	368.80	1,475.20
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	18.45
BLIND RIVET AVIBVLB	19	0.55	10.45
SCREW (SF PLUS M5X15)	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N5	15	0.55	8.25
BLIND RIVET N6	8	0.55	4.40
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
PUNCH RIVET N4	9	0.55	4.95
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 34,726.80

Claims Q1 / 3rd Party / Uninsured losses / Direct Settlement

Regn No.

Claim No.

Date & Time

04/04/18 @ 1430

Excess S\$

1500

Surveyor's Name

RASUL

Sign

Excess Paid

7600.00

Approved By

REVERT

Authorized Date

Time

Resurvey Party, PHOTO BY, REVEAL Yes/No, PVL Yes/No

Surveyor's Email

No. of Working Days Recommended

24 days (to be confirmed)

Labour 1	:	36,646.00
Parts	:	34,726.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	4,996.10

Grand Total : 76,368.90

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575656. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/052018/3576
Policy No:	NIL	Date of Loss:	01/04/2018
Vehicle Reg. No.:	SKP3345X	Driveable?	
Driver Age/Info:	38	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	VOHRA RUPINDER KAUR	Contact No:	+6592473212
Driver:	VOHRA RUPINDER KAUR		
Make/Model:	BMW 428i, 2.0 CONVERTIBLE D/AB HID NAV (A)	Vehicle Reg. Date:	29/08/2014
Vehicle Colour:	BLUE	Chassis No:	WBA3V32070J993033
Engine No:	B9310771N20B20A		
Odometer:	0 KM		
Paint Type:			<i>Not Authorized</i>
Total Loss?	NO		<i>61 Laps @ 7</i>
Est. Duration of Repair (day)	<i>20/18 day</i>		<i>Running After Paint</i>
Description of Accident/Loss	REFER TO SKETCH PLAN		<i>Ex @ 1500h</i>
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	43,104.60
Miscellaneous Items	0.00
Labour	5,190.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	48,294.60
+ GST 7.00% (S\$)	3,380.62
Nett Amount (S\$)	51,675.22

This claim is handled by: YAP JIN HUI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 May 2018)

Parts: 143 BMW 428i 2.0 CONVERTIBLE D/AB HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SKP3345X/07/05/2018 14:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*Front grille @ \$100/pc <i>OLJ SKR</i>	<i>NLSM</i> 0.00	0.00	*200.00 F ✓
2	1		*Front bonnet	0.00	0.00	<i>B1</i> *920.00 F ✓
3	10		*Front bonnet insulator clips @ \$3/pc	0.00	0.00	<i>m</i> *30.00 F ✓
4	1		*Front bumper	<i>Bulcom</i> 0.00	0.00	*850.00 F ✓
5	1		*Front bumper inside pad	0.00	0.00	<i>CM</i> *90.00 F ✓
6	1		*Front bumper reinforcement	0.00	0.00	<i>B1</i> *280.00 F ✓
7	1		*Front bumper sponge	<i>Sm</i> 0.00	0.00	<i>CM</i> *30.00 F ✓
8	1		*Front bumper lower bean	0.00	0.00	<i>R</i> *100.00 F ✓
9	2		*Front bumper bracket @ \$15/pc	<i>mjcm</i> 0.00	0.00	<i>R</i> *30.00 F ✓
10	2		*Front bumper fog lamp @ \$210/pc	0.00	0.00	*420.00 F ✓
11	2		*Front bumper fog lamp cover @ \$28/pc	0.00	0.00	<i>Sm</i> *56.00 F ✓
12	1		*Front bumper centre grille	0.00	0.00	<i>Sm</i> *40.00 F ✓
13	1		*Front bumper lower grille	0.00	0.00	<i>A</i> *30.00 F ✓
14	1		*Front bumper towing cover	0.00	0.00	<i>R</i> *20.00 F ✓
15	1		*Front bumper RH nozzler gun	0.00	0.00	<i>Sm</i> *120.00 F ✓
16	1		*Front bumper RH nozzler gun cover	0.00	0.00	<i>R</i> *30.00 F ✓
17	1		*Front bumper number plate garnish	0.00	0.00	<i>Sm</i> *40.00 F ✓
18	2		*Front bumper side retainer @ \$15/pc	0.00	0.00	*30.00 F ✓
19	<i>A1</i>		*Front bumper parking sensor @ \$190/pc <i>OLJ SKR</i>	<i>15 OLJ D17</i> 0.00	0.00	*760.00 F ✓
20	1		*Front bumper under cover	0.00	0.00	<i>CM</i> *160.00 F ✓
21	2		*Front bumper air dust @ \$60/pc	0.00	0.00	<i>CM</i> *120.00 F ✓
22	2		*Front headlamp @ \$1750/pc <i>OLJ CM</i>	<i>NLS</i> 0.00	0.00	*3,500.00 F ✓
23	1		*Front RH headlamp HID bulb	0.00	0.00	<i>Sm</i> *220.00 F ✓
24	1		*Front RH headlamp ECU 1	0.00	0.00	<i>Sm</i> *550.00 F ✓
25	1		*Front RH headlamp ECU 2	0.00	0.00	<i>Sm</i> *610.00 F ✓
26	1		*Front RH headlamp ECU 3	0.00	0.00	<i>Sm</i> *480.00 F ✓
27	2		*Front headlamp bracket @ \$50/pc	0.00	0.00	<i>R</i> *100.00 F ✓
28	1		*Front top panel	0.00	0.00	<i>R</i> *150.00 F ✓
29	2		*Front fender @ \$620/pc	0.00	0.00	<i>B1</i> *1,240.00 F ✓
30	1		*Front fender inner shield	0.00	0.00	<i>CM</i> *90.00 F ✓
31	10		*Front fender clips @ \$3/pc	0.00	0.00	<i>m</i> *30.00 F ✓
32	2		*Front sport logos @ \$45/pc	0.00	0.00	<i>m</i> *90.00 F ✓
33	2		*Front doors @ \$1300/pc <i>OLJ B1</i>	<i>NLS wan</i> 0.00	0.00	*2,600.00 F ✓
34	2		*Front side skirts @ \$280/pc	0.00	0.00	<i>CM</i> *560.00 F ✓
35	20		*Front side skirts clips @ \$3/pc	0.00	0.00	<i>m</i> *60.00 F ✓
36	1		*Rear LH fender	0.00	0.00	*1,300.00 F ✓
37	2		*Front wheel sport rims @ \$950/pc <i>OLJ SKR 405</i>	0.00	0.00	*1,900.00 F ✓
38	2		*Front wheel tyre @ \$450/pc <i>CM OLJ SKR 900/16 NLS R1</i>	0.00	0.00	*900.00 F ✓
39	2		*Front shock absorber @ \$400/pc	0.00	0.00	<i>B1</i> *800.00 F ✓
40	2		*Front shock absorber top mounting @ \$180/pc	0.00	0.00	<i>Sm</i> *360.00 F ✓
41	2		*Front knuckle arm @ \$380/pc	0.00	0.00	<i>B1</i> *760.00 F ✓
42	2		*Front wheel bearing @ \$410/pc	0.00	0.00	<i>m</i> *820.00 F ✓
43	2		*Front lower arm @ \$150/pc	0.00	0.00	<i>D1's</i> *300.00 F ✓
44	2		*Front rack end @ \$220/pc	0.00	0.00	<i>D1's</i> *440.00 F ✓
45	1		*Front steering rack and pinion	<i>B1/Sm</i> 0.00	0.00	*2,900.00 F ✓
46	1		*Front engine cross-member	0.00	0.00	<i>B1</i> *1,000.00 F ✓
47	2		*Front engine mounting @ \$150/pc	0.00	0.00	<i>CM</i> *300.00 F ✓
48	2		*Rear wheel sport rim @ \$950/pc	0.00	0.00	<i>R</i> *1,900.00 F ✓
49	2		*Rear wheel tyre @ \$450/pc	0.00	0.00	<i>Sm</i> *900.00 F ✓
50	2		*Rear shock absorber @ \$280/pc	0.00	0.00	<i>B1</i> *560.00 F ✓

Vin's Motor Pte Ltd/SKP3345X/07/05/2018 14:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
51	2		*Rear knuckle arm @ \$900/pc	0.00	0.00	R ₁ *1,800.00 F	2
52	2		*Rear lower arm @ \$210/pc	0.00	0.00	D ₁ *420.00 F	2
53	2		*Rear side arm no.1 @ \$80/pc	0.00	0.00	L ₁ *160.00 F	2
54	2		*Rear side arm no.2 @ \$100/pc	0.00	0.00	L ₂ *200.00 F	2
55	1		*Rear cross-member	0.00	0.00	R ₁ *1,600.00 F	2
56	1		*Rear axle gear	0.00	0.00	R ₂ *2,900.00 F	2
57	1		*Rear bumper	0.00	0.00	C ₁ *900.00 F	1
58	1		*LH body under cover	0.00	0.00	C ₁ *90.00 F	1
59	1		*RH body under cover	0.00	0.00	C ₁ *90.00 F	1
60	1		*Center body under cover	0.00	0.00	C ₁ *150.00 F	1
61	1		*Rear exhaust	0.00	0.00	R ₁ *1,100.00 F	1

F=Franchise part.

Sub Total (S\$)	39,186.00
+ Margin on L,N Items 10.00% (S\$)	3,918.60
Total Parts (S\$)	43,104.60

Vin's Motor Pte Ltd/SKP3345X/07/05/2018 14:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To towing	New	120.00 X
2	To remove and refix engine	New	580.00
3	To remove and refix front undercarriage	New	320.00
4	To remove and refix rear undercarriage	New	320.00
5	To refill air con gas	New	150.00
6	To check wheel alignment	New	100.00 ✓
7	To repair front and rear damages	New	1,800.00
8	To spray painting	New	1,800.00 ✓
Gross Labour Cost (S\$)			5,190.00

Vin's Motor Pte Ltd/SKP3345X/07/05/2018 14:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018 13:53 Sendback Est	07 May 2018 14:03 S\$48,294.60	08 May 2018 10:21 Edit Adj Rpt	S\$28,500.00 Edit Estimates	S\$28,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	VOHRA RUPINDER KAUR, ID: G5736875L, Tel: +6592473212		
Vehicle Reg. No.:	SKP3345X	Date of Loss:	01/04/2018 13:00 - :59 [43 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 554222	Policy/Cover Note No.:	27771807SMP (Comprehensive) Coverage: 29/08/2017 - 28/08/2018
		Excess:	S\$1,500.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/06/2018]		
Driver/Custodian:	VOHRA RUPINDER KAUR (38), NRIC: G5736875L, Tel: +6592473212		
Adj Asg. Remarks:	Owner has changed workshop from Performance Motors to Vin's Motor. Please survey and revert. Please arrange surveyor Kenneth to survey this vehicle.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (05/07/2018): Alert - Adj Mandate Approved (S\$28500.00) - SKP3345X - Claim Handler: Joslin Lim
- MSIG_SG (28/06/2018): Alert - Adj Mandate Maintained - SKP3345X - Claim Handler: Joslin Lim
- MSIG_SG (09/05/2018): Alert - Adj Mandate Approved (S\$18636.50) - SKP3345X - Claim Handler: Joslin Lim

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKP3345X (554222)
OD
Apr 1 2018 1:00PM
[VOHRA RUPINDER KAUR]
Vin's Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/05/18 14:03	Repairer Estimates	1 Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 10:25	Accident Statement From:OD - Reg. No: SKP3345X, Claimant: VOHRA RUPINDER KAUR	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 13:53	Adjuster Immediate Advice	1 Load HTM	
2	09/05/18 14:01	Adjuster Immediate Advice	1 Load HTM	
3	28/06/18 11:33	Adjuster Immediate Advice	1 Load HTM	

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 14:03	General View	1 Load JPG	✓
2	09/05/18 14:03	General View	1 Load JPG	✓
3	09/05/18 14:03	General View	1 Load JPG	✓
4	09/05/18 14:03	General View	1 Load JPG	✓
5	09/05/18 14:03	General View	1 Load JPG	✓
6	09/05/18 14:03	General View	1 Load JPG	✓
7	09/05/18 14:03	General View	1 Load JPG	✓
8	09/05/18 14:03	General View	1 Load JPG	✓
9	09/05/18 14:03	General View	1 Load JPG	✓
10	09/05/18 14:03	General View	1 Load JPG	✓
11	09/05/18 14:03	General View	1 Load JPG	✓
12	09/05/18 14:03	General View	1 Load JPG	✓
13	09/05/18 14:03	General View	1 Load JPG	✓
14	09/05/18 14:03	General View	1 Load JPG	✓
15	09/05/18 14:03	General View	1 Load JPG	✓
16	09/05/18 14:03	General View	1 Load JPG	✓
17	09/05/18 14:03	General View	1 Load JPG	✓
18	09/05/18 14:03	General View	1 Load JPG	✓
19	09/05/18 14:03	General View	1 Load JPG	✓
20	09/05/18 14:03	General View	1 Load JPG	✓
21	09/05/18 14:03	General View	1 Load JPG	✓
22	09/05/18 14:03	General View	1 Load JPG	✓
23	09/05/18 14:03	General View	1 Load JPG	✓
24	09/05/18 14:03	General View	1 Load JPG	✓
25	09/05/18 14:03	General View	1 Load JPG	✓
26	09/05/18 14:03	General View	1 Load JPG	✓
27	09/05/18 14:03	General View	1 Load JPG	✓
28	09/05/18 14:03	General View	1 Load JPG	✓

Assessment Reports					
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
29	09/05/18 14:03	General View		Load JPG	
30	09/05/18 14:03	General View		Load JPG	
31	09/05/18 14:03	General View		Load JPG	
32	09/05/18 14:03	General View		Load JPG	
33	09/05/18 14:03	General View		Load JPG	
34	09/05/18 14:03	General View		Load JPG	
35	09/05/18 14:03	General View		Load JPG	
36	09/05/18 14:03	General View		Load JPG	
37	09/05/18 14:03	General View		Load JPG	
38	09/05/18 14:03	General View		Load JPG	
39	09/05/18 14:03	General View		Load JPG	
40	09/05/18 14:03	General View		Load JPG	
41	09/05/18 14:03	General View		Load JPG	
42	09/05/18 14:03	General View		Load JPG	
43	09/05/18 14:03	General View		Load JPG	
44	09/05/18 14:03	General View		Load JPG	
45	09/05/18 14:03	General View		Load JPG	
46	09/05/18 14:03	General View		Load JPG	
47	09/05/18 14:03	General View		Load JPG	
48	09/05/18 14:03	General View		Load JPG	
49	09/05/18 14:03	General View		Load JPG	
50	09/05/18 14:03	General View		Load JPG	
51	09/05/18 14:03	General View		Load JPG	
52	09/05/18 14:03	General View		Load JPG	
53	09/05/18 14:03	General View		Load JPG	
54	09/05/18 14:03	General View		Load JPG	
55	09/05/18 14:03	General View		Load JPG	
56	09/05/18 14:03	General View		Load JPG	
57	09/05/18 14:03	General View		Load JPG	
58	09/05/18 14:03	General View		Load JPG	
59	09/05/18 14:03	General View		Load JPG	
60	09/05/18 14:03	General View		Load JPG	
61	09/05/18 14:03	General View		Load JPG	
62	09/05/18 14:03	General View		Load JPG	
63	09/05/18 14:03	General View		Load JPG	
64	09/05/18 14:03	General View		Load JPG	
65	09/05/18 14:03	General View		Load JPG	
66	09/05/18 14:03	General View		Load JPG	
67	09/05/18 14:03	General View		Load JPG	
68	09/05/18 14:03	General View		Load JPG	
69	09/05/18 14:03	General View		Load JPG	
70	09/05/18 14:03	General View		Load JPG	
71	09/05/18 14:03	General View		Load JPG	
72	27/06/18 10:28	Reinspection Photo		Load JPG	
73	27/06/18 10:28	Reinspection Photo		Load JPG	
74	27/06/18 10:28	Reinspection Photo		Load JPG	
75	27/06/18 10:28	Reinspection Photo		Load JPG	
76	27/06/18 10:28	Reinspection Photo		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18006184/KVBS2

Date: 09/07/2018

REFERENCE

Insured/Claimant:	VOHRA RUPINDER KAUR	Policy No:	27771807SMP	
Date of Loss:	01/04/2018	Nature of Claim:	OD	Claim No: 554222

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP3345X		
Make & Model:	BMW 428i, 2.0 CONVERTIBLE D/AB HID NAV (A)	Engine No:	B9310771N20B20A
Reg. Date:	29/08/2014 (Man. Year: 2014)	Chassis No:	WBA3V32070J993033
Colour:	Metallic Dark Blue	Odometer:	34691 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$152,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,104.60	31,375.50	11,729.10	27.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,190.00	4,520.00	670.00	12.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,294.60	35,895.50	12,399.10	25.67
Approved Total (Overridden) (S\$)		28,500.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	48,294.60	27,000.00	21,294.60	44.09
+ GST 7.00/7.00% (S\$)	3,380.62	1,890.00	1,490.62	44.09
Nett Amount (S\$)	51,675.22	28,890.00	22,785.22	44.09

INSPECTION

Date of Assignment:	08/05/2018	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	08/05/2018	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	18.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)

Parts: 143 BMW 428I 2.0 CONVERTIBLE D/AB HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKP3345X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*Front grille @ \$100/pc (WCP)	O/s Scratched/N/s Cracked	200.00 F	*200.00 F
2	1		*Front bonnet (WCP)	Bent	920.00 F	*920.00 F
3	10		*Front bonnet insulator clips @ \$3/pc (WCP)	Necessary	30.00 F	*30.00 F
4	1		*Front bumper (WCP)	Buckled/Cracked	850.00 F	*850.00 F
5	1		*Front bumper inside pad (WCP)	Cracked	90.00 F	*90.00 F
6	1		*Front bumper reinforcement (WCP)	Bent	280.00 F	*280.00 F
7	1		*Front bumper sponge (WCP)	Serviceable	30.00 F	*- F
8	1		*Front bumper lower bean (WCP)	Repair	100.00 F	*- F
9	2		*Front bumper bracket @ \$15/pc (WCP)	Repair	30.00 F	*- F
10	2		*Front bumper fog lamp @ \$210/pc (WCP)	Mtg Cracked	420.00 F	*420.00 F
11	2		*Front bumper fog lamp cover @ \$28/pc (WCP)	Serviceable	56.00 F	*- F
12	1		*Front bumper centre grille (WCP)	Serviceable	40.00 F	*- F
13	1		*Front bumper lower grille (WCP)	Serviceable	30.00 F	*- F
14	1		*Front bumper towing cover (WCP)	Dented	20.00 F	*20.00 F
15	1		*Front bumper RH nozzler gun (WCP)	Serviceable	120.00 F	*- F
16	1		*Front bumper RH nozzler gun cover (WCP)	Dented	30.00 F	*30.00 F
17	1		*Front bumper number plate garnish (WCP)	Serviceable	40.00 F	*- F
18	1		*Front bumper side retainer @ \$15/pc (WCP)	O/s Distorted	30.00 F	*15.00 F
19	1		*Front bumper parking sensor @ \$190/pc 4 Pcs (WCP)	O/s Scratched	760.00 F	*190.00 F
20	1		*Front bumper under cover (WCP)	Cracked	160.00 F	*160.00 F
21	2		*Front bumper air dust @ \$60/pc (WCP)	Cracked	120.00 F	*120.00 F
22	2		*Front headlamp @ \$1750/pc (WCP)	O/s Cracked/N/s Mtg Cracked	3,500.00 F	*3,500.00 F
23	1		*Front RH headlamp HID bulb (WCP)	Necessary	220.00 F	*220.00 F
24	1		*Front RH headlamp ECU 1 (WCP)	Serviceable	550.00 F	*- F
25	1		*Front RH headlamp ECU 2 (WCP)	Serviceable	610.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
26	1	*Front RH headlamp ECU 3 (WCP)	Serviceable	480.00 F	*- F
27	2	*Front headlamp bracket @ \$50/pc (WCP)	Repair	100.00 F	*- F
28	1	*Front top panel (WCP)	Repair	150.00 F	*- F
29	2	*Front fender @ \$620/pc (WCP)	Bent	1,240.00 F	*1,240.00 F
30	1	*Front fender inner shield (WCP)	Cracked	90.00 F	*90.00 F
31	10	*Front fender clips @ \$3/pc (WCP)	Necessary	30.00 F	*30.00 F
32	2	*Front sport logos @ \$45/pc (WCP)	Necessary	90.00 F	*90.00 F
33	2	*Front doors @ \$1300/pc (WCP)	O/s Bent/N/s Warped	2,600.00 F	*2,600.00 F
34	2	*Front side skirts @ \$280/pc (WCP)	Cracked	560.00 F	*560.00 F
35	20	*Front side skirts clips @ \$3/pc (WCP)	Necessary	60.00 F	*60.00 F
36	1	*Rear LH fender (WCP)	Bent/Warped	1,300.00 F	*1,300.00 F
37	1	*Front wheel sport rims @ \$950/pc (WCP)	O/s Dented	1,900.00 F	*950.00 F
38	1	*Front wheel tyre @ \$450/pc (@ \$450.00 DISC 90%) (WCP)	Frt O/s Cut/N/s Serviceable	900.00 F	*405.00 FS
39	2	*Front shock absorber @ \$400/pc (WCP)	Bent	800.00 F	*800.00 F
40	2	*Front shock absorber top mounting @ \$180/pc (WCP)	Serviceable	360.00 F	*- F
41	2	*Front knuckle arm @ \$380/pc (WCP)	Bent	760.00 F	*760.00 F
42	2	*Front wheel bearing @ \$410/pc (WCP)	Necessary	820.00 F	*820.00 F
43	2	*Front lower arm @ \$150/pc (WCP)	Distorted	300.00 F	*300.00 F
44	2	*Front rack end @ \$220/pc (WCP)	Distorted	440.00 F	*440.00 F
45	1	*Front steering rack and pinion (WCP)	Bent/Jammed	2,900.00 F	*2,900.00 F
46	1	*Front engine cross-member (WCP)	Bent	1,000.00 F	*1,000.00 F
47	2	*Front engine mounting @ \$150/pc (WCP)	Cracked	300.00 F	*300.00 F
48	2	*Rear wheel sport rim @ \$950/pc (WCP)	Repair	1,900.00 F	*- F
49	2	*Rear wheel tyre @ \$450/pc (WCP)	Serviceable	900.00 F	*- F
50	2	*Rear shock absorber @ \$280/pc (WCP)	Bent	560.00 F	*560.00 F
51	2	*Rear knuckle arm @ \$900/pc (WCP)	Bent	1,800.00 F	*1,800.00 F
52	2	*Rear lower arm @ \$210/pc (WCP)	Distorted	420.00 F	*420.00 F
53	2	*Rear side arm no.1 @ \$80/pc (WCP)	Distorted	160.00 F	*160.00 F
54	2	*Rear side arm no.2 @ \$100/pc (WCP)	Serviceable	200.00 F	*- F
55	1	*Rear cross-member (WCP)	Bent	1,600.00 F	*1,600.00 F
56	1	*Rear axle gear (WCP)	Repair	2,900.00 F	*- F
57	1	*Rear bumper (WCP)	Cracked	900.00 F	*900.00 F
58	1	*LH body under cover (WCP)	Cracked	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*RH body under cover (WCP)	Cracked	90.00 F	*90.00 F
60	1		*Center body under cover (WCP)	Cracked	150.00 F	*150.00 F
61	1		*Rear exhaust (WCP)	Bent	1,100.00 F	*1,100.00 F
					Sub Total (\$\$)	39,186.00 28,560.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	3,918.60 2,815.50
					Total Parts (\$\$)	43,104.60 31,375.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To towing F.O.C	New	120.00	-
2	To remove and refix engine	New	580.00	400.00
3	To remove and refix front undercarriage	New	320.00	280.00
4	To remove and refix rear undercarriage	New	320.00	240.00
5	To refill air con gas	New	150.00	100.00
6	To check wheel alignment	New	100.00	100.00
7	To repair front and rear damages	New	1,800.00	1,600.00
8	To spray painting	New	1,800.00	1,800.00
Gross Labour Cost (\$\$)			5,190.00	4,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >