

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 09 May 2018

Preliminary Advice

Vehicle No	: SKP3345X	Accident Date	: 01/04/2018
Make	: BMW 428i	Policy No.	: 27771807SMP
Assignment Date	: 08/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 08/05/2018	Est. Duration of Repair	: 18.00
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and n/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	48,294.60
Revised Amount	:S\$	18,636.50
Check Items (Estimated)	:S\$	27,912.60
Total	:S\$	46,549.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	152,000.00
COE / PARF Rebate	:S\$	100,422.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,578.00

Remarks

(X) The vehicle is economical for repair.

(X) Vehicle repair on Lump Sum basis.