

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 05 Apr 2018

Preliminary Advice

Vehicle No	: SKP3345X	Accident Date	: 01/04/2018
Make	: BMW 428I	Policy No.	: 27771807SMP
Assignment Date	: 04/04/2018	Excess	: S\$1,500.00
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 24.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	71,372.80
Revised Amount	:S\$	42,521.75
Check Items (Estimated)	:S\$	23,025.25
Total	:S\$	65,547.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	152,000.00
COE / PARF Rebate	:S\$	100,422.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,578.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

() The vehicle is economical/not economical for repair.

(X) Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$51,578.00