

INS. CASE OWNER:

CC 4 WP 1800

LR:
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

3/4/18

Date / Time:

3/4/18

Registered in Merimen:

4/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 8276A

Claim No.:

421918441456

Name of Insured:

WPP

Policy No.:

99999999

Insured Tel No.:

HP:

4/4/18

Make / Model:

Honda

Excess Sec II :\$S

D.O.A.:

Place of Accident:

PASIR RIS DR 1

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN 00 EE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLE 204TH

INSRS:
WSP:
Tel:
Liability:
RMKS:

leang.

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
6/4/18	SLE 8276A	Non-Reporting ltr (1st):	
20/4/18	OI HIT TP FROM REAR	Non-Reporting ltr (2nd):	NA
3/7/18	TP WKSP informed us that this case is handled by lawyer. According to TP, they said OI refused to make report, so they pass lawyer. XPS.	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	204 6-4-18
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$S	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No. : 27
Repair Cost:	\$S		
Loss of Rental (LOR):	\$S	(days)	
Loss of Use (LOU):	\$S	(S days)	
Loss of Income (LOI):	\$S	(S x days)	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/> [Tick only one]
GIA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost	\$S		
Total:	\$S	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S	Name 1:	
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

COPY SENT
4/7/18WSP PASS TO
LAWYER1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP \$250
3) Survey fee:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ2047H Yr Regn: 2016 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c. 1986Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 23774 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 28U600091223Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65R17R: 225/65R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/04/18Survey held at LeanyDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP A19</u>
<u>30/4/18</u>	<u>L/S \$4,600</u>
	<u>R (\$5,929.70 / 56%)</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos:

Others:

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18006188/Ajb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 04-04-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 8276A	Veh. Inspected	SLJ 2047H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/04/2018	Inspection Date	03/04/2018
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

TPHCR
Joy.

SLJ204TH
Toyota Harrier 1986cc
ZSU600091223

Rear Number Plate	} Not NEC	30(SN) x
Rear Number Plate Holder		30(SN) x
Rear Bumper Deformed		1381.50 ✓
Rear Bumper Clips. <i>new</i>		30 ✓
Rear Bumper Side Holder x02 <i>new</i>		68.5 x 2 = 137 ✓
Rear Bumper Sponge <i>crushed</i>		125.50 ✓
Rear Bumper Lower Garnish <i>deformed</i>		455 ✓
Rear Bumper Reflector x02 <i>not new</i>		85 x 2 = 170 x
Reverse Sensor <i>Damaged</i>		280(SN) 200(SN)
Rear End Panel <i>Regrind</i>		721.30 x
Rear End Panel Top Garnish	} Not new	301.70 x
Rear End Panel Sealant		60(SN) x
Tailgate <i>Dented.</i>		1680.10 ✓
Tailgate Lock <i>Damaged</i>		418.60 -
Tailgate Lock Sensor	} <i>new</i>	159.70 x
Tailgate Weatherstripe		321.10 x
Tailgate Inner Trim Board <i>crushed</i>		645.10 ✓
Tailgate Inner Trim Board clips <i>new</i>		30 ✓

SLJ 204TH.

Tailgate Glass Moulding }
Tailgate Glass Sealant. } New

Harrier Wording.

Rear Exhaust Pipe

Rear Exhaust Mounting.

Rear Camera.

Spare Tyre Panel Top Cover.

178.70 -

60(su) -

68.90 -

638.80 X

55 X

580(su) X

561.60 X

8,079.4

As 7.

P - 6,059.70
SN - 1040

~~1200~~ 600

~~1200~~ 650

~~50~~ 30

150 X

~~100~~ 50

~~100~~ 50

~~150~~ 50

~~180~~ 120

~~150~~ 80

~~150~~ X

347.5

hist: 5150.40

Rem 25%: 3862.80

S.N: 260

labour: 1630

total: 5752.80

/s: 4.6K

04 Days

Panel Beating

Spray Painting.

Wiring.

To undersent

To remove reverse sensor

To remove rear camera.

To remove upholstery

To remove tailgate glass,

To transfer tailgate fittings.

To remove exhaust pipe.

LKK Auto Consult

the Repairer of the

- To resurvey before
- To display damage
- Parts price
- Third party
- No illegal mod
- Supplemental
- is subject to fit

Acknowledged by

Signature:

Date:

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 6 April 2018 5:19 PM
To: 'Eileen, May Hwee Yap'
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: ACCIDENT INVOLVING SLE 8276A (LCRF) & SLJ 2047H ON 02/04/2018(14:30) ALONG PASIR RIS DRIVE 1

06 April 2018

LION CITY RENTALS PTE LTD

Policy Holder

LKK : CC6/LCR18006188/Ajb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 8276A (LCRF) & SLJ 2047H ON 02/04/2018(14:30) ALONG PASIR RIS DRIVE 1

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLJ 2047H against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 3 July 2018 10:57 AM
To: 'Khoo, Kay-Eng'
Cc: Admin A; CS A Team
Subject: RE: Our Ref: 4319184414SG; Your Ref: SLJ2047H *LKK REF: CC4/LCR18006188/Ajb3

Dear Kay Eng,

We called M/s Leang Automotive and they informed us that they appointed solicitors for handling from the very start as they had communicated with the insured driver directly and had issues.

They only agreed through solicitors to have our surveyor Mr. Adrian Ling perform pre-repair inspection on 3.4.2018.

The repair cost was finalized on 30/04/2018 at lump sum \$4,600.00 and 4 days for repair.

In view of this, we will submit wp report to your good office.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Khoo, Kay-Eng [mailto:Kay-Eng.Khoo@aig.com]
Sent: Tuesday, 3 July 2018 10:20 AM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: RE: Our Ref: 4319184414SG; Your Ref: SLJ2047H *LKK REF: CC4/LCR18006188/Ajb3

Dear Joy,

I have received a Letter of Demand from TP solicitors on this. Please advise and let us have your last communication with Leang Automotive in regards to the Direct Settlement and Letter of Demand/Finalization.

Please also advise with the workshop why the matter was passed on to solicitors for our records.

Thank you.

Khoo Kay Eng
AIG
Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026 | Fax +(65) 6835 7416

kay-eng.khoo@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Joy Irene (LKKAUTO) [<mailto:JoyIrene@lkkauto.com>]

Sent: Tuesday, July 03, 2018 10:01 AM

To: Khoo, Kay-Eng

Cc: Admin A; CS A Team

Subject: RE: Our Ref: 4319184414SG; Your Ref: SLJ2047H *LKK REF: CC4/LCR18006188/Ajb3

Hi Kay Eng,

Our status : Pending letter of demand and its supporting documents from M/s Leang Automotive.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Hsiao Tong (LKKAUTO)

Sent: Tuesday, 3 July 2018 9:21 AM

To: Khoo, Kay-Eng <Kay-Eng.Khoo@aig.com>

Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 4319184414SG; Your Ref: SLJ2047H *LKK REF: CC4/LCR18006188/Ajb3

Hi Mr Khoo,

We will check and get back to you.

Hi Joy,

Kindly assist. CC4/LCR18006188/Ajb3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khoo, Kay-Eng [<mailto:Kay-Eng.Khoo@aig.com>]

Sent: Tuesday, 3 July 2018 9:09 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: Our Ref: 4319184414SG; Your Ref: SLJ2047H

Importance: High

Hi LKK Auto Consultants,

Please assist current status of this matter, noted Fast Lane in Progress.

Have you directly settled the matter with the workshop?

Thank you.

Khoo Kay Eng

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026 | Fax +(65) 6835 7416

kay-eng.khoo@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Edit Reg		03 Apr 2018 00:00 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	TOH PENG YANG, ID: S69454551								
Vehicle Reg. No.:	SLJ2047H	Date of Loss:	02/04/2018 14:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4319184414SG	Policy/Cover Note No.:	0999994806						
Vehicle Reg. No. (Insured):	SLE8276A	Policy No. (Claimant):	MOMVP000003191-00-000						
		Excess:							
Repairer:	Leang Automotive - Kaki Bukit (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ2047H (4319184414SG)
[SLE8276A]
TP
TOH PENG YANG
Apr 2 2018 2:00PM
[LCRF PTE LTD]
Leang Automotive - Kaki Bukit

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print	
1	05/04/18 15:27	Accident Statement From: SC - Reg. No: SLE8276A, Claimant: LCRF PTE LTD									1	Load HTM		
											3 per page		<input checked="" type="checkbox"/>	
Photos/Images														
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
2	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
3	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
4	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
5	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
6	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
7	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
8	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
9	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
10	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
11	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
12	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
13	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
14	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
15	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
16	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
17	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
18	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
19	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
20	30/04/18 14:56	General View									1	Load JPG	<input checked="" type="checkbox"/>	
21	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
22	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
23	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
24	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
25	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
26	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
27	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
28	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
29	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
30	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
31	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
32	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	
33	30/04/18 14:57	Reinspection Photo									1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	30/04/18 14:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 16:03	EMAIL FROM AIG DD 03042018	 Load PDF	
2	04/04/18 17:05	TP GIA REPORT	 Load PDF	
3	06/04/18 17:55	LETTER TO LCRF	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18006188/AJB3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994806
Claimant Vehicle No : SLJ2047H **Insured Vehicle No :** SLE8276A
 Date of Loss: 02/04/2018 Nature of Claim: TP Claim No: 4319184414SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ2047H**
 Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 3ZRB902971
 Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: ZSU600091223
 Colour: Maroon Odometer: 23774 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,119.60	4,122.80	4,996.80	54.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,630.00	1,800.00	52.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,549.60	5,752.80	6,796.80	54.16
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	12,549.60	4,600.00	7,949.60	63.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 03/04/2018
 Date Inspected: 03/04/2018 Inspected At: Leang Automotive - Kaki Bukit (HQ)
 AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT
 AVE 6 #01-68
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	1,381.50 F	*1,381.50 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*REAR BUMPER SIDE HOLDER	Necessary	137.00 F	*137.00 FL
6	1		*REAR BUMPER SPONGE	Cracked	125.50 F	*125.50 FL
7	1		*REAR BUMPER LOWER GARNISH	Deformed	455.00 F	*455.00 FL
8	2		*REAR BUMPER REFLECTOR	Not Necessary	170.00 F	*- FL
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Repair	721.30 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	301.70 F	*- FL
12	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
13	1		*TAILGATE	Dented	1,680.10 F	*1,680.10 FL
14	1		*TAILGATE LOCK	Damaged	418.60 F	*418.60 FL
15	1		*TAILGATE LOCK SENSOR	Not Necessary	159.70 F	*- FL
16	1		*TAILGATE WEATHERSTRIPE	Not Necessary	321.10 F	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Cracked	645.10 F	*645.10 FL
18	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
19	1		*TAILGATE GLASS MOULDING	Necessary	178.70 F	*178.70 FL
20	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
21	1		*HARRIER WORDING	Necessary	68.90 F	*68.90 FL
22	1		*REAR EXHAUST PIPE	Not Necessary	638.80 F	*- FL
23	1		*REAR EXHAUST MOUNTING	Not Necessary	55.00 F	*- FL
24	1		*REAR CAMERA	Not Necessary	580.00 FS	*- FS
25	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	561.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	9,119.60	5,410.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,287.60
Total Parts (\$\$)	9,119.60	4,122.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	650.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	50.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,430.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >