

INS. CASE OWNER:

Bernard | CC 6/AIG1800 6190, Awbby

LKK:  
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

07/04/18

Date / Time:

3/4/18

Registered in Merimen:

4/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 71224

Name of Insured:

FHO LEE WAI

Insured Tel No.:

HP: 96200563

Excess Sec II :\$5

D.O.A: 07/04/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

77775095856

Policy No.:

210050665-01

Make / Model:

MAZDA

Place of Accident:

TAMPINES AVE 9 TMS TAMPINES AVE 10

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Insured Liability: %

Final ? Yes / No

SJP 2098C



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
6/4/18	SJP 2098C-X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
9/4/18	Confirm accident details. Inform TP claim. agree to settle. letter send out.	Call OI:	9/4/18
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

RECEIVED 17 MAY 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$5	( days) Reduction: %
		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 27
Repair Cost:	\$5 6955.00	
Loss of Rental (LOR):	\$5 -	( days)
Loss of Use (LOU):	\$5 400.00	(\$ 50 x 8 days)
Loss of Income (LOI):	\$5 -	(\$ x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	(Tick only one)
GIA/LTA Search	\$5 2.00	
Medical:	\$5 -	
Disbursement:	\$5 -	(e.g. Tow/ Independent)
Legal Cost	\$5 -	
Total:	\$5 7357.00	Global Sum \$5:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$5 7357.00	Name 1: Modern Automotive Pte Ltd
Payee 2: (Strike if N.A.)	\$5	Name 2:
Payee 3: (Strike if N.A.)	\$5	Name 3:

COMMENT 2/11/18

ASS. REC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJP 2098C Yr Regn: 2009 / March  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio cc 1496  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 56496 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NZE416109546Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 03/04/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

3/5/18 Confirm US \$ 6500.00 with 7 working days  
MV: 17K  
PV: 8.4K.  
Nett: 8.6K.

(Red) = \$ 3997.38  
 38 %

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18006190/Awb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 04-04-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 7122G	Veh. Inspected	SJP 2098C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/04/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	02/04/2018	Inspection Date	03/04/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 # 01-61  
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

<b>AIG ASIA PACIFIC INSURANCE PTE LTD</b>	<b>Quotation</b>
Charts Building	DATE : 03.04.2018
78 Shenton Way #07-16	VEH NO : SJP2098C
Singapore 079120	MODEL : Toyota Axio
Tel : 6419 - 3000	D O A : 02.04.2018
Fax : 6835 - 7416	YR REF : SJB7122G

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SJP2098C (Toyota Axio)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Rear Number Plate Lamp <i>new</i>	2	104.60 ✓
2	Rear Bumper <i>Distorted</i>	1	655.90 ✓
3	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
4	Rear Bumper Side Holder - LH & RH <i>new</i>	2	83.80 ✓
5	Rear Bumper Impact Bracket - LH & RH <i>Dented</i>	2	225.60 ✓
6	Taillamp - LH & RH <i>cracked</i>	2	642.00 ✓
7	Taillamp Lower Bracket - LH & RH <i>cracked</i>	2	128.80 ✓
8	Taillamp Panel - LH & RH <i>Repair</i>	2	321.60 ✗
9	Rear End Panel <i>Dented</i>	1	595.90 ✓
10	Rear End Panel Top Garnish <i>Deformed</i>	1	166.30 ✓
11	Bootlid <i>Distorted</i>	1	849.30 ✓
12	Bootlid Lock <i>Seized</i>	1	185.20 ✓
13	Bootlid Weatherstripe <i>cut</i>	1	172.90 ✓
14	Bootlid Hinge <i>Best</i>	2	85.80 ✓
15	Bootlid Inner Trim Board <i>3 new</i>	1	296.60 ✗
16	Bootlid Inner Trim Board Clips <i>3 new</i>	1 set	30.00 ✗
17	Bootlid Outer Garnish <i>cracked</i>	1	220.30 ✓
18	Toyota Logo <i>3 new</i>	1	47.20 ✓
19	Axio Wording <i>3 new</i>	1	44.20 ✓
20	X Emblem <i>3 new</i>	1	34.40 ✓
21	Spare Tyre Panel Top Cover <i>Deformed</i>	1	515.90 ✓
22	Rear Fender Inner Trim - LH & RH <i>3 new</i>	2	757.00 ✓
23	Rear Fender Inner Trim Clips <i>new</i>	2 sets	60.00 ✓
24	Rear Exhaust Pipe <i>Best</i>	1	882.10 ✓
25	Rear Exhaust Mounting <i>new</i>	1	39.10 ✗
26	Centre Exhaust Pipe <i>new</i>	1	782.00 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SJP2098C (Toyota Axio)

6382.6  
4786.95 Less 25%

7,956.50  
(1,989.13)  
\$ 5,967.38

S/NET ITEMS

1	Rear Number Plate	But	1	30.00	-
2	Rear Number Plate Holder	Del	1	30.00	-
3	Reverse Sensor	Changed	1	280.00	200
4	Rear End Panel Sealant	New	1	60.00	-
5	Rear Camera	Changed	1	480.00	400
Total Parts				\$	6,847.38

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	<del>1,400.00</del>	1000
2	To putty & spray up paint works	\$	<del>1,400.00</del>	1200
3	To check wiring	\$	<del>50.00</del>	30
4	To underseal	\$	<del>150.00</del>	50
5	To remove reverse sensor	\$	<del>100.00</del>	50
6	To remove rear camera	\$	<del>100.00</del>	50
7	To remove upholstery	\$	<del>150.00</del>	80
8	To remove exhaust pipe	\$	<del>150.00</del>	80
9	To transfer bootlid fittings	\$	<del>150.00</del>	80
Total Labour		\$	3,650.00	

Grand Total \$ 10,497.38

Total: 8126.55  
L/S: 65K  
07 Days

**LKK NOTE:** Insurers hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts must be replaced with original or equivalent
- Third party claims must be settled
- No illegal modification(s) is allowed
- Suppliers (if any) must be resurveyed and is subject to final approval from Insurance Company

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

Acknowledged by Repairer  
Signature:  
Date:

## MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747-6720

Email: chin@modernautomotive.com.sg

Your Ref : SJB7122G

Our Ref : SJP2098C

Date : 02.05.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SJP2098C & SJB7122G ON 02.04.2018  
ALONG TAMPINES AVENUE 9

---

We refer to the above matter.

We have been authorized by our client Mr Lim Tow Ee to make claim against your insured vehicle No. SJB7122G in respect of the above accident for the following :

Repair Cost	\$ 6,955.00	(Incl GST)
Loss of use (\$100 x 8 days)	\$ 800.00	(7 repair days, 1 Sunday)
Search fee	\$ 2.00	
<b>Total :</b>	<b>\$ 7,757.00</b>	

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully

  
\_\_\_\_\_  
Modern Automotive Pte Ltd



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18006190/Awb3

10 April 2018

**Kho Chee Wah**  
Blk 501 Tampines Central 1  
#03-251  
Singapore 520501

Dear Sir/Madam,

**ACCIDENT INVOLVING SJB 7122G AND SJP 2098C ON 02/4/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORIZATION

Date: ..... 21/4/18 .....

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

..... SJP 2098 C & SJB 7122 G .....

ON ..... 21/4/18 ..... ALONG ..... Tampines Avenue 9 .....

.....  
This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

**MODERN AUTOMOTIVE PTE LTD** is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully

.....  
  
Signature of Owner

.....  
Lim Tony Ee S1693316C  
Name / NRIC



**RELEASE VOUCHER**  
**(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)**

"We/I, MODERN AUTOMOTIVE PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 6,955.00 (repair cost), S\$ 400.00 (loss of rental/use), S\$ 2.00 (disbursement), for vehicle no. SJP 2098C that was damaged pursuant to the accident which occurred on 02/04/2018 (date) along TAMPINES AVE 9 TWDS TAMPINES AVE 10 (location) involving vehicle no/s SJB 7122G.

This is pursuant to the inspection conducted on 03/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM TOW EE (the third party claimant") of vehicle no. SJP 2098C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJP 2098C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of MAY (month) 2018 (year)

LWP



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01- 58 / 61 SINGAPORE 408717

TEL : 67474422, 67454422 FAX : 67476720

GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
SINGAPORE 079120

Attention : Motor Claim Department

Contact : 6415-3727 6419-3000

## Tax Invoice : TP001186

Date : 02/05/2018

Vehicle Num. : SJP 2098C

Make/Model : TOYOTA AXIO-2009

Chassis/Eng# : NZA1416109546/1NZD321359

Accident Date : 02/04/2018

Claim No. :

Reference :

Policy No. : V8008843

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		6,500.00
		Labour Total S\$ :		6,500.00

Total S\$ :	6,500.00
GST @ 7% S\$ :	455.00
Amount Due S\$ :	6,955.00

  
MODERN AUTOMOTIVE PTE LTD

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-048748  
Date of Request: 02/04/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 02/04/2018  
Enquiry By Chin Sol Shong  
TP Vehicle No. SJB7122G  
Accident Date 02/04/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJB7122G	AIG Asia Pacific Insurance Pte. Ltd.	28/02/2018-27/02/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-048748  
Date of Request: 02/04/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 02/04/2018  
Enquiry By Chin Sol Shong  
TP Vehicle No. SJB7122G  
Accident Date 02/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 <a href="#">Edit Reg</a>		03 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$56,500.00</b> <a href="#">Edit Estimates</a>	<b>\$56,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured: **KHO CHEE WAH**, ID: -

Main Claimant: **LIM TOW EE**, ID: S1693316C

Vehicle Reg. No.: <b>SJP2098C</b>	Date of Loss: 02/04/2018 08:00 - :59 <b>[108 Months and 20 Days From LTA Reg Date (Man Yr)]</b>
Claim Type: <b>TP / 7334520958SG</b>	Policy/Cover Note No.: 2100502665-01 (Comprehensive)
Vehicle Reg. No. (Insured): <b>SJB7122G</b>	Policy No. (Claimant): VB008843
Excess:	

Repairer: **Modern Automotive Pte Ltd (HQ)** Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Ler, Bernard-JQ**]  
BernardJQian.Ler@aig.com

Claimant's Insurer: **Great American Insurance Company (HQ)** - Tel: 6804 6047

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 13/04/2018]**

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

































There are no mail for this case.



















































**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)




















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJP2098C (7334520958SG)  
[SJB7122G]  
TP  
LIM TOW EE  
Apr 2 2018 8:35AM  
[KHO CHEE WAH]  
Modern Automotive Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
<b>Assessment Reports</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/04/18 15:34	Accident Statement <small>From: DO - Reg. No: SJB7122G; Claimant: KHO CHEE WAH</small>	 Load HTML	
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters / Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/05/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	03/05/18 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	03/05/18 15:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	03/05/18 15:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	03/05/18 15:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	03/05/18 15:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 14:22	TP GIA REPORT	 Load PDF	
2	09/05/18 08:22	WORKSHOP INVOICE	 Load PDF	
3	09/05/18 08:22	AUTHORISATION TO ACT FORM	 Load PDF	
4	09/05/18 08:22	Release Voucher	 Load PDF	
5	09/05/18 08:22	GIA SEARCH	 Load PDF	
6	09/05/18 08:22	LETTER TO OI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJB7122G (Insd veh)	Model:	TOYOTA AXIO 1.5 (A)
	SJP2098C (TP veh)		
Date of Accident:	02/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,232.19
Final Repair Cost	:	\$	6,955.00
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,357.00

8.00 days at \$50.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 7,357.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18006190/AWB3Q2

Date: 09/05/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502665-01  
 Claimant Vehicle No: SJP2098C Insured Vehicle No: SJB7122G  
 Date of Loss: 02/04/2018 Nature of Claim: TP Claim No: 7334520958SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP2098C**  
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 1NZD321359  
 Reg. Date: 13/03/2009 (Man. Year: 2008) Chassis No: NZE1416109546  
 Colour: Red Odometer: 56496 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,847.37	5,506.95	1,340.42	19.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,620.00	1,030.00	28.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,497.37</b>	<b>8,126.95</b>	<b>2,370.42</b>	<b>22.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		
(S\$)	10,497.37	6,500.00	3,997.37	38.08
<b>+ GST 7.00/7.00% (S\$)</b>	<b>734.82</b>	<b>455.00</b>	<b>279.82</b>	<b>38.08</b>
<b>Nett Amount (S\$)</b>	<b>11,232.19</b>	<b>6,955.00</b>	<b>4,277.19</b>	<b>38.08</b>
<b>+ Loss of Use (8.0 x S\$50.00/day) (S\$)</b>		<b>400.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>7,357.00</b>		

### INSPECTION

Date of Assignment: 03/04/2018  
 Date Inspected: 03/04/2018 Inspected At: Modern Automotive Pte Ltd (HQ)  
 Blk 3023A Ubi Road 1, #01-61 & #01-58  
 Singapore 408717

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	104.60 FL	*- FL
2	1		*REAR BUMPER	Distorted	655.90 FL	*655.90 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
4	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	83.80 FL	*83.80 FL
5	2		*REAR BUMPER IMPACT BRACKET -LH & RH	Dented	225.60 FL	*225.60 FL
6	2		*TAILLAMP -LH & RH	Cracked	642.00 FL	*642.00 FL
7	2		*TAILLAMP LOWER BRACKET -LH & RH	Cracked	128.80 FL	*128.80 FL
8	2		*TAILLAMP PANEL -LH & RH	Repair	321.60 FL	*- FL
9	1		*REAR END PANEL	Dented	595.90 FL	*595.90 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	166.30 FL	*166.30 FL
11	1		*BOOTLID	Distorted	849.30 FL	*849.30 FL
12	1		*BOOTLID LOCK	Damaged	185.20 FL	*185.20 FL
13	1		*BOOTLID WEATHERSTRIP	Cut	172.90 FL	*172.90 FL
14	2		*BOOTLID HINGE	Bent	85.80 FL	*85.80 FL
15	1		*BOOTLID INNER TRIM BOARD	Not Necessary	296.60 FL	*- FL
16	1		*SET BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FL	*- FL
17	1		*BOOTLID OUTER GARNISH	Cracked	220.30 FL	*220.30 FL
18	1		*TOYOTA LOGO	Necessary	47.20 FL	*47.20 FL
19	1		*AXIO WORDING	Necessary	44.20 FL	*44.20 FL
20	1		*X EMBLEM	Necessary	34.40 FL	*34.40 FL
21	1		*SPARE TYRE PANEL TOP COVER	Deformed	515.90 FL	*515.90 FL
22	2		*REAR FENDER INNER TRIM -LH & RH	Torn	757.00 FL	*757.00 FL
23	2		*SETS REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FL	*60.00 FL
24	1		*REAR EXHAUST PIPE	Bent	882.10 FL	*882.10 FL
25	1		*REAR EXHAUST MOUNTING	Not Necessary	39.10 FL	*- FL
26	1		*CENTRE EXHAUST PIPE	Not Necessary	782.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
28	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
29	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR CAMERA	Damaged	480.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,836.50</b>	<b>7,102.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,989.13</b>	<b>1,595.65</b>
<b>Total Parts (\$\$)</b>	<b>6,847.37</b>	<b>5,506.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,400.00	1,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,400.00	1,200.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	50.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO REMOVE EXHAUST PIPE	New	150.00	80.00
9	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,650.00</b>	<b>2,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >