

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8792U

DATE 3/4/2018 11:47

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Sponge ✓			\$ 142.20
	Front Bumper Reinforcement ✓			\$ 526.10
	Front Bumper Grille (LH) ✓			\$ 40.30
	Front Bumper Bracket Top (LH) ✓			\$ 22.40
	Front Bumper Side Bracket ✓			\$ 14.30
	Headlamp Support Panel Assy ✓			\$ 1,067.50
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) ✓			\$ 169.80
	Front Fender Retainer ✓			\$ 9.20
	Frt Wheel Hub Cap, LH ✓			\$ 150.70
	SUB TOTAL			\$ 4,711.80
	LESS 20%			\$ 942.36
	DISCOUNTED TOTAL			\$ 3,769.44
	Labour Charge			400
	Panel Beating			\$ 750.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 20 50.00
	Tuff Kote			\$ 20 50.00
	Remove/Refix Aircon & Refill Gas			\$ X 150.00
	Frt Wheel Alignment			\$ X 80.00
	TOTAL LABOUR			\$ 1,580.00
	ESTIMATE TOTAL			\$ 5,349.44
Kahr 11/11/18 3/4/18 1425hr 3 Day PIP Before Paint photo				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance company

Signature:
Date: