

### REPAIR ESTIMATE\*

DATE 2/4/2018 15:22

**MODEL : HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ✓			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Rubber Mat X			\$ 50.00
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			200
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,631.58
	Kalin (KK)			
	M 3/4/18 1100hrs			
	2 hrs			
	P/P			
	Better Print photo			
	KK Auto Consultants hence notify the Repairer of the following:			
	To resurvey before/after spray painting			
	To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	No illegal modification(s) is allowed			
	Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company			
	Acknowledged by Repairer Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			