

SS. REC. BY:

REF:

CS/FCU8006195/Kvb22

Special instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

(WS Eileen Lee

of

FCL

Date/Time:

03042018 4:41pm

Estimated Cost:

Bill to:

OD / ~~TR~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLG 958H

Insured:

SHA 2458A

at Workshop m/s

Esteem Performance

Tel:

8799 0066

of

385 Sin Ming Drive

Policy No.:

Claim No:

D18002575MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28032018

(Client's Record)

CA / REV / REP. / REV 24 HRS DS:

H.O.D. Endorsement:

Date/Time:

03042018 5:15pm

Person Contacted:

Carmen

Vehicle IN / OUT

Date/Time

Action/Instruction (V) Estimate

SLG 958H - X

SHA 2458A - CC3 / CAT 13011033 / Mem 3p

DATE: 010813

6/4/18

Email preli revised to FCI

3/8 810061.77 Confirmed (Recd 5763.47, 367)

09/01/17
Surveyor

REF: FCL

ASSIGNMENT

From: _____ Date: 04/04/2018

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 958H

at Workshop m/s: Esteem Performance

of: AMK

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLG 958H Yr Regn: 09/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour: M-P. White A/C: Insured / Std / NI / NA

Sp. Reading: 172833 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU703533623

Gen. Cond: Good / Fair / Poor / Burnt


Steering: None / Jammed / Leaked / Burnt or

Brake: None / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Yoko B.S 195/65R15
Yoko R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Front 4 mm R/Bal. 6 mm

L/Bal. 4 mm L/Bal. 6 mm

D.O.A. 28/3/18 D.O.I. 4/4/18

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/4 File pass to Catherine

RECEIVED 3 AUG 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 10
Resurvey No. of Trip: 2

1) _____
Date/Time, File Return to?

2) 3/8 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Report Format: CWS
Lump Sum / I.B.I. (\$) 10,061.77

Survey Fee:	5x15
Transportation:	170475
S + RS, SI	50
Photocopy	50150
Others	28
TOTAL	123



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18006195/Kvb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2458A	Veh. Inspected	SLG 958H
Policy No.		Coverage (\$)	0.00
Claim No.	D18002575MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/03/2018	Inspection Date	04/04/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236525)  PRI Documents  Close 

PRI Header Details

Claim No	D18002575MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ES
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/ Mobile: 87990066 , Phone: 64841221 , Fax: EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2458A	TP Vehicle No	SLG958
PRI Recieved Date	29-03-2018 09:07:27 PM	Surveyor Appointed Date	03-04-2018 04:41:18 PM	Surveyor Accept Date	04-04-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	04-04-2018	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action

Surveyor Job Remarks

1-4-2018

MOTOR SURVEY ASSIGNMENT

Date	29-03-2018	Our Ref No. D18002575MFSH
Accident Date	28-03-2018	Claim Type. Third Party
Insured Vehicle	SHA2458A	Third Party Vehicle. SLG958H
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 87990066	Fax No. 64847829
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

*5:15pm
Carmen
veh: ✓
1/4/18*

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 April 2018 8:59 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002575MFSH/1,SLG 958H
Attachments: SLG 958H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLG 958H
Date of survey: 4/4/2018
Number of days:10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 3 April 2018 5:16 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002575MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 April 2018 4:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002575MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002575MFSH

Our ref: CS/FCI18006195/Kvb

Date : 5/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 958H


We thank for your instruction on 3/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/4/2018 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,247.44
Revised Estimate Amount	: S\$9,628.42
"Check" Items Amount	: S\$3,010.73
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2018 16:00
Date Of Accident	28/03/2018 18:40
Exact Location Of Accident	HOLLAND ROAD TOWARDS ORCHARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG958H
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90977736

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	YIP CHI WING (YE ZHIRONG)
NRIC No	S7870694E
Date Of Birth	24/04/1978
Occupation	OUTDOOR
Date Of Driving Pass	21/02/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90012404
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 95 HAVELOCK ROAD #21-581
Postcode	160095
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2458A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	GOH SIAM PEN

NRIC/Passport Number

S1058729H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

YIP CHI WING

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLG958H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

3L 29/3/2018 1:25pm

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer as police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
29/3/2018 1.25pm
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180328/2205

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180328/2205

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2018 20:18	Vide Report No.:	Station Diary No.:
--------------------------------------------	------------------	--------------------

Informant's Particulars

Name of Informant: YIP CHI WING		Address: 95 HAVELOCK RD #21-581 HDB BUKIT MERAH SINGAPORE 160095	
ID Type / ID No.: NRIC NO / S7870694E		Contact No.: Home/Office: Mobile: 90012404	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 39	Date of Birth: 24/04/1978	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/03/2018 18:40	Type of Location:
Location: Along Road 1 HOLLAND ROAD TOWARDS ORCHARD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA2458A	Car	HYUNDAI	I40 1.7L CRDI AT ABS AIRBAG 4DR		Seriously Damaged	0
SLG958H	Car	TOYOTA	PRIUS HYBRID 1.8 CVT		Seriously Damaged	2



**SINGAPORE
POLICE FORCE**



T/20180328/2205

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20180328/2205

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH SIAM PEN	ID No.	S1058729H
Related Vehicle	SHA2458A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YIP CHI WING	ID No.	S7870694E
Related Vehicle	SLG958H (Car)	Contact No.	90012404
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/03/18 at about 1840hrs

While I was driving along Holland Road towards Orchard, a car in front of me wanted to turn into the condominium (The Coterie). I slowed down as I was behind that vehicle waiting for him to turn. Once the car in front of me completed its turn as I was about to step onto the accelerator again I looked at the back mirror and saw a taxi coming from behind at a high speed before it collided onto the rear of my vehicle. One of my passenger got sent to the hospital due to neck injuries.



SINGAPORE
POLICE FORCE



T/20180328/2205

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3


Report No. T/20180328/2205

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / WONG ZI WEI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/03/2018 20:18
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case: 
Authentication Stamp NP168	Signature: 



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp Perf.com.sg

Repair Estimates

SLG 958 H

*Not Authorized
 I.B.I
 Resurvey before repair*

Parts	(a) Cost / List Price Items	\$	14,296.58
	Plus/Less 25%	\$	3,574.15
	Total of Cost / List	\$	10,722.44
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	11,017.44
Labour		\$	4,230.00
Total		\$	15,247.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 4/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : pc Date: 4/4/18

Spare Parts

Vehicle No. : SLG 958 H
 Make & Model : TOYOTA PRIUS
 Chassis No. : JTDKB3FU703533623

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Taildoor absorber RH <i>Sw</i>	1	\$296.40		X
25	Tail door plate garnish <i>CM</i>	1	\$782.50		✓
26	Tail door inner trim	1	\$278.90		? X
27	Tail door inner trim clip	10	\$28.00		? X
28	Taildoor spoiler	1	\$1,567.83		? X
29	Tail end panel <i>B</i>	1	\$596.60		✓
30	Tail end panel garnish <i>D</i>	1	\$151.60		✓
31	Tail end panel garnish clip <i>Ne</i>	10	\$35.00		✓
32	Boot weatherstrip <i>DISAD</i>	1	\$353.10		✓
33	Spare tyre well panel	1	\$793.15		? X
34	Spare tyre board <i>Return</i>	1	\$566.79		✓
35	Spare tyre compartment sponge LH	1	\$297.67		? X
36	Spare tyre compartment sponge RH <i>Return</i>	1	\$297.67		✓
37	Tail lamp LH - UPPER <i>R</i>	1	\$498.75		X
38	Tail lamp RH - UPPER	1	\$498.75		? X
39	Tail lamp LH - LOWER <i>R</i>	1	\$511.60		X
40	Tail lamp RH - LOWER	1	\$511.60		? X
41	Taildoor glass sealant <i>Ne</i>	1	\$50.00	S.N	✓
42	Exhaust pipe <i>R</i>	1	\$854.10		✓
43	Exhaust pipe mouting	1	\$38.40		? X
44	Exhaust insulator <i>R</i>	1	\$267.40		✓
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLG 958 H Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,600.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,400.00	1200
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$180.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$250.00	90
7	To remove & refit Taildoor glass to assit work load	\$120.00	✓
8	To remove & refit exhaust system to assist work load.	\$180.00	60
9	To transfer boot mechanism to new boot	\$150.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
11	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

278.90	}	CHECK ITEM
28.00		
1567.83		
793.15		
297.67		
498.75		
511.60		
38.40		
4014.30		
1003.58 (25% DISC)		
3010.73 LIST ITEM AFTER DISC (CHECK ITEM)		
0.00 LABOUR (CHECK ITEM)		

3010.73 ✓

TOTAL = 12639.15 (PAY ITEM + CHECK ITEM)

KV



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 958 H

Finalized

Not Authorized
t.B.1
Resurvey & repair

Parts (a) Cost / List Price Items	\$	14,296.58
Plus/Less 25%	\$	3,574.15
Total of Cost / List	\$	10,722.44
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	295.00
Total Parts Cost	\$	11,017.44
Labour	\$	4,230.00
Total	\$	15,247.44

8969-03
2242-26
6726.77

295
7021.77
3040
10061.77

✓ OK

The above total will be subjected to 7% G.S.T. 15,825.24

15,680.78

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 4/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Pe Date: 4/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLG 958 H Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year Manufacture : 2016
 Chassis No. : JTDKB3FU703533623 Engine No. : _____
 Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear number plate <i>B₁</i>	1	\$45.00	S.N	✓
2	Reverse sensor <i>Sher</i>	1	\$200.00	S.N	✓
3	Rear bumper <i>B₁</i>	1	\$497.50		✓
4	Rear bumper clip <i>me</i>	10	\$40.00		✓
5	Rear bumper side retainer LH <i>su</i>	1	\$112.70		X
6	Rear bumper side retainer RH <i>D's</i>	1	\$112.70		✓
7	Rear bumper reinforcement <i>B₁</i>	1	\$398.90		✓
8	Rear bumper lower garnish centre <i>mit</i>	1	\$582.60		✓
9	Rear bumper lower garnish LH <i>mit</i>	1	\$149.70		✓
10	Rear bumper lower garnish RH <i>B₁</i>	1	\$149.70		✓
11	Rear bumper tow cover <i>mit</i>	1	\$31.70		✓
12	Rear bumper under cover <i>C M</i>	1	\$355.20		✓
13	Rear bumper under cover LH <i>D's</i>	1	\$187.60		✓
14	Rear bumper under cover RH <i>C M</i>	1	\$187.60		✓
15	Rear bumper under cover clip <i>me</i>	4	\$14.00		✓
16	Tail door <i>B₁</i>	1	\$1,122.50		✓
17	Tail door lock <i>me</i>	1	\$487.70		✓
18	Tail door emblem <i>me</i>	1	\$61.70		✓
19	Wording "PRIUS" <i>me</i>	1	\$51.90		✓
20	Wording "HYBRID" <i>me</i>	1	\$55.47		✓
21	Tail door hinge LH <i>R</i>	1	\$87.60		X
22	Tail door hinge RH <i>R</i>	1	\$87.60		X
23	Taildoor absorber LH <i>me</i>	1	\$296.40		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4486.47

SN: 245

Spare Parts

Vehicle No. : SLG 958 H
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU703533623

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Taildoor absorber RH <i>Sm</i>	1	\$296.40		X
25	Tail door plate garnish <i>CMA</i>	1	\$782.50		✓
26	Tail door inner trim <i>Sm</i>	1	\$278.90		X
27	Tail door inner trim clip <i>na</i>	10	\$28.00		X
28	Taildoor spoiler <i>Sm</i>	1	\$1,567.83		X
29	Tail end panel <i>By</i>	1	\$596.60		✓
30	Tail end panel garnish <i>pd</i>	1	\$151.60		✓
31	Tail end panel garnish clip <i>na</i>	10	\$35.00		✓
32	Boot weatherstrip <i>DISAD</i>	1	\$353.10		✓
33	Spare tyre well panel <i>R</i>	1	\$793.15		X
34	Spare tyre board <i>Return</i>	1	\$566.79		✓
35	Spare tyre compartment sponge LH <i>Sm</i>	1	\$297.67		X
36	Spare tyre compartment sponge RH <i>Return</i>	1	\$297.67		✓
37	Tail lamp LH - UPPER <i>R</i>	1	\$498.75		X
38	Tail lamp RH - UPPER <i>Sm</i>	1	\$498.75		X
39	Tail lamp LH - LOWER <i>R</i>	1	\$511.60		X
40	Tail lamp RH - LOWER <i>Sm</i>	1	\$511.60		X
41	Taildoor glass sealant <i>na</i>	1	\$50.00	S.N	✓
42	Exhaust pipe <i>R</i>	1	\$854.10		✓
43	Exhaust pipe mouting <i>Sm</i>	1	\$38.40		X
44	Exhaust insulator <i>R</i>	1	\$267.40		✓
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3904.76

SN: 50



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLG 958 H Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,600.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,400.00	1200
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$180.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$250.00	90
7	To remove & refit Taildoor glass to assist work load	\$120.00	✓
8	To remove & refit exhaust system to assist work load.	\$180.00	60
9	To transfer boot mechanism to new boot	\$150.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
11	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. : SLG 958 H
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU703533623

Submit By : CARMEN LIM
Year Manufacture : 2016
Engine No. : _____
Cost / List _____

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Spare tyre lock nut	<i>CR</i> 1	\$35.60	✓	
2	RH rear inner trim	<i>Reform</i> 1	\$386.75	✓	
3	Antenna Electrical key	<i>CR</i> 1	\$155.45	✓	
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

577.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006195/Kvbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2458A	Veh. Inspected	SLG 958H
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002575MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	03/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FU703533623	Colour	METALLIC PEARL WHITE
Odometer	172833	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm
L/H Front Tyre	195/65 R15	BRIDGESTONE	4 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/03/2018	Inspection Date	04/04/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 958H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	112.70	112.70
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER GARNISH CENTRE	MISSING	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	MISSING	149.70	149.70
1	REAR BUMPER LOWER GARNISH RH	BUCKLED	149.70	149.70
1	REAR BUMPER TOW COVER	MISSING	31.70	31.70
1	REAR BUMPER UNDER COVER	CRACKED	355.20	355.20
1	REAR BUMPER UNDER COVER LH	DISTORTED	187.60	187.60
1	REAR BUMPER UNDER COVER RH	CRACKED	187.60	187.60
4	REAR BUMPER UNDER COVER CLIP	NECESSARY	14.00	14.00
1	TAIL DOOR	BENT	1,122.50	1,122.50
1	TAIL DOOR LOCK	DENTED	487.70	487.70
1	TAIL DOOR EMBLEM	NECESSARY	61.70	61.70
1	WORDING "PRIUS"	NECESSARY	51.90	51.90
1	WORDING "HYBRID"	NECESSARY	55.47	55.47
1	TAIL DOOR HINGE LH	TO REPAIR SEE LABOUR	87.60	-
1	TAIL DOOR HINGE RH	TO REPAIR SEE LABOUR	87.60	-
1	TAILDOOR ABSORBER LH	SERVICEABLE	296.40	-
1	TAILDOOR ABSORBER RH	SERVICEABLE	296.40	-
1	TAIL DOOR PLATE GARNISH	CRACKED	782.50	782.50
1	TAIL DOOR INNER TRIM	SERVICEABLE	278.90	-
10	TAIL DOOR INNER TRIM CLIP	NOT NECESSARY	28.00	-
1	TAILDOOR SPOILER	SERVICEABLE	1,567.83	-
1	TAIL END PANEL	BENT	596.60	596.60
1	TAIL END PANEL GARNISH	DENTED	151.60	151.60
10	TAIL END PANEL GARNISH CLIP	NECESSARY	35.00	35.00

Report Ref No. CS/FCI18006195/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT WEATHERSTRIP	DISTORTED / DENTED	353.10	353.10
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	793.15	-
1	SPARE TYRE BOARD	DEFORMED	566.79	566.79
1	SPARE TYRE COMPARTMENT SPONGE LH	SERVICEABLE	297.67	-
1	SPARE TYRE COMPARTMENT SPONGE RH	DEFORMED	297.67	297.67
1	TAIL LAMP LH - UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP RH - UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP LH - LOWER	TO REPAIR SEE LABOUR	511.60	-
1	TAIL LAMP RH - LOWER	SERVICEABLE	511.60	-
1	EXHAUST PIPE	BENT	854.10	854.10
1	EXHAUST PIPE MOUNTING	SERVICEABLE	38.40	-
1	EXHAUST INSULATOR	BENT	267.40	267.40
1	SPARE TYRE LOCK NUT (ADDITIONAL)	CRACKED	35.60	35.60
1	RH REAR INNER TRIM (ADDITIONAL)	DEFORMED	386.75	386.75
1	ANTENNA ELECTRICAL KEY (ADDITIONAL)	CRACKED	155.45	155.45
	LESS 25% DISCOUNT		-3,718.60	-2,242.26
			11,155.78	6,726.77
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	45.00	45.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	TAILDOOR GLASS SEALANT (SN)	NECESSARY	50.00	50.00
			295.00	295.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL, PANEL, LHR FENDER, RHR FENDER). INCLUSIVE OF THE REPAIR OF TAIL DOOR HINGE LH, TAIL DOOR HINGE RH, SPARE TYRE WELL PANEL AND TAIL LAMP LH - LOWER.		1,600.00	1,200.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)		1,400.00	1,200.00
	TO CHECK WIRING.		50.00	20.00

Report Ref No. CS/FCI18006195/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.		180.00	100.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.		250.00	90.00
	TO REMOVE & REFIT TAILDOOR GLASS TO ASSIST WORK LOAD.		120.00	120.00
	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD.		180.00	60.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		150.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	TOWING.		60.00	50.00
			4,230.00	3,040.00
	GRAND TOTAL		15,680.78	10,061.77
	RECOMMENDED COST OF REPAIRS			10,061.77

Report Ref No. CS/FC118006195/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.