

ASS. REC. BY:

REF:

CS/FCU 8006196 / Kgbnz

Special Instruction:

Surveyor:

Konmeth

ASSIGNMENT (Office)

From (Person):

(WS) Lurene Juv

of

FCL

Date/Time:

03042018 4:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 5466K

Insured:

SHA 9878A

at Workshop m/s

T & T Auto

Tel:

9145 9776

of

160 Sin Ming Drive #08-14

Policy No:

Claim No:

D18002584MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

03042018 4:58pm

Person Contacted:

Vincent

Vehicle (IN) OUT

Date/Time

Action/Instruction

(✓) Estimate

SJJ 5466K - X

SHA 9878A - N3 / TNC170122311 / Gubee

D.O.A. 21062017

04/4/18 @ 5:11pm revised to Lurene by email.

REF: FCI

ASSIGNMENT

From:

Date: 04/04/2018

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No:

SJJ 5466k

at Workshop m/s

T & T

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJJ 5466k

Yr Regn:

09, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tug Atlas

C.G.

1598

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

151586

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EE106121765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

27/3/18

D.O.I.

4/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/4 File passed to Customer

6/4 8 Food (Paid \$915.50, 58%)

RECEIVED 6 APR 2018

Date/Time, File Pass to?

11/06/14 typist

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) \$ - RS, \$ SI

) Photos

) Others

TOTAL

Report Format:

7P

Lump Sum / B.I. (\$

700

100

50

50

11

211



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006196/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9878A	Veh. Inspected	SJJ 5466K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002584MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/03/2018	Inspection Date	04/04/2018	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date 02-04-2018 Our Ref No. D18002584MFSH

Accident Date 27-03-2018 Claim Type. Third Party

Insured Vehicle SHA9878A Third Party Vehicle. SJJ5466K

Survey Location 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY

Contact Person. VINCENT TAN

Contact No. 62666876/ 91459776 Fax No. 62666861

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop T & T AUTO SERVICES Attention. NIL
PTE LTD

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236535)



PRI Documents



Close



PRI Header Details

Claim No	D18002584MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & T 8
Workshop Name	T & T AUTO SERVICES PTE LTD (Contact Person : VINCENT TAN)	Survey Location & Contact Details	160 SIN MING DRIVE #08-14 SIN MING AUTO Mobile: 91459776 , Phone: 62666876 , Fax: EmailId: TNTAUTOSERVICES@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9878A	TP Vehicle No	SJJ546
PRI Recieved Date	03-04-2018 02:37:14 PM	Surveyor Appointed Date	03-04-2018 04:05:47 PM	Surveyor Accept Date	04-04-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-04-2018	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 5 April 2018 5:11 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002584MFSH/1
Attachments: CSFCI18006196Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJJ 5466K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 3 April 2018 5:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002584MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 04/04/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 April 2018 4:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002584MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002584MFSH

Date: 05 April 2018

Our Ref: CS/FCI18006196/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJJ 5466K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/04/2018 at the premises of M/s T & T AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,675.50</u>
Revised Estimate Amount	: S\$ <u>910.48</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the n/s rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

ESTIMATE

DATE : 03/04/2018
VEHICLE NO : SJJ 5466 K
MAKE/MODEL : Toyota Altis
ACC DATE : 27/03/2018

PARTICULAR		AMOUNT S\$	
LIST ITEMS:			
1	1 REAR BUMPER	<i>Del/way</i> 495.80	✓
2	1 REAR BUMPER SPONGE	<i>Sn</i> 155.80	X
3	1 REAR BUMPER SIDE RETAINER (OUTER) - LH	<i>me</i> 91.50	✓
4	1 REAR BUMPER SIDE RETAINER - (INNER) - LH	<i>Sn</i> 90.90	X
		834.00	
Less Discount:		25%	
		208.50	
		625.50	
SPECIAL NETT ITEMS:			
1	10 REAR BUMPER CLIP	<i>me</i> 50.00	✓
		50.00	
LABOUR CHARGES:			
1	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	500.00	<i>2001</i>
2	TO SPRAY PAINTING ON AFFECTED AREA	500.00	<i>2201</i>
		1,000.00	
GRAND TOTAL:		1,675.50	

Singapore Dollars: One Thousand Six Hundred And Seventy Five And Cents Fifty Only.


T & T Auto Services Pte Ltd

Not Notarized
U/S 8700
Money After painting
2 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006196/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9878A	Veh. Inspected	SJJ 5466K	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002584MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106121765	Colour	METALLIC BLUE	
Odometer	151586	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	8 mm	
L/H Front Tyre	195/65 R15	PIRELLI	8 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	8 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2018	Inspection Date	04/04/2018	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5466K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / WARPED	495.80	495.80
1	REAR BUMPER SPONGE	SERVICEABLE	155.80	-
1	REAR BUMPER SIDE RETAINER (OUTER)-LH	NECESSARY	91.50	91.50
1	REAR BUMPER SIDE RETAINER (INNER)-LH	SERVICEABLE	90.90	-
	LESS 25% DISCOUNT		-208.50	-146.83
			625.50	440.47
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	LABOUR			
	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS.		500.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREA.		500.00	220.00
			1,000.00	420.00
	GRAND TOTAL		1,675.50	910.47
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			700.00

Report Ref No. CS/FCI18006196/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.