

ASS. REC. BY:

REF: CS/FCU8006206/T12/bn2

Special Instruction:

Surveyor:

Tauhidh

ASSIGNMENT (Office)

From (Person): (WS) Lurren Jaw of FCL Date/Time: 03/04/2018 350pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 2862U Insured: SHA 8790A

at Workshop m/s Tan Chong Motor Tel:

of 911 Bukit Timah Road

Policy No: Claim No: D18001851MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 03/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 2004.2018 @ 10am H.O.D. Endorsement:

Date/Time: 04/04/2018 10:13am Person Contacted: Lawrence Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 2862U - x
	SHA 8790A - CS/QWD 8027651 / Rfn DCA: 11/03/2018
23/04/18	@ 15:31pm. re-used to Lurren Jaw via email.
21/5/18	@ 4.13pm confirmed with Sipah Anal Ag @ 1683.44, 2 days. CPed @ 2053.60, 55%



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001859MFSH

Date: 23 April 2018

Our Ref: CS/FC118006206/T1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 2862U.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/04/2018 at the premises of M/s Tan Chong Motor Sales Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,730.04</u>
Revised Estimate Amount	: <u>S\$ 1,683.44</u>
"Check" Items Amount	: <u>S\$ 993.60</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Repair days: 2 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully,
Taufikh
Automotive Assessor

*Call bule
demonstrasi***MOTOR SURVEY ASSIGNMENT**

Date 06-03-2018 Our Ref No. D18001859MFSH

Accident Date 03-03-2018 Claim Type. Third Party

Insured Vehicle SHA8790A Third Party Vehicle. SKV2862U

Survey Location 913 BUKIT TIMAH ROAD

Contact Person. LAWRENCE TEO

Contact No. 64667711/ 64601694

Fax No. 64697472

*Spm
Lawrence
VOT MD in*

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA

Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop TAN CHONG MOTOR SALES PTE LTD Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235632)  PRI Documents  Close 

PRI Header Details

Claim No	D18001859MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TAI LTD
Workshop Name	TAN CHONG MOTOR SALES PTE LTD (Contact Person : LAWRENCE TEO)	Survey Location & Contact Details	913 BUKIT TIMAH ROAD Mobile: 64601694 , Phone: 64667711 , Fax: EmailId: LAWRENCETEO@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8790A	TP Vehicle No	SKV280
PRI Recieved Date	03-04-2018 01:26:01 PM	Surveyor Appointed Date	03-04-2018 03:50:30 PM	Surveyor Accept Date	04-04-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	04-04-2018	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action

Surveyor Job Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 21 May 2018 4:13 PM
To: Norsipah; Taufikh (LKKAuto); SUR
Subject: RE: SKV2862U

Dear Sipah,

Confirm final fig \$1,683.44 before GST and 2 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah [mailto:norsipah@tanchong.com]
Sent: Thursday, 17 May 2018 3:16 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SKV2862U

Hi

For your finalization.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D: +6567038915

Website: www.tanchong.com :: www.nissan.com.sg

From: Singapore Printer
Sent: Thursday, 17 May 2018 1:59 PM
To: Norsipah <norsipah@tanchong.com>
Subject: Attached Image

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 23 April 2018 3:31 PM
To: 'Claim Workflow System'; 'LURENEJAW@MSFIRSTCAPITAL.COM.SG'
Cc: 'assignments@lkkauto.com'; 'sur@lkkauto.com'
Subject: FW: SURVEY ASSESSMENT - D18001859MFSH/1
Attachments: SKV 2862U - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKV 2862U.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 4 April 2018 10:15 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001859MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 April, 2018 3:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001859MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Aviva Ltd., 4 Shenton Way, #01-01 SGX Centre 2, Singapore 068807. Tel: (65) 6827 9966 www.aviva.com.sg

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION
(REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

CERTIFICATE NUMBER, 10688929

1) VEHICLE REGISTRATION NO.

SKV2862U

2) NAME OF INSURED

FAMILY NAME
GIVEN NAME

LIM
BOON WHATT

3) EFFECTIVE DATE OF COMMENCEMENT OF INSURANCE FOR THE PURPOSE OF THE ACT

09-Sep-2016 00:00hours

4) DATE OF EXPIRY OF INSURANCE

08-Sep-2018 23:59hours

5) PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE

Any driver aged 30 or over

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been canceled at the time of accident or loss.

Please refer to the policy document for full terms and conditions.

6) LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

NAMED DRIVER

7) FINANCE COMPANY

HONG LEONG FINANCE LTD

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), or any amendment, act or acts passed in substitution thereof.

Issued in Singapore: 19-Aug-2016 at 14:24hours

Aviva Ltd.

IMPORTANT NOTE:

- If you want to cancel your policy at any time, you will need to return the certificate to us.
- You MUST report all accidents to Us within 24 hours of the occurrence regardless of whether You intend to claim on Your own policy or not, or whether Your car is damaged or not. Should You fail to do so, Your No Claims Discount could be affected and Your claim may be prejudiced.

Nishit Majmudar
Chief Executive Officer

In case of vehicle breakdown, accident or windscreen damage, please call 6333 2222 (24 hours) immediately.

ORIGINAL

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7211971A



Name



LIM BOON WHATT
(LIN WENFA)

林文发

Race

CHINESE

Date of Birth

30-03-1972

Sex

M

Country of Birth

SINGAPORE

S7211971A

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S7211971A

Name:

LIM BOON WHATT
(LIN WENFA)

Birth Date: 30 Mar 1972

Issue Date: 15 Aug 2003



000748916D

0621132



NRIC No. S7211971A



Blood Group Date of issue

O+ 18-11-1992

Address
47 HINDHEDE WALK #09-07
SINGAPORE 587977

NRIC No: S7211971A

Date: 31/01/2010

No: 6419208

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 07 Aug 1992

NP 428A



Licence No: S7211971A

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

1135
0210-4118

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0118/2018
DATE : 02-APR-2018

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

ms

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848 / 68543466
FAX : 65073849
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : LIM DOON WHATT (LIN WENFA)
ADDRESS : 47 HINDHEDE WALK
#09-07
S(587977)
TELEPHONE NO : 82236847/82236849

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SHA8790A
VEHICLE NO : SKV2862U
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2173948A
CHASSIS NO : SJNFEAJ11U1445652
MILEAGE : 1 KM
DATE IN : 02/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 03/03/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(Lawrence)

any
Lawrence
20/04/18
Resurvey before paint
sure @ Kuantan.com
2 days
15/04/18
20/04
COA

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV2862U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓
2	ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	1000.00	390
3	ZZ/002	S/PAINT END PANEL AND REAR BUMPER (2 TONE)	800.00	350
TOTAL LABOUR CHARGES			1910.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV2862U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			? 100.00 <i>X</i>
2 REVERSE SENSOR (J11 & T32)	SENSOR-TE5140			<i>cut</i> 210.00
3 CANOE BUMPER \$6.50 EA X 02	76882-0M000	13.00		<i>net</i>
4 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 <i>net</i>
5 BRACKET-BUMPER RH	85220-4EA0A	35.90		? <i>PHN</i>
6 BRACKET-BUMPER LH	85221-4EA0A	35.90		? <i>PHN</i>
7 STAY ASSY-REAR RH	H5210-4EAMA	126.00		? <i>PHN</i>
8 STAY ASSY-REAR LH	H5211-4EAMA	126.00		? <i>PHN</i>
9 REINF-BUMPER RR	H5030-4EAMA	619.20		? <i>PHN</i>
10 ENERGY ABSORBER	85090-4EA0B	126.40		? <i>PHN</i>
11 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20		<i>net</i>
12 RETAINER-BUMPER RH	79184-4EA0A	23.80		? <i>PHN</i>
13 RETAINER-BUMPER LH	79185-4EA0A	23.80		? <i>PHN</i>
14 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80		<i>net</i>
15 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80		<i>cut</i>
16 FASCIA-RR BUMP	85022-4EA0H	717.00		<i>del</i>
SUB TOTAL		1890.80	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		378.16	0.00	0.00
GRAND TOTAL		1512.64	0.00	314.40
OVERALL TOTAL		1827.04		

LEGEND: REMARKS(OX) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV2862U

TOTAL LABOUR CHARGES	1910.00
TOTAL SPARE PARTS CHARGES	1827.04
GRAND TOTAL	3737.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0118/2018
DATE : 02-APR-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 55073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : LIM BOON WHATT (LIN WENFA)
ADDRESS : 47 HINDHEDE WALK
#09-07
S(587977)
TELEPHONE NO : 82236847/82236849

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SHA8790A
VEHICLE NO : SKV2862U
MODEL CODE : FRLARBJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2173948A
CHASSIS NO : 8JNPEAJ11U1445652
MILEAGE : 1 KM
DATE IN : 02/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 03/03/2018

Lawrence

[Signature]

0.15

Renne

100/day x 02

= # 200 per

= # 24/r

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH M/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV2862U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
2	ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	1000.00	390.00
3	ZZ/002	S/PAINT END PANEL AND REAR BUMPER (2 TONE)	800.00	350.00
TOTAL LABOUR CHARGES			1910.00	850.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV2862U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			100.00 X
2 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 OK
3 CANOE BUMPER \$6.50 EA X 02	76882-0M000	13.00		OK
4 GROMMET BUMPER \$2.20 EA X 02	01281-00111		4.40	OK
5 BRACKET-BUMPER RH	85220-4EA0A	35.90		X
6 BRACKET-BUMPER LH	85221-4EA0A	35.90		X
7 STAY ASSY-REAR RH	H5210-4EAMA	126.00		X
8 STAY ASSY-REAR LH	H5211-4EAMA	126.00		X
9 REINF-BUMPER RR	H5030-4EAMA	619.20		X
10 ENERGY ABSORBER	85090-4EA0B	126.40		X
11 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20		OK
12 RETAINER-BUMPER RH	79184-4EA0A	23.80		X
13 RETAINER-BUMPER LH	79185-4EA0A	23.80		X
14 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80		OK
15 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80		OK
16 FASCIA-RR BUMP	85022-4EA0H	717.00		OK
SUB TOTAL		773.80	0.00	214.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		154.76	0.00	0.00
GRAND TOTAL		619.04	0.00	214.40
OVERALL TOTAL		833.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 509623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKV2862U

NETT ITEM	773.80
LESS 20.00%)	-154.76
NETT AMOUNT	619.04
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	214.40
LESS .00%)	0.00
SPECIAL NETT AMOUNT	214.40
TOTAL LABOUR CHARGES	850.00
TOTAL SPARE PARTS CHARGES	833.44

TOTAL CHARGES	1683.44
ADD 7 % GST	117.84

GRAND TOTAL	1801.28



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006206/T1qbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8790A	Veh. Inspected	SKV 2862U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001859MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1445652	Colour	BRONZE	
Odometer	54144	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/03/2018	Inspection Date	20/04/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2862U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	CANOE BUMPER @\$6.50 (N)	NECESSARY	13.00	13.00
1	BRACKET-BUMPER RH (N)	NOT NECESSARY	35.90	-
1	BRACKET-BUMPER LH (N)	NOT NECESSARY	35.90	-
1	STAY ASSY-REAR RH (N)	NOT NECESSARY	126.00	-
1	STAY ASSY-REAR LH (N)	NOT NECESSARY	126.00	-
1	REINF-BUMPER RR (N)	NOT NECESSARY	619.20	-
1	ENERGY ABSORBER (N)	NOT NECESSARY	126.40	-
3	CLIP BUMPER @\$7.40 (N)	NECESSARY	22.20	22.20
1	RETAINER-BUMPER RH (N)	NOT NECESSARY	23.80	-
1	RETAINER-BUMPER LH (N)	NOT NECESSARY	23.80	-
4	CLIP BUMPER @\$1.20 (N)	NECESSARY	4.80	4.80
1	FINISHER-REAR BUMPER TOW (N)	CUT	16.80	16.80
1	FASCIA-RR BUMP (N)	DEFORMED	717.00	717.00
	LESS 20% DISCOUNT		-378.16	-154.76
			1,512.64	619.04
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR (J11 & T32)(SN)	CUT	210.00	210.00
2	GROMMET BUMPER @\$2.20 (SN)	NECESSARY	4.40	4.40
			314.40	214.40
LABOUR				
	SUPPLY & INSTALL REVERSE SENSOR.		110.00	110.00
	REPAIR END PANEL AND RENEW REAR BUMPER.		1,000.00	390.00
	S/PAINT END PANEL AND REAR BUMPER (2 TONE).		800.00	350.00
	-		-	-
	-		-	-
	-		-	-
			1,910.00	850.00
GRAND TOTAL			3,737.04	1,683.44

Report Ref No. CS/FCI18006206/T1qbn2



RECOMMENDED COST OF REPAIRS			1,683.44
-----------------------------	--	--	-----------------

Report Ref No. CS/FCI18006206/T1qbn2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.