* 1.5mc2oin	1 3	M.I.		N 12 () 11K	6-
INS. CASE OWNE	R. Dellyn'	CC3 /AIG1800	620 /	KN07/	
Surveyor:	Adian	DOI: ASSIG	NMENT	Date / Time :	Ulap 14
Pre-assign / CCU				Registered in Merimen:	
Insured Vehicle N	CVY	N 85221	Claim No.	n9/114	454
Name of Insured	. Um Fur	YEN MES SOH UM F		no050	5975-0000D
			YEV Make / Mode	MADI	
Insured Tel No. Excess Sec II :S\$	-	D.O.A: 14 18	Place of Acci	10.000	maneymound ru
Is driver the owne	-		Parts St. Asset	7.15.5	
If NO, Driver Na	NO SA ASSOCIATION	/ (saute of Accident	OI GIA REPO	DRT- VES NO : TP GIA	REPORT: NEW / NO
Driver Tel		(V/L: (YE)\$ / NO)	Insured Liabi		al? Yes/No
SLC 137	(a				
			S t 		in the second se
INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
Date/ Time					ON WATER CO.
1.14/18	3- CHK1345		1.7	STAGE Non-Reporting ltr (1st):	DATE / PIC
Soan	JUM 844 V -	्राम् विविधः वर्गस्य विद्यापि	ON DIRTHAM	Non-Reporting ltr (2nd):	
WWW				Non-Reporting by (Final): Notification by (if non-pic	kup):
4/4/18	RECUIVE VY	deo From TP.		Call OI:	9/4/18
9/4/18	Called O2D	Mr Sh Confirm det	Fail Inform	After call itr to Of: Documentation Check L	ist: Handler Typist
7,17/16	and the second s	ance to gette. The	Her and	Notification ltr (if non-pic	
	aut.	7	4.67	After call ltr to OI:	
	Eman			Authorisation To Act: Release Voucher:	
SOUTH	CWHOTS			Final Repair Bill:	
74/2/18	File pass +	o typist type report	L. ,	Car Rental Invoice:	
116118	sman to	A Mi to SEPK W	midali	Towing Invoice	
18/6/18	Mardala	approve bia mera	u	Medical Bill:	
F	RECEIVED	9 111M page		PIR:	
		8 JUN 2018		Mandate/Reject Instruc	tion:
				LOD Payment Breakdown Fo	um:
PRELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos:	
				Others:	
FINALIZATION	Date/Time:	Confirm with: (days) Reduction:	%	Confirm by:	oil Call
Repair Cost: FINAL SETTLEMENT	Date/Time: 18/6			Email Call	
Final Liability:	% 100 (A	greed / Assessed) BOLA S/N No. :	N/L.	If NO or B 28, Ass. Lia	4
Repair Cost:	28 10662 -85	/ 4 days) VIDD. 00		- Page	oto baton
Loss of Rental (LOR): Loss of Use (LOU):	SS 400.00	(4 days) ¥ 100.00 x days)		500	Collins
Loss of Income (LOI):	SS (S	x days)			
LOR only LOU only GIA/LTA Search	SS LOR + LOU	LOR + LOI [Tick only of	one]		
Medical:	55			1) Claim status: Normal	/Reject/Private Settle
Disbursement:	S5	(e.g. Tow/ Indepen	dent)	2) Report Format:	
Legal Cost Total:	ss 11062.85	Global Sum SS:		3) Survey fee:	
FINAL PAYMENT	Date/Time:	Confirm with:		Email Call	
Payee 1:	£8. 60001 ss	Name 1: Premium F	estidonotiles	Pte Ltd	
Payee 2: (Strike if N.A.)	SS 400.00	Name 2: ANBARAS	AN RAMASI	AMY	
Payee 3: (Strike if N.A.)	SS	Name 3:			

			1
-1	١.		ſ
	۱r	V	۲.
	v		b

ASSIGNMENT

From: Date:	Veh No: SLC1376. Yr Ragn: 2016 , April
Estimated Cost:	Type (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Audi A4 Seden c.c 1395
at Workshop m/s	Colour Blac. A/C: Insured / Std / NI / NA
of	Sp.Reading 21214. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: WAUZZZF40G4040396
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
₩	Tyre Size: F: 205/60R16.
(Policy Condition)	R: 205/60R/6
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO OF CONTINENTIAL.
Bal. or Market Value:	Front / Rear /
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 90 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. % mm L/Bal. 0.6 mm
Est. Repairs: 04 My days Res.: Yes or No	D.O.A. D.O.I. 06/08/18
Lum Sum: I-R-> % 3 Val.: Yes or No	Survey held at Remium .
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Front Ms.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction T P Al6	
18/2/18 Confirm 7-8-2 \$9965-28	with 4 working days
	1 Bed & Grist 72
	57.V
	327)
	e sues v
	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Eco	
	Interview (\$) Photos
Report Format :	Tech. Invs (\$) Others
nepole i villiat	
Lump Sum / I.B.I: (\$:Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inte	rnationale Des Experts En Auton	nobile				
AIG ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC3/AIG18006210/wb3					
78 SHENTON WAY #0 CHARTIS BUILDING SINGAPORE 079120	8-16	Date: 04-04-2018					
1.	Policy Particu	lars :- THIRD PARTY CLA	M				
Insured Veh.	SLM 8532T	Veh. Inspected	SLC 137G				
Policy No.		Coverage (\$)	0.00				
Claim No.		Excess (\$)	0.00				
Assign From		Assign Date	04/04/2018				
2.	Vehicle F	Particulars & Condition					
Make & Model		c.c	0				
Engine No.	HIDDEN	Year of Reg.					
Chassis No.		Colour					
Odometer	5	Steering					
Brakes		Modification					
General							
3.	Co	nditions of Tyres					
	Size	Make	Balance				
R/H Front Tyre			mm				
L/H Front Tyre			mm				
R/H Rear Tyre			mm				
L/H Rear Tyre			mm				
4.	Desc	ription of Damages					
5.	Ge	neral Information					
Accident Date	03/04/2018	Inspection Date					
Survey held at	PREMIUM AUTOMOBILES						
	55 UBI ROAD 1 . SINGAPORE 408699						
5a.		Remarks					
A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	A"WITHOUT PREJUDICE" BAS NS, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.				

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

-4

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/0411/2018/CCS

Date : 04-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.

Your insured vehicle no: SLM 8532 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Anbarasan Ramasamy

Address : 3 Sin Ming Walk

#11-23

Singapore 575575

 Telephone
 : HP +65 94309960

 Type of Claim
 : Third Party Claims

 Policy No.
 : 2100462075-01000

Vehicle No : SLC 137 G

Model Code : Audi A4 SEDAN 1.4 TFSI

Model / Year : Apr-16
Engine No : CVN 005486

Chassis No : WAUZZZF40GA040396

Mileage :

Date In :

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 03-Apr-18
Place of Accident : Marymount Road

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 137 G.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	~ 1
2	To dismantle and renew front bumper and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 1,200.00	750 1000/
3	To respray front bumper.		\$ 800.00	1550
4	To carry out diagnostic checks.	S/N	\$ 192.00	/ /
	TOTAL LABOUR CHARGES	:	\$ 2,552.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 137 G.

S/N	Parts Description		Damage Pa S/NETT	arts & Prices REMARKS
1	FRONT BUMPER Jehn A	\$	1,849.00	- 1479.50
2	FRONT BUMPER GRILLE - CENTER 7 mm 60	\$	171.00	*
3	FRONT BUMPER GUIDE - LH	\$	31.00	9
4	FRONT BUMPER FOAM	s	107.00	95.30
5	FRONT REINFORCEMENT BEAM Sed	\$	702.00	2 561-60
6	FRONT BUMPER SUPPORT - LH	\$	24.00	*
7	FRONT LOCK CARRIER BRACKET Encled.	\$	118.00	44.80
8	FRONT BUMPER GRILLE - LH JUN	\$	118.00	- + 5518.40
9	LED HEADLIGHT - LH Cruled	\$	6,973.00	33 10.40
10	POWER MODULE FOR MAIN LIGHT	\$	695.00	pt.
11	CONTROL UNIT FOR LIGHT CONTROL SYSTEM	5	657.00	4
12	HEADLIGHT WASH CYLINDER BRACKET - LH 766 NEW	s	6.00	+
13	HEADLIGHT WASHER CYLINDER - LH THE NEW	\$	184.00	*
14	FRONT NO. PLATE Not m S/N	5	25.00	×
15	SUNDRIES Nec	\$	300.00	3 3.34
	TOTAL SPARE PARTS :	\$	11,960.00	-
	TOTAL LABOUR CHARGES	\$	2,552.00	
	GRAND TOTAL :	\$	14,512.00	=

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :

Surveyed Date
Authorised Date

Excess Cost

Please Note

Liability

Remarks :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: Date:

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

Hol Authorised, 04 Days.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd.

Johnny Boo Body Repair Manager Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/TP/0411/2018/CCS
Date 24-Apr-18

Service Advisor Jeffery Tan Pages 1

Regn No SLC 137 G

Model No Audi A4 SEDAN 1.4 TFSI

Quantity	Description	U	nit Price	Amount
Parts 1 2	Wheel spoiler - LHS to a Temperature sensor bracket coule d	\$ \$	63.00 16.00 79.00	20.1.6
	TOTAL	\$	79.00	

Adria Ling-Als. 25/04/18. For Premium Automobiles Pte Ltd

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/0411/2018/CCS

Date : 4-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.

Your insured vehicle no: SLM 8532 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Anbarasan Ramasamy

Address : 3 Sin Ming Walk

#11-23

Vehicle No : SLC 137 G

Model Code : Audi A4 SEDAN 1.4 TFSI

 Model / Year
 : Apr-16

 Engine No
 : CVN 005486

Chassis No : WAUZZZF40GA040396

Mileage

Date In :

Liability :

Excess Cost : Estimated By : Johnny Boo / Allan Wu

Accident Date : 3-Apr-18

Place of Accident : Marymount Road

Hi Adrian 4 days of repairs - ok - jb - 12 May 16

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 137 G.

S/N	Nature of Jobs		Estimated Charges	urveyor's mmendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 1,000.00
3	(Added \$250/- for added parts and checked items) To respray front bumper.		\$ 800.00	\$ 550.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	;	\$ 2,552.00	\$ 2,102.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 137 G.

				Damage Pa	rts	& Prices
S/N	Parts Description			S/NETT		REMARKS
1	FRONT BUMPER		s	1,849.00	\$	1,479.20
2	FRONT BUMPER GRILLE - CENTER		\$	171.00	*	1,475.20
3	FRONT BUMPER GUIDE - LH		\$	31.00		
4	FRONT BUMPER FOAM		s	107.00	\$	85.20
5	FRONT REINFORCEMENT BEAM		5	702.00	\$	561.60
6	FRONT BUMPER SUPPORT - LH		s	24.00		
7	FRONT LOCK CARRIER BRACKET		\$	118.00	\$	94.00
8	FRONT BUMPER GRILLE - LH		\$	118.00		
9	LED HEADLIGHT - LH		\$	6,973.00	\$	5,578.40
10	POWER MODULE FOR MAIN LIGHT		\$	695.00		
11	CONTROL UNIT FOR LIGHT CONTROL SYSTEM		\$	657.00		
12	HEADLIGHT WASH CYLINDER BRACKET - LH		\$	6.00		
13	HEADLIGHT WASHER CYLINDER - LH		\$	184.00		
14	FRONT NO. PLATE	S/N	\$	25.00		
15	SUPPLEMENTARY		\$	79.00	\$	62.64
16	SUNDRIES		\$	300.00	\$	2.24
	TOTAL SPARE PARTS	3	\$	12,039.00	\$	7,863.28
	TOTAL LABOUR CHARGES		\$	2,552.00	\$	2,102.00
	GRAND TOTAL	12	\$	14,591.00	\$	9,965.28

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/TP/0411/2018/CCS

Date 24-Apr-18 Service Advisor Jeffery Tan

Pages 1

Regn No SLC 137 G

Model No Audi A4 SEDAN 1.4 TFSI

Quantity	Description	U	nit Price	-	Amount
Parts 1 2	Wheel spoiler - LHS Temperature sensor bracket	\$	63.00 16.00	s s	50.16 12.48
	Control of Annable and Annable and Control of Control o	\$	79.00	\$	62.64
	TOTA	L \$	79.00		

For Premium Automobiles Pte Ltd

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu

Claims Consultant

View Received Message

This mail is associated with:

*SLC137G (2151211149SG) [SLM8532T]

ANBARASAN RAMASAMY Apr 3 2018 8:00PM [LIM FUN YEN MRS SOH-LIM FUN YEN] Premium Automobiles Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward		
From To Subject	LKK HC	1			_EXPRESS), sent on - Claim Handler: Ke	18/06/2018 09:52 AM. asaval, Jaclyn-M	
Approved	J:11062.85	÷					
DOCUM	ENTS SU	AMARY					
	re no docur	Activities to the second secon					



AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: CC3/AIG18006210/wb3 Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/TP/0411/2087/MAS

24 May 2018

Telephone +65-Telefax +65-

EMail

Our department

Our Ref

Your Ref Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLC 137 G, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. SLC 137 G, claimant, Mr. Anbarasan Ramasamy, please find the related document as per attached.

- A copy of the Original invoice no. 85012528 S\$10,662.85
- 2. A copy of Authorization to Act duly signed by client
- 3. A copy of the Release Voucher attached
- 4. A copy of Breakdown of Payment attached
- Rental bill \$\$400.00 (\$\$100.00 x 4 days)

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls


AIG - SLC 137 G


Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183


BREAKDOWN OF PAYMENT

Vehicle No: SLC 137 G Accident on 03/04/2018		
		Marymount Road
Involving vehicle/s SI	LM 8532 T	
1) Repair cost	s 10,662.85	Payable to: <u>Premium Automobiles Pte Ltd</u>
2) GIA/LTA search fee	<u> </u>	Payable to: <u>Premium Automobiles Pte Ltd</u>
3) L oss of Use o r Rental Car	\$ 400.00	Payable to: ANBARASAN RAMASAMY
4) Medical fees	\$	Payable to:
5) Others	\$	Payable to:











51 UBLAVE 1, #01-25 PAYA UBTINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX: (065) 62564315

Our Ref: CC3/AIG18006210/wb3

10 April 2018

LIM FUN YEN MRS SOH-LIM FUN YEN

13 Jalan Mata Ayer #01-75 Singapore 759155

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 8532T AND SLC 137G ON 03/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau Case Handler DID: 6841 8625

DID: 6841 8625 FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

AUTHORISATION TO ACT

(AIG Express Third Party Claim)

I. Anbarasan Ramasamy	(the third party cla	aimant) of 3 Sin Mir	Walk #11-23
Singapore 575575		of SLC 137 G	
hereby authorize Premium Automobi	iles Pte Ltd	("the workshop	") to act for me
with respect to my claim for repair co	sts and/or rental and/or	loss of use ("claim"	') for my vehicle
no. SLC 137 G that was damaged	pursuant to the accide	ent which occurred o	03/04/2018
(date) along Marymount Road		(location) involving	ng vehicle no/s
SLM 8532 T ("the accident").			
I further authorize the workshop to sett and the workshop is further authorized payment cheque/s being made in favou	to receive payment fu		
further acknowledge that any settlem prejudice and without admission of lial			
ehicle/s is concerned.			
Dated this	(month) 20 <u>1</u> 3 (year) Onuuh C	PIE (100 *
igned by "the third party claimant"	Sig	med by "the worksho	p"

(with chop)

(with chop if applicable)

RELEASE VOUCHER (AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd	("the workshop") hereby confirm that we/
have reached an agreement with the appointed surve	
AUTO CONSULTANTS PTE LTD (name of sur	
\$\$10663. & (Repair Cost). 5\$ 400-09Loss of Frenty	
SLC 137 G that was damaged pursuant to the acc	tident which occurred on 03/04/2018(data) stone
	ation) involving vehicle no/s SLM8532T. This is
pursuant to the inspection conducted on 06/04/2018 (c	[: [
We/I confirm that we/I are/am authorized by the ow	ner Anbarasan Ramasamy
("the third party claimant") of vehicle no. SLC 137 G	_ make the claim as set out in the above paragraph
and we/I have full authority to settle the matter on hi	s/her hehalf in a manner that we/I deem fit We/I
enclose herein the letter of authority given by "the third	party claimant".
We/I further confirm that we/I will indemnify AIG Asi	a Pacific Insurance Pte Ltd for all damages, loss
and/or expense that they will or have already incurred i	n the event that "the third party claimant" after the
above said agreement lodges a further claim against	the former for any loss and expenses suffered
pertaining to costs of repairs and/or rental and/or loss	of use pursuant to the damage to SLC 1374
(vehicle no.) as a result of the accident.	
We/I confirm that the agreement reached above is in for	all and final settlement of any claim of "the third
party claimant" pursuant to the accident and that further	r this settlement is reached on a without prejudice
and without admission of liability basis.	
This agreement is subject to the application of Singapo	ore law and the Singapore Courts have exclusive
urisdiction over any dispute arising out of the same.	
Dated this 18 (day) of 6 (month)	20 <u>18</u> (year)
· · · · · · · · · · · · · · · · · · ·	A MI SE PIE CO
Luf (n)	- Human

Signed by appointed surveyor

Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 5836 2223 Main Telefax 6471 3733 Page 1 15:19

Alexandra Service Centre 291 Alexandra Road Singapore 159338 Telephone 6388 2223 Telefax 6475 1023

Ubi Service Centre 55 Ubi Road 1 INS STANK 408 SON VOICE hour Breakstown Service

Customer Service Service Appointment

9828 1233

Company Telephone 15368,322502271W Small

customer.care@premiumauto.com.sg

SST Reg. No. 199302271W

Invoice: 85012528

Account: A0006

(T ALG AGIA PACIFIC INSURANCE PTE LTD

AIS ASIA PACIFIC INSURANCE PTE LTD

15:19

MOTOR CLAIM DEPT

AIS BUILDING

78 SHENTON WAY

Date : 21/05/2018

MOTOR CLAIM DEPT

AIG SUILDING

78 SHENTON WAY

#07-16

#07-16 SINGAPORE 079120 079120

Term : 30

Order : SLC01376

SINGAPORE 079120

Regn No.: SLC01376 (V 29362)

Regn Date: 28/04/2016

Mileage: 21748

WIP No. 1 61060

Model: A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF408A040396

Engine: CVN 005486

Dept: U

VSB No.:

You have been assisted by :- UB-Carrine

(50)

	Det	ails	Qty	Unit Price	Amount
BGDYWDRK	TO REMOVE AND TRANSFER FRONT W HEADLIGHTS, HORNS, OUTSIDE TEMPE HEADLIGHT WASHER ASSY	IRE HARNESS FOR	368.98	1.00	360.00
BODYWORK	TO DISMANTLE AND RENEW FRONT B	M: DISMANTLE AND RENEW FRONT BUMPER AND LHS CADLIGHT. REDRGANISE FRONT CRASH MANAGEMENT			1, 200. 20
BODYWORK	TO RESPRAY FRONT BUMPER		550.00	1,00	550,00
BODYWORK	M TO CARRY OUT DIAGNOSTIC CHECK		192.00	1.80	192.00
A890941773A	HEADLIGHT	Less 220%	1.08	6973.00	5, 578, 49
A8W8853887A	SPOILER	Less 020%	1.00	62.70	59, 16
9849897559A	FDAM INSER	Less 020x	1.08	106.50	85,20
A8W0807113	BRACKET	Less 020%	1.00	702.00	561.60
A840807065C GRU	COVER	Less 020X	1.00	1849.00	1,479.20
A849828536	BRACKET	Less 020%	1.00	15.60	12.48

Sub-Total

7% GST

Grand Total

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefav 6471 3733 Alexandra Service Centre 281 Alexendra Road Singapore 159938

Service Appointment

6166 2323 9828 1233

15:19 Page 2

Telephone 6388 2223 Telefas 6475 1023

INS STREET ASSESSINUTICE From Breakdown Service Company (LEE) NGS41/130/02271H Custor

customer.care@premiumauto.com.sg

AIS ASIA PACIFIC INSURANCE PTE LTD

GST Reg. No. 199902271W

Date

Invoice: 85012528

Account: A0006

(8)

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

907-15

SINGAPORE 079120 079120

: 21/05/2018

Order : SLC01376

#07-16

Term : 30

SINGAPORE @79120

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON HAY

Regn No.: SLC0137B (V 29362)

Regn Date: 28/04/2016

Mileage: 21748

WIP No.: 51060

Model: A4 SEDAN 1.4 TFSI S tronic

AIG ASIA PACIFIC INSURANCE PTE LTD

Chassis: WAUZZZF40GA640396

Engine: CVN 005486

Dept: U

VSB No. :

You have been assisted by :- UB-Carrine

(50)

			Details	Qty	Unit Price	Amount
X	A848887771 AN 91093981	BRACKET RIVET	Less 020% Less 020%	1.00	117.59 8.79	94.00 2.24
	rts 7,863,25				Sub-Total	9, 965, 28

7,863.28 Parts Labour 0.00 Sublet 2,102,00 Menus 0.00 Lubricant 8.88

Received by

7% GST

Grand Total

9,965.28

697.57

10, 662, 85

For & on behalf of Premius Automobiles Pte Ltd



CHAN'S & SONS ENTERPRISE 363 Sembawang Road, Goodlink Park, Singapore 758379. Tel: 6753 2536 Fax: 6756 7565 Breakdown Recovery: 9742 9446

Hirar's Name	0	EVEN ENGINE C	Date of Birth	Passport/	Nria Na.	Nation	ality	
ANK	SARASAN RAY	YM#2AM	20.03.197	31573	1117	SOL		
Address	SIN MING	WALK	Occupation	Driving Lie	ence No	Date o	Date of Expiry	
11 00		Postal Code	Contact No	Mobile Ph				
11-,57		5119575		× 943	099	60		
Joint Hirer's / Guarantoi	's Name		Date of Birth	Passport/	Nric No.	Nation	ality	
Address			Occupation	Driving Lic	ence N	Date o	I Expiry	
<u> </u>		Postal Code	Contact No	Mobile Ph	ane No.	_		
NECK OUT	Date	Time	Mileage	+	=			
CHECK OUT	24.04.208	08	К	u E	1/4) 1/2	3/4 F	
CHECK IN	28 4 18 ·	11-30 om ·	Mileage	Remarks				
IMPORTANT NOTE	S:			UNIT	П	RATE (\$)	TOTAL (\$)	
	INGAPORE use. See clause 1/ en for vehicle that returns early		RATE	4	0	æ100	+00	
. Own Damage Liabi	lity - First \$1500 for damage aged vehicle is under repair.		DISCOUNT					
· Third Party Liability	- First \$2000 for any Third Part		GST ® 7%					
	of \$3000 for drivers under 24 s driving experience.	yrs old or above 70yrs	TOTAL				400	
	for all parking fines & traffic sun y's advance notice is required		EXTENSION	+	\top		V12742	
will be allowed.			EXTENSION		++	20.0	04-023	
Saturday where retu	returned at the same time a urn time is before 10am.		Jeffrey 1	todi	+	1 2010	04-000	
	er office hour will be charged to charged at 1/5 of the daily rate.	the next working cay.	1 0,	-	+			
	enance, please check water &	engine oil daily.		1	1			
 Please check that y vehicle. Our compo belongings after the 	ou have not left any of your pe any and staff will not be resp vehicle is returned.	Ref SLC137	137	51				
 For the comfort of carrying of pets in t smoky, smelly or dir 	other users, please refrain fr he car. A cleaning charge of \$ ty vehicle.	om smoking, eating or 200 will be imposed for	DEPOSIT (refundat	seles La				
. Carrying of PASSE	NGERS in commercial vehicle covered under hirer's workn				E			

Hirer's Signature	Joint Hirer's/ C	Suarantor's Signature	tor CHA	N'S & SONS ENTERPRISE
VEHICLE NO.	KX 8913G	MODEL	K3	
FROM 24.0	4.2018	RETURN		"Estimate Data For actual return see CHEC

CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park, Singapore 758379 Tel: 67532536 Fax:67567565 GST Reg No: 51-936900-M



Hirer:

ANBARASAN RAMASAMY

OFFICIAL RECEIPT

AMOUNT (SGD) DESCRIPTION

Official Receipt No

: 201804-0335

Account of

: ANBARASAN RAMASAMY

Date Issued

: 30/04/2018

Vehicle Reg No.

: SKX8913G

Rental Dates

: 24/04/2018

Amount Received

: S\$ 400.00

Payment Type:

: VISA

V127423

S\$

400.00

Payment for Invoice

: AR1804-0468

Comments

TOTAL AMOUNT RECEIVED

S\$

400.00

MERCHER COLA

Merchant Solutions

Chief & A Mark ENGLANTS NO 141 YEARSKING 20

HID

930792055684422

(III)

bL188517

XXXXXXXXXXXXXXXXXX IMI

Ulan

EXPLIPY: XX/AA

SALE

OPR 38 2010 38:32 BATCH: 600016

RRH MODE 1962 7425 TRACE - 027425

211178

560496.29

TARBONISER STORAFORE

WERE THE COCK - 202575

I REALL OF YOU AND READ AND A AMERICAN

MA DUPLICATE MM

* This is a computer generated document. No signature is required.



19

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	Ins Auth'ed	Sta	tus	
Main	04 Apr 2018 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	\$\$9,965.28			Re	Pending for Surve Report Cancel Case		
	Main	1	Reference	Cla	im Deta	ils \	Docume	nts	٦.	Show All
CLAIM SU	BFOLDER DE	TAILS			- William III	[Created	by adjuster]			and the later is not the
Insured:	LIM FUN	YEN MRS SOH-	LIM FUN YEN, ID:							
Main Claimant:	ANBARAS	AN RAMASAM	r, ID: S73117561							
Vehicle Reg No.:	SLC137	G		c	ate of L		8 20:00 - :59 s and 6 Days Fr	om LTA R	TA Reg Date (Man Yr)]	
Claim Type	TP / 215	1211149SG			olicy/Co		75			
Vehicle Reg No. (Insured):		SLM8532T			olicy No Claimant		2100462075-01000			
				8	xcess:					
Repairer:	Premium	Automobiles P	te Ltd (UBI) 55 Ubi	Road 1, 4086	99 Ubi -	Tel: 67689828/9	9827/9911			
Handling Insurer:		Pacific Insurar esaval@aig.com	ce Pte. Ltd. (Expre	ss) - Tel: 65-	5419-30	00 [Handled t	y Kesaval, Jac	:lyn-M]		
Claimant's Insurer:	AIG Asia	Pacific Insuran	ce Pte. Ltd. (SG) -	Tel: 65-6419-	3000					
Adjuster:	LKK Auto	Consultants Pt	te Ltd (HQ) - Tel: 62	56-3561 [landled	by ADRIAN LIN	(G) [Final F	Rpt due	13/04/20	018]
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compos	e Case Mail
 AIG_SG 	EXPRESS (18	/06/2018): Aler	t - Adj Mandate App	proved (S\$1	062.85) - SLC137G -	Claim Handler	Kesaval	Ja	
ALL ASSO	CIATED TAS	iks∃				View All	Search Tasks	Create N	ew Task	Complete
Due Date	e Priority	Type Tas	sk Group Subjec	t Handler	As	signed By	Completed O	n Cr	eated On	Done

Merimen e-Claims Page 1 of 2

Claim Documents

*SLC137G (2151211149SG) [SLM8532T] TP ANBARASAN RAMASAMY Apr 3 2018 8:00PM

Apr 3 2018 8:00PM [LIM FUN YEN MRS SOH-LIM FUN YEN] Premium Automobiles Pte Ltd

Let	ters/Corresponder	nces	1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
Ass	sessment Reports		1 per	page VI	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	La Pari	Thumbnail	-
1	05/04/18 12:11	Accident Statement From:SC - Reg. No: SLM8532T, Claimant: LIM FUN YEN MRS SOH-LIM FUN YEN	0	Load HTM	
Pho	otos/Images		3 per	page V	Z
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	[5 per	Thumbnail	Action Printers
1	16/05/18 00:53	General View	0	Load JPG	V
2	16/05/18 00:53	General View	0	Load JPG	3
3	16/05/18 00:53	General View	0	Load JPG	V
4	16/05/18 00:53	General View	0	Load JPG	V
5	16/05/18 00:53	General View	0	Load JPG	V
6	16/05/18 00:53	General View	0	Load JPG	V
7	16/05/18 00:53	General View	0	Load JPG	V
8	16/05/18 00:53	General View	0	Load JPG	V
9	16/05/18 00:53	General View	0	Load JPG	V
10	16/05/18 00:53	General View	0	Load JPG	V
11	16/05/18 00:53	General View	0	Load JPG	V
12	16/05/18 00:53	General View	0	Load JPG	V
13	16/05/18 00:53	General View	0	Load JPG	V
14	16/05/18 00:53	General View	0	Load JPG	V
15	16/05/18 00:53	General View	0	Load JPG	V
16	16/05/18 00:53	General View	0	Load JPG	V
17	16/05/18 00:54	Reinspection Photo	0	Load 3PG	V
18	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
19	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
20	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
21	16/05/18 00:54	Reinspection Photo	Ð	Load JPG	V
22	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
23	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
24.	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
25	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
26	16/05/18 00:54	Reinspection Photo	Ð	Load JPG	V
27	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
28	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
29	16/05/18 00:54	Reinspection Photo	0	Load JPG	[2]
30	16/05/18 00:54	Reinspection Photo	0	Load JPG	7

Let	ters/Corresponder	ces	1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
31	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
32	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
33	16/05/18 00:54	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/18 16:50	TP GIA REPORT	0	Load PDF	
2	04/04/18 16:50	OI GIA REPORT	0	Load PDF	
3	09/04/18 17:32	TP ESTIMATE- MARKED	0	Load PDF	
4	31/05/18 17:01	RENTAL RECEIPT	0	Load PDF	
5	31/05/18 17:01	LETTER TO OI	0	Load PDF	
6	20/06/18 08:55	WORKSHOP INVOICE	0	Load PDF	
7	20/06/18 08:55	AUTHORISATION TO ACT FORM	0	Load PDF	
8	20/06/18 08:55	Release Voucher	0	The latest terminal to the latest terminal termi	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

Page 1 of 1

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM8532T (Insd veh)			Model:	AUDI A4 1.4 TFSI S TRONIC
	SLC137G (TP veh)			(A)	
Date of Accident: 03/04/2018					
Global Sum Settlen	ent :	[] Yes	3	[X] No	
Repair Estimate			: \$	15,594.86	
Final Repair Cost			: \$	10,662.85	
Loss of Use			: \$		days at \$0.00 per day
Rental (if any)			: \$	400.00	4 days
LTA / GIA Search F	ee		: \$	0.00	
Others:			: \$	0.00	
			: \$		
Final Settlement Su	m		: \$	11,062.85	
Is Third Party World below) A) For Non GIA R		65		X] YES	[] NO (Kindly indicate
B) For GIA Regist					e: Yes / No BOLA Scenario No:
BOLA Liability: * Assessed Liab	artest the many of	A STATE OF THE PARTY OF THE PAR			ty (*):(%) ases where BOLA does not apply.
Remarks					
Payment Instruction	n: Paye	e's Breakdo	wn		
Premium Auto	mobiles	Pte Ltd		: \$	10,662.8
2) Anbarasan Ra	masamy	Vi.		: \$	400.00
				20 Jun	
JOANNE I	EE KHA	ANG MIN		2018	
LKK Auto C	onsultar	nts Pte Ltd		Date	

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Page 1 of 4 Adjuster Report

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006210/AWB3Q2

Date: 20/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

2100503975 Policy No:

Claimant Vehicle No:

Reg. Date:

SLC137G

Insured Vehicle No: SLM8532T

TP

Odometer:

Date of Loss: 03/04/2018 Nature of Claim:

Claim No: 2151211149SG

21214 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC137G

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN005486 28/04/2016 (Man. Year: 2016) Chassis No: WAUZZZF40GA040396

Colour:

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 205/60 R16 Rear Tyre Size: Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,022.64	7,863.28	4,159.36	34.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,552.00	2,102.00	450.00	17.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,574.64	9,965.28	4,609.36	31.63
+ GST 7.00/7.00% (S\$)	1,020.22	697.57	322.65	31.63
Nett Amount (S\$)	15,594.86	10,662.85	4,932.01	31.63
+ Car Rental (4.0	x S\$100.00/day) (S\$)	400.00		
	Nett Liability (S\$)	11,062.85		

INSPECTION

Date of Assignment: 06/04/2018

Date Inspected: 06/04/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)

> 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 20/6/2018

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

	*FRONT BUMPER			
	THOM: DOM: LIX	Deformed	1,849.00 FS	*1,479.20 FS
	*FRONT BUMPER GRILLE -CENTER	Not Necessary	171.00 FS	*-FS
	*FRONT BUMPER GUIDE -LH	Not Necessary	31.00 FS	*-FS
	*FRONT BUMPER FOAM	Torn	107.00 FS	*85.20 FS
	*FRONT REINFORCEMENT BEAM	Bent	702.00 FS	*561.60 FS
	*FRONT BUMPER SUPPORT -LH	Not Necessary	24.00 FS	*-FS
	*FRONT LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
	*FRONT BUMPER GRILLE -LH	Not Necessary	118.00 FS	*-FS
	*LED HEADLIGHT -LH	Cracked	6,973.00 FS	*5,578.40 FS
	*POWER MODULE FOR MAIN LIGHT	Not Necessary	695.00 FS	*-FS
	*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Not Necessary	657.00 FS	*-FS
	*HEADLIGHT WASH CYLINDER BRACKET -LH	Not Necessary	6.00 FS	*-FS
	*HEADLIGHT WASHER CYLINDER -LH	Not Necessary	184.00 FS	*-FS
	*FRONT NO .PLATE	Not Necessary	25.00 FS	*-FS
	*SUNDRIES	Necessary	300.00 FS	*2.24 FS
	*WHEEL SPOILER -LHS	Torn	50.16 FS	*50.16 FS
	*TEMPERATURE SENSOR BRACKET	Cracked	12.48 FS	*12.48 FS
part. S=Spc	Nett.	Total Parte (SS)	12 022 64	7,863.28
р	art. S=Spc	*WHEEL SPOILER -LHS	*WHEEL SPOILER -LHS Torn *TEMPERATURE SENSOR BRACKET Cracked art. S=SpcNett.	*WHEEL SPOILER -LHS Torn 50.16 FS *TEMPERATURE SENSOR BRACKET Cracked 12.48 FS

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amoun
Lab	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS ,RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	1,000.00
3	TO RESPRAY FRONT BUMPER	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192,00
	Gross Labou	r Cost (S\$)	2,552.00	2,102.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >