

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0411/2018/CCS
Date : 04-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.
Your insured vehicle no: SLM 8532 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Anbarasan Ramasamy
Address : 3 Sin Ming Walk
#11-23
Singapore 575575
Telephone : HP +65 94309960
Type of Claim : Third Party Claims
Policy No. : 2100462075-01000
Vehicle No : **SLC 137 G**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Apr-16
Engine No : CVN 005486
Chassis No : WAUZZZF40GA040396
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 03-Apr-18
Place of Accident : Marymount Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 137 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 750	
3	To respray front bumper.	\$ 800.00 550	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 137 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Reh</i>	\$ 1,849.00	✓
2	FRONT BUMPER GRILLE - CENTER <i>3 new</i>	\$ 171.00	x
3	FRONT BUMPER GUIDE - LH	\$ 31.00	x
4	FRONT BUMPER FOAM <i>torn</i>	\$ 107.00	✓
5	FRONT REINFORCEMENT BEAM <i>?</i>	\$ 702.00	?
6	FRONT BUMPER SUPPORT - LH <i>new</i>	\$ 24.00	x
7	FRONT LOCK CARRIER BRACKET <i>?</i>	\$ 118.00	?
8	FRONT BUMPER GRILLE - LH <i>ht</i>	\$ 118.00	✓
9	LED HEADLIGHT - LH <i>cracked</i>	\$ 6,973.00	✓
10	POWER MODULE FOR MAIN LIGHT <i>new</i>	\$ 695.00	x
11	CONTROL UNIT FOR LIGHT CONTROL SYSTEM <i>new</i>	\$ 657.00	x
12	HEADLIGHT WASH CYLINDER BRACKET - LH <i>?</i>	\$ 6.00	?
13	HEADLIGHT WASHER CYLINDER - LH <i>?</i>	\$ 184.00	?
14	FRONT NO. PLATE <i>Not m</i>	S/N \$ 25.00	x
15	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 11,960.00	
TOTAL LABOUR CHARGES		: \$ 2,552.00	
GRAND TOTAL		: \$ 14,512.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 06/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant