

# JAS AUTO SERVICES

6D Mandai Estate #03-02 M-Space, Singapore 729938

Tel: 6453 1967 Fax: 6457 3091

53255447K

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 04-Apr-18

Acknowledged by Repairer

Signature:

Date:

M/s AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
Singapore 079120

Fax: 6419 1000

Attn: Motor Claim Dept

Re: Accident on 30/03/2018. Between SJQ3332P AND GBD3117H(Your Insured).

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim**.

## Parts

|   |                   |
|---|-------------------|
| 1pc Bootlid / bnc                             | \$1,228.60 /      |
| 1pc Bootlid rubber X NN                       | \$120.00 X        |
| 1pc Bootlid plastic garnish(below logo) / CNA | \$245.50 /        |
| 1pc Rear bumper / TN                          | \$844.80 /        |
| 1pc Rear bumper retainer LH / MS              | \$48.00 /         |
| 1pc Rear bumper tow cover / MS                | \$40.00 /         |
| 1pc Rear bumper reflector LH / MS             | \$62.40 /         |
| 1pc Rear undershield LH / MS                  | \$150.50 /        |
| 1pc Taillamp LH / CNA                         | 420.5 \$645.80 /  |
| 1pc Rear end panel X                          | \$420.50 X        |
| 1pc Exhaust pipe X repair                     | \$1,108.60 X      |
| 1pc Exhaust pipe rubber mounting / TN         | 3099.15 \$58.85 / |

20%: 2479.32

Total: \$4,973.55  
Less: 20% \$994.71  
**\$3,978.84**

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.

To putty & respray paint on the relevant repaired areas.

To rust proof affected areas where necessary.

\$1,000.00 500  
\$800.00 600  
\$90.00 40

**Parts & Labour Total: \$5,868.84**

Your Faithfully,

JAS AUTO SERVICES



Que Quey.  
24/4/18.

3619.32  
20%: 2900.  
4 Days.  
Lumpsum repair  
After repair photos.