

SS. PEC. BY:

REF:

CS/FCL18006216/KTB

Special Instruction:

UNV/JOY

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCL Date/Time: 04042018 12:37pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 9101Y Insured: SIB 4138E

at Workshop n/s Jim Tan Motor Tel: 8484 5418

of Blk 176 Sin Ming Drive #03-09

Policy No: _____ Claim No: D18002654MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 31-05-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS · DS1 09.04.2018 @ after 10:30am H.O.D. Endorsement: _____

Date/Time: 04042018 14:37pm Person Contacted: Richard Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 9101Y - X
	SIB 4138E - 100/AXA 17/0011-35 / m/w/b/c/g
	lump sum \$15000 (Red: 2590.35 : 34%)

REF: FCI

ASSIGNMENT

From: _____ Date: 09104118

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKT 9101Y

at Workshop m/s: Lim Tun Motor

of: Blk 176, Sin Ming Drive #03-09

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) after 10:30am

Make of Veh: _____

Veh No: SKT 9101Y Yr Regn: 05 11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Bmw A1 118i c.c. 1995

Colour: M. Grey A/C Insured / Std / NI / NA

Sp. Reading: 67431 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAUM12000VH86331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$54k

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

Front		Rear	
R/Bal. <u>8</u> mm		R/Bal. <u>8</u> mm	
L/Bal. <u>8</u> mm		L/Bal. <u>8</u> mm	
D.O.A. <u>31/3 118</u>		D.O.I. <u>9/4/18</u>	

CA / REV / REP. / 24 HRS hup

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at: _____ ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/4 file pass to Catherine

RECEIVED 2 + APR 2018

Date/Time File Pass to? Preli. Report

2/14 Typist Final Report

Date/Time File Return to? _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:	<u>150</u>
Transportation:	<u>50</u>
_____S + RE_____S	<u>507.50</u>
Photos	<u>26</u>
Others	
TOTAL:	<u>526</u>

Report Format: TP

Lump Sum / I.B.I: (\$ 50007)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18006216/Ktb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4138E	Veh. Inspected	SKT 9101Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18002654MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	04/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/03/2018	Inspection Date	09/04/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	03-04-2018	Our Ref No. D18002654MFSH
Accident Date	31-03-2018	Claim Type. Third Party
Insured Vehicle	SHB4138E	Third Party Vehicle. SKT9101Y
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE	
Contact Person.	RICHARD ANG	
Contact No.	64520893/ 84845418	Fax No. 64589127
Survey Type	DIRECT SETTLEMENT:	<i>OK 03/04/18 @ 11:30pm Richard veh ref in</i>
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236615)  **PRI Documents**  **Close** 

PRI Header Details

Claim No	D18002654MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LIM
Workshop Name	LIM TAN MOTOR PTE LTD (Contact Person : RICHARD ANG)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #03-09/10/06 SIN P Mobile: 84845418 , Phone: 64520893 , Fax: EmailId: RICHARD@LTM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4138E	TP Vehicle No	SKT910
PRI Recieved Date	03-04-2018 08:54:44 PM	Surveyor Appointed Date	04-04-2018 12:37:15 PM	Surveyor Accept Date	04-04-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	04-04-2018	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action

Surveyor Job Remarks

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
 Owner ID: 60628

Vehicle Details

Vehicle No.: SKT9101Y
 Vehicle to be Exported: Yes
 Intended De-registration Date: 02 Apr 2018
 Vehicle Make: B.M.W.
 Vehicle Model: 118i A
 Primary Colour: Grey
 Manufacturing Year: 2010
 Engine No.: A729I773N43B20AY
 Chassis No.: WBAUM12000VH86331
 Maximum Power Output: 105.0 kW (140 bhp)
 Open Market Value: \$35,928.00
 Original Registration Date: 26 May 2011
 First Registration Date: 26 May 2011
 Transfer Count: 1
 Actual ARF Paid: \$35,928.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 25 May 2021
 PARF Rebate Amount: \$23,353.00

Intended COE Rebate Details

COE Expiry Date: 25 May 2021
 COE Category: E - Open Category
 COE Period(Years): 10
 QP Paid: \$57,100.00
 COE Rebate Amount: \$17,298.00
Total Rebate Amount: \$40,651.00

The information contained herein is correct as at 02 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 14:14
Date Of Accident	31/03/2018 12:05
Exact Location Of Accident	SENGKANG EAST ROAD TOWARDS HOUGANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9101Y
Insured/Policyholder	
Name Of Registered Owner	TAY SUE LEN (ZHENG SHILING)
NRIC No	S7536062B
Email Address	TAYSERENE.SG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97208088
Alternative Phone No	OTHERS-97208088

Vehicle Particulars

Manufacturer	BMW
Model	118I A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5070598770-02
Cover Note Number	

Driver

Name of Driver	TAY SUE LEN (ZHENG SHILING)
NRIC No	S7536062B
Date Of Birth	28/11/1975
Occupation	OUTDOOR
Date Of Driving Pass	14/05/1996
Driving Experience	21 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97208088
Fax Number	
Contact Number	OTHERS-97208088
Email Address	TAYSERENE.SG@GMAIL.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

02 APR 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

ANG WEI GUANG
S8410708E

K1

Not Notified
 11pm @ 5000
 5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKT 9101 Y
 MAKE : B.M.W
 MODEL : 118I A
 YEAR : 2010
 CHASSIS NO : WBAUM12000VH86331

SURVEYOR NAME	: Kenneth (LKK)
DATE OF SURVEY	: 09.04.2018
TIME OF SURVEY	: 10.40am

DATE : 3-Apr-18
 DATE OF ACCIDENT : 31-Mar-18
 THIRD PARTY REF : SHB4138E / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper	Nett		\$ 994.70	
1 pc	Rear Bumper Reinforcement	Nett		\$ 385.25	
2 pcs	Rear Bumper Retainer	Nett	\$ 45.35	\$ 90.70	
3 pcs	Rear Bumper Sensor	Nett	\$ 236.85	\$ 710.55	
1 pc	Rear Bumper Lower Cover	Nett		\$ 34.20	
1 pc	Rear Bumper Tow Cover	Nett		\$ 44.20	
1 pc	Rear End Panel	Nett		\$ 487.55	
1 pc	N/S Tallamp	Nett		\$ 332.55	
1 pc	Rear Boot Lid	Nett		\$ 1,301.65	
1 pc	Rear Boot Lock	Nett		\$ 129.95	
1 pc	Rear Boot Rubber	Nett		\$ 181.65	
1 pc	Rear Boot Centre Rubber	Nett		\$ 69.50	
1 pc	Rear Boot 118 Emblem	Nett		\$ 69.50	
1 pc	Rear Boot M Logo	Nett		\$ 89.95	
1 pc	Rear Exhaust Silencer Box	Nett		\$ 847.50	
				\$ 6,005.35	
	To putty & spray painting.			\$ 700.00	
	To check rear wiring and replace sensor.			\$ 80.00	
	To anti-rust.			\$ 60.00	
	To replace rear exhaust silencer box			\$ 80.00	
	Labour Charges.			\$ 600.00	
TG-RA/-	TOTAL				\$ 7,525.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: [Signature]
 Date: 02/04/18
 Website: www.LTM.sg
 GST Reg No: M2-0018080-0

Not Authorized
 L1 Bay @ 7
 4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKT 9101 Y
 MAKE : B.M.W
 MODEL : 118I A
 YEAR : 2010
 CHASSIS NO : WBAUM12000VH86331

SURVEYOR NAME	: Kenneth (LKK)
DATE OF SURVEY	: 09.04.2018
TIME OF SURVEY	: 10.40am

DATE : 3-Apr-18
 DATE OF ACCIDENT : 31-Mar-18
 THIRD PARTY REF : SHB4138E / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper	Nett		B ₁ \$	994.70
1 pc	Rear Bumper Reinforcement	Nett		\$	385.25
2 pcs	Rear Bumper Retainer	Nett	\$ 45.35	N/S DIT	90.70
4 pcs	Rear Bumper Sensor	Nett	\$ 236.85		947.40
1 pc	Rear Bumper Lower Cover	Nett		\$	34.20
1 pc	Rear Bumper Tow Cover	Nett		\$ S _m	44.20
1 pc	Rear End Panel	Nett		\$	487.55
1 pc	N/S Taillamp	Nett		\$ S ₁	332.55
1 pc	Rear Boot Lid	Nett		\$ B ₁	1,301.65
1 pc	Rear Boot Lock	Nett		\$ R	129.05
1 pc	Rear Boot Rubber	Nett		\$ S _m	181.65
1 pc	Rear Boot Centre Rubber	Nett		\$	69.50
1 pc	Rear Boot 118 Emblem	Nett		\$ M	69.50
1 pc	Rear Boot M Logo	Nett		\$ M	89.95
1 pc	Rear Exhaust Silencer Box	Nett		\$ B ₁	847.50
					\$ 6,005.35
	To putty & spray painting.			600	\$ 700.00
	To check rear wiring and replace sensor.				\$ 80.00
	To anti-rust.			\$ 30	60.00
	To replace rear exhaust silencer box			\$ 60	80.00
	Labour Charges.			500	\$ 600.00
TG-RA/-	TOTAL				\$ 7,525.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized by Repairer

Blk 178 Sin Ming Drive #01-27 Singapore 575721
 Tel: 65-64520893 Fax: 65-64520827 Website: www.LTM.sg
 Co. Reg No 199307277D GST Reg No M2-0019005-0



SUPPLEMENTARY TO REPAIR

VEHICLE NO. : SKT 9101 Y
 MAKE : B.M.W
 MODEL : 118i A
 YEAR : 2010
 CHASSIS NO : WBAUM12000VH86331

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 13-Apr-18
 DATE OF ACCIDENT : 31-Mar-18
 THIRD PARTY REF : SHB4138E / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper Inner Plate (Centre)	Nett			\$ ^{CPA} 65.00 ✓
	parts \$4,932.00				
	Supp \$65.00				
	<u>\$4,997.00</u>				
	labour \$1,270.00				
	<u>\$6,267.00</u>				
	less 20% \$1,253.40				
	<u>\$5,013.60</u>				
	4/5 \$5,000.00 ✓ ok				
	05 days				
TG-RA/-					\$ 65.00

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520003 Fax: 65-64588127 Website: www.LTM.sg
 Co.Reg No. 190307277D GST Reg No. M2-0019066-0



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006216/Ktbq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4138E	Veh. Inspected	SKT 9101Y
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002654MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	04/04/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 118I (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAUM12000VH86331	Colour	METALLIC GREY
Odometer	67431	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	8 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	8 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	8 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/03/2018	Inspection Date	09/04/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 9101Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	BENT	994.70	994.70
1	REAR BUMPER REINFORCEMENT (N)	BENT	385.25	385.25
2	REAR BUMPER RETAINER @\$45.35 (N)	N/S DISTORTED	90.70	45.35
4	REAR BUMPER SENSOR @\$236.85 (N)	SHORTED (3 PCS ONLY)	947.40	710.55
1	REAR BUMPER LOWER COVER (N)	SERVICEABLE	34.20	-
1	REAR BUMPER TOW COVER (N)	SERVICEABLE	44.20	-
1	REAR END PANEL (N)	BENT	487.55	487.55
1	N/S TAILLAMP (N)	SERVICEABLE	332.55	-
1	REAR BOOT LID (N)	BENT	1,301.65	1,301.65
1	REAR BOOT LOCK (N)	TO REPAIR SEE LABOUR	129.05	-
1	REAR BOOT RUBBER (N)	SERVICEABLE	181.65	-
1	REAR BOOT CENTRE RUBBER (N)	SERVICEABLE	69.50	-
1	REAR BOOT 118 EMBLEM (N)	NECESSARY	69.50	69.50
1	REAR BOOT M LOGO (N)	NECESSARY	89.95	89.95
1	REAR EXHAUST SILENCER BOX (N)	BENT	847.50	847.50
1	REAR BUMPER INNER PLATE (CENTRE) (N) (ADDITIONAL)	CRACKED	65.00	65.00
			6,070.35	4,997.00
LABOUR				
TO PUTTY & SPRAY PAINTING .			700.00	600.00
TO CHECK REAR WIRING AND REPLACE SENSOR .			80.00	80.00
TO ANTI-RUST.			60.00	30.00
TO REPLACE REAR EXHAUST SILENCER BOX .			80.00	60.00
LABOUR CHARGES .INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK .			600.00	500.00
			1,520.00	1,270.00
GRAND TOTAL			7,590.35	6,267.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/FCI18006216/Ktbq2



Report Ref No. CS/FCI18006216/Ktbq2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.