

2-4-18

King's Auto Spray Paint Pte Ltd
81K160 Sin Ming Drive #05-10
Sin Ming Autocity Singapore 575722

CHIA PETER JOE

Re: Estimate cost for SKT1813D SUZUKI

SUPPLY OF PARTS:

1pc front bumper	Bu \$659.55 ✓
1pc front bumper cover	Ln 29.15 X
1pc front bumper sport lamp	Ln 160.20 X
1pc front bumper sport lamp cover	Ln 40.00 X
1pc front sport lamp cover reflector	Ln 90.00 X
1pc front bumper beam	R 345.00 X
2pc front bumper brackets @ 20	R 40.00 X
2pc front bumper side retainer @ 20	Also R 40.00 X
1pc front Head lamp L/H	CA 480.45 2
1pc front Head lamp lower garnish	Ln 16.00 X
1pc front grille	Ln 320.15 X
1pc front fender L/H	R 346.55 ✓
1pc front fender inner trim	D1 85.80 ✓
10pc front fender inner trim clips @ 3.00	MC 30.00 ✓
1pc front sport rim	PA \$480.00 ✓
	<u>\$3162.85</u>

158

LABOUR:

To check wheel alignment - computerise

80.00 60d

To renew the above mentioned parts

Knocking, cutting, welding & straighten

450d

700.00

650.00 400d

\$4592.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorise
U Lim @ 2150h
Purvey After Paym 4 days