

Sheet1

LC AUTOMOTIVE

BLOCK 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB Singapore 417800
 Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email : chris_chanbebe@hotmail.com

TPAXA.

Vic

MING TEIK COMPANY PTE LTD
 Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

Jm6BMA2A860328064 06th APRIL 2018

Accident date: 03th APRIL 2018

Estimated repair cost for vehicle no: SLA212H MAZDA 3

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Distorted</i>		\$1,331.20 957.40
2	2	Rear Boot Lid Hinges <i>Dist</i>	\$131.20	\$262.40 ✓
3	2	Rear Boot Lid shock absorber <i>new</i>	\$259.50	\$519.00 X
4	1	Rear boot lid emble logo <i>new</i>		\$53.70 ✓
5	2	Rear Boot Lid side reflector <i>cracked</i>	\$445.74	\$891.48 825
6	1	Rear boot lid Mazda logo <i>new</i>		\$35.00 ✓
7	1	Rear boot lid 3 logo <i>new</i>		\$30.00 ✓
8	1	Rear boot lid inner rubber <i>at</i>		\$213.90 ✓
9	1	Rear Boot Lid Inner Lock <i>Distorted</i>		\$266.20 ✓
10	10	Rear Boot Lid Inner Trim board clips <i>new</i>	\$4.20	\$42.00 30
11	1	Rear Boot Lid Inner Trim board <i>Distorted</i>		\$412.60 12040
12	1	Rear Boot Lid inner center rubber <i>new</i>		\$58.00 X
13	2	Rear tail lamp - LED <i>LH at RH cracked</i>	\$2,552.20	\$5,104.40 1699.20
14	2	Rear tail lamp panel <i>Distorted</i>	\$149.50	\$299.00 ✓
15	4	Rear tail lamp clips <i>new</i>	\$5.00	\$20.00 ✓
16	1	Rear end panel <i>Distorted</i>		\$438.70 ✓
17	1	Rear End Panel Top Garnish <i>new</i>		\$223.35 +
	1	Rear Fender-LH <i>Repis</i>		\$950.00 X
	1	Rear Fender Inner Trim Board <i>Distorted</i>		\$425.00 235.60
18	1	Rear Bumper <i>Distorted</i>		\$1,015.10 ✓
19	2	Rear Bumper Side Bracket <i>new</i>	\$68.80	\$137.60 ✓
20	2	Rear Bumper side reflector <i>new</i>	\$58.80	\$117.60 X
	2	Rear bumper towing cover <i>new</i>	\$68.80	\$137.60 X
21	1	Rear Bumper reverse sensor <i>Distorted</i>		\$350.00 ✓

Sheet1

22	1	Rear Bumper number plate	ut		\$50.00 ✓
23	1	Rear Bumper number plate lamp	HN		\$245.90 x
24	8	Rear bumper clips	Ner	\$4.50	\$36.00 ✓
25	1	Rear Bumper reinforcement	Bent		\$423.10 ✓
26	1	rear camera	Damaged		\$500.00 ✓

Rear Windscreen
Rear Windscreen Moulding
Rear Windscreen Sealant

967.10 ut ✓
85.40 Ner ✓
100-60 NEC ✓

Subtotal :-

\$14,588.83

9110.8

7288.64

Labour charges

To Remove & refix cushion

~~\$120.00~~ 60.

To Remove & refix rear windscreen

~~\$150.00~~ x 120.

Gum

\$50.00 x

To Remove & refix reverse Sensor

~~\$100.00~~ 50.

To Remove & refix rear camera

~~\$150.00~~ 50

Tuff kote

~~\$150.00~~ 40.

To Check Wiring System

~~\$80.00~~ 30

Panel beating

~~\$1,400.00~~ 900

Spray painting

~~\$1,400.00~~ 900.

Subtotal :-

\$3,600.00

Total:-

\$18,188.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9438.64
H/S TSK
06 Days.