

ASS. REC. BY:

REF: CS/CTI18006242/Rlq d3br Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)From (Person): Irene Tay of CTI Date/Time: 4/1/18 @ 2.20pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLL 9232H Insured: GBC 9838Bat Workshop m/s Vermogen Ace Tel: 65155230of 1 Bkt Batok Crescent # 04-54/55Policy No: DMCVSN3030861702 Claim No: SNM18D01669C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/03/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^{'wp'}

H.O.D. Endorsement: _____

Date/Time: 9:17am @ 5/1/18 Person Contacted: Paulo Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 9232H - CC3 / LER17008522 / Hlpa3s2 D.O.A: 27/1/17
	GBC 9838B - CC6 / III15012600 / Klyg3g2 D.O.A: 24/7/15
12/1/18 @	1104an Drawn finalized with Paulo Baldoz vs \$3350, 5 days. (Red \$8477.15, 7r/0)

Signature: *Faruk*

REF: CTI

11597K

ASSIGNMENT

From: _____ Date: **5/4/18**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLL 9232H**

at Workshop m/s: **Vermogen Ace**

of: **6 Beni Sector**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SLL 9232H** Yr Regn: **2017 / MAR**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **TOYOTA SIENNA H4 1.5** c.c. **1496**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **89240** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **NHP 1702667354**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ~~Rim~~ / STD A/Rim or

Tyre Size: F: **185/60R15**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **ROADSTONE**

Front Rear

R/Bal. **5** mm R/Bal. **5** mm

L/Bal. **5** mm L/Bal. **5** mm

D.O.A. **28/03/18** D.O.I. **05/04/18**

Survey held at: **Vermogen**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **N/S Rear**

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **1wp**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

RECEIVED 20 SEP 2018

Date/Time File Pass to? : Preli. Report

128/9 : Final Report

Date/Time File Return to? _____

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:	210
Transportation	_____
Photos	_____
Others	_____
TOTAL	210

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format: **NER-TP**

Lump Sum / B.I. (\$): **3350**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18006242/R1qd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 05-04-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 9838B	Veh. Inspected	SLL 9232H
Policy No.	DMCVSN3030861702 (Coverage (\$)	0.00
Claim No.	SNM18D01669C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	05/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/03/2018	Inspection Date	05/04/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018		04 Apr 2018 14:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POLYPET, Co. Reg. No.: 53013965X		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLL9232H	Date of Loss:	28/03/2018 15:00 - :59
Claim Type:	TP / SNM18D01669C02	Policy/Cover Note No.:	DMCVSN3030861702 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC9838B	Policy No. (Claimant):	999995166
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/04/2018]		
Driver/Custodian (Insured):	NALLAIYAN TAMILANBAN (31 / Male), NRIC: G8365243N, Tel: +6594999593		
Adj Asg. Remarks:	NO EST, ASSIGN LKK AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: juan paulo baldoz <paulovermogenace@gmail.com>
Sent: Thursday, 29 March, 2018 3:48 PM
To: Claims Dept of CTI; Joel Goh
Cc: vmg.vermogenace; Eric Glorioso; ezel tejano; Minoko; pila.vermogenace; Edmond Lim jian zhi; Lina Rosli; Luis Tan; Paul
Subject: China Taiping Insurance (Singapore) Pte Ltd : Our Ref: SLL9232H Your Ref: GBC9838B DOA: 28/03/2018 / LOA: INSTITUTION HILL) : PLEASE ARRANGE TP SURVEY
Attachments: SLL9232H 28MAR2018 TP.PDF

Dear Sir / Madam,

Kindly arrange our client's vehicle for pre-repair survey at Vermogen Ace Pte Ltd here at 6 Benoi Sector S(629904). on Monday 02/04/2018.

Please refer to the attachment and revert to us soon.

Dear Officer In-charge,

Please let us know what is the liability?

Kindly check & revert to us as soon as possible.

Thank you.

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Monday, 17 September 2018 11:04 AM
To: Rasul (LKKAuto)
Cc: Shiau Chan (LKKAuto); Asher Sng (LKKAuto); Taufikh (LKKAuto); Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Luis Tan; Paul Tan; Minoko Chan; Pila Ng; Lina Rosli; Desmond Kor; Edmond Lim
Subject: Re: THIRD PARTY FOR FINALISE (LKK)

Dear Rasul,

We confirmed COR @ **\$3,350** bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz
Vermogen Ace Pte Ltd
Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6358 3031
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

On Wed, Aug 15, 2018 at 3:19 PM, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Paulo,

The rear bumper reflector LH and rear fender air duct LH photos not received

And as for the rear rim cover LH price check required 250 reduce to 180

Offer finalise amount at \$ 3,350.00 / 5 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Wednesday, 15 August, 2018 12:25 PM

To: Shiau Chan (LKKAuto)

Cc: Asher Sng (LKKAuto); Taufikh (LKKAuto); Rasul (LKKAuto); Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Luis Tan; Paul Tan

Subject: Re: THIRD PARTY FOR FINALISE (LKK)

Dear Rasul,

Please check and confirm finalise COR @ **\$3,550** bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Thu, Jul 19, 2018 at 5:55 PM, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Paulo Baldoz,

Kindly re-forward the final bill of SLL 9232H to us for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>

Sent: Wednesday, 6 June 2018 2:50 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: THIRD PARTY FOR FINALISE (LKK)

Dear Officer in-charge,

Any update regarding on this cases?

Kindly check and revert to us as soon as possible, and finalise to expedite the claim.

SLR9578D DOA: 26/09/2017 (LONPAC TP)

SLD4407X DOA: 21/12/2017 (LONPAC TP)

SLC2397J DOA: 03/01/2018 (ECICS TP)

SLR3346X DOA: 03/01/2018 (SOMPO TP)

SLD8133X DOA: 22/01/2018 (SOMPO TP)

SLD3727D DOA: 09/02/2018 (SOMPO TP)

SLF8321Y DOA: 08/04/2018 (SOMPO TP)

SKU2046P DOA: 31/01/2018 (SOMPO TP)

SLE6466G DOA: 14/04/2018 (CHINA TAIPING TP)

SLL9232H DOA: 28/03/2018 (CHINA TAIPING TP)

SLC6777U DOA: 08/05/2018 (AXA TP)

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLL9232H
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Chassis No.:	NHP1707067354
Propellant:	Petrol-Electric
Engine No.:	1NZR459355
Motor No.:	H16A00554
Engine Capacity:	1496 cc
Power Rating:	45.0 kW
Maximum Power Output:	73.0 kW (97 bhp)
Maximum Laden Weight:	1765 kg
Unladen Weight:	1380 kg
Year Of Manufacture:	2016
Original Registration Date:	15 Mar 2017
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$49,751.00
COE Expiry Date:	14 Mar 2027
Road Tax Expiry Date:	14 Sep 2018
PARF Eligibility Expiry Date:	14 Mar 2027
Inspection Due Date:	14 Mar 2020
Intended Transfer Date:	02 Apr 2018
CO2 Emission:	92.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$24,708.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2018 11:43
Date Of Accident	28/03/2018 15:45
Exact Location Of Accident	INSTITUTION HILL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL9232H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995166
Cover Note Number	

Driver

Name of Driver	IAN SHI MINGHONG
NRIC No	S9137728D
Date Of Birth	16/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	08/11/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B (ENTTRANCE B) ENTRANCE 6 BENOI SECTOR
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC9838B
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

3/29/2018

19 Institution Hill - Google Maps

Google Maps 19 Institution Hill



Image capture: Oct 2016 © 2016 Google

Singapore

Google, Inc.

Street View - Oct 2016



Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 2

Zasjiduljuman Hill

SKETCH PLAN

- (A) S1192324
- (B) QBC9838B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to attached.

Ian Shi ming hong
S913772817

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:



[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:


[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

20180329

APPENDIX E

SKETCH PLAN



STATEMENT

On 28th march 2018, at about 7.45pm, I, Zan Shi, NRIC 54177220 was travelling along
 Inhibition Hill towards river valley road at the speed of about 15-20km/h, suddenly a van
 CR08 98388 reversed out from a minor road at a fast speed I couldn't react and he ran
 onto my left side of my vehicle to the side of his car asked me to request a Ching and also
 his back right rear was dented after the incident.

SIGNATURE

NAME : Zan Shi
 DATE : ~~28/03/18~~ 29/03/18



SLL9232H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 28/3/2018

Vehicle Reg. No. : SLL9232H
Vehicle Reg. Date: 15-Mar-2017
Make / Model : T. SIENTA HYBRID 1.5G
Engine No. : 1NZR459355
Chassis No. : NHP1707067354

COST OF CLAIMS

Parts Cost / List Items :	\$	<u>10,376.20</u>
Plus/Less <u>25%</u>	\$	<u>2,594.05</u>
Total Cost / List :	\$	<u>7,782.15</u>
Special Nett Items :	\$	<u>590.00</u>
Total Parts Amount :	\$	<u>8,372.15</u>
Total Labour Amount :	\$	<u>3,400.00</u>
Gross Total :	\$	<u>11,772.15</u>
GST % : <u>7%</u>	\$	<u>824.05</u>
Nett Amount :	\$	<u>12,596.20</u>

Surveyor Name and Company :

RASUL CLKK
Date of survey : 05/04/18 @ 1700
Part by Part / (Lump Sum) : 5 days
Resurvey Before Paint / (After Paint)
Authorize/Not Authorize/Without Prejudice
Email : _____
Fax No : _____
HP No : 90010068

[Handwritten Signature]
6/4/18

This claim is handled by : PAULO BALDOZ

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLL9232H
 Vehicle Reg. Date: 15/3/2017
 Make / Model : T. SIENTA HYBRID 1.5G CVT
 Engine No. : 1NZR459355
 Chassis No. : NHP1707067354

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	X SCA	\$ 168.40		
2	1	Rear number plate lamp assy	X SCA	\$ 158.00		
3	1	Rear bumper	SCA	\$ 838.80		
4	1	Rear bumper cover center	X AN	\$ 182.40		
5	1	Rear bumper cover LH	SCA	\$ 195.50		
6	1set	Rear bumper clips	SCA	\$ 25.00		
7	1	Rear bumper side retainer LH	SCA	\$ 82.00		
8	1	Rear bumper bracket LH	SCA	\$ 82.00		
9	1	Rear bumper sponge	X SCA	\$ 98.00		
10	1	Rear bumper reflector LH	X AN	\$ 108.00	X	
11	1	Rear bumper splash shield LH	X	\$ 170.00		
12	1	Tail gate	X	\$ 1,360.00		
13	1	Tail gate lock	X	\$ 246.60		
14	1	Tail gate striker	X	\$ 48.00		
15	1	Tail gate stay LH	X	\$ 320.00		
16	1	Tail gate logo	X	\$ 50.00		
17	1	Tail gate emblem RH	X AN	\$ 59.40		
18	1	Tail gate outer garnish	X	\$ 84.50		
19	1	Tail gate weatherstrip	X	\$ 145.00		
20	1	Tail gate lamp LH	X	\$ 360.00		
21	1	Tail door trim	X	\$ 280.00		
22	1	Tail gate inner side trim LH	X	\$ 750.00		
23	1	Tail lamp LH	SCA	\$ 390.00		
24	1	Tail lamp bracket LH	? X SCA	\$ 90.00	X	
25	1	Tail gate inner handle	X AN	\$ 90.00		
26	1	Antenna sensor	X SCA	\$ 190.00		
27	1	Rear end panel outer	X	\$ 498.20		
28	1	Rear end panel inner	X	\$ 498.20		
29	1	Rear end panel garnish	X	\$ 195.20		
30	1	Rear fender LH	SCA	\$ 1,676.00		
31	1	Rear fender garnish lower LH	X AN	\$ 607.00		
32	1	Rear fender garnish upper LH	X AN	\$ 180.00		
33	1	Rear fender air duct LH	? X SCA	\$ 150.00	X	
34	1	Rear end panel sealant	X AN	\$ 80.00		
35	1	Sundries	SCA	\$ 60.00		10
36	1	Tail gate seal	X AN	\$ 40.00		
37	1	Rear fender sealant	SCA	\$ 80.00		60
38	1	Rear windscreen sealant	SCA	\$ 80.00		40
39	1	Rear rim cover LH	X SCA	\$ 250.00		price? 180
40	0	0				



SLL9232H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 28/3/2018

Vehicle Reg. No. : SLL9232H
Vehicle Reg. Date: 15-Mar-2017
Make / Model : T. SIENTA HYBRID 1.5G
Engine No. : 1NZR459355
Chassis No. : NHP1707067354

COST OF CLAIMS

Parts Cost / List Items : \$ 10,376.20
Plus/Less 25% \$ 2,594.05
Total Cost / List : \$ 7,782.15
Special Nett Items : \$ 590.00
Total Parts Amount : \$ 8,372.15
Total Labour Amount : \$ 3,400.00
Gross Total : \$ 11,772.15
GST % : 7% \$ 824.05
Nett Amount : \$ 12,596.20

Surveyor Name and Company :

RASUL (LKK)
Date of survey : 05/04/18 @ 1100
Part by Part / (Lump Sum) : 5 days
Resurvey Before Paint / (After Paint)
Authorize/Not Authorize/Without Prejudice
Email :
Fax No :
HP No : 90010068

This claim is handled by : PAULO BALDOZ

L/S = 3550

Handwritten calculations:
P = 3547.30
- 25%

2660.48
SN = 360
L = 1430

4450.48
- 20%

3560.38
2466.97
290.00
1430.00

4186.97
20%

3349.58
42,335.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLL9232H
Vehicle Reg. Date: 15/3/2017
Make / Model : T. SIENTA HYBRID 1.5G CVT
Engine No. : 1NZR459355
Chassis No. : NHP1707067354

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	X	\$ 168.40		
2	1	Rear number plate lamp assy	X	\$ 158.00		
3	1	Rear bumper	DE	\$ 838.80		
4	1	Rear bumper cover center	X	\$ 182.40		
5	1	Rear bumper cover LH	SCA	\$ 195.50		
6	1set	Rear bumper clips	nu	\$ 25.00		
7	1	Rear bumper side retainer LH	nu	\$ 82.00		
8	1	Rear bumper bracket LH	nu	\$ 82.00		
9	1	Rear bumper sponge	X	\$ 98.00		
10	*1	Rear bumper reflector LH	SVG X?	\$ 108.00	popoh	
11	1	Rear bumper splash shield LH	X	\$ 170.00		
12	1	Tail gate	X	\$ 1,360.00		
13	1	Tail gate lock	X	\$ 246.60		
14	1	Tail gate striker	X	\$ 48.00		
15	1	Tail gate stay LH	X	\$ 320.00		
16	1	Tail gate logo	X	\$ 50.00		
17	1	Tail gate emblem RH	X	\$ 59.40		
18	1	Tail gate outer garnish	X	\$ 84.50		
19	1	Tail gate weatherstrip	X	\$ 145.00		
20	1	Tail gate lamp LH	X	\$ 360.00		
21	1	Tail door trim	X	\$ 280.00		
22	1	Tail gate inner side trim LH	X	\$ 750.00		
23	1	Tail lamp LH	gto	\$ 390.00		
24	1	Tail lamp bracket LH	? X	\$ 90.00		
25	1	Tail gate inner handle	X	\$ 90.00		
26	1	Antenna sensor	X	\$ 190.00		
27	1	Rear end panel outer	X	\$ 498.20		
28	1	Rear end panel inner	X	\$ 498.20		
29	1	Rear end panel garnish	X	\$ 195.20		
30	1	Rear fender LH	H	\$ 1,676.00		
31	1	Rear fender garnish lower LH	X	\$ 607.00		
32	1	Rear fender garnish upper LH	X	\$ 180.00		
33	*1	Rear fender air duct LH	? X	\$ 150.00	popoh	
34	1	Rear end panel sealant	X	\$ 80.00		
35	1	Sundries	to nu	\$ 60.00	10	
36	1	Tail gate seal	X	\$ 40.00		
37	1	Rear fender sealant	nu	\$ 80.00	60	
38	1	Rear windscreen sealant	Fender Dealer glass	\$ 80.00	40	
39	1	Rear rim cover LH	ASU	\$ 250.00	price?	
40	0	0				

3289.30
256
2466.97

290

P=3547.30
SN = 300

180

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018		04 Apr 2018 14:20 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	POLYPET, Co. Reg. No.: 53013965X								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLL9232H	Date of Loss: 28/03/2018 15:00 - :59 [12 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM18D01669C02	Policy/Cover Note No.: DMCVSN3030861702 (Comprehensive)							
Vehicle Reg. No. (Insured):	GBC9838B	Policy No. (Claimant): 999995166							
		Excess: S\$0.00							
Repairer:	Vermogen Ace Pte Ltd (HQ) Blk B, 44 Benoi Rd, 629904 Pioneer - Tel: 65155230								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/04/2018]								
Driver/Custodian (Insured):	NALLAIYAN TAMILANBAN (31 / Male), NRIC: G8365243N, Tel: +6594999593								
Adj Asg. Remarks:	NO EST, ASSIGN LKK AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL9232H (SNM18D01669C02)**
[GBC9838B]
TP
LCRF PTE LTD
Mar 28 2018 3:00PM
[POLYPET]
Vermogen Ace Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Video			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 11:58	Video - Accident [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:55	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	29/03/18 12:53	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/09/18 11:40	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	28/09/18 11:40	Chassis Number	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	28/09/18 11:40	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
14	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
27	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
28	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
29	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
30	28/09/18 11:40	General View	Load JPG	<input checked="" type="checkbox"/>
31	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	28/09/18 11:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/04/18 14:19	PRS	Load PDF	
2	04/04/18 14:19	OI GIA REPORT	Load PDF	

No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:54	IDENTIFICATION CARD & DRIVING LICENCE <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	29/03/18 12:54	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	29/03/18 12:54	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
4	29/03/18 12:54	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 11:58	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:55	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	29/03/18 12:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)		Thumbnail Print
3	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	29/03/18 12:53	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vermogen Ace Pte Ltd (HQ)		Thumbnail Print
1	29/03/18 12:54	IDENTIFICATION CARD & DRIVING LICENCE		Load JPG <input checked="" type="checkbox"/>
2	29/03/18 12:54	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>
3	29/03/18 12:54	Accident Sketch Plan		Load TIF <input type="checkbox"/>
4	29/03/18 12:54	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006242/R1QD3E2

Date: 01/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3030861702

Claimant Vehicle No: SLL9232H Insured Vehicle No: GBC9838B

Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: SNM18D01669C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9232H**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZR459355

Reg. Date: 15/03/2017 (Man. Year: 2016) Chassis No: NHP1707067354

Colour: Grey Odometer: 89240 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Roadstone 5 mm Rear Left Side: Roadstone 5 mm

Front Right Side: Roadstone 5 mm Rear Right Side: Roadstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,372.15	2,756.97	5,615.18	67.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,430.00	1,970.00	57.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,772.15	4,186.97	7,585.18	64.43
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	11,772.15	3,350.00	8,422.15	71.54
+ GST 7.00/7.00% (S\$)	824.05	234.50	589.55	71.54
Nett Amount (S\$)	12,596.20	3,584.50	9,011.70	71.54

INSPECTION

Date of Assignment: 04/04/2018

Date Inspected: 05/04/2018 Inspected At: Vermogen Ace Pte Ltd (HQ)
1 BUKIT BATOK CRESCENT
#04-54/55 WCEGA PLAZA
SINGAPORE 658064

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
Parts: M1-MPV	TOYOTA SIENNA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL9232H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	168.40 FL	*- FL
2	1		*REAR NUMBER PLATE LAMP ASSY	Serviceable	158.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	838.80 FL	*838.80 FL
4	1		*REAR BUMPER COVER CENTER	Not Necessary	182.40 FL	*- FL
5	1		*REAR BUMPER COVER LH	Scratched	195.50 FL	*195.50 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH	Necessary	82.00 FL	*82.00 FL
8	1		*REAR BUMPER BRACKET LH	Necessary	82.00 FL	*82.00 FL
9	1		*REAR BUMPER SPONGE	Serviceable	98.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	108.00 FL	*- FL
11	1		*REAR BUMPER SPLASH SHIELD LH	Not Necessary	170.00 FL	*- FL
12	1		*TAIL GATE	Not Necessary	1,360.00 FL	*- FL
13	1		*TAIL GATE LOCK	Not Necessary	246.60 FL	*- FL
14	1		*TAIL GATE STRIKER	Not Necessary	48.00 FL	*- FL
15	1		*TAIL GATE STAY LH	Not Necessary	320.00 FL	*- FL
16	1		*TAIL GATE LOGO	Not Necessary	50.00 FL	*- FL
17	1		*TAIL GATE EMBLEM RH	Not Necessary	59.40 FL	*- FL
18	1		*TAIL GATE OUTER GARNISH	Not Necessary	84.50 FL	*- FL
19	1		*TAIL GATE WEATHERSTRIP	Not Necessary	145.00 FL	*- FL
20	1		*TAIL GATE LAMP LH	Not Necessary	360.00 FL	*- FL
21	1		*TAIL DOOR TRIM	Not Necessary	280.00 FL	*- FL
22	1		*TAIL GATE INNER SIDE TRIM LH	Not Necessary	750.00 FL	*- FL
23	1		*TAIL LAMP LH	Broken	390.00 FL	*390.00 FL
24	1		*TAIL LAMP BRACKET LH	Serviceable	90.00 FL	*- FL
25	1		*TAIL GATE INNER HANDLE	Not Necessary	90.00 FL	*- FL
26	1		*ANTENNA SENSOR	Not Necessary	190.00 FL	*- FL
27	1		*REAR END PANEL OUTER	Not Necessary	498.20 FL	*- FL
28	1		*REAR END PANEL INNER	Not Necessary	498.20 FL	*- FL
29	1		*REAR END PANEL GARNISH	Not Necessary	195.20 FL	*- FL
30	1		*REAR FENDER LH	Bent	1,676.00 FL	*1,676.00 FL
31	1		*REAR FENDER GARNISH LOWER LH	Not Necessary	607.00 FL	*- FL
32	1		*REAR FENDER GARNISH UPPER LH	Not Necessary	180.00 FL	*- FL
33	1		*REAR FENDER AIR DUCT LH	Serviceable	150.00 FL	*- FL
34	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*SUNDRIES	Necessary	60.00 FS	*10.00 FS
36	1		*TAIL GATE SEAL	Not Necessary	40.00 FS	*- FS
37	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*60.00 FS
38	1		*REAR FENDER QUARTER GLASS	Necessary	80.00 FS	*40.00 FS
39	1		*REAR RIM COVER LH	Scratched	250.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	10,966.20	3,579.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,594.05	822.33
					Total Parts (\$\$)	8,372.15	2,756.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, RR FENDER LH, RR FENDER GARNISH UPPER LH	New	1,200.00	700.00
2	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
3	TO REMOVE AND REPLACE REVERSE SENSOR	New	150.00	0.00
4	TO REMOVE AND REFIT INNER TRIM, INNET SEAT, TRIM BOARD, TO ASSIST REPAIR	New	200.00	80.00
5	TO RUSTPROOF ACCIDENT REPAIR AREA	New	150.00	40.00
6	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	150.00	0.00
7	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, RR FENDER LH, RR FENDER GARNISH UPPER LH	New	1,200.00	500.00
8	TO REMOVE AND REFIT REAR FENDER QUARTER GLASS	New	250.00	80.00
Gross Labour Cost (S\$)			3,400.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >