

ASS. REC. BY:

REF:

cs/CTI18006248/Acd3

Special Instruction:

Surveyor
Merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

4/4/18 @ 2:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 4647Y

Insured:

SJK 8464R

at Workshop m/s

SK Automobile

Tel:

6789 5155

of

23 Kaki Bkt Ave 4 #03-01

Policy No:

DMPCSN3043611705

Claim No:

SNM18D01684C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/03/2018

CA / REV / REP. / REV 24 HRS 'wpr

H.O.D. Endorsement:

Date/Time:

9:03am @ 5/4/18

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SKA 4647Y - NA / INC 110 22206 / W1

D.O.A 24/10/11

SJK 8464R - X.

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 4647 Yr Regn: 2011, March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Touran cc 1380
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 125326 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVG 2221 T2BW 053512
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 05/04/18
 Survey held at S.K.
 Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Chinn.</u>
<u>16/2</u>	<u>Adrian confirmed L.S. \$5200/- with repairer. (Red 16, 06.5.42, 75%)</u>

RECEIVED 17 FEB 2020

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 5200/-)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18006248/Ard3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 05-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 8464R	Veh. Inspected	SKA 4647Y	
Policy No.	DMPCSN3043611705	Coverage (\$)	0.00	
Claim No.	SNM18D01684C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/03/2018	Inspection Date	05/04/2018	
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		04 Apr 2018 14:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:			
Main Claimant:	SITI RAHUDA BINTE RAHMAN		
Vehicle Reg. No.:	SKA4647Y	Date of Loss:	30/03/2018 00:00 - :59
Claim Type:	TP / SNM18D01684C02	Policy/Cover Note No.:	DMPCSN3043611705
Vehicle Reg. No. (Insured):	SJK8464R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/04/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (04/04/2018): Cancellation of Assignment: SKA4647Y

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

GET A CHEAPER QUOTE NOW!

WWW.DUC.COM[illegible]

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4614H
Vehicle Details	
Vehicle No.:	SKA4647Y
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4L AT TSI 1T32B4
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	CAV258956
Chassis No.:	WVGZZZ1TZBW053512
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,179.00
Original Registration Date:	02 Mar 2011
First Registration Date:	02 Mar 2011
Transfer Count:	1
Actual ARF Paid:	\$19,179.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2021
PARF Rebate Amount:	\$11,507.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$13,868.00
Total Rebate Amount:	\$25,375.00

The information contained herein is correct as at 02 Apr 2018

OK

\$40 800
- 25 375

15 425

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/03/2018 11:10
Date Of Accident	30/03/2018 16:40
Exact Location Of Accident	CIQ JOHOR
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA4647Y
Insured/Policyholder	
Name Of Registered Owner	SITI RAHUDA BINTE RAHMAN
NRIC No	S9034614H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +85-93399469
Alternative Phone No	OTHERS-93399469
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	TOURAN
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098189342
Cover Note Number	
Driver	
Name of Driver	MOHAMED IRAWADI BIN MOHAMED ALI
NRIC No	S8235983D
Date Of Birth	18/11/1982
Occupation	INDOOR
Date Of Driving Pass	04/04/2017
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91444954
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 524B #04-611 PASIR RIS STREET 51 COSTA RIS
 Postcode 512524
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 7

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK8464R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

31 MAR 2018

Policyholder's Signature: 

Date & Time: 10:00 AM

Driver's Signature: 

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature

Singapore 415933

Name: Tel: 67416697 Fax: 67492305

NRIC/PR No.: Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At On 30/03/18, at about 1640hrs, I was travelling along the Malaysia's C1Q after exiting from the custom clearance counter. I was travelling straight when a car SJK 8964R (MITSUBISHI LANCER) exit from one of the custom counter and hit my ^{front} right fender, bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

31 MAR 2018

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Reporting Centre Singapore 415933
Name: Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Accident Sketch Plan Pg. 1



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA	DATE	: 2/4/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SKA4647Y
ADDRESS	: <i>Tanze</i>	MODEL	: VOLKSWAGEN TOURAN
TEL. NO.	:	CHASSIS NO	: <i>WV6Z221T2B4053512</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		<i>undercoverage, ??</i>
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR SIDE MIRROR RH <i>new</i>	1	\$887.00	\$ 887.00
2	FRONT DOOR RH <i>Repair</i>	1	\$2,277.00	\$ 2,277.00
3	FRONT DOOR HINGE RH <i>7</i>	2	\$90.73	\$ 181.46
4	FRONT DOOR CHECKER RH <i>new</i>	1	\$90.50	\$ 90.50
5	FRONT DOOR WEATHERSTRIP RH <i>new</i>	1	\$120.30	\$ 120.30
6	FRONT DOOR INNER LOCK RH	1	\$582.50	\$ 582.50
7	FRONT BUMPER <i>Rehnd</i>	1	\$1,456.00	\$ 1,456.00
8	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$698.00	\$ 698.00
9	FRONT BUMPER SPONGE <i>new</i>	1	\$298.00	\$ 298.00
10	FRONT BUMPER LOWER COVER <i>new</i>	1	\$285.00	\$ 285.00
11	FRONT BUMPER SIDE RETAINER RH <i>new</i>	1	\$112.00	\$ 112.00
12	HEADLAMP RH <i>cash d</i>	1	\$2,124.00	\$ 2,124.00
13	WIPER WASHER TANK <i>Rehnd</i>	1	\$321.00	\$ 321.00

Handwritten notes and marks:
 +
 +
 x
 x
 x
 x
 -
 x
 +
 x
 1045
 215

14	FRONT FENDER INNER PANEL RH <i>Regi</i>	1	\$458.00	\$ 458.00	+
15	FRONT FENDER COWLING RH <i>Rehd</i>	1	\$245.00	\$ 245.00	✓
16	FRONT FENDER GLASS MOULDING RH <i>m</i>	1	\$228.60	\$ 228.60	✓
17	FRONT WHEEL ABSORBER <i>Best</i>	1	\$568.00	\$ 568.00	: 435
18	FRONT WHEEL KUNCKER BEALRING <i>rec</i>	1	\$345.00	\$ 345.00	: 255
19	FRONT KUNCKER ARM <i>Best</i>	1	\$456.00	\$ 456.00	✓
20	FRONT DRIVE SHAFT RH <i>3M</i>	1	\$2,151.00	\$ 2,151.00	+
21	STEERING RACK AND PINION <i>Rec</i>	1	\$2,985.00	\$ 2,985.00	+
22	FRONT LOWER ARM <i>Best</i>	1	\$698.00	\$ 698.00	: 345

499260
449334

TOTAL PRICE \$ 16,399.36
LESS 20% 10. \$ 3,279.87
SUB TOTAL PRICE \$ 13,119.49

11567.36
14,759.42

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT DOOR SEALANT RH <i>Rec m</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT DOOR INNER TRIM BOARD CLIP <i>Rec m</i>	18	\$ 6.50	\$ 117.00	+
3	FRONT BUMPER CLIPS <i>Rec</i>	12	\$ 6.50	\$ 78.00	30
4	REAR FENDER OUTER PROTECTOR CLIP <i>Rec Rec</i>	4	\$ 6.50	\$ 26.00	+
5	REAR FENDER INNER COWLING CLIP <i>Rec</i>	10	\$ 6.50	\$ 65.00	30
6	FRONT WHELL TYRE RH <i>Rec m</i>	1	\$ 480.00	\$ 480.00	+
7	FRONT WHELL RIM RH <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00	500-
8	BRAKE OIL <i>Rec</i>	1	\$ 60.00	\$ 60.00	40

600

TOTAL \$ 2,106.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,200.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	600	
3	TUFF COAT	\$250.00	+	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND FACILITATE REPAIR	\$150.00	+	
6	CONDUCT WATER LEAKAGE TEST	\$180.00	+	
7	TRANFER FRONT DOOR MECHANISM	\$100.00	+	

8	REMOVE & REINSTALL FRONT WINDOW GLASS <i>Fender</i>	\$80.00	40	
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$450.00	220	
10	TO PRESS REAR WHEEL BEARING	\$80.00	x	
11	FOUR WHEEL ALIGNMENT	\$250.00	80	
12	RESET ABS LIGHT	\$380.00	x	

TOTAL

\$4,400.00

1470

TOTAL PARTS COST : \$ 15,225.49
TOTAL LABOUR COST : \$ 4,400.00
TOTAL REPAIR COST : \$ 19,625.49 *21,265.49*

APPROVED DETAILS

EXCESS
NO. OF WORKING DAY:
RE-SURVEY
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

22316.62

Adrian King

total: 6563.34

h/s 05/04/18.

h/s: S21 ✓

05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006248/ACD3N2
Date: 17/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3043611705
Claimant Vehicle No: SKA4647Y Insured Vehicle No: SJK8464R
Date of Loss: 30/03/2018 Nature of Claim: TP Claim No: SNM18D01684C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA4647Y
Make & Model: VOLKSWAGEN TOURAN, 2.0 TSI (A) Engine No: CAV258956
Reg. Date: 02/03/2011 (Man. Year: 2010) Chassis No: WVGZZZ1TZBW053512
Colour: Grey Odometer: 125326 km
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,916.62	5,093.34	12,823.28	71.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	1,470.00	2,930.00	66.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,316.62	6,563.34	15,753.28	70.59
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	22,316.62	5,200.00	17,116.62	76.70
+ GST 7.00/7.00% (S\$)	1,562.16	364.00	1,198.16	76.70
Nett Amount (S\$)	23,878.78	5,564.00	18,314.78	76.70

INSPECTION

Date of Assignment: 04/04/2018
Date Inspected: 05/04/2018 Inspected At: SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
Singapore 415933
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2020)

Parts: M1-MPV VOLKSWAGEN TOURAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA4647Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR SIDE MIRROR RH	Not Necessary	887.00 FL	*- FL
2	1		*FRONT DOOR RH	Repair	2,277.00 FL	*- FL
3	2		*FRONT DOOR HINGE RH	Not Necessary	181.46 FL	*- FL
4	1		*FRONT DOOR CHECKER RH	Not Necessary	90.50 FL	*- FL
5	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	120.30 FL	*- FL
6	1		*FRONT DOOR INNER LOCK RH	Not Necessary	582.50 FL	*- FL
7	1		*FRONT BUMPER	Deformed	1,456.00 FL	*1,456.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	698.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	298.00 FL	*- FL
10	1		*FRONT BUMPER LOWER COVER	Not Necessary	285.00 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	112.00 FL	*112.00 FL
12	1		*HEADLAMP RH	Cracked	2,124.00 FL	*1,045.00 FL
13	1		*WIPER WASHER TANK	Deformed	321.00 FL	*215.00 FL
14	1		*FRONT FENDER INNER PANEL RH	Repair	458.00 FL	*- FL
15	1		*FRONT FENDER COWLING RH	Deformed	245.00 FL	*245.00 FL
16	1		*FRONT FENDER GLASS MOULDING RH	Necessary	228.60 FL	*228.60 FL
17	1		*FRONT WHEEL ABSORBER	Bent	568.00 FL	*435.00 FL
18	1		*FRONT WHEEL KNUCKER BEALRING	Necessary	345.00 FL	*255.00 FL
19	1		*FRONT KNUCKER ARM	Bent	456.00 FL	*456.00 FL
20	1		*FRONT DRIVE SHAFT RH	Not Necessary	2,151.00 FL	*- FL
21	1		*STEERING RACK AND PINION	Not Necessary	2,985.00 FL	*- FL
22	1		*FRONT LOWER ARM	Bent	698.00 FL	*545.00 FL
23	1		*FRONT DOOR SEALANT RH	Not Necessary	80.00 FS	*- FS
24	18		*FRONT DOOR INNER TRIM BOARD CLIP	Not Necessary	117.00 FS	*- FS
25	12		*FRONT BUMPER CLIPS	Necessary	78.00 FS	*30.00 FS
26	4		*REAR FENDER OUTER PROTECTOR CLIP	Not Necessary	26.00 FS	*- FS
27	10		*REAR FENDER INNER COWLING CLIP	Necessary	65.00 FS	*30.00 FS
28	1		*FRONT WHEEL RIM RH	Cut	1,200.00 FS	*500.00 FS
29	1		*BRAKE OIL	Necessary	60.00 FS	*40.00 FS
30	1		*FRONT WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,673.36	5,592.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,756.74	499.26
Total Parts (\$\$)	17,916.62	5,093.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND FACILITATE REPAIR	New	150.00	0.00
6	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
7	TRANFER FRONT DOOR MECHANISM	New	100.00	0.00
8	REMOVE & REINSTALL FRONT FENDER WINDOW GLASS	New	80.00	40.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	450.00	220.00
10	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
11	FOUR WHEEL ALIGNMENT	New	250.00	80.00
12	RESET ABS LIGHT	New	380.00	0.00
Gross Labour Cost (S\$)			4,400.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >