

Surveyor: Meimen ASSIGNMENT (Office)

From (Person): Irene Tan of MSIA Date/Time: 04/04/18 @ 5pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKP 3662E Insured: SLE 98024

at Workshop n/s: Hock Wah Motor Tel: 6441 5655

of Blk 3011 Bedok North Ave 4 # 01-2008

Policy No: MSD/VPCP/17-001915 Claim No: Msc/V/18-00486

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ (Client's Record) D.O.A. 02/04/2018

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:05am @ 5/4/18 Person Contacted: Mavis Vehicle IN /  OUT

Date/Time	Action/Instruction (✓) Estimate
	SKP 3662E - X
	SLE 98024 - X
09/4/18 @ 5.50pm	revised to Irene Tan via Meimen.

MS1W

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKP 3662E

at Workshop m/s: hndclawh

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 70k

ID/C Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GR / PR Seen:  Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

20/9/2007  
Vehicle: IN / OUT

Veh No: SKP 3662E Yr Regn: 9, 07

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Mercedes C200 1796

Colour: black A/C: Insured / Std / NI / NA

Sp. Reading: 135363 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD 2040412A 052404

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM / I /

TOYO / YOKO or Continental

Front R/Bal: 6 mm

Rear R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 2/4/18

D.O.I. 6/4/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 47613

20/4/18 contact L/S @ 4000 with maris.  
(Head 36401, 6716)  
CR seen.  
J. [Signature]  
20/04/2018

RECEIVED 24 APR 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 4

1) 20/4/18 [Signature]

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos

Others

TOTAL

200
10

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 4000



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006250/Uqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-04-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLF 9802U	Veh. Inspected	SKP 3662E
Policy No.	MSD/VPCP/17-001915	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	05/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/04/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006250/Uqd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-04-2018



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2018		04 Apr 2018 17:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G								
Main Claimant:	YUEN KIN CHONG, ID: S1624708A								
Vehicle Reg. No.:	SKP3662E	Date of Loss:	02/04/2018 00:00 - :59 [126 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VPCP/17-001915 Coverage: 19/09/2017 - 18/09/2018						
Vehicle Reg. No. (Insured):	SLF9802U	Policy No. (Claimant):							
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd - bedok (HQ) Blk 3011 Bedok North Avenue 4, #01-2008/2010/2012/2014, 489977 Bedok - Tel: 64415655								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/04/2018]								
Driver/Custodian (Insured):	LIM BENG CHEONG (), NRIC: S7535247F								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 09 Apr 2018

**Preliminary Advice**

Insured Vehicle No	: SLF9802U	Accident Date	: 02/04/2018
TP Vehicle No	: SKP3662E	Assignment Date	: 04/04/2018
Make	: MERCEDES-BENZ C200	Est. Duration of Repair	: 4.00
Date of Inspection	: 06/04/2018		
Inspection At	: HOCK WAH MOTOR WORKSHOP PTE LTD - BEDOK (HQ) BLK 3011 BEDOK NORTH AVENUE 4, #01-2008/2010/2012/2014 SINGAPORE 489977		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,401.00
Revised Amount	:S\$	5,417.00
Check Items (Estimated)	:S\$	3,080.00
Total	:S\$	8,497.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

**CHEAPEST CAR**  
**INSURANCE RENEWAL**



Free roadside assistance

Free claims support

**GET A CHEAPER QUOTE NOW!**

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Citroen Grand C4 Picasso 1.6A EHD1 ETG6 Halogen.



Fully C&C Maintained. High OMV. 5 Years C&C Warranty And Accident Free. 7 Seater Direct Owner StarAd

**PRIME MOTOR & LEASING**  
ICHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES  
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Mercedes-Benz c200

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Mercedes-Benz c200	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Mercedes-Benz C-Class C200K Avantgarde (New 5-yr COE)	\$62,800	\$12,550 /yr	01-Apr-2008	1,796 cc	-	Luxury	Available
C200 Avantgarde, Higher Spec Yet Same 1.8 Litre. AMG Front And Back Bodykit. Viewing By Appointment. Allmotoring.sg								
Posted: 06-Apr-2018 Tags: 2008 Mercedes-Benz C200K, Mercedes-Benz C200K, Mercedes-Benz, C200K, Used Mercedes-Benz								
	Mercedes-Benz C-Class C200K Avantgarde (COE till 10/2027)	\$81,777	\$8,590 /yr	10-Oct-2007	1,796 cc	-	Luxury	Available
Luxurious C200K Avantgarde! New COE, With Affordable Depreciation. Regularly Serviced And Maintained. Nice Car Plate. New Road Tax. Easy Financing. Responsive, Reliable Engine, With Good Ride Comfort,...								
Posted: 01-Apr-2018 Tags: 2007 Mercedes-Benz C200K, Mercedes-Benz C200K, Mercedes-Benz, C200K, Used Mercedes-Benz								
	Mercedes-Benz C-Class C200K Avantgarde (COE till 09/2027)	\$76,800	\$8,100 /yr	26-Sep-2007	1,796 cc	114,000 km	Luxury	Available
Free 6 Month Road Tax And Warranty, \$10k Drive Away, Flawless Interior Condition, One Of The Most Popular Model For Renewal Of COE, All Wear And Tear Replace, Reliable Engine, Too Good To Scrap. 10 Ye...								
Global Carz Pte Ltd Posted: 20-Mar-2018 Tags: 2007 Mercedes-Benz C200K, Mercedes-Benz C200K, Mercedes-Benz, C200K, Used Mercedes-Benz								
	Mercedes-Benz C-Class C200 (New 10-yr COE)	\$61,800	\$6,170 /yr	06-Mar-1998	1,998 cc	280,000 km	Luxury	Available
Low Mileage C200 With Keyless Entry, Come With New 10 Years COE, Very Original Well Kept Condition, Lots Of Parts Change To Ensure The Ride For The Next 10 Years, View And Test To Believe The Well Kep...								
Posted: 02-Mar-2018 Tags: 1998 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz								

Car Buying Car Selling Car Ownership  
Car Aftermarket On The Move Lifestyle



	Mercedes-Benz C-Class C200K (New 10-yr COE)	\$79,800	\$7,970 /yr	14-Feb-2008	1,796 cc	-	Luxury	Available
Very Affordable, Low Monthly At \$800 Plus! Ideal For Renewal Of COE! Extended Warranty Available! High Trade-in! Rare Condition, Powerful & Luxurious Sedan Kept In Tip Top Condition, For You To View A...								
Dickson Automobile Posted: 04-Feb-2018 Tags: 2008 Mercedes-Benz C200K, Mercedes-Benz C200K, Mercedes-Benz, C200K, Used Mercedes-Benz								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page



# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
 BEDOK NORTH AVE 4,  
 #01-2008/10/12 SINGAPORE 489977  
 TEL : 6441 5655 FAX : 6441 5355/6243 8121  
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1624708A  
 YUEN KIN CHONG  
 NO 60 SEA BREEZE AVENUE  
  
 SINGAPORE 487573  
 TEL : FAX :  
 PH : 90733156  
 ATTN :

*Not Authorized  
 Make  
 2/5 \$4020/-  
 4 day.  
 6/4/18  
 Take photo. Attention*

## ESTIMATE BILL

Number : EB00004791  
 Date : 3/4/2018  
 Case No : AD00009647  
 Vehicle No : SKP3662E  
 Chassis : WDD2040412A052464  
 Year of Mfr : 2007  
 Policy No : 5094318989  
 Model : MERCEDES BENZ C  
 200 KOMPRESSOR

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BOOTLID <i>100/3uc 2</i>	1.0	1,550.00	0	1,550.00
2	REAR BOOTLID EMBLEM <i>rec 60</i>	1.0	78.00	0	78.00
3	REAR BOOTLID LOGO <i>rec</i>	1.0	48.00	0	48.00
4	REAR BOOTLID MOUDLING <i>rec</i>	1.0	190.00	0	190.00
5	REAR BOOTLID HINGE LH <i>17</i>	1.0	140.00	0	140.00
6	REAR BOOTLID HINGE RH <i>17</i>	1.0	140.00	0	140.00
7	REAR BOOTLID INNER LOCK <i>17</i>	1.0	280.00	0	280.00
8	REAR BOOTLID RUBBER <i>17</i>	1.0	160.00	0	160.00
9	REAR END PANEL <i>R</i>	1.0	1,180.00	0	1,180.00
10	REAR FENDER LAMP ASSEMBLY LH <i>1 1</i>	1.0	550.00	0	550.00
11	REAR FENDER LAMP ASSEMBLY RH <i>1 1</i>	1.0	550.00	0	550.00
12	REAR BUMPER <i>100/20</i>	1.0	1,350.00	0	1,350.00
13	REAR BUMPER SIDE RETAINER LH <i>rec</i>	1.0	38.00	0	38.00
14	REAR BUMPER SIDE RETAINER RH <i>rec</i>	1.0	38.00	0	38.00
15	REAR BUMPER CENTRE MOULDING <i>rec</i>	1.0	105.00	0	105.00
16	REAR BUMPER MOULDING LH <i>rec</i>	1.0	95.00	0	95.00
17	REAR BUMPER MOULDING RH <i>rec</i>	1.0	95.00	0	95.00
18	REAR BOOTLID INNER GARNISH CLIP LH <i>17</i>	8.0	9.00	0	72.00
19	REAR BOOTLID INNER GARNISH CLIP RH <i>17</i>	8.0	9.00	0	72.00
20	REAR BUMPER REINFORCEMENT <i>R</i>	1.0	640.00	0	640.00
<b>Nett Price - Parts Sub Total</b>					<b>7,371.00</b>
21	REAR NUMBER PLATE <i>34</i>	1.0	30.00	0	30.00
22	REAR NUMBER PLATE HOLDER <i>34</i>	1.0	30.00	0	30.00
23	REAR BUMPER REVERSE SENSOR LH <i>shuf</i>	2.0	140.00	0	280.00
24	REAR BUMPER REVERSE SENSOR RH <i>shuf</i>	2.0	140.00	0	280.00
25	REAR TYRE PANEL - REPAIR	1.0			
<b>Special Nett Price - Parts Sub Total</b>					<b>620.00</b>
<b>Parts Total</b>					<b>7,991.00</b>
26	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
27	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
28	ANTI-RUST COATING	1.0	180.00	0	180.00
29	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
30	WIRING	1.0	80.00	0	80.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

*3849  
 3464.1  
 5044.1*



# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
 BEDOK NORTH AVE 4,  
 #01-2008/10/12 SINGAPORE 489977  
 TEL : 6441 5655 FAX : 6441 5355/6243 8121  
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

**TO :** S1624708A  
 YUEN KIN CHONG  
 NO 60 SEA BREEZE AVENUE

SINGAPORE 487573  
 TEL : FAX :  
 PH : 90733156  
 ATTN :

## ESTIMATE BILL

**Number :** EB00004791  
**Date :** 3/4/2018  
**Case No :** AD00009647  
**Vehicle No :** SKP3662E  
**Chassis:** WDD2040412A052464  
**Year of Mfr** 2007  
**Policy No** 5094318989  
**Model :** MERCEDES BENZ C  
 200 KOMPRESSOR

**Term:**

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<b>Labour 1 Sub Total</b>				2,410.00
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey it on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p> </div>					
SINGAPORE DOLLARS : ELEVEN THOUSAND ONE HUNDRED TWENTY-NINE AND CENTS SEVEN ONLY			<b>Less Excess</b>		0.00
			<b>SUBTOTAL</b>		10,401.00
			GST 7.00%		728.07
			<b>TOTAL</b>		<b>11,129.07</b>

Date of accident : 02/04/2018 12:15 PM. Place : WOODLAND CAUSEWAY > JOHOR BAHRU (SINGAPORE SIDE)

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



\_\_\_\_\_  
 CUSTOMER SIGNATURE

\_\_\_\_\_  
 AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006250/UQD3N2

Date: 25/04/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001915
Claimant Vehicle No :	SKP3662E	Insured Vehicle No :	SLF9802U
Date of Loss:	02/04/2018	Nature of Claim:	TP
		Claim No:	MSCN/18-000486

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKP3662E	Engine No:	27195030955094
Make & Model:	MERCEDES-BENZ C200, 1.8 Kompressor (A)	Chassis No:	WDD2040412A052464
Reg. Date:	21/09/2007 (Man. Year: 2007)	Odometer:	135363 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,991.00	3,784.10	4,206.90	52.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,230.00	1,180.00	48.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,401.00</b>	<b>5,014.10</b>	<b>5,386.90</b>	<b>51.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
(S\$)	10,401.00	4,000.00	6,401.00	61.54
+ GST 7.00/7.00% (S\$)	728.07	280.00	448.07	61.54
<b>Nett Amount (S\$)</b>	<b>11,129.07</b>	<b>4,280.00</b>	<b>6,849.07</b>	<b>61.54</b>

## INSPECTION

Date of Assignment:	04/04/2018	
Date Inspected:	06/04/2018 Inspected At:	Hock Wah Motor Workshop Pte Ltd - bedok (HQ) Blk 3011 Bedok North Avenue 4, #01-2008/2010/2012/2014 Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
<b>Parts:</b> 143	MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKP3662E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount	
1	1	*REAR BOOTLID	Dented/Buckled	1,550.00 F	*1,550.00 FN	
2	1	*REAR BOOTLID EMBLEM	Necessary	78.00 F	*60.00 FN	
3	1	*REAR BOOTLID LOGO	Necessary	48.00 F	*48.00 FN	
4	1	*REAR BOOTLID MOULDING	Necessary	190.00 F	*190.00 FN	
5	1	*REAR BOOTLID HINGE LH	Not Necessary	140.00 F	*- FN	
6	1	*REAR BOOTLID HINGE RH	Not Necessary	140.00 F	*- FN	
7	1	*REAR BOOTLID INNER LOCK	Twisted	280.00 F	*280.00 FN	
8	1	*REAR BOOTLID RUBBER	Not Necessary	160.00 F	*- FN	
9	1	*REAR END PANEL	Repair	1,180.00 F	*- FN	
10	1	*REAR FENDER LAMP ASSEMBLY LH	Not Necessary	550.00 F	*- FN	
11	1	*REAR FENDER LAMP ASSEMBLY RH	Not Necessary	550.00 F	*- FN	
12	1	*REAR BUMPER	Dented/Deformed	1,350.00 F	*1,350.00 FN	
13	1	*REAR BUMPER SIDE RETAINER LH	Necessary	38.00 F	*38.00 FN	
14	1	*REAR BUMPER SIDE RETAINER RH	Necessary	38.00 F	*38.00 FN	
15	1	*REAR BUMPER CENTRE MOULDING	Necessary	105.00 F	*105.00 FN	
16	1	*REAR BUMPER MOULDING LH	Necessary	95.00 F	*95.00 FN	
17	1	*REAR BUMPER MOULDING RH	Necessary	95.00 F	*95.00 FN	
18	8	*REAR BOOTLID INNER GARNISH CLIP LH	Not Necessary	72.00 F	*- FN	
19	8	*REAR BOOTLID INNER GARNISH CLIP RH	Not Necessary	72.00 F	*- FN	
20	1	*REAR BUMPER REINFORCEMENT	Repair	640.00 F	*- FN	
21	1	*REAR NUMBER PLATE	Bent	30.00 FS	*20.00 FS	
22	1	*REAR NUMBER PLATE HOLDER	Bent	30.00 FS	*20.00 FS	
23	1	*REAR BUMPER REVERSE SENSOR LH (2 Pcs)	Shorted (1 Pc only)	280.00 FS	*140.00 FS	
24	1	*REAR BUMPER REVERSE SENSOR RH (2 Pcs)	Shorted (1 Pc only)	280.00 FS	*140.00 FS	
25	1	*REAR TYRE PANEL (NPA)	Repair	0.00 FS	*- FS	
				<b>Sub Total (\$\$)</b>	<b>7,991.00</b>	<b>4,169.00</b>
				- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	384.90
				<b>Total Parts (\$\$)</b>	<b>7,991.00</b>	<b>3,784.10</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,000.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	600.00
3	ANTI-RUST COATING	New	180.00	50.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
5	WIRING	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,410.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >