

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 53300 Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: m-white/red A/C: Insured / Std / NI / NA

Sp.Reading: 78402 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 279361

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 10/4/15

D.O.I. 14/4/15

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	KIV
	Temporary close as not finalise given and KIV
	12/11/14

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

____ S + RS. ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18006260/Ktb	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 05-04-2018	
		Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		SHC 5330D
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		14/04/2015
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/04/2015	Inspection Date	14/04/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5330D -

ROEL

Not Authenticated
1-B.1

Vehicle No.: 90,765.83
 Chassis No.:
 Vehicle Make: 70 97,737.27
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5330D - ROEL
 VF1ABL15AUC279361
 RENAULT
 LATITUDE
 10.04.2015

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>B/K</i> 807.53 ✓
2	1	BUMPER SPOILER FRT	\$	<i>D.V</i> 116.51 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>C.R</i> 253.00 ✓
4	1	BUMPER BRACKET FRT LH	\$	<i>G.M</i> 97.06 +
5	1	BUMPER SUPPORT FRT LH	\$	<i>Out</i> 15.31 +
6	1	BUMPER BRACKET FRT RH	\$	<i>C.R</i> 96.65 ✓
7	1	BUMPER SUPPORT FRT RH	\$	<i>D.V</i> 15.31 ✓
8	1	BUMPER UNDERTRAY FRT	\$	303.09 7
9	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Su</i> 132.83 X
10	1	BUMPER FOG LAMP GRILLE RH	\$	<i>M.V</i> 132.83 ✓
11	1	BUMPER GRILLE LOWER FRT	\$	<i>D.V</i> 171.02 ✓
12	1	BUMPER BEAM FRT	\$	<i>R</i> 585.95 ✓
13	1	RADAIOR GRILLE	\$	<i>D.V</i> 1,094.73 ✓
14	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>na</i> 144.46 ✓
15	1	RADAIOR GRILLE FRAME	\$	<i>C.R</i> 867.79 2
16	1	WIPER RESERVOIR	\$	<i>De</i> 144.67 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>C.R</i> 394.81 2
18	1	BONNET	\$	<i>X</i> 1,244.63 X
19	1	BONNET HINGE LH	\$	<i>R</i> 223.27 X
20	1	BONNET HINGE RH	\$	<i>R</i> 223.27 X
21	1	HEADLALMP LH	\$	759.25 7
22	1	HEADLALMP RH	\$	<i>C.R</i> 759.25 ✓
23	1	FENDER PANEL FRT LH	\$	<i>R</i> 502.46 X
24	1	FENDER PANEL FRT RH	\$	<i>R</i> 502.46 X
25	1	FENDER WHEELARCH FRT LH	\$	<i>Su</i> 89.44 X
26	1	FENDER WHEELARCH FRT RH	\$	<i>D.V</i> 178.74 ✓
27	1	RADIATOR	\$	770.64 7
28	1	A/C CONDENSER	\$	1,295.11 7
TOTAL			\$	11,922.07
10%			\$	1,192.21
			\$	10,729.86

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5330D -**ROEL****Specical Nett**

1SET	RADAI TOR GRILLE FRAME CLIP	\$	<i>Mr</i> 52.00 ✓
1SET	BUMPER CLIP FRT	\$	<i>Mr</i> 66.00 ✓
1SET	BUMPER UNDERTRAY SCREW	\$	2.70 7
1	TOW COVER FRT	\$	<i>Net</i> 14.50 ✓
1SET	RADAI TOR GRILLE SCREW	\$	<i>Mr</i> 16.00 ✓
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>Mr</i> 69.00 ✓
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>Mr</i> 70.00 ✓
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>Mr</i> 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>Mr</i> 30.00 X
4	FRAME FULL SUPPORT PANEL SCREW	\$	<i>Mr</i> 80.00 X
1SET	NUMBER PLATE WITH HOLDER	\$	<i>Mr</i> 140.00 X
1SET	WHEELARCH CLIP LH	\$	<i>Mr</i> 30.50 X
1SET	WHEELARCH CLIP RH	\$	<i>Mr</i> 29.40 ✓

TOTAL	\$	620.10
--------------	-----------	---------------

TOTAL PARTS	\$	11,349.96
--------------------	-----------	------------------

Putty and spray painting of the affected portion.	\$	3,000.00 <i>4401</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>6001</i>
To rust-proofing of the affected areas.	\$	<i>Mr</i> 170.00 X
Towing Fees.	\$	120.00 <i>501</i>
To vacuum, replace, refix and recharge Air - condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>Mr</i> 220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHC 5330D -

ROEL

To remove and refit interior fittings,
trimings, garnish, fittings and other, to
enable repair.

\$

~~ 380.00 X

To check ABS brake efficiency, final
checking and testing.

\$

~~ 380.00 X

TOTAL	\$	4,790.00
--------------	-----------	-----------------

Over All Total	\$	16,139.96
-----------------------	-----------	------------------

< parts by parts > Repair Days

~~10 DAYS~~

4 days

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5330D -**ROEL***Not Authenticated
I.B.I*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5330D - ROEL

VF1ABL15AUC279361

RENAULT

LATITUDE

10.04.2015

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>B/KRA</i> 807.53 ✓
2	1	BUMPER SPOILER FRT	\$	<i>D.I.</i> 116.51 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>CRA</i> 253.00 ✓
4	1	BUMPER BRACKET FRT LH	\$	<i>GPA</i> 97.06 +
5	1	BUMPER SUPPORT FRT LH	\$	<i>D.I.</i> 15.31 +
6	1	BUMPER BRACKET FRT RH	\$	<i>CRA</i> 96.65 —
7	1	BUMPER SUPPORT FRT RH	\$	<i>D.I.</i> 15.31 —
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 303.09 X
9	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 132.83 X
10	1	BUMPER FOG LAMP GRILLE RH	\$	<i>M.I.</i> 132.83 ✓
11	1	BUMPER GRILLE LOWER FRT	\$	<i>D.I.</i> 171.02 ✓
12	1	BUMPER BEAM FRT	\$	<i>R</i> 585.95 ✓
13	1	RADAITOR GRILLE	\$	<i>D.I.</i> 1,094.73 ✓
14	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>M</i> 144.46 ✓
15	1	RADAITOR GRILLE FRAME	\$	<i>CRA</i> 867.79 ✓
16	1	WIPER RESERVOIR	\$	<i>D.I.</i> 144.67 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CRA</i> 394.81 ✓
18	1	BONNET	\$	<i>R</i> 1,244.63 X
19	1	BONNET HINGE LH	\$	<i>R</i> 223.27 X
20	1	BONNET HINGE RH	\$	<i>R</i> 223.27 X
21	1	HEADLALMP LH	\$	<i>SL</i> 759.25 X
22	1	HEADLALMP RH	\$	<i>CRA</i> 759.25 ✓
23	1	FENDER PANEL FRT LH	\$	<i>R</i> 502.46 X
24	1	FENDER PANEL FRT RH	\$	<i>R</i> 502.46 X
25	1	FENDER WHEELARCH FRT LH	\$	<i>SL</i> 89.44 X
26	1	FENDER WHEELARCH FRT RH	\$	<i>D.I.</i> 178.74 ✓
27	1	RADIATOR	\$	<i>SL</i> 770.64 X
28	1	A/C CONDENSER	\$	<i>SL</i> 1,295.11 X

TOTAL	\$	11,922.07
10%	\$	1,192.21
	\$	10,729.86

Specical Nett

1SET	RADAITOR GRILLE FRAME CLIP	\$	<i>Mr</i> 52.00 ✓
1SET	BUMPER CLIP FRT	\$	<i>Mr</i> 66.00 ✓
1SET	BUMPER UNDERTRAY SCREW	\$	<i>nr</i> 2.70 X
1	TOW COVER FRT	\$	<i>Mr</i> 14.50 ✓
1SET	RADAITOR GRILLE SCREW	\$	<i>Mr</i> 16.00 ✓
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>Mr</i> 69.00 ✓
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>Mr</i> 70.00 ✓
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nr</i> 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nr</i> 30.00 X
4	FRAME FULL SUPPORT PANEL SCREW	\$	<i>nr</i> 80.00 X
1SET	NUMBER PLATE WITH HOLDER	\$	<i>Sm</i> 140.00 X
1SET	WHEELARCH CLIP LH	\$	<i>nr</i> 30.50 X
1SET	WHEELARCH CLIP RH	\$	<i>Mr</i> 29.40 ✓

TOTAL \$ 620.10

TOTAL PARTS \$ 11,349.96

Putty and spray painting of the affected portion.	\$	3,000.00 <i>4401</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>6001</i>
To rust-proofing of the affected areas.	\$	<i>nr</i> 170.00 X
Towing Fees.	\$	120.00 <i>501</i>
To vacuum, replace, refix and recharge Air - condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>