

REF: NS/INC18006267/Sgbe2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SHB833H

Yr Regn:

7/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prous 4

C.C. 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

33489

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK133F4703576990

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/3/18

D.O.I.

2/4/18

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 833H

NS/INC12005000/R/K

Date: 12/03/18

Tax/03/18/137

SLS 5507E

-X

Lk

NTUC

Final Fig @ 2142.65 (led @ 6440.85, 75%)

SLS 5507E

RECEIVED 24 APR 2018

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

4

Date/Time, File Return to?

☐

Final Report

Resurvey No. of Trip:

2

Survey Fee:

160

Transportation

) S + RS = \$

Photos

Others

TOTAL

35

195

Report Format:

Lump Sum / I.B.L. (\$) 7P 2142.65

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006267/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-04-2018



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 5507E	Veh. Inspected	SHB 833H
Policy No.	5094617334	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/03/2018	Inspection Date	02/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0989809-002	COMFORT TRANSPORTATION	SH 7032U	SLU 9220U
2	MT/0986682-002	SMRT TAXI PTE LTD	SHF 243P	SLC 1382H
3	MT/0990239-002	COMFORT TRANSPORTATION	SHD 3689C	SLV 2508G
4	MT/0990490-001	COMFORT TRANSPORTATION	SHA 2258K	GZ 3691R
5	MT/0989768-002	CITYCAB PTE LTD	SHA 8769M	FBL 6863A
6	MT/0989478-002	COMFORT TRANSPORTATION	SHA 7625B	FC 1037B
7	MT/0989906-002	COMFORT TRANSPORTATION	SHC 1583S	GBB 557B
8	MT/0989127-002	COMFORT TRANSPORTATION	SHD 4936H	SJR 7916Z
9	MT/0989972-002	COMFORT TRANSPORTATION	SHC 8253Z	FY 4003M
10	MT/0989045-002	CITYCAB PTE LTD	SHA 9241L	SKJ 6237L
11	MT/0968779-002	SMRT BUSES LTD	SMB 1430X	SJG 2543G
12	MT/0988223-002	SMRT TAXIS PTE LTD	SHB 833H	SLS 5507E

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5094617334	JAMITASH & CO	53362636J	GPC	drive CLASSIC	SL55507E	SL55507E	27/09/2017	26/09/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB833H
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8263645
Chassis No.:	JTDKB3FU703576990
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,884.00
Total Rebate Amount:	\$36,634.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2018 15:16
Date Of Accident	28/03/2018 17:35
Exact Location Of Accident	NEW UPPER CHANGI RD
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB833H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	ANG AH LEE
NRIC No	S1523838J
Date Of Birth	27/04/1962
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1980
Driving Experience	37 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	125
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG NEW UPPER CHANGI ROAD (OPPOSITE BEDOK SWIMMING COMPLEX) TOWARDS GEYLANG ROAD. VEHICLES INFRONT STOPPED AND I SLOWED DOWN AND STOPPED AS WELL. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLS5507E HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS5507E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YUSOFF BIN AHMAD
NRIC/Passport Number	S0060368F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

New upper Changi Rd (Opp. Bedok swimming complex)



A-5HB 833H

B - SLS5507E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] 29 Mar 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 29/3/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

NINE

G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB833H
Ref. No : TAX/03/18/2139
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : ANG AH LEE
Type of Accident : HEAD TO REAR
Date / Time of Accident : 28/03/2018 05:33:00 PM
Accident Reported Date / Time : 29/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 28/03/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095294
Special Instruction to ARC, if any :
TOWED \$40 / SLS5507E
Prepared Date : 29/03/2018 03:36:47 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703576990

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,476.00	0.00
Total Material Charges	: 4,361.43	4,361.43
Other Charges	: 560.00	0.00
TOTAL	: 7,411.43	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 29/03/2018 03:58:08 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/03/2018 03:55:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/29/2018 3:56:06 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 7
TO RESPRAY TAIL GATE	378.00	0.00 X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 7
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 50
Total Spray Painting & Panel Beating	1,476.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 Y
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	560.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace R	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓ NEC	No
52462470 30			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace X	No
52462470 20			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace X	No
52462470 10			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace X	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace X	No
52591470 50			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace X	No
52565479 00			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace ✓ CRK	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEC	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace X	No
81581470 10			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Replace ?	No
58398470 50			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace X	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace X	No
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ✓ Defon.	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace X	No
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace X	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace R	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace ✓ NEC	No
75441470 90			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
75442471 30			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace ?	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6563747060			LINER, REAR FENDER, RH	1	135.80	25.00	101.85	Replace	Replace	No
TOTAL MATERIALS								4,259.62	4,259.58	
TOTAL MATERIALS(Discounted)								4,361.43	4,361.43	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

6-4-18 / 11:36


6-4-18 / 15:36

SMRT Accident Vehicle Repair Estimates

2-4-18 / 15:36

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB833H
Ref. No : TAX/03/18/2139
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : ANG AH LEE
Type of Accident : HEAD TO REAR
Date / Time of Accident : 28/03/2018 05:33:00 PM
Accident Reported Date / Time : 29/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 28/03/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095294
Special Instruction to ARC, if any :



TOWED \$40 / SLS5507E Alk P/P
BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianyeang@lkkauto.com HP: 90036121
Prepared Date : 29/03/2018 03:36:47 PM

Recording Camera

Radio Antenna

1st witness

2nd witness

Date

Date

33488

 $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ 1

Supplementary

to Recheck the Supplementary part 11/5/18

33547

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

6-4-2018

Vehicle Return Time:

10:30 am

SMRT staff name:

Page: 4

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703576990

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	400.00
Total Spray Painting Charges	: 1,476.00	350.00
Total Material Charges	: 2,160.12	1,212.65
Other Charges	: 560.00	120.00
TOTAL	: 5,210.12	2,082.65
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 29/03/2018 03:58:08 PM	02/04/2018 03:36:46 PM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/03/2018 03:55:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0160

Invoice No :

Quotation Date : 7/4

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/29/2018 3:56:06 PM

1212.65
+ 400.00
+ 470.00 530

2082.65

Sebastian
16/4/18

Remark : 1) Spray Rear Bumper Reinforcement : + \$100
2) Towing - \$40 , because NTUC.

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	400.00 /
Total Labour	1,014.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	50.00 /
Total Spray Painting & Panel Beating	1,476.00	350.00

(5) Spray Rear Bumper Reinforcement \$100. /

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	40.00 X NTIC
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	560.00	120.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	R 1	423.90	100.00	0.00	Replace	Repair	No	R
5216116010			CLIPS PIECE, FRT & RR BUMPER	✓ 10	1.50	25.00	11.25	Replace	Replace	No	✓
5246247030			PAD, RR BUMPER, RH & LH, 1	X 0	3.80	25.00	0.00	Replace	Not given	No	X
5246247020			PAD, RR BUMPER, RH & LH, 2	X 0	3.80	25.00	0.00	Replace	Not given	No	X
5246247010			PAD, RR BUMPER, RH & LH, 3	X 0	3.80	25.00	0.00	Replace	Not given	No	X
5219147030			SEAL, RR BUMPER ARM, RH & LH	X 0	11.00	25.00	0.00	Replace	Not given	No	X
5259147050			SEAL, RR BUMPER, RH	X 0	85.20	25.00	0.00	Replace	Not given	No	X
5256547900			FILLER, RR BUMPER, RH	✓ 1	119.90	25.00	89.92	Replace	Replace	No	✓
			SENSOR REVERSE	✓ 1	180.00	0.00	180.00	Replace	Replace	No	✓
			PIXEL STICKER	✓ 2	60.00	0.00	120.00	Replace	Replace	No	✓
5202347030			REAR BUMPER REINFORCEMENT	✓ 1	318.80	25.00	239.10	Replace	Replace	No	✓
5257547040			RETAINER, RR BUMPER, RH	X 0	112.70	25.00	0.00	Replace	Not given	No	X
8158147010			LENS & BODY ASSY, RR BUMPER, RH	X 1	486.80	10.00	438.12	Replace	Check	No	X
5839847050			COVER, REAR FLOOR UNDER, RH	X 0	169.50	25.00	0.00	Replace	Not given	No	X
5245347010			GUARD, RR BUMPER, LOWER	✓ 1	558.30	25.00	418.73	Replace	Replace	No	✓
5216947020			COVER, GUARD RR BUMPER LOWER	✓ 1	14.80	25.00	11.10	Replace	Replace	No	✓
5246147010			PAD, RR BUMPER, CTR	X 0	2.20	25.00	0.00	Replace	Not given	No	X
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	X 0	929.60	25.00	0.00	Replace	Not given	No	X
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	R 1	891.20	100.00	0.00	Replace	Repair	No	R
7540348010			EMBLEM SUB-ASSY REAR	✓ 1	46.30	25.00	34.72	Replace	Replace	No	✓
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	✓ 1	52.30	25.00	39.22	Replace	Replace	No	✓
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	✓ 1	52.30	25.00	39.22	Replace	Replace	No	✓
	COMMON		SMRT LOGO	✓ 1	7.80	0.00	7.80	Replace	Replace	No	✓
			STICKER DECAL 6555 8888	✓ 1	21.60	0.00	21.60	Replace	Replace	No	✓
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	X 1	629.80	25.00	472.35	Replace	Check	No	X
	COMMON	4006314	SEALANT SIKAFLEX	X 1	37.00	0.00	37.00	Replace	Check	No	X
6563747060			LINER, REAR FENDER, RH	X 0	135.80	25.00	0.00	Replace	Not given	No	X
TOTAL MATERIALS							2,160.15	1,212.66			
TOTAL MATERIALS(Discounted)							2,160.12	1,212.65			

Added Spare Parts / Material Usage After Surveyor Signed off



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

6-4-18 / 11:36
6-4-18 / 15:36

6/4

Reg. No : SHB833H
Ref. No : TAX/03/18/2139
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : ANG AH LEE
Type of Accident : HEAD TO REAR
Date / Time of Accident : 28/03/2018 05:33:00 PM
Accident Reported Date / Time : 29/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 28/03/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095294
Special Instruction to ARC, if any :



TOWED \$40 / SLS5507E Alk P/P
BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianeang@lkkauto.com HP: 90036121
Prepared Date : 29/03/2018 03:36:47 PM

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 2-4-18

2nd witness

Date

33488

 $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ 1

Supplementary

to Rectify the Supplementary part 11/12/18

33547

LEE SHENG AUTO PTE LTD

6-4-2018

10:30 am

QC 11.04.11.44

Reject RR Bumper

Paint Peel

16.27 PMS

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDK83FU703576990

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,014.00	400.00
Total Spray Painting Charges	1,476.00	350.00
Total Material Charges	2,160.12	1,212.65
Other Charges	560.00	120.00
TOTAL	5,210.12	2,082.65
Lum Sum Total	0.00	0.00
No. of Repair Days	6.00	4.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	29/03/2018 03:58:08 PM	02/04/2018 03:36:46 PM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/03/2018 03:55:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : RN-1804-0160

Invoice No :

Quotation Date : 7/4

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/29/2018 3:56:06 PM

1212.65 /
+ 400.00 /
+ 470.00 530

2082.65 = 2142.65

Remark : 1) Spray Rear Bumper Reinforcement : + \$100
2) Towing - \$40, because NINE.

Sebastian
16/4/18

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	400.00 /
Total Labour	1,014.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	50.00 /
Total Spray Painting & Panel Beating	1,476.00	350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	40.00 X NTK
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	560.00	120.00

8583.20

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	100.00	0.00	Replace	Repair	No <i>R</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <i>N/C</i>
5246247030			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5246247020			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5246247010			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	0.00	Replace	Not given	No <i>X</i>
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	0.00	Replace	Not given	No <i>X</i>
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace	No <i>OKA</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>DRG</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>Not</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No <i>DT</i>
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	0.00	Replace	Not given	No <i>X</i>
8158147010			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	10.00	438.12	Replace	Check	No <i>X</i>
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	0.00	Replace	Not given	No <i>X</i>
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.73	Replace	Replace	No <i>Def</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No <i>Def</i>
5246147010			PAD, RR BUMPER, CTR	1	2.20	25.00	0.00	Replace	Not given	No <i>X</i>
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	0.00	Replace	Not given	No <i>X</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No <i>R</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No <i>✓</i>
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>✓</i>
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>✓</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>✓</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>✓</i>
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Check	No <i>X</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No <i>X</i>
6563747060			LINER, REAR FENDER, RH	1	135.80	25.00	0.00	Replace	Not given	No <i>X</i>
TOTAL MATERIALS								2,160.15	1,212.65	
TOTAL MATERIALS(Discounted)								2,160.12	1,212.65	

Added Spare Parts / Material Usage After Surveyor Signed off



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006267/Sqbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 26-04-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 5507E	Veh. Inspected	SHB 833H
Policy No.	5094617334	Coverage (\$)	0.00
Claim No.	MT/0988223-002	Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKB3FU703576990	Colour	MAROON
Odometer	33484	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/03/2018	Inspection Date	02/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 833H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	CLIPS PIECE, FRT & RR BUMPER (DISC 25%)	NECESSARY	15.00	11.25
1	FILLER RR BUMPER RH (DISC 25%)	CRACKED	119.90	89.92
1	REAR BUMPER REINFORCEMENT (DISC 25%)	DENTED	318.80	239.10
1	GUARD RR BUMPER LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER GUARD RR BUMPER LOWER (DISC 25%)	DEFORMED	14.80	11.10
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	PAD, RR BUMPER RH & LH, 1	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER RH & LH, 2	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER RH & LH, 3	NOT NECESSARY	3.80	-
1	SEAL RR BUMPER ARM RH & LH	NOT NECESSARY	11.00	-
1	SEAL RR BUMPER RH	NOT NECESSARY	85.20	-
1	RETAINER RR BUMPER RH	NOT NECESSARY	112.70	-
1	LENS & BODY ASSY, RR BUMPER, RH	NOT NECESSARY	486.80	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	PAD, RR BUMPER CTR	NOT NECESSARY	2.20	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	NOT NECESSARY	929.60	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	NOT NECESSARY	629.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	LINER, REAR FENDER RH	NOT NECESSARY	135.80	-
1	COVER, RR BUMPER ASSY	TO REPAIR	423.90	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR	891.20	-
			5,433.20	1,212.65

Report Ref No. NS/INC18006267/Sqbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,334.00	480.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,576.00	450.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TOWING CHARGE.		80.00	-
			3,150.00	930.00
	GRAND TOTAL		8,583.20	2,142.65
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,142.65

Report Ref No. NS/INC18006267/Sqbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.