

REF: NS/INC18006268 / Srbn2

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No.

SHB 5737U

Yr Regn:

19/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4

C.C. 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

22733

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK133K4 403577238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/3/18

D.O.I.

3/4/18

Survey held at

SMR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 5737U - X

SKZ 9804X - X

Confirm \$1397.74, 2 days  
Red: \$3029.86, 687

TAX/03/18/2151

Lick

PTMC

SKZ 9804X

RECEIVED 24 APR 2018

Date/Time. File Pass to?



Preli. Report

1) typul



Final Report

Date/Time. File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$

1397.74

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation.

) S + RS SI

Photos

Others

TOTAL

160

35

195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006268/Srb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-04-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 9804X	Veh. Inspected	SHB 5737U
Policy No.	5087784562-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	31/03/2018	Inspection Date	03/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5087784562-01	LIOW FOOK HENG	S1295907I	GPC	drive PREMIUM	SKZ9804X	SKZ9804X	18/02/2018	17/02/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0991340-002	COMFORT TRANSPORTATION PTE LTD	SH 7013A	SJL 3277S
2	MT/0990420-002	COMFORT TRANSPORTATION PTE LTD	SHC 1833X	GBG 6935C
3	MT/0991001-002	COMFORT TRANSPORTATION PTE LTD	SHB 4181D	SJF 4165G
4	MT/0987576-002	SMRT TAXIS	SHB 5490E	SGN 2724A
5	MT/0988974-002	SMRT TAXIS	SHF 474P	SKP 1761R
6	MT/0988606-002	SMRT TAXIS	SHF 287M	SHD 1850R
7	MT/0988375-002	SMRT TAXIS	SHB 5737U	SKZ 9804X
8	MT/0991050-002	COMFORT TRANSPORTATION PTE LTD	SHD 6647D	SLM 4176P
9	MT/0991603-001	COMFORT TRANSPORTATION PTE LTD	SH 9594B	SJF 8421R
10	MT/0989297-002	SMRT TAXIS	SHB 5445L	GZ 8719M
11	MT/0989010-002	SMRT TAXIS	SHB 668T	SLV 3014H
12	MT/0988555-002	SMRT TAXIS	SHB 5515T	SLS 2028R
13	MT/0981124-002	SMRT BUSES	SMB 8039Y	SJC 8146B
14	MT/0991610-001	COMFORT TRANSPORTATION PTE LTD	SHC 8728X	GBG 2031L
15	MT/0991074-002	COMFORT TRANSPORTATION PTE LTD	SHC 2948S	GZ 1977E
16	MT/0990979-002	COMFORT TRANSPORTATION PTE LTD	SHD 6658Y	FBK 791T
17	MT/0990696-002	COMFORT TRANSPORTATION PTE LTD	SHD 4138U	PC 2948Y
18	MT/0990960-002	COMFORT TRANSPORTATION PTE LTD	SHD 4928G	YP 6440T

**Janice Lee (LKKAuto)**

---

**From:** Sebastian Yeang (LKK Auto)  
**Sent:** Monday, April 23, 2018 9:33 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHB5737U  
**Attachments:** SHB\_5737\_U\_ESTIMATE\_REPLY.pdf

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,  
Sebastian | Automotive Assessor  
LKK Auto Consultants  
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]  
Sent: Saturday, 14 April 2018 11:25 AM  
To: Sebastian Yeang (LKK Auto)  
Cc: SUR; CS A Team  
Subject: SHB5737U

Hi Sebastian,

Attached herewith the repair estimate of SHB 5737U having Case No: TAX/03/18/2151.

There is no change to the approved amount of \$1,397.74 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Sent: Friday, 13 April 2018 5:25 PM  
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Subject: Scan Data from FX-D421D6

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	02/04/2018 20:46
Date Of Accident	31/03/2018 22:15
Exact Location Of Accident	JUNCTION OF WOODLANDS AVE 7 AND WOODLANDS AVE 6
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHB5737U
-----------------------------	----------

**Insured/Policyholder**

Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

**Insurance Company**

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

**Driver**

Name of Driver	LIM LEE CHOON ALEX (LIN LICHUN)
NRIC No	S7927522J
Date Of Birth	09/09/1979
Occupation	OUTDOOR
Date Of Driving Pass	29/04/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 07-327  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5  
 Passenger 1 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 2 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 3 NAME: : UNKNOWN  
 GENDER: : FEMALE  
 Passenger 4 NAME: : UNKNOWN  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ9804X  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver LIOW YU SEN, ACER

NRIC/Passport Number

S9227440C

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)





Woodlands Ave 7



A  
B

A - SHB5737V  
B - SKZ9804X

Centre  
Pavilion

Woodlands Ave 6



SKETCH PLAN


Refer to attach


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/3/18 at 10:15pm. I was travelling along Woodlands Ave 7 ~~and~~ and stopped at the extreme right lane at traffic lights was Red, intending to turn into Woodlands Ave 6. when suddenly an Audi SKZ 9804X bumped into our rear loudly. Both me and my passengers were shocked.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5369K
<b>Vehicle Details</b>	
Vehicle No.:	SHB5737U
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8264990
Chassis No.:	JTDKB3FU403577238
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,884.00
<b>Total Rebate Amount:</b>	<b>\$36,634.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Apr 2018

OK

## SMRT Accident Vehicle Repair Estimates

*NTM C*

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5737U  
 Ref. No : TAX/03/18/2151  
 Reg. Date : 19/12/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : LIM LEE CHOON ALEX (LIN LICHUN)  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 31/03/2018 10:50:00 PM  
 Accident Reported Date / Time : 02/04/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095318  
 Special Instruction to ARC, if any :  
 TOWED \$ 40/ SKZ9804X  
 Prepared Date : 02/04/2018 12:03:56 PM


*Sebastian*  
*3/4/18*

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

LKK Auto Consultants hence notify  
 the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU403577238

Mileage :

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	918.00	0.00
Total Material Charges :	1,848.42	1,848.42
Other Charges :	540.00	0.00
<b>TOTAL :</b>	<b>4,151.42</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>0.00</b>	<b>0.00</b>
No. of Repair Days :	5.00	<del>0.00</del>
Prepared / Adjusted By :		2 days
Arc / Surveyor Sign Off Date :	02/04/2018 01:42:49 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/04/2018 01:42:49 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00 300
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 7
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 X
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>540.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>✓ Dttf</i>	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace <i>?</i>	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace <i>?</i>	No
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace <i>x</i>	No
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace <i>x</i>	No
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace <i>x</i>	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace <i>x</i>	No <i>NW</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace <i>?</i>	No
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace <i>x</i>	No
5256647900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace <i>x</i>	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>✓ Defect</i>	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>✓ Conf</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>✓ N/C</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>?</i>	No <i>NW</i>
<b>TOTAL MATERIALS</b>							<b>1,668.45</b>	<b>1,668.42</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>1,848.42</b>	<b>1,848.42</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									





SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68862623

Accident Reporting Number : 68862672


5-4.18/12.16  
5-4.18/16.16

## SMRT Accident Vehicle Repair Estimates

3-4-18/16.36

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5737U  
Ref. No : TAX/03/18/2151  
Reg. Date : 19/12/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : LIM LEE CHOON ALEX (LIN LICHUN)  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 31/03/2018 10:50:00 PM  
Accident Reported Date / Time : 02/04/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian NG  
Vehicle is Towed Back? : Yes  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095318  
Special Instruction to ARC, if any :  
TOWED \$ 40/ SKZ9804X NTUC P/P  
Question mark item photo, BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121  
Prepared Date : 02/04/2018 12:03:56 PM

4760  
6025  
819+97606025 Lim 1310 x 1745  
145+  
150022734  
↓  
1 1 1  
1/4 1/2 3/4 1  
22795

Recording Camera



Radio Antenna



1st witness

3-4-18

Date

3-4-18

2nd witness

Date

QC 5/4/18 12:07 PM

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

5/4/18

Vehicle Return Time:

11:00 AM

SMRT sign

Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403577238

Mileage

0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	845.00	300.00
Total Spray Painting Charges	918.00	200.00
Total Material Charges	1,454.99	867.74
Other Charges	540.00	30.00
<b>TOTAL</b>	<b>3,757.99</b> 4427.6	<b>1,397.74</b>
Lum Sum Total	0.00	0.00
No. of Repair Days	5.00	2.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	02/04/2018 01:42:49 PM	03/04/2018 04:16:31 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/04/2018 01:42:49 PM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0276

Invoice No :

Quotation Date : 12/4

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 4/3/2018 4:20:18 PM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00 ✓	300.00 /
<b>Total Labour</b>	<b>845.00</b>	<b>300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 /
TO RESPRAY BUMPER BEAM	180.00 X	0.00
TO RESPRAY FILLER RR BUMPER LH	180.00 X	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00 X	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>918.00</b>	<b>200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>540.00</b>	<b>30.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	✓ 1	423.90	25.00	317.92	Replace	Replace	No ✓
52576470 40			RETAINER, RR BUMPER, LH	X 1	111.50	25.00	83.63	Replace	Check	No X
52575470 40			RETAINER, RR BUMPER, RH	X 1	112.70	25.00	84.53	Replace	Check	No X
52462470 30			PAD, RR BUMPER, RH & LH, 1	X 0	3.80	25.00	0.00	Replace	Not given	No X
52462470 20			PAD, RR BUMPER, RH & LH, 2	X 0	3.80	25.00	0.00	Replace	Not given	No X
52462470 10			PAD, RR BUMPER, RH & LH, 3	X 0	3.80	25.00	0.00	Replace	Not given	No X
52191470 30			SEAL, RR BUMPER ARM, RH & LH	X 0	11.00	25.00	0.00	Replace	Not given	No X
52023470 30			REAR BUMPER REINFORCEMENT	X 1	318.80	25.00	239.10	Replace	Check	No X
52566479 00			FILLER, RR BUMPER, LH	X 0	119.90	25.00	0.00	Replace	Not given	No X
52565479 00			FILLER, RR BUMPER, RH	X 0	119.90	25.00	0.00	Replace	Not given	No X
52453470 10			GUARD, RR BUMPER, LOWER	✓ 1	558.30	25.00	418.72	Replace	Replace	No ✓
52169470 20			COVER, GUARD RR BUMPER LOWER	✓ 1	14.80	25.00	11.10	Replace	Replace	No ✓
			PIXEL STICKER	✓ 2	60.00	0.00	120.00	Replace	Replace	No ✓
			SENSOR REVERSE	X 1	180.00	0.00	180.00	Replace	Check	No X
TOTAL MATERIALS								1,455.00 867.74		
TOTAL MATERIALS(Discounted)								1,454.99 867.74		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

867.74  
+ 300.00  
+ 230.00  
-----  
1397.74

Substition  
25/4/18



Thatcham escribe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006268/Srbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-05-2018

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 9804X	Veh. Inspected	SHB 5737U
Policy No.	5087784562-01	Coverage (\$)	0.00
Claim No.	MT/0988375-002	Excess (\$)	0.00
Assign From		Assign Date	03/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403577238	Colour	MAROON
Odometer	22733	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	31/03/2018	Inspection Date	03/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5737U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.92
1	GUARD,RR BUMPER LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER GUARD RR BUMPER LOWER (DISC 25%)	CUT	14.80	11.10
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	RETAINER,RR BUMPER,LH	NOT NECESSARY	111.50	-
1	RETAINER,RR BUMPER,RH	NOT NECESSARY	112.70	-
2	PAD,RR BUMPER,RH & LH,1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH,2@\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH,3@\$3.80	NOT NECESSARY	7.60	-
2	SEAL,RR BUMPER ARM,RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	FILLER,RR BUMPER,LH	NOT NECESSARY	119.90	-
1	FILLER,RR BUMPER,RH	NOT NECESSARY	119.90	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
			2,124.60	867.74
<b>LABOUR</b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,045.00	330.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,018.00	200.00
	TOWING CHARGE.		80.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,303.00	530.00
<b>GRAND TOTAL</b>			<b>4,427.60</b>	<b>1,397.74</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,397.74</b>

Report Ref No. NS/INC18006268/Srbn2

YEANG WAI KEEN  
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.