

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 454H**AAD1804-011**

Not Notified
61 Rm @ 5600

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 454H
 KL1LA69RJBB088988
 CHEVROLET
 EPICA 2.0
 31.3.2018
AXA

PART**LIST**

1	1	Rear Bumper	\$	<i>Bike</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>R</i> 239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	<i>Sn</i> 68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>Diy</i> 68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>Ru</i> 119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>R</i> 623.76	✓
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	X
14	1	Bootlid	\$	<i>R</i> 973.00	✓
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00	X
16	1	Bootlid Weatherstrip	\$	<i>Diy</i> <i>1/2</i> 344.28	<i>50% Sn 172.14 Sn</i>
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Ru</i> 120.62	✓
19	1	Bootlid Logo	\$	<i>Ru</i> 138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Ru</i> 119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>CM</i> 217.97	✓
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	X
23	1	Bootlid Reflector LH	\$	<i>CM</i> 128.40	✓
24	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30	X
25	1	Rear Tail Lamp LH	\$	<i>M3 Diy</i> 479.30	✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	✓
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00	X
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44	X
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00	X

Trans-cab Auto Services Pte Ltd**AAD1804-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 454H

30	1	Rear Fender Inner Trim LH	\$	<i>Per</i> 418.44	X
----	---	---------------------------	----	-------------------	---

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Phat</i> 300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00	X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00	X
6	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00	—
7	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00	—
8	1	Rear Exhaust Mounting	\$	<i>nn</i> 10.00	X
9	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00	X
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00	X
11	1	Spare Tyre	\$	<i>nn</i> 180.00	X
12	1	Spare Wheel Rim	\$	<i>nn</i> 126.74	X

TOTAL	\$	1,000.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>600</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>200</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>600</i>
----	--------	------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	<i>600</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1804-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 454H

To transfer of end panel fittings and conduct
water seepage test. \$ *~ 170.00* X

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *~ 380.00* X

To check steering geometry and computer
wheel alignment \$ *~ 220.00* X

\$ **8,150.00**

TOTAL \$ **20,587.43**

(Lump Sum)**Repair Days***10 Days**5 days*