

COMFORTDELGRO ENGINEERING PTE LTD

ACG

DOA: 03.04.18

REPAIR ESTIMATE*

VEHICLE NO : SHB6324X

MAKE : HYUNDAI

MODEL : SONATA

Date : 04.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper <i>X Repair</i>			\$ 538.80
1	Front Bumper Top Bracket - LH <i>X see</i>			\$ 22.40
1	Front Bumper Side Bracket - LH <i>X see</i>			\$ 14.30
1	Front Bumper Protector - LH <i>X see</i>			\$ 29.20
10	Front Bumper clips <i>X see</i>		\$2.20	\$ 22.00
1	Front Fender - LH <i>X Repair</i>			\$ 593.00
1	Front Fender Retainer - LH <i>X see</i>			\$ 9.20
SUB TOTAL				\$ 1,228.90
LESS 20%				245.78
DISCOUNTED TOTAL				\$ 983.12
				\$ 0.00
Labour Charge				
Panel Beating				\$ 400.00 ²⁰⁰
Spray Painting Charge				\$ 400.00 ³⁶⁰
Tuff Kote				\$ 100.00 ^{X see}
TOTAL LABOUR				\$ 900.00
ESTIMATE TOTAL				\$ 1,883.12

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kahin 16/4/18
4/4/18 1305hrs
2 Days
4/1

LKK Auto
 the Repa
 • To resur
 • To displa
 • This prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary terms must be resurveyed and is subject to final approval from insurance Company

Acknowledg
 Signature
 Date

Alfa Repair p lot