

ASS. REC. BY:

REF: CS/CNB18006287/STbez

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Muhammad Asyraf of CNB Date/Time: 07/03/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QX 620H Insured:

at Workshop m/s SMRT Tel:

of 60 Woodlands Ind Park #4

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	QX 620H - x
9/4/18	Sent assessment & photo
	Man Hour : 35.
	Submit report
	Report attention to Asyraf.
	Attn. Asyraf

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No.

Qx 6204

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Sylphy 2.0L

C.C.

Colour

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

No Display

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN15BAG 11Z0210039

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Fallon

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/6/18

Survey held at

215 Sy Kadet Dr

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 9 MAY 2018

Date/Time: File Pass to?

1) Ato Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation.

) \$ - RS. \$

) Photos

) Others

TOTAL

280

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF18006287/Stb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 05-04-2018



Code : SPF

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 620H
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From MUHAMMAD ASYRAF	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date
Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Monday, 2 April, 2018 10:29 AM
To: Muhammad Asyraf ANUAR (CNB)
Cc: Sylvester QUAH (CNB); Shirlene YEO (CNB); assignments; Olivia Lau (LKKAuto)
Subject: RE: Quotation for 2 CNB vehicle assessments

Hi Mr. Asyraf,

The particular of the personnel for clearance on the following date are as below:-

1st Vehicle

Vehicle Number : QX620H
Make & Model : NISSAN / SYLPHY 2.0L CVT ABS D/AB 2WD 4DR
Location : SMRT
Date : **2 April 2018**
Surveyor name : Yeang Wai Keen
FIN Number : G6623944L
Vehicle Number : GBA 4927X
Contact Number : 9003 6121

2nd Vehicle

Vehicle Number : QX1141S
Make & Model : LF SONATA 2.0 GLS A/T
Location : Police Cantonment Complex
Date : **3 April 2018**
Surveyor name : Xing Guo Qiang
NRIC Number : S7977793E
Vehicle Number : GBC 6569Y
Contact Number : 8288 0282

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Asyraf ANUAR (CNB) [mailto:Muhammad_Asyraf_ANUAR@cnb.gov.sg]
Sent: Monday, 26 March 2018 11:24 AM
To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Cc: Sylvester QUAH (CNB) <Sylvester_QUAH@cnb.gov.sg>; Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: Quotation for 2 CNB vehicle assessments

Hi Celine

As spoken, kindly submit the particular of the personnel for clearance on the following date.

1st Vehicle

Vehicle Number : QX620H
Make & Model : NISSAN / SYLPHY 2.0L CVT ABS D/AB 2WD 4DR
Location : SMRT
Date : **2 April 2018**
Surveyor name :
NRIC Number :
Vehicle Number :
Contact Number :

2nd Vehicle

Vehicle Number : QX1141S
Make & Model : LF SONATA 2.0 GLS A/T
Location : Police Cantonment Complex
Date : **3 April 2018**
Surveyor name :
NRIC Number :
Vehicle Number :
Contact Number :

Beside the quotation given by our vendor, is there any document do you need to assess on the vehicle?

Thank you.

Muhammad Asyraf Bin Anuar
Logistics, Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6627 | FAX: (65) 6224 3204



Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB [fb.com/CNB.DrugFreeSG](https://www.facebook.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://www.instagram.com/cnb.drugfreesg)

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]

Sent: Friday, 9 March, 2018 10:35 AM

To: Muhammad Asyraf ANUAR (CNB) <Muhammad_Asyraf_ANUAR@cnb.gov.sg>

Cc: Sylvester QUAH (CNB) <Sylvester_QUAH@cnb.gov.sg>; Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: Quotation for 2 CNB vehicle assessments

Dear Mr. Asyraf,

Please be informed that our fee charge is \$280.00 (before GST) per vehicle which we are providing same services and rates to SPF.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto)

Sent: Thursday, 8 March 2018 9:42 AM

To: Muhammad Asyraf ANUAR (CNB) <Muhammad_Asyraf_ANUAR@cnb.gov.sg>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Cc: Sylvester QUAH (CNB) <Sylvester_QUAH@cnb.gov.sg>; Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Quotation for 2 CNB vehicle assessments

Hi Mr. Asyraf,

Thank you for the call. We will get back to you soon.

Celine – please

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Muhammad Asyraf ANUAR (CNB) [mailto:Muhammad_Asyraf_ANUAR@cnb.gov.sg]

Sent: Wednesday, 7 March, 2018 7:17 PM

To: assessments@lkkauto.com

Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Sylvester QUAH (CNB) <Sylvester_QUAH@cnb.gov.sg>; Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>

Subject: Quotation for 2 CNB vehicle assessments

Dear Sir / Madam

As spoken, we understand that your firm is providing vehicle assessments and third party claim services for SPF. We hope that you can extend the services and rates to us too.

Please assist to provide us quotations for the 2 assessments on the following CNB vehicles with details as attached and shown below. Please note that this is not a confirmation of services.

1st Vehicle

Vehicle Number : QX620H

Make & Model : NISSAN / SYLPHY 2.0L CVT ABS D/AB 2WD 4DR

Location of vehicle : SMRT

2nd Vehicle

Vehicle Number : QX1141S

Make & Model : LF SONATA 2.0 GLS A/T

Location : Police Cantonment Complex

Thanks and Regards

Muhammad Asyraf Bin Anuar
Logistics, Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6627 | FAX: (65) 6224 3204



Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB [fb.com/CNB.DrugFreeSG](https://www.facebook.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://www.instagram.com/cnb.drugfreesg)

Denise Tay (LKKAuto)

From: Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>
Sent: Tuesday, 8 May 2018 6:14 PM
To: Denise Tay (LKKAuto); Muhammad Asyraf ANUAR (CNB)
Cc: Sylvester QUAH (CNB); Celine Fong (LKKAuto); assignments; Olivia Lau (LKKAuto)
Subject: RE: Quotation for 2 CNB vehicle assessments

Message Classification: Restricted

Hi Denise

Yes, pls submit the e-invoices for both vehicles and attention to Asyraf. Thanks

Shirlene Yeo (Ms)
Manager, Logistics Unit
Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6626



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Tuesday, 8 May, 2018 6:03 PM

To: Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>; Muhammad Asyraf ANUAR (CNB)

<Muhammad_Asyraf_ANUAR@cnb.gov.sg>

Cc: Sylvester QUAH (CNB) <Sylvester_QUAH@cnb.gov.sg>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: Quotation for 2 CNB vehicle assessments

Dear Shirlene,

No, can I submit? We will prepared the invoice is needed.

How about QX620H?

Best Regards,

Denise Tay | Case Handler



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	CAR	UNIT	INTEL OPS	Reference No.
VEH NO:	QX 620 H	REPAIR TYPE:	ACCIDENT			0620/CNB.4W/17/11/01
VEH MAKE/MODEL:	NISSAN SYLPHY 2.0L					

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
Scope Of Repairs						
1.1	Front Bonnet		1		0.00	0.00
1.2	Bonnet Hinge Left & Right		2		0.00	0.00
1.3	Bonnet Lock Catch Assy.		1		0.00	0.00
1.4	Bonnet Liner & Trim		1		0.00	0.00
1.5	Bonnet Front Chrome Strip		1		0.00	0.00
1.6	Front Fender RH		1		0.00	0.00
1.7	Front Fender Liner RH		1		0.00	0.00
1.8	Clips For Fender Liner		10		0.00	0.00
1.9	Front Bumper		1		0.00	0.00
1.10	Front Bumper Retainer Left & Right		2		0.00	0.00
1.11	Front Number Plate Holder		1		0.00	0.00
1.12	Front Number Plate		1		0.00	0.00
1.13	Front Grille Chrome		1		0.00	0.00
1.14	Clips For Front Grille Chrome		8		0.00	0.00
1.15	Radiator Assy		1		0.00	0.00
1.16	Radiator Upper Hose		1		0.00	0.00
1.17	Radiator Lower Hose		1		0.00	0.00
1.18	Radiator Expansion Tank		1		0.00	0.00
1.19	Radiator Fan Crowling		1		0.00	0.00
1.20	Radiator Fan Motor Assy		1		0.00	0.00
1.21	Radiator Fan Blades		1		0.00	0.00
1.22	Air Con Condenser Assy		1		0.00	0.00
1.23	Engine Top Cover		1		0.00	0.00
1.24	Wiper Water Tank		1		0.00	0.00
1.25	Air In-let Hose		1		0.00	0.00
1.26	Head Lamp Assy LH		1		0.00	0.00
1.27	Head Lamp Assy RH		1		0.00	0.00
Additional Services						
2.1	Coolant	\$50.00	1	0%	50.00	50.00
2.2	Air Con Gas	\$50.00	1	0%	50.00	50.00
Remarks:					Parts Total:	\$ 100.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
Scope Of Repairs				
1.1	Front Bonnet :	6	8	0.00
	Remove & Replace Bonnet			
	Remove & Replace Bonnet Hinges LH & RH			
	Remove & Replace Bonnet Lock Catch Assy			
	Remove & Replace Bonnet Liner & Trimmings			
	Replace Bonnet Front Chrome Strip			
1.2	Front Fender RH :		4.5	0.00
	Remove & Replace Front Fender RH			
	Remove & Replace Front Fender Liner RH			
	Remove & Replace Front Fender Liner Clips			
1.3	Front Bumper :	5	8	0.00
	Remove & Replace Front Bumper			
	Remove & Replace Front Bumper Retainer LH & RH			
	Remove & Replace Front Number Plate & Holder			
	Remove & Replace Front Chrome Grille			
1.4	Radiator & Air Con Condenser Assy :	7	8	0.00
	Remove & Replace Radiator Unit			
	Remove & Replace Radiator Upper & Lower Hose			
	Remove & Replace Radiator Expansion Tank			
	Remove & Replace Radiator Fan Crowling			
	Remove & Replace Radiator Fan & Motor			
	Remove & Replace Air Con Condenser Unit			
	Re-fill Coolant to Radiator Unit			
	Re-Fill Air Con Gas to Condenser Unit			
	Re-Wiring For Radiator Fan Motor			
1.5	Head Lamps LH & RH	2	2	0.00
	Remove & Replace Head Lamps LH & RH			
	Re-Wiring For Head Lamps Units			
1.6	Others	0.5	2	0.00
	Remove & Replace Engine Top Cover			
	Remove & Replace Wiper Water Tank			
	Remove & Replace Air In-let Hose			
1.7	Spary Painting	10	12	0.00
	To apply Primer Coating For New Fender RH, Bonnet & Front Bumper			
	To Spary Paint New Fender RH, Bonnet & Front Bumper			
SUB-TOTAL			43	0.00
Additional Services				
2.1	Towing Service From Station to Workshop (SOR 8)	138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)	44.10	1	44.10
SUB-TOTAL			2	182.70
Labour Total:				\$ 182.70

Registration No. QX 620H

S/N	ITEM DESCRIPTION	PARTS			TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP		
1	MATERIALS					
1.1	Front Bonnet	1	Bent	\$0.00	\$0.00	
1.2	Bonnet Hinge Left & Right	2	Bent	\$0.00	\$0.00	
1.3	Bonnet Lock Catch Assy	1	Damage	\$0.00	\$0.00	
1.4	Bonnet Liner & Trim	1	Torn	\$0.00	\$0.00	
1.5	Bonnet Front Chrome Strip	1	Missing	\$0.00	\$0.00	
1.6	Front Fender RH	1	Bent	\$0.00	\$0.00	
1.7	Front fender Liner RH	1	Deformed	\$0.00	\$0.00	
1.8	Clips For Fender Linder	10	Necessary	\$0.00	\$0.00	
1.9	Front Bumper	1	Deformed	\$0.00	\$0.00	
1.10	Front Bumper Retainer Left & Right	2	Necessary	\$0.00	\$0.00	
1.11	Front Number plate Holder	1	Crack	\$0.00	\$0.00	
1.12	Front Number plate	1	Crack	\$0.00	\$0.00	
1.13	Front Grille Chrome	1	Missing	\$0.00	\$0.00	
1.14	Clips For Front Gille Chrome	8	Necessary	\$0.00	\$0.00	
1.15	Radiator Assy	1	Bent	\$0.00	\$0.00	
1.16	Radiator Upper Hose	1	Bent	\$0.00	\$0.00	
1.17	Radiator Lower Hose	1	Unconfirm	\$0.00	\$0.00	
1.18	Radiator Expansive Tank	1	Dent	\$0.00	\$0.00	
1.19	Radiator Fan Crowling	1	Unconfirm	\$0.00	\$0.00	
1.20	Radiator Fan Motor Assy	1	Unconfirm	\$0.00	\$0.00	
1.21	Radiator Fan Blades	1	Unconfirm	\$0.00	\$0.00	
1.22	Air Con Condenser Assy	1	Damage	\$0.00	\$0.00	

1.23	Engine Top Cover	1		Crack	\$0.00	\$0.00
1.24	Wiper Water Tank	1		Not Necessary	\$0.00	\$0.00
1.25	Air In-let Hose	1		Crack	\$0.00	\$0.00
1.26	Head Lamp Assy LH	1		Crack	\$0.00	\$0.00
1.27	Head Lamp Assy RH	1		Crack	\$0.00	\$0.00
	SCOPE OF REPAIRS					
1.1	Front Bonnet:					6
	Remove & Replace Bonnet					
	Remove & Replace Bonnet Hinges LH & RH					
	Remove & Replace Bonnet Lock Catch Assy					
	Remove & Replace Bonnet Liner & Trimmings					4.5
	Replace Vbonnet Front Chrome Strip					
1.2	Front Fender RH:					
	Remove & Replace Front Fender RH					
	Remove & Replace Front Fender Liner RH					5
	Remove & Replace Front Fender Liner Clips					
1.3	Front Bumper:					
	Remove & Replace Front Bumper					
	Remove & Replace Front Bumper Retainer LH & RH					
	Remove & Replace Front number Plate & Holder					7
	Remove & Replace Front Chrome Grille					
1.4	Radiator & Air Con Condenser Assy:					
	Remove & Replace Radiator Unit					
	Remove & Replace Radiator Upper & Lower Hose					
	Remove & Replace Radiator Expansion Tank					
	Remove and Replace Radiator Fan Crowling					
	Remove and Replace Radiator Fan & Motor					
	Remove & Replace Air Con Condenser Unit					
	Re-fill Coolant to Radiator Unit					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CENTRAL NARCOTICS BUREAU			Ref : CS/CNB18006287/Stbe2	
CORPORATE SERVICES DIVISION BLK B, POLICE CANTONMENT COMPLEX 393 NEW BRIDGE ROAD SINGAPORE 088763			Date : 15-05-2018	
ATTN : MUHAMMAD ASYRAF			Code : CNB	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		QX 620H
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From MUHAMMAD ASYRAF		Assign Date		07/03/2018
2. Vehicle Particulars & Condition				
Make & Model		NISSAN SYLPHY 2.0 L		c.c 0
Engine No.		HIDDEN		Year of Reg.
Chassis No.		JN1BBAG11Z0210059		Colour BROWN
Odometer		-		Steering IN ORDER
Brakes		IN ORDER		Modification NIL
General		FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	FALKEN	6 mm
	L/H Front Tyre	195/60 R16	FALKEN	6 mm
	R/H Rear Tyre	195/60 R16	FALKEN	6 mm
	L/H Rear Tyre	195/60 R16	FALKEN	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		Inspection Date 06/04/2018		
Survey held at		2B SUNGEI KADUT DR		
Repairer		SMRT AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				



Registration No. QX 620H

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bonnet	1	Bent	\$0.00	\$0.00	
1.2	Bonnet Hinge Left & Right	2	Bent	\$0.00	\$0.00	
1.3	Bonnet Lock Catch Assy	1	Damage	\$0.00	\$0.00	
1.4	Bonnet Liner & Trim	1	Torn	\$0.00	\$0.00	
1.5	Bonnet Front Chrome Strip	1	Missing	\$0.00	\$0.00	
1.6	Front Fender RH	1	Bent	\$0.00	\$0.00	
1.7	Front fender Liner RH	1	Deformed	\$0.00	\$0.00	
1.8	Clips For Fender Linder	10	Necessary	\$0.00	\$0.00	
1.9	Front Bumper	1	Deformed	\$0.00	\$0.00	
1.10	Front Bumper Retainer Left & Right	2	Necessary	\$0.00	\$0.00	
1.11	Front Number plate Holder	1	Crack	\$0.00	\$0.00	
1.12	Front Number plate	1	Crack	\$0.00	\$0.00	
1.13	Front Grille Chrome	1	Missing	\$0.00	\$0.00	
1.14	Clips For Front Gille Chrome	8	Necessary	\$0.00	\$0.00	
1.15	Radiator Assy	1	Bent	\$0.00	\$0.00	
1.16	Radiator Upper Hose	1	Bent	\$0.00	\$0.00	
1.17	Radiator Lower Hose	1	Unconfirm	\$0.00	\$0.00	
1.18	Radiator Expansive Tank	1	Dent	\$0.00	\$0.00	
1.19	Radiator Fan Crowling	1	Unconfirm	\$0.00	\$0.00	
1.20	Radiator Fan Motor Assy	1	Unconfirm	\$0.00	\$0.00	
1.21	Radiator Fan Blades	1	Unconfirm	\$0.00	\$0.00	
1.22	Air Con Condenser Assy	1	Damage	\$0.00	\$0.00	
1.23	Engine Top Cover	1	Crack	\$0.00	\$0.00	
1.24	Wiper Water Tank	1	Not Necessary	\$0.00	\$0.00	
1.25	Air In-let Hose	1	Crack	\$0.00	\$0.00	
1.26	Head Lamp Assy LH	1	Crack	\$0.00	\$0.00	
1.27	Head Lamp Assy RH	1	Crack	\$0.00	\$0.00	

	SCOPE OF REPAIRS					
1.1	Front Bonnet:					6
	Remove & Replace Bonnet					
	Remove & Replace Bonnet Hinges LH & RH					
	Remove & Replace Bonnet Lock Catch Assy					
	Remove & Replace Bonnet Liner & Trimmings					
	Replace Vbonnet Front Chrome Strip					4.5
1.2	Front Fender RH:					
	Remove & Replace Front Fender RH					
	Remove & Replace Front Fender Liner RH					
	Remove & Replace Front Fender Liner Clips					5
1.3	Front Bumper:					
	Remove & Replace Front Bumper					
	Remove & Replace Front Bumper Retainer LH & RH					
	Remove & Replace Front number Plate & Holder					
	Remove & Replace Front Chrome Grille					7
1.4	Radiator & Air Con Condenser Assy:					
	Remove & Replace Radiator Unit					
	Remove & Replace Radiator Upper & Lower Hose					
	Remove & Replace Radiator Expansion Tank					
	Remove and Replace Radiator Fan Crowling					
	Remove and Replace Radiator Fan & Motor					
	Remove & Replace Air Con Condenser Unit					
	Re-fill Coolant to Radiator Unit					
	Re-fill Air Con Gas to condenser Unit					
	Re-Wiring For Radiator Fan Motor					2
1.5	Headlamps LH & RH					
	Remove & Replace Headlamps LH & RH					
	Re- Wiring for head lamps units					0.5
1.6	Others					
	Remove & Replace Engine Top Cover					
	Remove & Replace Wiper Water Tank					
	Remove & Replace Airr-in-let Hose					10
1.7	Spray Painting					

	To apply Primer Coating for New Fender RH, Bonnet & Front Bumper					
	To Spray Paint New Fender RH, Bonnet & Front Bumper					
COSTING		TOTAL PARTS COST		\$0.00		
		TOTAL MAN-HOUR				35

Registration No. QX 620H

Vehicle Inspected By

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.