

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SMB339J

Ref. No

BUS/06/17/5018

Reg. Date

01/01/1900

Vehicle Type

BUS -12M

Make

MAN

Model

MAN

Name of Driver

Lai Koon Siung

Type of Accident

SIDE SWIPE

Date / Time of Accident

11/06/2017 06:09:00 PM

Accident Reported Date / Time :

12/06/2017 12:00:00 AM

Surveyor is Required?

: Yes

Survey by

AIG

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued?

Accident Repair Job Card No

Special Instruction to ARC, if any :

RIGHT CENTER PORTION.

TP: SLN8979H

Prepared Date

: 13/06/2017 05:45:14 PM



Sebastian. 5/4/18. - Lup Sun Repair. - Photo After Paint. LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Rapairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage :

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

0

3-10-15.

Total Labout Charges : 2,120.00 0.00

Total Spray Painting Charges : 1,200.00 0.00

 Total Material Charges
 : 2,596.07
 2,596.07

 Other Charges
 : 0.00
 0.00

 TOTAL
 : 5,916.07
 0.00

 Lum Sum Total
 : 0.00
 0.00

 No. of Repair Days
 : 4.00
 0.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date : 03/04/2018 08:20:40 AM 01/01/1900 12:00:00 AM

8

Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/06/2017 08:52:27 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

the Reparent of the following:

- A before latter by penting
- A server that it during resurces
- A server with a burner resurces
- A server with a burner bush
- A server with the server bush
- A server with the server and
- A server with the ser

BUS/06/17/5018 Page: 2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	0.00 1570			
Total Labour	2,120.00	0.00			

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	0.00 10 62
Total Spray Painting & Panel Beating	1,200.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

BUS/06/17/5018 Page:

3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
	COMMO N	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace NEC	No
A01001- CW568		6009987	RH SIDE PANEL R6	1	1,776.80	10.00	1,599.12	Replace	Replace R	No
A01001- CW567		6009988	RH SIDE PANEL R7	1	885.50	10.00	796.95	Replace	Replace R	No
TOTAL MATERIALS 2,596.0							2,596.07	2,596.07		
TOTAL MATERIALS(Discounted)							2,596.07 2,596.07			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

BUS/06/17/5018 Page: 4