

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
143 Cecil Street #01-01 GB Building
069542

Attention : Motor Claim Department
Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000051

Date : 04/04/2018
Vehicle Num. : SLN 6384L (LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 03/04/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER <i>- Cant</i>	550.00	445.2
3.	1	FRONT LH FENDER <i>- Bul</i>	950.00	
3.	1	FRONT BUMPER RETAINER LH <i>- McC</i>	250.00	92.3
List TotalS\$:			1,750.00	
25.00% Discount S\$:			437.50	
			1,312.50	

1.	1	SPECIAL NETT ITEMS :		
2.	1	FRONT BUMPER CLIP <i>- /</i>	50.00	30
2.	1	FRONT FENDER HYBRID EMBLEM <i>- / McC</i>	100.00	30
Special Nett Total S\$:			150.00	
LABOUR :				
TO LABOUR FOR REMOVING & REPAIRS THE FRT LH FENDER, FRT BUMPER & FRT ACCIDENT AFFECTED AREAS.			550.00	350
TO PUTTY & SPRAY PAINT THE FRT BUMPER, FRT LH FENDER & AFFECTED AREAS,			550.00	400
Labour Total S\$:			1,100.00	

E. & O.E.

Total S\$: 2,562.50

for WORLD AUTO PTE LTD

3 Days.
Unpsum Repairs.
After repair photos.
Gino Qiang - 8288 0282
04/4/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: