



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party - AXA
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Lkk 210 pm

Not Authorized
11 Day 8?
Recovery After Paving
4-5 days

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 TAILGATE	1 PC	1,088.00	✓
2 TAILGATE HINGE LH - CHECK PRICE	1 PC	0.00	X
3 TAILGATE HINGE RH - CHECK PRICE	1 PC	0.00	✓
4 TAILGATE ABSORBER LH	1 PC	90.00	✓
5 TAILGATE ABSORBER RH	1 PC	90.00	X
6 TAILGATE INNER LOCK - CHECK PRICE	1 PC	0.00	?
7 TAILGATE INNER LOCK CATCH	1 PC	13.00	X
8 TAILGATE RUBBER (AT BODY) - CHECK PRICE	1 PC	0.00	?
9 TAILGATE INNER TRIMBOARD - CHECK PRICE	1 PC	0.00	?
10 TAILGATE EMBLEM WITH CTR OUTER GARNISH ASSY - CHECK PRICE	1 PC	0.00	X
11 TAILGATE LOGO (CARENS) LH - CHECK PRICE	1 PC	0.00	✓
12 TAILGATE LOGO (CVVT) RH - CHECK PRICE	1 PC	0.00	✓
13 TAILGATE LOGO (2.0) RH - CHECK PRICE	1 PC	0.00	✓
14 TAILGATE LOGO (CYCLE CARRIAGE) RH - CHECK PRICE	1 PC	0.00	✓
15 TAILGATE LOGO (ELITE) - CHECK PRICE	1 PC	0.00	✓
16 REAR BUMPER	1 PC	501.00	✓
17 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE	1 PC	0.00	X
18 REAR BUMPER SIDE RETAINERS RH - CHECK PRICE	1 PC	0.00	X
19 REAR BUMPER CLIPS	12 PC	24.00	✓
20 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	422.00	?
21 REAR BUMPER SPONGE - CHECK PRICE	1 PC	0.00	?
22 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	✓
23 REAR END PANEL CHECK PRICE	1 PC	0.00	?
24 REAR END PANEL TOP GARNISH - CHECK PRICE	1 PC	0.00	?
25 TAILAMP LH	1 PC	357.00	X
26 TAILAMP RH	1 PC	357.00	✓
27 TAILAMP CLIPS	6 PC	12.00	X
		3,068.00	
	Less 10%	306.80	2,761.20



Special Nett

28 REVERSE SENSOR	1 SET	200.00	X
29 REVERSE CAMERA - CHECK PRICE	1 PC	0.00	X
30 NUMBER PLATE	1 PC	35.00	X
31 INNER SEAL	1 PC	40.00	205m
32 WINDSCREEN SEALANT	1 PC	40.00	✓
		315.00	315.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: **MC0912984**
Date: 04 Apr 2018
Policy No: SII7V08573
Veh Reg No: **SJQ8090D**
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
LABOUR			
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
34 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
35 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	601 X
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	280.00	601
37 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	601
38 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	501
39 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	301
40 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,REAR BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	5001
41 TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT WITH BRACKET,TAILAMP PANEL,SPARE TYRE PANEL.	1 PC	900.00	5001
		2,460.00	2,460.00
Total			S\$ 5,536.20
Add GST @ 7%			387.53
Total Amount Payable			S\$ 5,923.73

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY THREE AND CENTS SEVENTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE