



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

PC 4873 R

Parts	(a) Cost / List Price Items	_____
	Plus/Less _____	_____
	Total of Cost / List	=====
	(b) Nett Price Items	\$ 4,367.90
	Less 10%	\$ 436.79
	Total of Nett Item	\$ 3,931.11
	(c) Special Nett Items	\$ 265.00
Total Parts Cost		\$ 4,196.11
Labour		\$ 3,110.00
Total		\$ 7,306.11

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **PC 4873 R**
Make & Model : **NISSAN NV350**
Chassis No : **JN1MC2E26Z0006646**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen sealant	1	\$50.00	S.N 40V <i>ur</i>	
2	Reverse sensor	2	\$200.00	S.N <i>slant</i>	
3	Rear bumper	1	\$690.60	N <i>ur</i>	
4	Rear bumper clip	10	\$35.00	N <i>ur</i>	
5	Rear bumper side retainer LH	1	\$22.10	N <i>ur</i>	
6	Rear bumper side retainer RH	1	\$22.10	N <i>ur</i>	
7	Tail door	1	\$2,264.60	N <i>ur</i>	
8	Tail door lock	1	\$363.10	N <i>ur</i>	
9	Tail door emblem	1	\$66.40	N <i>ur</i>	
10	Wording "NV350"	1	\$110.10	N <i>ur</i>	
11	Wording "URVAN"	1	\$65.50	N <i>ur</i>	
12	Tail door sticker "70km/h"	1	\$15.00	S.N <i>ur</i>	
13	Tail end panel - inner	1	\$464.20	N <i>ur</i>	
14	Tail end panel - outer	1	\$264.20	N <i>ur</i>	
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **PC 4873 R** Submit By : **Carmen Lim**
Make & Model : **NISSAN NV350** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$1,200.00	600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	30
4	To tuff coat	\$150.00	40
5	To remove & refit reverse sensor	\$120.00	60
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
7	To remove & refit rear windscreen.	\$120.00	100
8	To transfer boot mechanism to new boot	\$120.00	60
9.	To do anti-rust	800	150

Noted
LKS Rep
AP
Pain
Hbb Auto
KMG
Gwdays
5/4/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.