



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EW2244U

Mr Aw Nguan Seng
2 Jalan Kerayong
Singapore 759300
Mobile: 97232244

Vehicle & Document Information
WIP No 22542
Reg No/Reg Date EW2244U / 11/03/2016
Date In/Mileage / 0
Chassis No WDD1179422N246610
Engine No 27091030721612
Make/Model MB/MB CLA 180 SHOOTING BRAKE (X117) "URB
Colour/Trim 026 650 Calcit Whit/ 046 651 DINAMICA/AR

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	04/04/2018/ 14:44	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100455585 // 04/04/2018 DRIVE IN/EXCESS : 04/04/2018 // TP VEH NO SJV3920R EQ INS DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				960 1200.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				600 750.00
A BPIRES RESPRAY REAR BUMPER			0.10	✓ 380.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.				✓ 120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				
M REAR BASIC MOUNTING FOR BUMPER	1.00	115.84	00.00	? 115.84
M REAR BUMPER LOWER	1.00	209.96	00.00	sub 209.96
M REAR BUMPER	1.00	1438.22	00.00	del 1438.22
M REAR CROSS MEMBER	1.00	559.63	00.00	? 559.63

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Tan Jun 97495749
30/4/18 @ 1545
03 days
siv@lkhaut.com
Resurvey before part

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
112, 6771 4353 HP: 9186 5109 Fax: 6872 1272
yikchanhoe.yik@cyclecarriage.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary survey must be resurveyed and is subject to final approval from insurance company

Confirmed & accepted by

Authorized signatory and company stamp

Nett 4,773.65
7% GST on 4773.65 334.16
Total Payable 5,107.81

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS