

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC1654X

MAKE : HYUNDAI

MODEL : i40

Date: 05.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X rep.</i>			\$ 603.60
10	Rear Bumper clips @ \$2.20 <i>X</i>			\$ 22.00
	SUB TOTAL			\$ 625.60
	LESS 20%			125.12
	DISCOUNTED TOTAL			\$ 500.48
1	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70 Nett
				\$ 135.70
	Labour Charge			<i>100</i>
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 570.00
	ESTIMATE TOTAL			\$ 1,206.18

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1

LKK Auto Consultants hence notify the Repairer. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*16/4/16**5/4/16 1326**2 Pys**4**After Repair pld*