

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6932 K

1 pc	Rear bumper <i>X/14/12</i>	\$	696.00
1 pc	Rear bumper n/s side bracket <i>X</i>	\$	29.00
1pc	Rear n/s fender <i>X/14/12</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>X</i>	\$	120.00
1 pc	Rear windscree moulding <i>X</i>	\$	87.00
1 pc	Rear n/s door <i>/</i>	\$	791.00
1 pc	n/s wheel cover <i>/</i>	\$	116.00
		\$	3,044.00
Less 10%		\$	304.40
		\$	2,739.60

S/NETT

1 set	Rear n/s fender inner shield clips <i>X</i>	\$	28.00
1 set	Rear bumper clips <i>/</i>	\$	48.00
1 pc	rear n/s fender sticker <i>/</i>	\$	60.00
1 pc	n/s door sticker <i>/</i>	\$	100.00

Sundry	\$	50.00 20
To check wheel alignment	\$	80.00 x
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To dismantle and refit the inner component of rear n/s door into new shell door	\$	150.00 50
To dismantle and refit the rear windscreen	\$	120.00 x
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of same	\$	900.00 600
To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper	\$	800.00 720
To apply rustproofing on the repaired and replaced panels.	\$	150.00 50
		<hr/>
		\$ 5,405.60

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Signature:

Date:

Kehz 10/11/18
5/4/8 1515hr
3 Days
P/P
Dehu Prit pl