

Surveyor
M. Lim

REF: C33 / msh17021004 / R196-1

Special Instructions:

YS: \$ 5200.00

From (Person): Onhia Nyuk Rui of msh Date/Time: 02042018
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Automax Survey

Workshop: Eng Soon.

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: SKW 903T Insured: GBF 2585K

at Workshop m/s Eng Soon Painting
of Blk 4393J Woodlands Rd Yew Tee

Policy No: 29006429MKE Claim No: 535302

Sum Insured: Excess:

Make of Veh: D.O.A. 31102017

(Client's Record)

09.04.2018 (Monday) @ 4pm

Do Not Timelike
H.O.D. Enforcement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)

Date/Time: 08/6/18 Submit Final Fig 2150, 4 days (Red \$ 3050, 59 %; Original 7 days)

Date/Time	Action/Instruction
	PR3 & Paper Survey done by Sebastian (refer to the file)
	No. 52 Tulas Crescent Singapore 638731 (Mr. Hong - 9366 7783)
	SKW 903T - C33 / msh17021004 / 53602
	GBF 2585K - X
	Rasul, PLS see my remarks

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 08 JUN 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 08/6/18 File Pass to trust

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

N/S	O/S

8/6/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021004/qb-1

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBF 2585K	Veh. Inspected	SKW 903T
Policy No.		Coverage (\$)	0.00
Claim No.	535302	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/10/2017	Inspection Date	09/04/2018
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 2 April, 2018 10:55 AM
To: Chhia Nyuk Pui
Cc: assignments; litigation@bonniekwok.com
Subject: RE: Your ref: BK.18346.18. st. Our ref: 535302 (OIV: GBF2585K)

Dear Ms Chhia,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui [mailto:NyukPui_Chhia@sg.msig-asia.com]
Sent: Monday, 2 April 2018 10:42 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; litigation@bonniekwok.com
Subject: FW: Your ref: BK.18346.18. st. Our ref: 535302 (OIV: GBF2585K)

Dear Veron

Good morning.

Please **confirm re-survey appointment** - 9 April 2018 at 4.00 p.m.

Thank you.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Monday, April 02, 2018 10:38 AM
To: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Subject: Re: Your ref: BK.18346.18. st. Our ref: 535302 (OIV: GBF2585K)

Without Prejudice

Hi Ms. Chhia,

Kindly have your surveyor attend at No. 52 Tuas Crescent Singapore 638731 on 9 April 2018 at 4.00 p.m. for the re-survey of our client's vehicle.

You may contact Mr. Chong Wei Ming at 93667783.

Kindly ensure that your surveyor attends punctually.

Kindly let us know which surveyor you have appointed so that we may inform our client accordingly.

Please let us have your offer of settlement as soon as possible.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 17:15 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DIETHELM MARINEDIESEL PTE LTD, Co. Reg. No.: 200919137E								
Main Claimant:	YUM FONG TRADING COMPANY PTE. LTD., Co. Reg. No.: 200704916W								
Vehicle Reg. No.:	SKW903T	Date of Loss:	31/10/2017 00:00 - :59 [85 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 535302	Policy/Cover Note No.:	2900642BMKC (Comprehensive) Coverage: 22/08/2017 - 21/08/2018						
Vehicle Reg. No. (Insured):	GBF2585K	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Soon Painting Services (HQ) 3933 WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 04/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (02/04/2018): Report Send Back Alerts - SKW903T (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-260, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110002J

Billing To: Yum Fong Trading Company Pte Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP17100016

Date: 08 DEC 2016

Vehicle no: SKW 903 T

Model: MITSUBISHI LANCER EX 2.0 GT

ITEM	DESCRIPTION	AMOUNT
1	Date of inspection : 11 November 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 650.00
2	Photography Services Develop photographs Storage of digital photographs	
3	To submit report by hand.	
4	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 650.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-260, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP17100016

Date : 08 DEC 2016

*Yum Fong Trading Company Pte Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969*

**THIRD PARTY SURVEY
ACCIDENT OCCURED ON 31 October 2017**

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

11 November 2017 with regard to the above matter.
SKW 903 T

1. VEHICLE PARTICULARS

Registration No : SKW 903 T
Model : MITSUBISHI LANCER EX 2.0 GT
Year / Capacity : 2010 / 1998 cc
Chassis No : JMYSNCY4AAU000334

Engine No : 4B11DG2043
Mileage : 169 440 KM
Colour : Metallic White

2. TYRES CONDITION

	<u>Size</u>	<u>Make</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	235/40/R18	Yokohama	9.00 mm	Sport
REAR O/S	235/40/R18	Yokohama	9.00 mm	Sport
FRONT N/S	235/40/R18	Yokohama	9.00 mm	Sport
REAR N/S	235/40/R18	Yokohama	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Front & side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<u>Nett Items</u>				
1 pc	Front bumper face R	bent	\$ 737.00	\$ 737.00
1 pc	Front bumper side retainer - RH ✓ NEC	damaged	\$ 41.00	\$ 41.00
12 pcs	Front bumper side retainer rivets ✓ NEC	necessary	\$ 36.00	\$ 36.00
10 pcs	Front bumper clips ✓ NEC	necessary	\$ 30.00	\$ 30.00
1 pc	Front bumper badge ✓ NEC	damaged	\$ 37.00	\$ 37.00
1 pc	Front fender - RH R	bent	\$ 479.00	\$ 479.00
1 pc	Front fender splash shield X R	bent	\$ 107.00	\$ 107.00
8 pcs	Front fender splash shield clips X R	necessary	\$ 24.00	\$ 24.00
1 pc	Side mirror housing assy ✓ DMG	grazed/deformed	\$ 779.70	\$ 779.70
1 pc	Front knuckle arm - RH X	bent	\$ 320.00	\$ 320.00
1 pc	Front lower arm X	bent	\$ 239.00	\$ 239.00
1 pc	Front wheel bearing kit X	damaged	\$ 134.00	\$ 134.00
1 pc	Front wheel bearing hub X	bent	\$ 240.00	\$ 240.00
1 pc	Front absorber X	bent	\$ 480.00	\$ 480.00
1 pc	Front absorber mounting X	bent	\$ 106.00	\$ 106.00
1 pc	Front absorber mounting bush X	damaged	\$ 22.00	\$ 22.00
Parts Sub-Total			\$ 3,791.70	\$ 3,791.70
Discount 10.00%			\$ 758.34	\$ 758.34
			\$ 3,033.36	\$ 3,033.36

Vehicle Number : SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<u>Special Nett Items</u>				
1 pc	Rim Assembly (Sport) X R	damaged	\$ 650.00	\$ 650.00
Special Nett Sub-Total			\$ 650.00	\$ 650.00
Spare Parts Total			\$ 3,683.36	\$ 3,683.36

923.70
- 10%
831.33

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------

Spare Parts Total of \$ 3,683.36 \$ 3,683.36

1	Towing	\$ 120.00	\$ 120.00 X Δ
2	To check wiring system	\$ 80.00	\$ 80.00 40 ✓
3	To buff coat affected areas	\$ 180.00	\$ 150.00 40 X Δ
4	To remove and refix front undercarriage	\$ 350.00	\$ 320.00 X
5	To check and adjust computer wheel alignment (before & after)	\$ 200.00	\$ 180.00 ✓ 600
6	To respray affected areas	\$ 1,000.00	\$ 800.00 600
7	To renew damaged parts, straighten & repair front support panel, front fender inner panel & aligned all parts	\$ 1,400.00	\$ 1,200.00 600

Total 7,013.36 6,513.36

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 5,200.00

Fong Kok Hing
Qualified Appraiser



Parts \$ 831.33
Labour \$ 1400.00

2231.33
Lump Sum - 20%

1785.06

Total \$ 1800 @ 4 days

7302 55

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677978
Tel: 6760 6271

M/s Yum Fong trading Company P/L
c/o M/s Eng Soon Painting Services
Block 4 Yew Tee Ind Est 393-J
Woodlands Road
Singapore 677969

Date: 8 December 2016

Dear Sir,

Date of accident : 31/10/2017
Final repair bill to SKW 903 T

To Supply,

Lump Sum repairs recommended By the surveyor	\$5,200.00
Total	\$5,200.00

Dollars : FIVE THOUSAND AND TWO HUNDRED ONLY

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 8879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Yum Fong Trading Company Pte Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP17100016

Date: 08 DEC 2016

Vehicle no: SKW 903 T

Model : MITSUBISHI LANCER EX 2.0 GT

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 11 November 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 650.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 650.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 8879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP17100016

Date: 08 DEC 2016

*Yum Fong Trading Company Pte Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969*

**THIRD PARTY SURVEY
ACCIDENT OCCURED ON 31 October 2017**

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 11 November 2017 with regard to the above matter.
We have carried out a physical inspection on the said SKW 903 T
We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No :	SKW 903 T	Engine No :	4B11DG2043
Model :	MITSUBISHI LANCER EX 2.0 GT	Mileage :	169 440 KM
Year / Capacity :	2010 / 1998 cc	Colour :	Metallic White
Chassis No :	JMYSNCY4AAU000334		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	235/40/R18	Yokohama	9.00 mm	Sport
REAR O/S	235/40/R18	Yokohama	9.00 mm	Sport
FRONT N/S	235/40/R18	Yokohama	9.00 mm	Sport
REAR N/S	235/40/R18	Yokohama	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 8879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front & side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number: SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

Nett Items

1 pc	Front bumper face	bent	\$ 737.00	\$ 737.00
1 pc	Front bumper side retainer - RH	damaged	\$ 41.00	\$ 41.00
12 pcs	Front bumper side retainer rivets	necessary	\$ 36.00	\$ 36.00
10 pcs	Front bumper clips	necessary	\$ 30.00	\$ 30.00
1 pc	Front bumper badge	damaged	\$ 37.00	\$ 37.00
1 pc	Front fender - RH	bent	\$ 479.00	\$ 479.00
1 pc	Front fender splash shield	bent	\$ 107.00	\$ 107.00
8 pcs	Front fender splash shield clips	necessary	\$ 24.00	\$ 24.00
1 pc	Side mirror housing assy	grazed/deformed	\$ 779.70	\$ 779.70
1 pc	Front knuckle arm - RH	bent	\$ 320.00	\$ 320.00
1 pc	Front lower arm	bent	\$ 239.00	\$ 239.00
1 pc	Front wheel bearing kit	damaged	\$ 134.00	\$ 134.00
1 pc	Front wheel bearing hup	bent	\$ 240.00	\$ 240.00
1 pc	Front absorber	bent	\$ 460.00	\$ 460.00
1 pc	Front absorber mounting	bent	\$ 106.00	\$ 106.00
1 pc	Front absorber mounting bush	damaged	\$ 22.00	\$ 22.00

Parts Sub-Total	\$ 3,791.70	\$ 3,791.70
Discount 10.00%	\$ 758.34	\$ 758.34
	\$ 3,033.36	\$ 3,033.36

Vehicle Number: SKW 903 T

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

Special Nett Items

1 pc	Rim Assembly (Sport)	damaged	\$ 650.00	\$ 650.00
Special Nett Sub-Total			\$ 650.00	\$ 650.00
Spare Parts Total			\$ 3,683.36	\$ 3,683.36

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

Spare Parts Total c/f \$ 3,683.36 \$ 3,683.36

1	Towing	\$ 120.00	\$ 120.00 X ⁿ
2	To check wiring system	\$ 80.00	\$ 60.00 30 Δ
3	To buff coat affected areas	\$ 180.00	\$ 150.00 X Δ
4	To remove and refix front undercarriage	\$ 350.00	\$ 320.00 90 Δ
5	To check and adjust computer wheel alignment (before & after)	\$ 200.00	\$ 180.00 60 Δ
6	To respray affected areas	\$ 1,000.00	800.00 500
7	To renew damaged parts, straighten & repair front support panel, front fender inner panel & aligned all parts	\$ 1,400.00	1,200.00 400

Total 7,013.36 1080
6,513.36

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 5,200.00

Fong Kok Heng
Qualified Appraiser



1636.83
1080.00
2716.83
20%
2173.46
43-2150
4 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2017 09:57
Date Of Accident	31/10/2017 08:35
Exact Location Of Accident	21 TUAS AVE 13 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW903T
Insured/Policyholder	
Name Of Registered Owner	YUM FONG TRADING COMPANY PTE. LTD.
Co Reg No	200704916W
Email Address	ALEXCHONG.YUMFONG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68623848

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 2.0M
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076182712-01
Cover Note Number	

Driver

Name of Driver	CHONG WEI MING
NRIC No	S9019140C
Date Of Birth	31/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	29/11/2010
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93667783
Fax Number	
Contact Number	OFFICE-68623848
Email Address	ALEXCHONG.YUMFONG@GMAIL.COM

Address	BLK 788C WOODLANDS CRESCENT #11-176
Postcode	733788
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED - VEH B REVERSED AND HIT MY VEH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GBF2585K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HANAPI BIN AHMAD
NRIC/Passport Number	S1492472H
Contact Number	92383455
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/10/17, My Car was parked stationary at 21 Tuas Ave 13, inside the parking lot.

The Lorry of GBF2585K had reversed and hit my car, causing damages to my side tender, (driverside), side mirror (driver side) and driver's door.

The road is wet after rain, rain had stop. the sky is cleared.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/11/2017

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FORM 1 (Rev 01/2017) VI

1000 hrs.

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/11/2017


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1000Hrs.



8.35am

On 30/10/17

GBF 2585K Had
Reversed into SKW903T
at Tuas Ave 13 Carpark.
Driver of GBF 2585K
Admit at fault and
Willing to pay Damages

Hanapi Bin Ahmad
81492472H

Grand Millennium Kuala Lumpur
160 Jalan Bukit Bintang, 55100 Kuala Lumpur
T+60 3 2117 4888 F+60 3 2142 1441

A handwritten signature in black ink, appearing to be "Hanapi Bin Ahmad".

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	01 Nov 2017		02 Nov 2017 17:15 Edit Adj Rpt	S\$2,150.00 Edit Estimates	S\$2,150.00 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DIETHELM MARINEDIESEL PTE LTD, Co. Reg. No.: 200919137E								
Main Claimant:	YUM FONG TRADING COMPANY PTE. LTD., Co. Reg. No.: 200704916W								
Vehicle Reg. No.:	SKW903T	Date of Loss:	31/10/2017 00:00 - :59 [85 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 535302	Policy/Cover Note No.:	29006428MKC (Comprehensive) Coverage: 22/08/2017 - 21/08/2018						
Vehicle Reg. No. (Insured):	GBF2585K	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Soon Painting Services (HQ) 3931 WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (10/05/2018): Alert - Adj Mandate Revoked - SKW903T - Claim Handler: Chhia Nyuk Pul MSIG_SG (02/04/2018): Report Send Back Alerts - SKW903T (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKW903T (535302)**
[GBF2585K]

TP













































YUM FONG TRADING COMPANY PTE. LTD.

Oct 31 2017 12:00AM

[DIETHELM MARINEDIESEL PTE LTD]

Eng Soon Painting Services

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page <input type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
		Thumbnail Print
1	10/01/18 17:18	Accident Statement From: SC - Reg. No: GBF2585K, Claimant: DIETHELM MARINEDIESEL PTE. LTD.
		1 Load HTML
Photos/Images		3 per page <input type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
		Thumbnail Print
1	24/01/18 10:41	General View
2	24/01/18 10:41	General View
3	24/01/18 10:41	General View
4	24/01/18 10:41	General View
5	24/01/18 10:41	General View
6	24/01/18 10:41	General View
7	24/01/18 10:41	General View
8	24/01/18 10:41	General View
9	24/01/18 10:41	General View
10	24/01/18 10:41	General View
11	24/01/18 10:41	General View
12	24/01/18 10:41	General View
13	24/01/18 10:41	General View
14	24/01/18 10:41	General View
15	24/01/18 10:41	General View
16	24/01/18 10:41	General View
17	24/01/18 10:41	General View
18	24/01/18 10:41	General View
19	24/01/18 10:41	General View
20	24/01/18 10:41	General View
21	24/01/18 10:41	General View
22	24/01/18 10:41	General View
23	24/01/18 10:41	General View
24	24/01/18 10:41	General View
25	24/01/18 10:41	General View
26	24/01/18 10:41	General View
27	24/01/18 10:41	General View
28	24/01/18 10:41	General View
29	24/01/18 10:41	General View
30	24/01/18 10:41	General View
31	24/01/18 10:41	General View
32	24/01/18 10:41	General View
33	24/01/18 10:41	General View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	24/01/18 10:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/01/18 10:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	24/01/18 10:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	24/01/18 10:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	08/06/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/11/17 17:16	Survey DISAGREE ON SJE, Appoint LKK as Surveyor	 Load PDF	
2	02/11/17 17:16	Request Pre-Repair Inspection	 Load PDF	
3	09/01/18 13:49	LOD from Bonnie Kwok	 Load PDF	
4	10/01/18 15:00	Final Repair Bill	 Load PDF	
5	10/01/18 15:00	Survey Fee & Report	 Load PDF	
6	10/01/18 15:00	Survey Report Photos	 Load PDF	
7	10/01/18 17:10	our email to LKK on whether their surveyor needs to do post repair survey or just a paper survey report	 Load PDF	
8	10/01/18 17:18	SKW903T GIA RPT From: SC - Reg. No: GBF2585K, Claimant: DIETHELM MARINEDIESEL PTE. LTD.	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/18 08:50	PHOTO	 Load PDF	
2	08/06/18 13:18	Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021004/R1QBE2-1

Date: 08/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29006428MKC

Claimant Vehicle No: SKW903T

Insured Vehicle No: GBF2585K

Date of Loss: 31/10/2017

Nature of Claim: TP

Claim No: 535302

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW903T

Make & Model: MITSUBISHI LANCER EX, 2.0 GT 5 ABS D/AB HID (M)

Engine No: 4B11DG2043

Reg. Date: 23/09/2010 (Man. Year: 2009)

Chassis No: JMYSNCY4AAU000334

Colour: White

Odometer: 0 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18

Rear Tyre Size: 235/40 R18

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,062.53	1,636.83	2,425.70	59.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,080.00	2,250.00	67.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,392.53	2,716.83	4,675.70	63.25
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	7,392.53	2,150.00	5,242.53	70.92

INSPECTION

Date of Assignment: 02/11/2017

Date Inspected: 09/04/2018 Inspected At:

Eng Soon Painting Services (HQ)
No. 52 Tuas Crescent
Singapore 638731

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2018)
Parts:	143	mitsubishi LANCER EX 2.0 GT 5 ABS D/AB HID (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW903T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FACE	Replaced	737.00 FN	*737.00 FN
2	1		*FRONT BUMPER SIDE RETAINER - RH	Replaced	41.00 FN	*41.00 FN
3	12		*FRONT BUMPER SIDE RETAINER RIVETS	Replaced	36.00 FN	*36.00 FN
4	10		*FRONT BUMPER CLIPS	Replaced	30.00 FN	*30.00 FN
5	1		*FRONT BUMPER BADGE	Replaced	37.00 FN	*37.00 FN
6	1		*FRONT FENDER - RH	Repaired	479.00 FN	*- FN
7	1		*FRONT FENDER SPLASH SHIELD	Serviceable	107.00 FN	*- FN
8	8		*FRONT FENDER SPLASH SHIELD CLIPS	Replaced	24.00 FN	*24.00 FN
9	1		*SIDE MIRROR HOUSING ASSY	Replaced	779.70 FN	*779.70 FN
10	1		*FRONT KNUCKLE ARM - RH	Not Necessary	320.00 FN	*- FN
11	1		*FRONT LOWER ARM	Not Necessary	239.00 FN	*- FN
12	1		*FRONT WHEEL BEARING KIT	Replaced	134.00 FN	*134.00 FN
13	1		*FRONT WHEEL BEARING HUP	Not Necessary	240.00 FN	*- FN
14	1		*FRONT ABSORBER	Not Necessary	460.00 FN	*- FN
15	1		*FRONT ABSORBER MOUNTING	Not Necessary	106.00 FN	*- FN
16	1		*FRONT ABSORBER MOUNTING BUSH	Not Necessary	22.00 FN	*- FN
17	1		*RIM ASSEMBLY (SPORT)	Repaired	650.00 FS	*- FS
					Sub Total (S\$)	4,441.70 1,818.70
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	379.17 181.87
					Total Parts (S\$)	4,062.53 1,636.83

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	120.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
4	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	350.00	90.00
5	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER)	New	200.00	60.00
6	TO RESPRAY AFFECTED AREAS	New	1,000.00	500.00
7	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT SUPPORT PANEL, FRONT FENDER INNER PANEL & ALIGNED ALL PARTS	New	1,400.00	400.00
Gross Labour Cost (S\$)			3,330.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >