

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

(V/L: YES / NO)



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
6/4/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
10/12/19	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	☒
	Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WP
\$350

Signature

REF: LPC

6343/ Rm - (C)

8380h

06 APR 2020 / JCL

ASSIGNMENT

From:

Date: 5/4/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SFZ7415H

at Workshop m/s

Prime Auto

of

6 Benoi place

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

18K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

10

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp,

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFZ 7415H

Yr Regn: 2005 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TAYOTA COROLLA RUNS 1.6 C.C. 1598

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

273894

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR0532EC107100588

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GOODRIDE

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

27/03/18

D.O.I.

05/04/18

Survey held at

PRIME AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S & O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

refer to email

* Got repair limit.

CLIS \$ 4,682

MV: \$18,000
 LTA: \$14,504
 Nett: \$3,496

(check items: \$4,734.32)

Date/Time: File Pass to?

☐

: Preli. Report

1)

Date/Time: File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Other

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18006343/R1ua3	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 05-04-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 8822K	Veh. Inspected	SFZ 7415H	
Policy No.	Z17VP05016102	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020491	Excess (\$)	0.00	
Assign From		Assign Date	01/01/1900	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/03/2018	Inspection Date		
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
 5 Benoi Place Singapore 629926
 Tel: 6861 0908 Fax: 6515 2948

Date: 04.04.2018

Lonpac Insurance Bhd
 100 Beach Road #19-00
 Shaw Tower
 Singapore 189702

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SFZ7415H TOYOTA ALTIS 2005

To supply

1)	1pc	front bumper	\$	461.90 DE
2)	1set	front bumper left side retainer	\$	35.10 ne
3)	1pc	front bumper right side retainer	\$	35.10 ne
4)	1pc	front bumper lower lip	\$	20.00 DE
5)	1pc	front bumper reinforcement	\$	342.00 ?
6)	1pc	left front fender	\$	203.70 ne
7)	1pc	left front fender cowl	\$	47.39 ne
8)	1set	left front cowl clip	\$	250.00 ne 2.50
9)	1pc	left front fender side panel protector 53828-12050	\$	66.90 ? ne
10)	1pc	left front fender apron sub assy 53702-1A080	\$	311.92 RX
11)	1pc	right front fender	\$	203.70 ne
12)	1set	right front fender cowl	\$	47.39 cut
13)	1set	right front fender cowl clip	\$	10.00 ne
14)	1pc	right front fender side panel protector	\$	66.90 ?
15)	1pc	left head lamp	\$	227.85 CRA
16)	1pc	front bonnet	\$	757.50 ne
17)	1pc	front bonnet insulator	\$	266.28 cut
18)	1pc	bonnet to radiator support seal 53381-02040	\$	28.15 ne
19)	1pc	radiator grille	\$	270.65 CRA
20)	1pc	raditor grille "Toyota" emblem	\$	59.10 ne
21)	1pc	radiator support panel sub assy 53201-1A240	\$	1,842.40 PA
22)	1pc	cowl panel sub assy 5570-1A460	\$	720.50 ?

23)	1pc	left top cowling side panel 55714-12110	\$	241.70	?
24)	1pc	right top cowling side panel 55713-12110	\$	241.70	?
25)	1pc	left cowling top ventilator louver 55709-02010	\$	82.60	?
26)	1pc	right cowling top ventilator louver 55708-02090	\$	82.60	?
27)	1pc	Air cleaner assy 17700-0D070	\$	362.60	?
28)	1pc	Air cleaner No.1 Hose 17881-0D040	\$	59.00	X } nu
29)	1pc	Air cleaner No. 1 inlet 17751-21070	\$	98.70	X } nu
30)	1pc	radiator assy 16410-0D120	\$	805.60	?
31)	1pc	radiator fan cowling 16711-0D041	\$	137.60	?
32)	1pc	radiator fan 16361-0D060	\$	83.90	X } nu
33)	1pc	radiator fan motor 16363-0M010	\$	250.10	X } nu
34)	1pc	A/con condenser 88450-02090	\$	1,211.50	?
35)	1pc	left drive shaft assy 43470-09670	\$	1,435.68	X
36)	1pc	left drive shaft joint assy 43403-12040	\$	429.10	X
37)	1pc	front axle left hub assy 43502-02070	\$	125.08	X
38)	1pc	front left disc rotor 43512-02060	\$	237.20	X
39)	1pc	left front lower ball joint assy 43330-09220	\$	150.70	X
40)	1pc	left front lower arm 48069-02090	\$	178.29	X
41)	1pc	left front shock absorber	\$	335.10	X
42)	1pc	right front shick absorber	\$	335.10	X
43)	1pc	left front stabilizer link assy 48820-02050	\$	171.05	X
44)	1pc	power steering rack & pinion gear assy 44250-02170	\$	1,978.20	X
45)	1pc	battery tray 74431-12020	\$	45.30	?
46)	1pc	left engine under cover 51442-02101	\$	92.10	cut -
47)	1pc	right engine under cover 51441-02061	\$	51.70	DE -
48)	1pc	engine mounting center member assy 51204-12130	\$	292.75	?
49)	1pc	front suspension crossmember sub assy 51201-12431	\$	1,612.18	?

Sub total parts \$ 17,401.56
 Less: 25% discount \$ (4,350.39)
 \$ 13,051.17

To supply S.Nett Parts

1)	1pc	front number plate <i>nn</i>	\$	35.00	X old change
2)	1tin	coolant	\$	20.00	nn

Sub total S.Nett Parts \$ 55.00

L/charges

1) Towing charges

\$ 50.00

- 2) To remove front undercarriage & suspension. Replace the above parts \$ 400.00 X
- 3) To remove radiator, a/con condenser, fan & cowling, refill a/con gas & coolant \$ ~~200.00~~ 100
- 4) To computerize wheel alignment \$ 80.00 X
- 5) To remove front bumper, bonnet, left & right fender, support panel, knock / welding left & right wheel house chassis, straighten wheel house chassis. Replace the above body parts and align front right & left doors & etc \$ ~~1,200.00~~ 1000
- 6) To putty, respray painting front bumper, bonnet inlet & outer, support panel, left & right fender, left & right wheel house panel. To polish \$ 1,000.00 /

sub total L/charges	\$ 2,930.00
Estimated total	\$ <u>16,036.17</u>

Raghu
Hp 90010068

10 days

L/S

05/04/18 @ 1640

Resay after repair

(To check m/v)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020491
Our ref: CC4/LPC18006343/R1ua3

Date: 09.04.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SFZ 7415H

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.04.2018 at the premises of M/s Prime Auto Claims Service Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	16,036.17	
Revised Estimate Amount	: S\$	5,852.51	
"Check" Items Amount	: S\$	4,734.32	
Total (Including Check Items)	: S\$	10,586.83	
Market Value	: S\$	18,000.00	(est.)
LTA Reimbursement Value	: S\$	14,504.00	(est.)
Nett Value	: S\$	3,496.00	(est.)

*** Note: Our surveyor has informed TP repairer on the limited repair cost.

Description of Damage:

The vehicle sustained damages at the
N/S & O/S front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 day

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

8380W

Vehicle Details

Vehicle No.:

SFZ7415H

Vehicle to be Exported:

Yes

Intended De-registration Date:

04 Apr 2018

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA 1.6

Primary Colour:

Grey

Manufacturing Year:

2005

Engine No.:

3ZZ4514124

Chassis No.:

MR053ZEC107100588

Maximum Power Output:

81.0 kW (108 bhp)

Open Market Value:

\$16,493.00

Original Registration Date:

27 Oct 2005

First Registration Date:

27 Oct 2005

Transfer Count:

1

Actual ARF Paid:

\$18,143.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

26 Oct 2020

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$28,399.00

COE Rebate Amount:

\$14,535.00

Total Rebate Amount:

\$14,535.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8380W
Vehicle Details	
Vehicle No.:	SFZ7415H
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Grey
Manufacturing Year:	2005
Engine No.:	3ZZ4514124
Chassis No.:	MR053ZEC107100588
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,493.00
Original Registration Date:	27 Oct 2005
First Registration Date:	27 Oct 2005
Transfer Count:	1
Actual ARF Paid:	\$18,143.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,399.00
COE Rebate Amount:	\$14,504.00
Total Rebate Amount:	\$14,504.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Apr 2018

OK

18,000
14,504

3,496

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 6 April, 2018 10:42 AM
To: 'Alice Leong'
Cc: Thin Thin (LKKAUTO)
Subject: SFZ 7415H DOA : 27/03/2018

Hi Alice,

The NETT amount to repair this vehicle is 3K only


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 4 April, 2018 4:55 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: PRI REQUEST TO ACCIDENT ON 27.03.2018 INVOLVING SFZ7415H & SJL8822K
Attachments: img-180404182212.pdf
Importance: High

04-04-2018 @ 5:24pm
Pei Yee van in

Our Ref : 17/18/18/VP05/020491

Dear Catherine,

Kindly proceed to conduct the pre-repair survey on without prejudice as our insured is claiming against the third party.

05/04/2018

Rosal

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Pei Yee [mailto:peiyee@primeautoclaims.com]
Sent: Wednesday, 4 April, 2018 4:34 PM
To: GERALD POH WEE BIN
Cc: aliceleong@primeautoclaims.com; chrissy@primeautoclaims.com
Subject: PRI REQUEST TO ACCIDENT ON 27.03.2018 INVOLVING SFZ7415H & SJL8822K
Importance: High

Hi

The above referred

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

Please inform surveyor to avoid 1145-1245pm lunch hour.

***We select LKK Auto Consultants Pte. Ltd.**

***Please arrange PRI soonest possible due to loss of income and loss of rental per day count.**

Thank you.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.
Office : 5 Benoi Place Singapore 629926
Workshop : 6 Benoi Place Singapore 629927
Tel: 6861 0908
Fax: 6515 2948

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Virus-free. www.avast.com

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 6 April, 2018 9:11 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: PRI REQUEST TO ACCIDENT ON 27.03.2018 INVOLVING SFZ7415H & SJL8822K
Attachments: 06042018090601.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: HMK

Dear Mei Kwan,

Attached insured's GIA report for your attention.

Kindly remind the case handler to assess liability before proceeding with a direct settlement as our insured is claiming against the third party.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 5 April, 2018 7:50 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ONG LI LI; ERIC WOO JUN KIAT; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: PRI REQUEST TO ACCIDENT ON 27.03.2018 INVOLVING SFZ7415H & SJL8822K

WITHOUT PREJUDICE

Your ref: 17/18/18/VP05/020491
LKK ref: CC4/LPC18006343/R1ua3

Dear Sir/ Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

***Please arrange PRI soonest possible due to loss of income and loss of rental per day count.**

Thank you.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.

Office : 5 Benoi Place Singapore 629926

Workshop : 6 Benoi Place Singapore 629927

Tel: 6861 0908

Fax: 6515 2948

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Virus-free. www.avast.com

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 16 December 2019 3:31 PM
To: Alice Leong
Cc: Admin A
Subject: Request for status - Accident between SFZ 7415H & SJL 8822K [Lonpac] on 27/03/2018

Tracking:	Recipient	Delivery
	Alice Leong	
	Admin A	
	olivialau@lkkauto.com	Delivered: 16/12/2019 3:31 PM
	shupei@lkkauto.com	Delivered: 16/12/2019 3:31 PM
	Meikwan@lkkauto.com	Delivered: 16/12/2019 3:31 PM

WITHOUT PREJUDICE

Dear Sir/Madam,

We would like to know whether your client is still pursuing the claim or not.

Please confirm.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Monday, 16 December 2019 5:05 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Request for status - Accident between SFZ 7415H & SJL 8822K [Lonpac] on 27/03/2018

Hi Khanchna,

We have closed file at our end.



Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: 16 December, 2019 3:31 PM
To: Alice Leong <aliceleong@primeautoclaims.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Request for status - Accident between SFZ 7415H & SJL 8822K [Lonpac] on 27/03/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We would like to know whether your client is still pursuing the claim or not.

Please confirm.

Thank you.

01 counterclaim DV

Tokio Marine Insurance Singapore Ltd



TOKIO MARINE
INSURANCE GROUP

Date : 25 July 2018
Total Pages : 01 (inclusive of this page)
To : Chua Tee Sing
C/o : C Yogarajah LLC
Attention : Helen
Your Ref : CY.9864.18(YLM)AC/hh
Email Add : helen@yoga-legal.com

By Email Only
Our Ref: M1801600/DS-01
From: Dillen Selvarajoo
Dept: Motor Claims
Phone: 6592-6414
Fax: 6221-2101

WITHOUT PREJUDICE
(SAVE AS TO COSTS)

Dear Sir,

ACCIDENT INVOLVING VEH NO: SJL8822K & SFZ7415H ALONG KALLANG AVE ON 27 MARCH 2018.
CLAIMANT: CHUA TEE SING - PROPERTY DAMAGE CLAIM OF VEH NO. SJL8822K

We confirm settlement as follows:

1. Cost of Repairs	S\$ 22,000.00
2. Rental Fees	S\$ 1,650.00
> x 80%	S\$ 23,650.00
> TM contribution -	S\$ 18,920.00
3. Survey Report Fee	S\$ 1,264.00
4. LTA Fee	S\$ 29.00
5. Costs	S\$ 963.00
> TOTAL	S\$ 25,816.00

FACTS

• I WAS DRIVING ALONG MAIN DRIVEWAY
WITHIN INDUSTRIAL COMPOUND, T/P COMING
OUT FROM SUB-DRIVEWAY OF CAR PARK
WITHOUT GIVING WAY AND COLLIDED WITH
O/I VEHICLE.

Please request the owner of the vehicle/property/claimant to sign on this letter, witnessed and send the original to us. The above settlement term shall be in full and final settlement of all claims (including personal injuries, property damage and or loss suffered by the claimant) arising out of the said accident and shall be treated as a Discharge to our company and our insured's liability. No further Discharge Voucher will be issued. This settlement does not preclude Our Insured/Authorised Driver/Tokio Marine Insurance Singapore Ltd rights. Furthermore, no admission of liability is admitted on Our Insured/Authorised Driver/Tokio Marine Insurance Singapore Ltd's part in any event whatsoever.

• T/P FAILS TO GIVE WAY
BEFORE DRIVING ACROSS
THE JUNCTION,
PRIMARILY LIABLE FOR
THE ACCIDENT

We shall process payment only upon receipt of the Discharge Voucher (with original signature) duly signed and witnessed. Please note our settlement above is on a without admission of liability basis.

For Tokio Marine Insurance Singapore Ltd.

*I/We accept the above offer

Signature / Authorised Signatory
(Rubber stamp for Co. where applicable)
CHUA TEE SING
Name & NRIC No. S7044947A

Date: 31/7/18

Witness

Signature

Name & NRIC No. Lee Shorley

Address

Date: 31/7/18

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection Policy Statement posted at www.tokiomarine.com



Date : 25 July 2018
 Total Pages : 01 (inclusive of this page)
 To : Chua Tee Sing
 C/o : C Yogarajah LLC
 Attention : Helen
 Your Ref : CY.9864.18(YLM)AC/hh
 Email Add : helen@yoga-legal.com

By Email Only
 Our Ref: M1801600/DS-01
 From: Dillen Selvarajoo
 Dept: Motor Claims
 Phone: 6592-6414
 Fax: 6221-2101

WITHOUT PREJUDICE
(SAVE AS TO COSTS)

Dear Sir,

ACCIDENT INVOLVING VEH NO: SJL8822K & SFZ7415H ALONG KALLANG AVE ON 27 MARCH 2018.
CLAIMANT: CHUA TEE SING – PROPERTY DAMAGE CLAIM OF VEH NO. SJL8822K

We confirm settlement as follows:

1. Cost of Repairs	S\$ 22,000.00
2. Rental Fees	S\$ 1,650.00
> x 80%	S\$ 23,650.00
> TM contribution -	S\$ 18,920.00
3. Survey Report Fee	S\$ 1,264.00
4. LTA Fee	S\$ 29.00
5. Costs	S\$ 963.00
> TOTAL	S\$ 21,176.00

Please request the owner of the vehicle/property/claimant to sign on this letter, witnessed and send the original to us. The above settlement term shall be in full and final settlement of all claims (including personal injuries, property damage and or loss suffered by the claimant) arising out of the said accident and shall be treated as a Discharge to our company and our insured's liability. No further Discharge Voucher will be issued. This settlement does not preclude Our Insured/Authorised Driver/Tokio Marine Insurance Singapore Ltd rights. Furthermore, no admission of liability is admitted on Our Insured/Authorised Driver/Tokio Marine Insurance Singapore Ltd's part in any event whatsoever.

We shall process payment only upon receipt of the Discharge Voucher (with original signature) duly signed and witnessed. Please note our settlement above is on a without admission of liability basis.

For Tokio Marine Insurance Singapore Ltd.

*I/We accept the above offer

Signature / Authorised Signatory
 (Rubber stamp for Co. where applicable)
 CHUA TEE SING
 Name & NRIC No. S7044947A
 Date: 31/7/18

Witness

Signature

Name & NRIC No. Lee Sharley S7723265B

Address

Date: 31/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18006343/R1ka3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 06-03-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJL 8822K	Veh. Inspected	SFZ 7415H
Policy No.	Z17VP05016102	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020491	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	04/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	MR053ZEC107100588	Colour	GREY
Odometer	273894	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODRIDE	5 mm
L/H Front Tyre	195/65 R15	GOODRIDE	5 mm
R/H Rear Tyre	195/65 R15	GOODRIDE	5 mm
L/H Rear Tyre	195/65 R15	GOODRIDE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2018	Inspection Date	05/04/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 7415H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	461.90	461.90
1	SET FRONT BUMPER LEFT SIDE RETAINER	NECESSARY	35.10	35.10
1	FRONT BUMPER RIGHT SIDE RETAINER	NECESSARY	35.10	35.10
1	FRONT BUMPER LOWER LIP	DEFORMED	20.00	20.00
1	FRONT BUMPER REINFORCEMENT	* CHECK	342.00	-
1	LEFT FRONT FENDER	BUCKLED	203.70	203.70
1	LEFT FRONT FENDER COWLING	NECESSARY	47.39	47.39
1	SET LEFT FRONT COWLING CLIP	NECESSARY	250.00	250.00
1	LEFT FRONT FENDER SIDE PANEL PROTECTOR 53828-12050	* CHECK	66.90	-
1	LEFT FRONT FENDER APRON SUB ASSY 53702-1A080	TO REPAIR SEE LABOUR	311.92	-
1	RIGHT FRONT FENDER	BUCKLED	203.70	203.70
1	SET RIGHT FRONT FENDER COWLING	CUT	47.39	47.39
1	SET RIGHT FRONT FENDER COWLING CLIP	NECESSARY	10.00	10.00
1	RIGHT FRONT FENDER SIDE PANEL PROTECTOR	* CHECK	66.90	-
1	LEFT HEAD LAMP	CRACKED	227.85	227.85
1	FRONT BONNET	BUCKLED	757.50	757.50
1	FRONT BONNET INSULATOR	CUT	266.28	266.28
1	BONNET TO RADIATOR SUPPORT SEAL 53381-02040	NECESSARY	28.15	28.15
1	RADIATOR GRILLE	CRACKED	270.65	270.65
1	RADIATOR GRILLE "TOYOTA" EMBLEM	NECESSARY	59.10	59.10
1	RADIATOR SUPPORT PANEL SUB ASSY 53201-1A240	BENT	1,842.40	1,842.40
1	COWLING PANEL SUB ASSY 5570-1A460	* CHECK	720.50	-
1	LEFT TOP COWLING SIDE PANEL 55714-12110	* CHECK	241.70	-
1	RIGHT TOP COWLING SIDE PANEL 55713-12110	* CHECK	241.70	-
1	LEFT COWLING TOP VENTILATOR LOUVER 55709-02010	* CHECK	82.60	-
1	RIGHT COWLING TOP VENTILATOR LOUVER 55708-02090	* CHECK	82.60	-
1	AIR CLEANER ASSY 17700-0D070	* CHECK	362.60	-
1	AIR CLEANER NO.1 HOSE 17881-0D040	NOT NECESSARY	59.00	-
1	AIR CLEANER NO.1 INLET 17751-21070	NOT NECESSARY	98.70	-

Report Ref No. CC4/LPC18006343/R1ka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR ASSY 16410-0D120	* CHECK	805.60	-
1	RADIATOR FAN COWLING 16711-0D041	* CHECK	137.60	-
1	RADIATOR FAN 16361-0D060	NOT NECESSARY	83.90	-
1	RADIATOR FAN MOTOR 16363-0M010	NOT NECESSARY	250.10	-
1	A/CON CONDENSER 88450-02090	* CHECK	1,211.50	-
1	LEFT DRIVE SHAFT ASSY 43470-09670	NOT NECESSARY	1,435.68	-
1	LEFT DRIVE SHAFT JOINT ASSY 43403-12040	NOT NECESSARY	429.10	-
1	FRONT AXLE LEFT HUB ASSY 43502-02070	NOT NECESSARY	125.08	-
1	FRONT LEFT DISC MOTOR 43512-02060	NOT NECESSARY	237.20	-
1	LEFT FRONT LOWER BALL JOINT ASSY 43330-09220	NOT NECESSARY	150.70	-
1	LEFT FRONT LOWER ARM 48069-02090	NOT NECESSARY	178.29	-
1	LEFT FRONT SHOCK ABSORBER	NOT NECESSARY	335.10	-
1	RIGHT FRONT SHOCK ABSORBER	NOT NECESSARY	335.10	-
1	LEFT FRONT STABILIZER LINK ASSY 48820-02050	NOT NECESSARY	171.05	-
1	POWER STEERING RACK & PINION GEAR ASSY 44250.02170	NOT NECESSARY	1,978.20	-
1	BATTERY TRAY 74431-12020	* CHECK	45.30	-
1	LEFT ENGINE UNDER COVER 51442-02101	CUT	92.10	92.10
1	RIGHT ENGINE UNDER COVER 51441.02061	DEFORMED	51.70	51.70
1	ENGINE MOUNTING CENTER MEMBER ASSY 51204-12130	* CHECK	292.75	-
1	FRONT SUSPENSION CROSSMEMBER SUB ASSY 51201-12431	* CHECK	1,612.18	-
	LESS 25% DISCOUNT		-4,350.39	-1,227.50
			13,051.17	3,682.51
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (NOT NECESSARY) (SN)	OLD DAMAGE	35.00	-
1	TIN COOLANT (SN)	NECESSARY	20.00	20.00
			55.00	20.00
	LABOUR			
	TOWING CHARGES.		50.00	50.00
	TO REMOVE FRONT UNDERCARRIAGE & SUSPENSION. REPLACE THE ABOVE PARTS.	NOT NECESSARY	400.00	-

Report Ref No. CC4/LPC18006343/R1ka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Reg. No. 199007190K COT Reg. No. 199007190K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE RADIATOR, A/CON CONDENSER, FAN & COWLING , REFILL A/CON GAS & COOLANT.	NOT NECESSARY	200.00	100.00
	TO COMPUTERRIZE WHEEL ALIGNMENT.		80.00	-
	TO REMOVE FRONT BUMPER, BONNET, LEFT & RIGHT FENDER, SUPPORT PANEL, KNOCK / WELDING LEFT & RIGHT WHEEL HOUSE CHASSIS, STRAIGHTEN WHEEL HOUSE CHASSIS. REPLACE THE ABOVE BODY PARTS AND ALIGN FRONT RIGHT & LEFT DOORS & ETC. INCLUSIVE OF THE REPAIR OF LEFT FRONT FENDER APRON SUB ASSY 53702-1A080.		1,200.00	1,000.00
	TO PUTTY, RESPRAY PAINTING FRONT BUMPER, BONNET INLET & OUTER, SUPPORT PANEL, LEFT & RIGHT FENDER, LEFT & RIGHT WHEEL HOUSE PANEL. TO POLISH.		1,000.00	1,000.00
			2,930.00	2,150.00
GRAND TOTAL			16,036.17	5,852.51
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$4,734.32 NETT				4,682.00

Report Ref No. CC4/LPC18006343/R1ka3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.