

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates



Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4303P

Ref. No : TAX/03/18/2140

Reg. Date : 07/05/2014

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : TAN HOCK CHENG

Type of Accident : HEAD TO SIDE

Date / Time of Accident : 30/03/2018 12:40:00 PM

Accident Reported Date / Time: 31/03/2018 12:00:00 AM

Surveyor is Required? : No

Survey by

Vehicle is Towed Back? : Yes

Towed Back Date/Time : 30/03/2018

Replacement Vehicle issued? : N

Accident Repair Job Card No : 000024095301

Special Instruction to ARC, if any :

GBE1386E

Prepared Date : 31/03/2018 09:48:14 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U805742185

Mileage

0

Work Shop :

Repair Completed Date / Time:

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

0.00

Total Spray Painting Charges

936.00

0.00

Total Material Charges

2,645.88

2,699.88

Other Charges

600.00

0.00

TOTAL

5,026.88

0.00

Lum Sum Total

5,050.00

0.00

No. of Repair Days

5.00

0.00

Prepared / Adjusted By

3 days

Arc / Surveyor Sing Off Date

31/03/2018 10:41:24 AM

01/01/1900 12:00:00 AM

'repared / Adjusted Date

Remarks

'repared Date : 31/03/2018 10:40:49 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

Page:

ection D - Details of Repair Estimates

art 1 - Labour Works

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
O REPAIR RH REAR PORTION	845.00	0.00 300			
otal Labour	845.00	0.00			

art 2 - Spray Painting & Panel Beating Related Works

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPSRAY REAR BUMPER	378.00	0.00 200
O RESPRAY REAR FENDER RH	378.00	0:00 200
O RESPRAY RIM	180.00	0.00 ×
otal Spray Painting & Panel Beating	936.00	0.00

'art 3 - Other Costs - Accident and Accident Repair Related Expenses

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
O CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 🗶		
O APPLY RUST-PROOFING ON AFFECTED REA	100.00	0:00 30		
O DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 ×		
O TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 ×		
O WASH AND VACUUM	60.00	0.00 ×		
O REMOVE AND REFIT TYRE RIM (SPRAYING URPOSE)	120.00	0.00 ×		
otal Other Costs	600.00	0.00		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159-		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
47905 52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace 7	No
+7020			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace / N	No
61604- 47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No
47090	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace		No No
	COMMO		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	NEC
42611- 47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace	, No
	TOTAL MATERIALS							2,257.20	2,257.20	
TOTAL MATERIALS(Discounted)							2,645.88	2,699.88		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								

Page: