

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 16 Apr 2018

Preliminary Advice

Insured Vehicle No	: SLE4592M	Accident Date	: 04/04/2018
TP Vehicle No	: SKC2721T	Assignment Date	: 05/04/2018
Make	: SUBARU IMPREZA	Est. Duration of Repair	: 4 days
Date of Inspection	: 13.04.2018		
Inspection At	: Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH Singapore 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear O/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,104.72
Revised Amount	:S\$	2,495.36
Check Items (Estimated)	:S\$	734.88
Total	:S\$	3,230.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.