

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0725/2018
DATE : 10-APR-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : MICHAEL HONG JUN HWA
ADDRESS : BLK 72 MARINE DRIVE, #06-63
#06-63
S(440072)
TELEPHONE NO : 90663500

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00410868
VEHICLE NO : SKC2721T
MODEL CODE : GE7BKAF
MODEL/YEAR : IMPREZA 2.0R-S AWD 5MT 4D
ENGINE NO : EJ20D717840
CHASSIS NO : JF1GE7KF39G005546
MILEAGE : 1 KM
DATE IN : 10/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 10/04/2018

Print Date : 10/04/2018
Print Time : 16:53:50

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKC2721T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FWD LOCATION:TPE TO TAMPINES AVE7 DATE:04/04/2018 TIME:0715 HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1680.00	1120/
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	840.00	✓
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	50.00	20
6	ZZ/005	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	?
7	ZZ/006	SUNDRIES	100.00	20
		TOTAL LABOUR CHARGES	2970.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKC2721T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 SKIRT R E4DR	52401FG0219P	288.00	?		
2 REAR BUMPER R	57704FG090	594.00	CM?		
3 BRKT LWR R BMPR	57707AG480	14.40	?		
4 REAR BUMPER BEAM	57711FG0509P	212.40	?		
5 REAR RH CORNER BRACKET	57717FG050	25.20	Dis		
6 BRACKET CORNER R SDN LH	57717FG060	25.20	Sm	X	
7 REA RH SIDE BRACKET	57717FG072	14.40	?		
8 REAR LH SIDE BRACKETH	57717FG082	14.40	?		
9 COVER-REAR BUMPER	57731FG010B7	14.40	Sm	X	
10 REFLEX REFLECTOR AY LH	84551AG090	72.00	Sm	X	
11 LENS & BODY FOG, R RH	84913AG180	144.00	Sm	X	
SUB TOTAL		1418.40		0.00	0.00
LESS DISCOUNT (NETT-20 %)		283.68		0.00	0.00
GRAND TOTAL		1134.72		0.00	0.00
OVERALL TOTAL		1134.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKC2721T

TOTAL LABOUR CHARGES 2970.00
TOTAL SPARE PARTS CHARGES 1134.72

GRAND TOTAL 4104.72 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

*Not Notified
1-B.1
Re survey B4 paint
4 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: