		h //
195000	ENTENAND CC 3/AIG180 0 6353 /	TIMAS LIBAC
INS. CASE OWNER:	Deforation CC / AIG 100	The state of the s
Surveyor	X68 DOI: ASSIGNMENT	Date / Time 5/4/18 Registered in Merimen: 5/9/18
Pre-assign / CCU	666 5295 Y	
Insured Vehicle No	Claim No.	9752 128 182661
Nume of Insured	Um AUR CON. ENGING SERVE POLICY NO.	
Insured Tel No.	HP: Make / Model	
Excess Sec II :SS	D.O.A : 5 4 8 Piace of Accid	en reviewale Lune
Is driver the owner	lice feed	
If NO. Driver Nan		RT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel 1		sy S Final ? Yes / No
STR MOIS		
INSRS:	INSRS: INSRS:	INSRS:
WSP: Previous	WSP: WSP. Tel:	WSP. Tel
Liability:	Liability: Liability:	Liability :
RMKS:	RMKS: RMKS:	RMKS:
Date/Time		STAGE DATE/PIC
1010	TUB 21-18 X : (18652) 1 X X	Non-Reporting by (1st):
114		Non-Reporting ltr (2nd): Non-Reporting ltr (Find):
a seed on		Notification lit (if non-pickup)
9/4/18	Spoke to OI he confirmed the accident details. Informed Trelain and	After call in to Ot: 77H III
	he agree to settle.	Documentation Check List: Handler Typist
	0	Notification fit (if non-pickup) After call fit to Ot
		Authorisation To Act
13-12-18	TRANSFER: THIN' TO JUY	Releuse Voucher:
	PENDING FINALISATION	Final Repair Hill:
	TENDER TIME TON	Towing Investor
	TO 41004034	LTA/GIA:
	- THE LOD IN BY FUMIL	Medical Bill PIR
	, 555 m 57 6-mile	Mandate/Reject Instruction:
25/00/19	THE AMEDIAL FOR MYNDRER YELDANT	LOD
PRELIMINARY ADVICE	Date/Time: Sent By:	Payment Breakdown Form: Post-Repair Photos:
02/09/19	- AG APPROVED WANDKIE.	Others:
FINALIZATION Remain Cost	Date/Time: Confirm with:	Confirm by:
Repair Cost: PIP	SS 14,864-36 14 days) Reduction: 29 5 Date/Time: 251019 Confirm with UAD1441	Email Call
Final Liability:	1 100 Pagreed Assessed BOLA S/N No.: 27	If NO or B 28. Ass. Lia:
Repair Cost: (W)(GC)	55 19,118.00	(OID MAKE- FAIDED UD)
Less of Rental (LOR): Less of Use (LOU):	55 1,020.005 60 s 17 days)	
Loss of Income (LOI):	SS - (S x days)	
LOR only LOU only	SS 2-00 [Tick only one]	
GIA/LTA Search Medical:	ss 2.60	1) Claim status: Neml/Rejoct/Private Settle
Disbursement	ss - (e.g. Towl Independent)	2) Report Format
Legal Cost Total:	SS 20, 140.08 Global Sum SS: —	3) Survey fee: \$320.00
FINAL PAYMENT	Date/Time: Confirm with:	Email Cal
Payee 1:	SS 20, 140-08 Name 1: PRELIUM AUTOM	DIBILBE PTE LTD
Payee 2: (Strike if N.A.)	SS Name 2:	•





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inte	rnationale Des	Experts En Autom	obile				
AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref :	CC3/AIG180063	353/ua3				
78 SHENTON WAY CHARTIS BUILDIN SINGAPORE 0791	IG	Date :	05-04-2018 AIG					
1.	Policy Particu	lars :- THIRI	D PARTY CLAI	M				
Insured Veh	. GBG 5295Y	Veh. Ir	nspected	SLB 2101B				
Policy No.		Cover	age (\$)	0.00				
Claim No.		Exces	s (\$)	0.00				
Assign Fron	ń	Assign	n Date	05/04/2018				
2.	Vehicle	Particulars 8	Condition					
Make & Mod	lel	c.c		0				
Engine No.	HIDDEN	Year o	Year of Reg.					
Chassis No.		Colour						
Odometer	*	Steering						
Brakes		Modification						
General								
3.	Co	nditions of	Tyres					
	Size	Make		Balance				
R/H Front T	/ге			mm				
L/H Front Ty	re			mm				
R/H Rear Ty	re			mm				
L/H Rear Ty				mm				
4.	Desc	ription of Da	amages					
5.		neral Inform						
Accident Da			ction Date					
Survey held	at PREMIUM AUTOMOBILES 55 UBI ROAD 1 . SINGAPORE 408699	S PTE LTD						
5a.	U-240-10 -	Remarks						

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/0419/2018/GW

Date : 06-Apr-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Hitachi Capital Asia Pacific PTE LTD

Address : 111 Somerest Road

#14-05

Singapore 238164

Telephone : HP +65 67341222
Type of Claim : Third Party Claims

Policy No. : MSD/VPVP/16-000955-00

Vehicle No : SLB 2101 B

Model Code : Audi A4 Sedan 1.4 TFSI 5

 Model / Year
 : Mar-16

 Engine No
 : CVN 004329

Chassis No : WAUZZZF48GA036824

Mileage :

Date In : Liability : -Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 05-Apr-18
Place of Accident : Fervale Lane

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 2101 B.

S/N	Nature of Jobs			Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	S	360.00	/
2	To remove and renew rear bumper, spoiler and reinforcement. Repair and reshape rear end panel, rhs tailamp panel, rhs rear fender. Renew damaged lights, align rear lid. Reinstall all parts removed.	2	s	1,500.00	1000
3	To respray paint on rear bumper, rear lid, rhs rear fender, end panelling.	3	s	2,500.00	1650
4	To cary out diagnostic check.	S/N	s	192.00	
+					
	TOTAL LABOUR CHARGES		\$	4,552.00	7702

+ SUPP LABOUR

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 2101 B.

			Damage Parts	s & Prices	
S/N	Parts Description		S/NETT	REMARKS	
1	REAR BUMPER / PL , NN	\$	1,907.00	1,625.60	1
2	REAR BUMPER FIXING PARTS X	\$	63.00 🔀		
3	REAR BUMPR SECURING STRIP / NEC.	5	184.00	152.80	性
4	REAR BUMPER SPOILER / SUR	\$	216.00	172.80	1
5	REAR BUMPER CARRIER & GNA	\$	786.00 >		
6	REAR LIGHT REFLECTOR-RH	5	35.00≯		
7	LED TAIL LIGHT-RH / CRA	\$	915.00	782.00	1
8	LED TAILIGHT TRIM-RH - NC.	\$	26.00	20.08	20.8
9	LED TAILIGHT INNER-RH - Cert.	\$	816.00	652.40	652
10	LED TAILIGHT INNER TRIM-RH / Cut	\$	26.00	20.08	20.8
11	REAR BUMPER GUIDE SECION-RH / CAA .	\$	38.00	50.40	-
12	REAR BUMPER LOWER GUIDE SECTION-RH / RC .	5	19.00	14.88	152
13	VENT TRIM X	\$	60.00 🗙		1900
14	REAR BUMPER SEAL RING 2	4 \$	14.00 >		
15	REAR BUMPER SENSOR	2 \$	421.00		
16	REAR BUMPER WIRING X	\$	598.00 ➤		
17	REAR AUDI EMBLEM /	\$	108.00	86.0	0 8
18	INSCRIPTION "A4"	\$	83.00	CG.1	4 66
19	INSCRIPTION "TFSI"	5	83.00	C.G. 1	6 66
20	SUNDRIES 7 /	\$	300.00	70.	72
	TOTAL SPARE PARTS	\$	6,698.00	J221	
	TOTAL LABOUR CHARGES :	\$	4,552.00		
	GRAND TOTAL	\$	11,250.00		
	Legend : Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.		refo.	3776.8	

+ SOAB HAMB

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Guo @i 04 : 09/4/18

Surveyed Date

Authorised Date

Excess Cost

before paint photos.
5 Pays.

Liability Remarks

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting.
- ⋆ To display damaged partial during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No litegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages Regn No

Model No

PA/TP/0419/2018/GW

24-Apr-18 CHANG

1 of 1 SLB 2101 B

Audi A4 SEDAN 1.4 TFSI

101: 0041	0055 / Pax: 6256 4315	model No		Cunn	PHY DESCRIPTION			
Quantity	Descri	Description					Amount	
1 2 3	To renew rhs 1/4 glass and rear winds facilitate fender renewal. To dislodge and reintall rear wire harr battery manager, fuse and relay trays equipment. To remove and reinstall rear seat, bat abcd pillar trims, luggage compartme Dislodge roof liner and disengage cur	ess for lights, electrical and audio k rest, hat trays, at trims, seat belts, tain airbag etc.	S/N S/N S/N	5 5	600.00 1,400.00 1,400.00	s	600.00 1,400.00 1,400.00	1
5	To cut out and weld rhs rear fender and To respray rhs sill panel, door entrang channel and end panelling. To carry of treatment and joint sealer works.	e, drain panel, roof	2.5	\$	3,600.00 2,600.00	\$	2,500.00 1,400.00	/
		TOTAL LABOUR	S :	\$	9,600.00	\$	7,300.00	6800
Parts 1 2 3 4 5 6 7 8 9 10 11	REAR FENDER - RH REAR SEAT GROMMET SET REAR 1/4 GLASS - RH REAR WINDSCREEN GLASS PRIMER 1/4 GLASS SEALANT REAR WINDSCREEN SEALANT ACRYLIC SEALER CAVITY WAX STONE CHIP METAL FILLER POWDER	BC.	2 S/N S/N S/N S/N S/N	****	2,347.00 37.00 541.00 1,014.00 37.00 100.00 200.00 180.00 140.00 180.00 280.00	\$	1,877.60 24.96 432.40 811.20 29.12 100.00 200.00 180.00 140.00 280.00	246
		MATERIALS LABOUR CHRGES	:	\$	5,056.00 9.600.00	S	4,255.28 7,300.00	20
		TOTAL	:	\$	14,656.00		11,555.28	

For Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

:

Surveyed Date

.

Authorised Date

.

Excess Cost

:

Liability Remarks

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

: Ubi Road 1

Contact No

: 6366 2323 : 6841 1183

Fax No Reference

: PA/TP/0419/2018/GW

Date

: 6-Apr-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Adrian, Guo Qiang days exclude 1 PH & 2 Sunday

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Hitachi Capital Asia Pacific PTE LTD

Address

: 111 Somerest Road

#14-05

Singapore 238164

Telephone

HP +65 67341222

Type of Claim

Third Party Claims MSD/VPVP/16-000955-00

Policy No. Vehicle No

SLB 2101 B

Model Code

Audi A4 Sedan 1.4 TFSI S

Model / Year

Mar-16

Engine No.

CVN 004329

Chassis No

WAUZZZF48GA036824

Mileage

Date In

Liability

Excess Cost

Estimated By

Johnny Boo / Allan Wu

Accident Date Place of Accident 5-Apr-18 Fervale Lane

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 2101 B.

S/N	Nature of Jobs			Estimated Charges		urveyor's ommendation	
1	To remove and transfer rear parking aid. Check function.	S/N	\$	360.00	s	360.00	/
2	To remove and renew rear bumper, spoiler and reinforcement. Repair and reshape rear end panel, rhs tailamp panel, rhs rear fender. Renew damaged lights, align rear lid. Reinstall all parts removed.		\$	1,500.00	\$	1,000.00	/
3	To respray paint on rear bumper, rear lid, rhs rear fender, end panelling.		\$	2,500.00	s	1,650.00	/
4	Added labour charges - see attached		\$	9,600.00	\$	7,300.00	6800
5	To cary out diagnostic check.	S/N	s	192.00	s	192.00	/
	TOTAL LABOUR CHARGES	:	\$	14,152.00	\$	10,502.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 2101 B.

					Damage Pa	irts		
S/N	Parts Description		_	_	S/NETT	_	REMARKS	
1	REAR BUMPER			\$	1,907.00	\$	1,525.60	1
2	REAR BUMPER FIXING PARTS			\$	63.00			
3	REAR BUMPR SECURING STRIP			\$	184.00	\$	152.80	MAT
4	REAR BUMPER SPOILER			\$	216.00	\$	172.80	1
5	REAR BUMPER CARRIER			\$	786.00			
6	REAR LIGHT REFLECTOR-RH			\$	35.00			
7	LED TAIL LIGHT-RH			\$	915.00	\$	732.00	/
8	LED TAILIGHT TRIM-RH			\$	26.00	\$	20.08	200
9	LED TAILIGHT INNER-RH			\$	816.00	\$	652.40	652
10	LED TAILIGHT INNER TRIM-RH			\$	26.00	\$	20.08	200
11	REAR BUMPER GUIDE SECION-RH			\$	38.00	\$	30.40	11
12	REAR BUMPER LOWER GUIDE SECTION-RH			\$	19.00	\$	14.88	150
13	VENT TRIM			\$	60.00			V.=3.997
14	REAR BUMPER SEAL RING		4	\$	14.00			
15	REAR BUMPER SENSOR		2	\$	421.00			
16	REAR BUMPER WIRING			\$	598.00			
17	REAR AUDI EMBLEM			\$	108.00	\$	86.00	80
18	INSCRIPTION "A4"			\$	83.00	\$	66.16	66
19	INSCRIPTION "TFSI"			\$	83.00	\$	66.16	66
21	Added parts - see attached			\$	5,056.00	\$	4,255.28	2.50
22	SUNDRIES			\$	300.00	\$	70.72	1
	TOTAL SPARE PARTS	1		\$	11,754.00	\$	7,865.36	1
	TOTAL LABOUR CHARGES	:		\$	14,152.00	\$	10,502.00	1000
	GRAND TOTAL	3	-	\$	25,906.00	\$	18,367.36	

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

17867.36

Joy Irene (LKKAuto)

From:

Carrine Leong <carrine.leong@premiumauto.com.sg>

Sent:

Wednesday, 19 June 2019 2:10 PM

To:

Guo Qiang (LKKAuto); CS A Team; Admin A; Joy Irene (LKKAuto)

Cc:

jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'

Subject:

RE: FINAL REVISION - SLB2101B - TP AIG - SURVEYED 9 APR 18

Attachments:

PA04192018 - SLB 2101 B - A4 Sedan 1.4 TFSI - REAR (AIG) + SUPP.XLS

Dear Guo Qiang / Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle. Revised estimate was mailed to you on 23 Jan, 21 Feb, 18 Apr & 15 May 2019. We sincerely appreciate your early closure.

Thanks & Best Regard Carrine Leong Claims Administrator

Premium Automobiles Pte Ltd (Rog No 199002271W)

55 Ubi Road I Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

x	

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]

Sent: Wednesday, 15 May, 2019 3:23 PM

To: 'Guo Qiang (LKK Auto)' <guoqiang@lkkauto.com>; 'cs-a@lkkauto.com' <cs-a@lkkauto.com>; 'admin-

a@lkkauto.com' <admin-a@lkkauto.com>; 'Adrian Ling' <adrianling@lkkauto.com>

Cc: 'jiayee.yap@premiumauto.com.sg' <jiayee.yap@premiumauto.com.sg>; 'Chang Chee Sing'

<claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SLB2101B - TP AIG - SURVEYED 9 APR 18

Importance: High

Dear Guo Qiang / Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle. Revised estimate was mailed to you on 23 Jan, 21 Feb & 18 Apr 2019.

We sincerely appreciate your early closure.

Thanks & Best Regard Carrine Leong Claims Administrator

Premium Automobiles Pte Ltd (#kg No 1999012271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]

Sent: Thursday, 18 April, 2019 2:21 PM

To: 'Guo Qiang (LKK Auto)' <<u>guoqiang@lkkauto.com</u>>; 'cs-a@lkkauto.com' <<u>cs-a@lkkauto.com</u>>; 'admin-a@lkkauto.com' <<u>admin-a@lkkauto.com</u>>; 'Adrian Ling' <<u>adrianling@lkkauto.com</u>>

Cc: 'jiayee.yap@premiumauto.com.sg' <jiayee.yap@premiumauto.com.sg>; 'Chang Chee Sing'

<claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SLB2101B - TP AIG - SURVEYED 9 APR 18

Dear Guo Qiang / Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle. Revised estimate was mailed to you on 23 Jan & 21 Feb 2019. We sincerely appreciate your early closure.

Thanks & Best Regard Carrine Leong Claims Administrator

Premium Automobiles Pte Ltd (Ileg No 1000002271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

×	
Email Disclaimer	
If you have received it in error,	ment, is confidential and may also be privileged. please notify us immediately by reply email and then delete this message from your system. or any purpose, or disclose its contents or any attachment to any other person. Thank you
From: Carrine Leong	mailto:carrine.leong@premiumauto.com.sg]
	bruary, 2019 4:11 PM
	ianling@lkkauto.com>; 'Guo Qiang (LKK Auto)' <guoqiang@lkkauto.com>; 'cs-a@lkkauto.co</guoqiang@lkkauto.com>
	'admin-a@lkkauto.com' <admin-a@lkkauto.com></admin-a@lkkauto.com>
	iumauto.com.sg' < <u>jiayee.yap@premiumauto.com.sg</u> >; 'Chang Chee Sing'
<claims@premiumau< td=""><td></td></claims@premiumau<>	
Subject: RE: FINAL RE	VISION - SLB2101B - TP AIG - SURVEYED 9 APR 18
Dear Adrian and all,	
Dear Adrian and an,	
Reminder	
	your confirmation of repair cost and days of repair for above vehicle.
	mailed to you on 23 Jan 2019.
	ate your early closure.
0.1000	
Thanks & Best Regard Carrine Leong	
Claims Administrator	
Premium Automobiles Pt 55 Ubi Road 1 Road Singa	
	6768 9925 f. +65 6841 1183
e. carrine.leong@premium	auto.com.sg w. www.audi.com.sg
	entre 281 Alexandra Road Singapore 159938 p. +65 6836 2223
×	

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify as immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Wednesday, 23 January, 2019 3:31 PM

To: Adrian Ling <adrianling@lkkauto.com>; Guo Qiang (LKK Auto) <guoqiang@lkkauto.com>; cs-a@lkkauto.com;

admin-a@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg;
Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLB2101B - TP AIG - SURVEYED 9 APR 18

Hi Adrian and all,

Revised estimate is thatched.

Please confirm repair cost of \$18,367.36 @ 14 days of repairs exclude 1 PH & 2 Sundays. Vehicle was reinspected by Rasul on 25 Apr 18

Your early closure is well appreciated.

Best regards - jb

Print Received Message

This mail is associated with:

*SLB2101B (9752428182SG) [GBG5295Y]

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD Apr 5 2018 9:00AM [Lim Air-con Engineering Services]

Premium Automobiles Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 25/10/2019 09:17 AM.

To

LKK HQ

Subject

Alert - Adj Mandate Approved (S\$20140.08) - SLB2101B - Claim Handler: Ler, Bernard-JQ

Approved:20140.08:mandate approval is subject to final repair bill & ATA

BREAKDOWN OF PAYMENT

Vehicle No:	SLB2101	В	
Accident on	05/04/2	018	at FERVALE LANE
Involving vehic	:le/s	GBG5295Y	<i>y</i>
1) Repair cost		s 19,118 0	Payable to: <u>Premium Automobiles Pte Ltd</u>
2) GIA/LTA sea	rch fee	\$ 200	Payable to: Premium Automobiles Pte Ltd
3) Loss of Use of Rental Car	or	s_ 1,020.00	Payable to: LEE LIEN SHUAN
4) Medical fees	i .	\$	Payable to:
5) Others		\$	Payable to:



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co.Reg No. 200412212G GST Reg. No. 20-0412212G A Member of MS&AD INSURANCE GROUP

CERTIFICATE OF INSURANCE

ROAD TRANSFORT ACT 1987 (MALAYSIA) THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA) THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

MOTORMAX PLUS Comprehensive

Certificate No. G 300013755 MCY

Excess: SGD1,500

Windscreen Excess: SGD100

- Index Mark and Registration Number of Vehicle SLB2101B
- Name of Policyholder 2.

Hitachi Capital Asia Pacific Pte. Ltd.

- Effective Date of the Commencement of Insurance for the purposes of the Act 30/03/2018
- Date of Expiry of Insurance 4 29/03/2019
- Persons or Classes of Persons entitled to drive* 5.

Any other person provided he is driving an the Palicyholder's order or with the Policyholder's permission.

- *Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Use for the carriage of passengers or goods in connection with the Policyholder's business. Use for social domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.
- * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 189) and Chapter 95 of the Road Transport Act, 1987 [Malaysia], are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle, If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offense under the Motor Vehicles (Third Party Risks and Compensation) Act [Cap. 189].

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Michael W Gourlay Chief Executive Officer



The owner and vehicle particulars for Vehicle No. SLB2101B as at 30 Mar 2016 are as follows:

1.	Name	: HITACHI CAPITAL ASIA PACIFIC PTE LTD
2.		: Company
3.	Identification No.	: 199400399N
4.		1-
5.		: 111 SOMERSET ROAD #11-05
		TRIPLEONE SOMERSET
		SINGAPORE 238164
6.	Mailing Address	: -
7.		: SLB2101B
8.		: 30 Mar 2016
9.		: 30 Mar 2016
10.		: 30 Mar 2016
11.	The late of the state of the st	: R10 - Private Hire (Self-Drive) Motor Car
12.		: Normal
13.	CONTRACTOR	: No Attachment
14.		; -
15.		
16.	Vehicle Make	: AUDI
17.	Vehicle Model	: A4 1.4 TFSI S TRONIC
18.		: 2016
19.		: White
20.		; ·
21.	Passenger Capacity	
22.	Chassis/Trailer Chassis No.	
23.		
24.	Propellant/Emission Standard Engine No./Motor No.	: CVN004329 / -
25.	Linguise 1407/14/0401-1407	: 1395/-
26.		: 110.0 / 147
27.		: 1450
28.		: 1945
29.		: \$32,076.00
30.	- 407 THE SECTION FOR SECTION OF THE	: Yes
31.		: 29 Mar 2026
32.		: \$13,453.00
33.	IU Label No.	:
34.	COE No.	: 2016040103001882N
35.	COE Expiry Date	: 29 Mar 2026
36.	COE Category	: B - Car (above 1600cc or 97kW (130bhp))
37.	Quota Premium/Prevailing Quota Premium	
38.		: \$46,502.00
39.	Actual ARF Paid	: \$26,907.00
40.	CO2 Emission(g/km)	: 119.00
41.	Actual CEVS Rebate Utilised	: \$10,000.00
42.	CEVS Surcharge Paid	* -
43.	Actual Green Vehicle Rebate Utilised	12
44.	Vehicle Lifespan Expiry Date	**
45.	Road Tax Amount	: \$582.00
46.	Road Tax Start Date	: 30 Mar 2016
47.	Road Tax End Date	29 Mar 2017
48.		: This is a public service vehicle.
100	annath and	This vehicle is eligible for PARF.
		To renew the COE, the Prevailing Quota Premium
		payable is that of Category B.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

Yr Ref: CC3/AIG18006353/UA3 / GBG5295Y

Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/TP/0419/2019/KK

22 August 2019

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SLB 2101 B, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. SLB 2101 B, claimant, Hitachi Capital Asia Pacific Pte Ltd, please find the related document as per attached.

- A copy of the Original invoice no. 85014147 S\$19,118.08.
- 2. A copy of Authorization to Act duly signed by client
- 3. A copy of the Release Voucher attached
- 4. A copy of Breakdown of Payment attached
- Loss of Use S\$1,020.00 (S\$60.00 x 14 working days + 2 Sunday + 1 PH)
- GIA Search Fee S\$2.00.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SLB 2101 B

Premium Automobiles Pte Lti Showroom 9 Leng Kee Road

Singapore 159090 Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699

Telephone (65) 6336 2323 Telefax (65) 684 11183



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC3/AIG18006353/Gua3

12 APRIL 2018

LIM AIR CON ENGINEERING SERVICES BLK 303C ANCHORVALE LINK #11-124 SINGAPORE 543303

Dear Sir/Madam,

ACCIDENT INVOLVING GBG 5295Y & SLB 2101B ON 05/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360 FAX: 6741 4108

Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

AUTHORISATION TO ACT

(AIG Express Third Party Claim)

I, HITACHI CAPITAL ASIA PACIFIC PTE LTD (the t	hird party claimant) of 111 Sowerset Road
# 14-05 Emplore 238164 (add	ress), owner of SLB2101B (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd	("the workshop") to act for me
	rental and/or loss of use ("claim") for my vehicle
no. st.821018 that was damaged pursuant	to the accident which occurred on05/04/2018
(date) alongFERVALE LANE	(location) involving vehicle no/s
GBG5295Y ("the accident").	
	we mentioned claim in a manner that they deem fit be payment further to settlement of my claim with orkshop.
	orkshop may reach on my behalf is on a without
vehicle/s is concerned.	
Dated this (day) of (m	nonth) 20 <u>18</u> (year)
HITACHI CAPILE SIA PACIFIC PTE LTD.	
Signed by "the third party claimant"	Signed by "the workshop"
(with chop if applicable)	(with chop)

AUTHORISATION TO ACT (AIG Express Third Party Claim)

Singapore 797497	(address), c	owner of	SLB2101B	(vehicle no.)
hereby authorize Premium A	automobiles Pte Ltd	(the workshop	") to act for me
with respect to my claim for re	epair costs and/or rental a	md/or loss o	of use ("claim") for my vehicle
no. SLB2101B that was d	lamaged pursuant to the	accident wh	ich occurred o	on05/04/2018
(date) along FERVALE	LANE	(loca	ation) involvir	ng vehicle no/s
GBG5295Y ("the acciden	11").			
I further authorize the worksho and the workshop is further au payment cheque/s being made	thorized to receive paym	ent further		
I further acknowledge that any				
prejudice and without admissi-	on of liability basis insof	ar as the dri	ver/owner/insu	rers of the other
vehicle/s is concerned.				
Dated this(day) of	May (month) 2	0 (§ (year)		
04.	•		JOBILET OF THE STATE OF THE STA	J 0)
Signed by "the third party clair	mant**	Signed b	y "the worksh	op"
(with chop if applicable)		(with ch	iop)	

RELEASE VOUCHER (AIG Express Third Party Claim)

-Wc/I, Premium Automobiles Pte Ltd	("the workshop") hereby confirm that we/l
have reached an agreement with the appointed sur	rveyor of AlG Asia Pacific Insurance Pte Ltd LKK
	surveyor) with respect to the amount claimed for
S\$ 19,118-08 (Repair Cost), S\$ 1,020.09 Loss of 1	(Disbursement), for vehicle no.
	accident which occurred on 05/04/2018 (date) along
FERVALE LANE	location) involving vehicle no/s GBG5295Y This is
pursuant to the inspection conducted on 9/4/2018	
We/I confirm that we/I are/am authorized by the	owner HITACHI CAPITAL ASIA PACIFIC PTE LTD
("the third party claimant") of vehicle no. SLB2101	B make the claim as set out in the above paragraph
and we/l have full authority to settle the matter on	his/her behalf in a manner that we/I deem fit. We/I
enclose herein the letter of authority given by "the thi	rd party claimant".
We/I further confirm that we/I will indemnify AIG	Asia Pacific Insurance Pte Ltd for all damages, loss
and/or expense that they will or have already incurre	ed in the event that "the third party claimant" after the
	inst the former for any loss and expenses suffered
pertaining to costs of repairs and/or rental and/or	loss of use pursuant to the damage to SLB2101B
(vehicle no.) as a result of the accident.	
We/I confirm that the agreement reached above is	in full and final settlement of any claim of "the third
party claimant" pursuant to the accident and that fur	ther this settlement is reached on a without prejudice
and without admission of liability basis.	
This agreement is subject to the application of Sin	gapore law and the Singapore Courts have exclusive
jurisdiction over any dispute arising out of the same.	
Dated this	th) 20 (year)
Signed by appointed surveyor	Signed by "the workshop" (with chop)

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 261 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

Ubi Service Centre 55 Ubi Road 1 Singapore 408899 Main Telephone 6385 2323 Main Telefax 6841 1163

Customer Service Service Appointment 24-hour Breakdown Service 6366 2323 customer.care@premiumauto.com.sg Email

INS TAX INVOICE

Page 1

11:16

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING 78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice: 85014147

Date : 21/08/2019

Order : SLB2101B

Term : 30

Account: A0006

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

{V 29334) Regn Date: 30/03/2016

Mileage: 40906

WIP No.: 61270

Regn No: SLB2101B

Chassis: WAUZZZF48GA036824

Engine: CVN 004329

Dept: U

You have been assisted by :- UB-Tony Foong

Model: A4 SEDAN 1.4 TFSI E tronic

0.33

		Details	Qty	Unit Price	Amount
5	BODYWORK	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	360.00	1100	360.00
5	BODYWORK	TO REMOVE AND RENEW REAR BUMPER, SPOILER AND REINFORCEMENT. REPAIR AND RESHAPE REAR END PANEL, RHS TAILAMP PANEL, RHS REAR FENDER. RENEW DAMAGED LIGHTS, ALIGN REAR LID, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
	BODYWORK	TO RESPRAY PAINT ON REAR BUMPER, REAR LID AND RHS REAR FENDER	1650.00	1.00	1,650.00
8	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Đ.	BODYWORK	TO RENEW RHS 1/4 GLASS AND REAR WINDSCHEEN TO FACILITATE FENDER RENEWAL	600,00	1.00	600.00
i:	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
	BODYWORK	TO REMOVE AND REINSTALL BEAR SEAT, BACK BEST, HAT TRAY, ABCD FILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS AND SEAT BELTS.DISLODGE BOOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	1400.00	1.00	1,400.00
	BODYWORK	TO CUT OUT AND WELD RHS REAR FENDER AND RHS	2000.00	1.00	2,000.00
	BODYWORK	M: TO RESPRAY RHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL AND END PANELLING, TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	1400.00	1.00	1,400.00

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

Ubi Service Centre 55 Ubi Road 1. Singapore 408699 Main Telephone 6388 2323 Main Telefax 6641 1163 **Customer Service** 6366 2323 Service Appointment 24-hour Breakdown Service 9828 1233 customer.care@premiumauto.com.sg Email

INS TAX INVOICE

Page

2

11:16

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice: 85014147

Order: SLB2101B

Term : 30

Account: A0006

CT

(3.)

Date : 21/08/2019

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING 78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SLB2101B

293341 (V

Regn Date: 30/03/2016

Mileage: 40906

WIP No.: 61270

Model: A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF48GA036824

Engine: CVN 004329

Dept: U

You have been assisted by :- DB-Tony Foong

(33)

		Details		Qty	Unit Price	Amount
S BOD	YWORK	TO SUPPLY 1/4 GLASS SEALANT, RE SEALANT, ACKYLIC SEALER, CAVITY	AR WINDSCREEN	1080.00	1100	1,080.00
A A A A A A A A A A A A A A A A A A A	W5809838 W59450946 W5945092C W5845298D MV: W5845501B NV: W5845501B NV: W5853741 22: W5853742 22: W5853742 22: W5853737A 22: W5807890 W5867900 W5867287B KM: C985373 KM: C98537	SPOILER REARWINDOW COVER INSCRIPTION 'A4' AUDI SIGN INSCRIPTION 'TPSI' GUIDE STRIP	Less 020%	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	2347.00 815.50 915.00 540.50 216.00 1014.00 1907.00 82.70 18.60 191.00 80.00 1.10 7.80 38.00 25.10 25.10 18.20 1.00	1,877.60 652.40 732.00 432.40 172.80 811.20 1,525.60 66.16 14.86 152.80 64.00 3.52 24.96 30.40 20.08 20.08 20.08

Parts 6,785.36 Labour 0.00 11,082.00 Sublet Menus 0.00 Lubricant 0.00

Sub-Total 17,867.36 1,250,72 7% GST 19,118.08

Grand Total

Received by

For & on behalf of Premium Automobiles Pte Ltd



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-051051

Date of Request:

05/04/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

Enquiry Date

05/04/2018

Enquiry By

Tony Foong Chin Fong

TP Vehicle No.

GBG5295Y

Accident Date

05/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature,

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-18-051051

Date of Request:

05/04/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

Enquiry Date

05/04/2018

Enquiry By

Tony Foong Chin Fong

TP Vehicle No.

GBG5295Y

Accident Date

05/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel, No.
GBG5295Y	AIG Asia Pacific Insurance Pte. Ltd.	29/08/2017-28/08/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	AL	ij Submitted	Ins Auth'ed	Status	
Main	05 Apr 2018 Edit Reg		09 Apr 2018 00:00 Edit Adj Rpt	S\$17,867	200	\$17,867.36 View Rpt		Pending for Report Cancel Case	Survey
	Main	R	eference	Cla	im Detail		Documents		Show All
CLAIM SU	BFOLDER DE					[Created	by adjuster]		
Insured:	Lim Air-c	on Engineering	Services, Co. Reg.	No.: 530338	IBA .				
Main Claimant:	HITACHI	CAPITAL ASIA	PACIFIC PTE LTD,	Co. Reg. No.	199400				
Vehicle Re No.:	SLB210	18		c	ate of Los	s: [24 Month	8 09:00 - :59 s and 6 Days From L	TA Reg Date (N	tan Yr)]
Claim Type	TP / 975	PARTIES APPLICATE AND APPLICATION OF THE PROPERTY OF THE PROPE			23 (Comprehensive)				
Vehicle Re No. (Insured):	GBG5295	Y		1.7	olicy No. Claimant):	MSD/VPVP	MSD/VPVP/16-000955-00		
great any.					xcess:				
Repairer:	Premium	Automobiles Pt	e Ltd (UBI) 55 Ubi	Road 1, 4085	99 Ubi - Ti	el: 67689828/	9827/9911		
Handling Insurer:		Pacific Insurant Qian.Ler@aig.com		ss) - Tel: fi5-	5419-3000) [Handled t	y Ler, Bernard-JQ]		
Claimant's Insurer:	MSIG Ins		ore) Pte. Ltd. (HQ)						
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel: 62	56-3561	tandled by	XING GUO C	[Final R	pt due 16/0	4/2018]
ASSOCIA	TED MAIL RE	CEIVED					View /	All Compos	e Case Mail
AIG_SC AIG_SC	_EXPRESS (02 5 (06/04/2018) OCIATED TAS	: NO OI GIA RE	- Adj Mandate Ap	proved (S\$2	0000.00)	- SLB2101B - - SLB2101B - View All	Claim Handler: Let Claim Handler: Let Search Tasks Crei Completed On	r, Berna r, Berna ete New Task	Complete

Claim Documents

*SLB2101B (97524281825G) [GBG5295Y] TP HITACHI CAPITAL ASIA PACIFIC PTE LTD Apr 5 2018 9:00AM

[Lim Air-con Engineering Services] Premium Automobiles Pte Ltd

Lett	ters/Corresponden	ices	1 per	page v	Z
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
	essment Reports		1 per	page 🔽	V
		AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	
No L	Finalized On 09/04/18 16:33	Accident Statement	0	Load HTM	-
_	(/3/04/10 10:33	From:SC - Reg. No: GBGS295Y, Claimant: LIM AIR CON ENGRG SERVICE		100-000-000-000-000-000-000-000-000-000	-
Pho	otos/Images		3 per	page 🔽	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	01/08/19 10:53	General View	0	Load JPG	2
2	01/08/19 10:53	General View	0	Load JPG	2
3	01/08/19 10:53	General View	0	Load JPG	2
4	01/08/19 10:53	General View	0	Load JPG	V
5	01/08/19 10:53	General View	0	Load 3PG	82
6	01/08/19 10:53	General View	0	Load JPG	12
7	01/08/19 10:53	General View	0	Load JPG	12
B	01/08/19 10:53	General View	0	Load JPG	R
9	01/08/19 10:53	General View	0	Load JPG	V
10	01/08/19 10:53	General View	0	Load 3PG	82
11	01/08/19 10:53	General View	0	Load JPG	82
12	01/08/19 10:53	General View	0	Load JPG	R
13	01/08/19 10:53	General View	0	Load JPG	R
14	01/08/19 10:53	General View	0	Load IPG	V
15	01/08/19 10:53	General View	0	Load JPG	2
16	01/08/19 10:53	General View	0	Load JPG	2
17	01/08/19 10:53	General View	0	Load 3PG	Z
18	01/08/19 10:53	Odometer Reading	0	Load JPG	N.
19	01/08/19 10:53	Chassis Number	0	Load JPG	N
20	01/08/19 10:54	Reinspection Photo	0	Load 3PG	8
	01/08/19 10:54	Reinspection Photo	0	Load JPG	R
21		The state of the s	0	Load JPG	V
22	01/08/19 10:54	Reinspection Photo	0	Load JPG	82
23	01/08/19 10:54	Reinspection Photo	0	Load JPG	V
24	01/08/19 10:54	Reinspection Photo	0	Load 3PG	8
25	01/08/19 10:54	Reinspection Photo	0	Load JPG	2
26	01/08/19 10:54	Reinspection Photo	0	Load JPG	2
2.7	01/08/19 10:54	Reinspection Photo		Load JPG	5
28	01/08/19 10:54	Reinspection Photo	0	_	-
29	01/08/19 10:54	Reinspection Photo	0	Load JPG	2
30	01/08/19 10:54	Reinspection Photo	0	Load 3PG	2
31	01/08/19 10:54	Reinspection Photo	0	Load 3PG	2
32	01/08/19 10:54	Reinspection Photo	0	Load JPG	-
33	01/08/19 10:54	Reinspection Photo	0	Load JPG	2
34	01/08/19 10:54	Reinspection Photo	0	Load JPG	2
35	01/08/19 10:54	Reinspection Photo	0	Load 3PG	V

Lett	ters/Corresponden	ces	1 per page	v	8
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumi	liand	and the second
					N
37	01/08/19 10:54	Reinspection Photo	■ Load	JPG	Ø
38	01/08/19 10:54	Reinspection Photo	C Load	JPG	2
39	01/08/19 10:54	Reinspection Photo	€ Load	JPG:	Y
40	01/08/19 10:54	Reinspection Photo	€ Load	JPG.	2
41	01/08/19 10:54	Reinspection Photo	€ Load	JPG	V
42	01/08/19 10:54	Reinspection Photo	■ Load	JPG	Ø
43	01/08/19 10:54	Reinspection Photo	■ Load	JPG	2
	01/08/19 10:54	Reinspection Photo	€ Load	1PG	2
44			O Load		Ø
45	01/08/19 10:54	Reinspection Photo	O Load		V
46	01/08/19 10:54	Reinspection Photo	O Load		Ø
47	01/08/19 10:54	Reinspection Photo			2
48	01/08/19 10:54	Reinspection Photo	O Load		-
49	01/08/19 10:54	Reinspection Photo	1 Load	JPG	82
50	01/08/19 10:54	Reinspection Photo	Load	JPG:	M
51	01/08/19 10:54	Reinspection Photo	① Load	JPG:	V
52	01/08/19 10:54	Reinspection Photo	■ Load	JPG	8
53	01/08/19 10:54	Reinspection Photo	1 Load	JPG	2
54	01/08/19 10:54	Reinspection Photo	O Load	3PG	2
Do	cumentation		1 per page	V	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thum	bnail	
1	05/04/18 21:46	TP GIA REPORT	1 Load	PDF	-
2	17/04/18 23:51	TP ESTIMATE - MARKED	1 Load	PDF	
3	26/08/19 17:04	GIA SEARCH	1 Load	PDF	
4	26/08/19 17:04	LETTER TO OI	1 Load	POF	_
5	30/10/19 10:29	WORKSHOP INVOICE	■ Load	PDF	
6	30/10/19 10:29	AUTHORISATION TO ACT FORM	■ Load	PDF	
7	30/10/19 10:29	Release Voucher	1 Load		
8	30/10/19 10:29	LOD	1 Load	PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPL	Secretaries have been	COURTEVAR
NOTE: TO HE COMPL	FIFTI PC	SURVETUR

$T = \Delta M$		
I E-MIN		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG5295Y (Insd veh)		Model:	AUDI A4 1.4 TFSI S TRONIC		
	SLB2101B (TP veh) Accident: 05/04/2018			(A)		
Date of Accident:						
Global Sum Settler	ment : [] Yes	[X] No			
Repair Estimate		: \$	26,862.65			
Final Repair Cost		: S	19,118.08			
Loss of Use		: \$	1,020.00	17.00 days at \$60.00 per day		
Rental (if any)		: \$	0.00	days		
LTA / GIA Search i	Fee	: \$	2.00			
Others:		: \$	0.00			
		: \$				
Final Settlement S	um	: \$	20,140.08			
A) For Non GIA F	Registered W	orkshop:	Agreed Liability			
B) For GIA Regis	stered Works	hop:	27	ele: Yes/ No BOLA Scenario No:		
BOLA Liability	100_	(%)	27 Assessed Liab	ility (*):(%)		
BOLA Liability	100_	(%)	27 Assessed Liab			
BOLA Liability * Assessed Lie Remarks	:100_ ability to be fill	(%) ad only for cha	27 Assessed Liab	ility (*):(%)		
BOLA Liability * Assessed Lie Remarks Payment Instruction	:100_ ability to be fill	(%) ad only for chai	27 Assessed Liab in collisions and fo	ility (*):(%) r cases where BOLA does not apply		
BOLA Liability * Assessed Lie Remarks Payment Instruct 1) Premium Auto	:100_ ability to be fill	(%) ad only for chai	27 Assessed Liab in collisions and fo	ility (*):(%) r cases where BOLA does not apply		
BOLA Liability * Assessed Lie Remarks Payment Instruction	:100_ ability to be fill	(%) ad only for chai	27 Assessed Liab in collisions and fo	ility (*):(%)		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Date

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006353/GHA3Q2

Date:

30/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700045523

Claimant Vehicle No:

SLB2101B

Insured Vehicle No: GBG5295Y

Date of Loss:

05/04/2018

Nature of Claim:

TP

Claim No: 9752428182SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLB2101B

Make & Model:

AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No:

CVN004329

Reg. Date: Colour:

30/03/2016 (Man. Year: 2016) White

Chassis No: Odometer:

WAUZZZF48GA036824 33605 km

Engine Capacity:

1395 cc

Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Rear Tyre Size:

245/40 R18

Front Tyre Size: Front Left Side:

Goodyear 6 mm

245/40 R18

Rear Left Side:

Goodyear 6 mm

Front Right Side:

Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,953.28	7,865.36	3,087.92	28.19
Miscellaneous Items		0.00	0.00	0.00	
Labour		14,152.00	10,002.00	4,150.00	29.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	25,105.28	17,867.36	7,237.92	28.83
	+ GST 7.00/7.00% (S\$)	1,757.37	1,250.72	506.65	28.83
	Nett Amount (S\$)	26,862.65	19,118.08	7,744.57	28.83
	+ Loss of Use (17.0 x S	\$\$60.00/day) (S\$)	1,020.00		
	+ Doc	/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	20,140.08		

INSPECTION

Date of Assignment:

09/04/2018

Date Inspected:

09/04/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

14.0 days

Manager: VIC ALPEH Adjuster: XING GUO QIANG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty F	art No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	63.00 FS	*-FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	184.00 FS	*152.80 FS
4	1		*REAR BUMPER SPOILER	Scratched	216.00 FS	*172.80 FS
5	1		*REAR BUMPER CARRIER	Not Necessary	786.00 FS	*-FS
6	1		*REAR LIGHT REFLECTOR -RH	Not Necessary	35.00 FS	*-FS
7	1		*LED TAIL LIGHT -RH	Cracked	915.00 FS	*732.00 FS
8	1		*LED TAIL LIGHT TRIM-RH	Necessary	26.00 FS	*20.08 FS
9	1		*LED TAIL LIGHT INNER -RH	Cut	816.00 FS	*652.40 FS
10	1		*LED TAIL LIGHT INNER TRIM-RH	Cut	26.00 FS	*20.08 FS
11	1		*REAR BUMPER GUIDE SECION -RH	Cracked	38.00 FS	*30.40 FS
12	1		*REAR BUMPER LOWER GUIDE SECTION -RH	Deformed	19.00 FS	*14.88FS
13	1		*VENT TRIM	Not Necessary	60.00 FS	*-FS
14	4		*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*-FS
15	2		*REAR BUMPER SENSOR	Not Necessary	421.00 FS	*-FS
16	1		*REAR BUMPER WIRING	Not Necessary	598.00 FS	*-FS
17	1		*REAR AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
18	1		*INSCRIPTION A4	Necessary	83.00 FS	*66.16 FS
19	1		*INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
20	1		*SUNDRIES	Necessary	300.00 FS	*70.72 FS
21	1		*REAR FENDER -RH	Buckled	1,877.60 FS	*1,877.60 FS
22	1		*SET REAR SEAT GROMMET	Necessary	24.96 FS	*24.96 FS
23	1		*REAR 1/4 GLASS-RH	Necessary	432.40 FS	
24	1		*REAR WINDSCREEN	Necessary	811.20 FS	*811.20FS
25	1		*GLASS PRIMER	Necessary	29.12 FS	*29.12 FS
26	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
28	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
29	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
30	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
31	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
21						

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			Lenwoonen
TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN FACILITATE FENDER RENEWAL	New	600.00	600.00
TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAYS, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
TO CUT OUT AND WELD RHS REAR FENDER AND RHS TAIL LAMP PANEL	New	3,600.00	2,000.00
TO RESPRAY RHS SILL PANEL ,DOOR ENTRANCE ,DRAIN PANEL ,ROOF CHANNEL AND END PANELLING .TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	2,600.00	1,400.00
TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION	New	360.00	360.00
TO REMOVE AND RENEW REAR BUMPER, SPOILER AND REINFORCEMENT. REPAIR AND RESHAPE REAR END PANEL, RHS TAILLAMP PANEL, RHS REAR FENDER. RENEW DAMAGED LIGHTS, ALIGN REAR LID. REINSTALL ALL PARTS REMOVED	New	1,500.00	1,000.00
TO RESPRAY PAINT ON REAR BUMPER ,REAR LID ,RHS REAR FENDER ,END PANELLING	New	2,500.00	1,650.00
TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labou	r Cost (S\$)	14,152.00	10,002.00
Report was unsubmitted durin	a this print-out		
	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN FACILITATE FENDER RENEWAL TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAYS, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO CUT OUT AND WELD RHS REAR FENDER AND RHS TAIL LAMP PANEL TO RESPRAY RHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION TO REMOVE AND RENEW REAR BUMPER, SPOILER AND REINFORCEMENT, REPAIR AND RESHAPE REAR END PANEL, RHS TAILLAMP PANEL, RHS REAR FENDER. RENEW DAMAGED LIGHTS, ALIGN REAR LID.REINSTALL ALL PARTS REMOVED TO RESPRAY PAINT ON REAR BUMPER, REAR LID, RHS REAR FENDER, END PANELLING TO CARRY OUT DIAGNOSTIC CHECK Gross Labour	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN FACILITATE FENDER RENEWAL TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEAT, BACK REST ,HAT TRAYS,ABCD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS ,SEAT BELTS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO CUT OUT AND WELD RHS REAR FENDER AND RHS TAIL LAMP PANEL TO RESPRAY RHS SILL PANEL ,DOOR ENTRANCE ,DRAIN PANEL ,ROOF CHANNEL AND END PANELLING .TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS TO REMOVE AND TRANSFER REAR PARKING NEW AID .CHECK FUNCTION TO REMOVE AND RENEW REAR BUMPER ,SPOILER AND REINFORCEMENT .REPAIR AND RESHAPE REAR END PANEL,RHS TAILLAMP PANEL ,RHS REAR FENDER .RENEW DAMAGED LIGHTS ,ALIGN REAR LID .REINSTALL ALL PARTS REMOVED TO RESPRAY PAINT ON REAR BUMPER ,REAR LID ,RHS REAR FENDER ,END PANELLING	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN FACILITATE FENDER RENEWAL TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAYS, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC TO CUT OUT AND WELD RHS REAR FENDER AND RHS TAIL LAMP PANEL TO RESPRAY RHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION TO REMOVE AND RENEW REAR BUMPER, SPOILER AND REINFORCEMENT, REPAIR AND RESHAPE REAR END PANEL, RHS TAILLAMP PANEL, RHS REAR FENDER, RENEW DAMAGED LIGHTS, ALIGN REAR LID. REINSTALL ALL PARTS REMOVED TO RESPRAY PAINT ON REAR BUMPER, REAR LID, RHS REAR FENDER, END PANELLING Gross Labour Cost (S\$) 14,152.00

< END OF ESTIMATES >