

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0419/2018/GW
Date : 06-Apr-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Hitachi Capital Asia Pacific PTE LTD
Address : 111 Somerest Road
#14-05
Singapore 238164
Telephone : HP +65 67341222
Type of Claim : Third Party Claims
Policy No. : MSD/VPVP/16-000955-00
Vehicle No : **SLB 2101 B**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Mar-16
Engine No : CVN 004329
Chassis No : WAUZZZF48GA036824
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 05-Apr-18
Place of Accident : Fervale Lane

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 2101 B.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$	360.00	
2	To remove and renew rear bumper, spoiler and reinforcement. Repair and reshape rear end panel, rhs tailamp panel, rhs rear fender. Renew damaged lights, align rear lid. Reinstall all parts removed.	\$	1,500.00	1000 .
3	To respray paint on rear bumper, rear lid, rhs rear fender, end panelling.	\$	2,500.00	1650
4	To carry out diagnostic check.	S/N \$	192.00	/
TOTAL LABOUR CHARGES		:	\$ 4,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 2101 B.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER / <i>re</i>	\$ 1,907.00	
2	REAR BUMPER FIXING PARTS X	\$ 63.00	
3	REAR BUMPR SECURING STRIP / <i>rec.</i>	\$ 184.00	
4	REAR BUMPER SPOILER / <i>sur</i>	\$ 216.00	
5	REAR BUMPER CARRIER ?	\$ 786.00	
6	REAR LIGHT REFLECTOR-RH ?	\$ 35.00	
7	LED TAIL LIGHT-RH / <i>CRA</i>	\$ 915.00	
8	LED TAILLIGHT TRIM-RH /	\$ 26.00	
9	LED TAILLIGHT INNER-RH /	\$ 816.00	
10	LED TAILLIGHT INNER TRIM-RH /	\$ 26.00	
11	REAR BUMPER GUIDE SECION-RH / <i>CRA</i>	\$ 38.00	
12	REAR BUMPER LOWER GUIDE SECTION-RH / <i>re</i>	\$ 19.00	
13	VENT TRIM ?	\$ 60.00	
14	REAR BUMPER SEAL RING ?	4 \$ 14.00	
15	REAR BUMPER SENSOR ?	2 \$ 421.00	
16	REAR BUMPER WIRING X	\$ 598.00	
17	REAR AUDI EMBLEM /	\$ 108.00	
18	INSCRIPTION "A4" /	\$ 83.00	
19	INSCRIPTION "TFSI" /	\$ 83.00	
20	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS		\$ 6,698.00	
TOTAL LABOUR CHARGES		\$ 4,552.00	
GRAND TOTAL		\$ 11,250.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gao Qiang
Surveyed Date : 09/4/18
Authorised Date :
Excess Cost :
Liability : before paint photos.
Remarks :
5 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant