

15/5/2018

INS. CASE OWNER:

Sahha | CC 6 / AIG180 06354, U ja302

LKK:
IDAC:

Surveyor:

M James

DOI:

ASSIGNMENT

6/4/18

Date / Time :

5/4/18

Registered in Merimen:

5/4/18

Pre-assign / CCU / FTE



Insured Vehicle No. :

SKB 1508E

Name of Insured :

TOY SUMIN, June

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

4/4/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

URGENT CHIA KHONG BOON

Driver Tel No. :

90468240 (V/L: YES / NO)

Claim No. :

85159286656

Policy No. :

2100301745-02700

Make / Model :

ANOL A1

Place of Accident :

BAYSHORE EXIT

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SDB 6673K



INSRS:

WSP:

Tel :

Liability :

RMKS:

Hockwan



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

6/4/18
Juy

SDB6673K - X ;
SKB 1508E - U3/AIG180/16630/AU03W2 ; POF: 25/4/18
9-4-18 @ 1029 W/OI 2 OTO, CONFIRMED
AGREED & AWARE
NCO ISSUE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI: JUY 9-4-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

RECEIVED 25 APR 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT	Date/Time: 25-4-18	Confirm with: MSW	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :
Repair Cost:	SS 3,103.22		
Loss of Rental (LOR):	SS 700.00	(7 days) X 100	
Loss of Use (LOU):	SS X	(5 x days)	
Loss of Income (LOI):	SS X	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS 2.00		
Medical:	SS		
Disbursement:	SS X	(e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost	SS		2) Report Format:
Total:	SS 3,805	Global Sum SS:	3) Survey fee:
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 3,805	Name 1: HOCK WAH MOTOR WORKSHOP PTE LTD	
Payee 2: (Strike if N.A.)	SS X	Name 2: X	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
6/4/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18006354/ja3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-04-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 1508E	Veh. Inspected	SDB 6673K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/04/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1173362Z
 AU SOON LANG
 NO

SINGAPORE
 TEL : FAX :
 PH : 9
 ATTN :

ESTIMATE BILL

Number : EB00004795
 Date : 05/04/2018
 Case No : AD00009655
 Vehicle No : SDB6673K
 Chassis : JHMFD16306S204411
 Year of Mfr : 2006
 Policy No
 Model : HONDA CIVIC

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts / notes are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplier (entry item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED SEVENTY-THREE AND CENTS TEN ONLY			Less Excess		0.00
			SUBTOTAL		4,367.38
			GST 7.00%		305.72
			TOTAL		4,673.10

Date of accident : 04/04/2018 07:10 AM. Place : JUNCTION OF UPP EAST COAST RD & BEDOK SOUTH AVE 1

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Apr 2018 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TEY SU MIN, JUNE , ID: S7318689G, Tel: +6597928609								
Main Claimant:	AU SOON LANG , ID: S1173362Z								
Vehicle Reg. No.:	SDB6673K	Date of Loss:	04/04/2018 07:00 - :59 [145 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8515928646SG	Policy/Cover Note No.:	2100301745						
Vehicle Reg. No. (Insured):	SKB1508E	Policy No. (Claimant):	DMPC18S001277						
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/04/2018]								
Driver/Custodian (Insured):	VINCENT CHIA KHENG BOON (), NRIC: S7340323E								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDB6673K (8515928646SG)**
[SKB1508E]
TP
AU SOON LANG
Apr 4 2018 7:00AM
[TEY SU MIN, JUNE]
Hock Wah Motor Workshop Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		<input type="checkbox"/>
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/04/18 10:17	Accident Statement From: SC - Reg. No: SKB1508E, Claimant: TEY SU MIN, JUNE	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 21:11	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/04/18 21:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/04/18 21:13	General View	Load JPG	<input checked="" type="checkbox"/>
19	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
20	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
21	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
22	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
23	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
24	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
25	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
26	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
27	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>
28	06/04/18 21:14	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/04/18 21:15	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/04/18 21:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/04/18 21:17	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/04/18 21:18	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/04/18 21:19	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 21:53	TP GIA REPORT	 Load PDF	
2	09/04/18 10:47	LETTER TO INSURED	 Load PDF	
3	09/04/18 23:21	TP ESTIMATE - MARKED	 Load PDF	
4	26/04/18 16:26	AUTHORISATION TO ACT	 Load PDF	
5	26/04/18 16:26	GIA SEARCH	 Load PDF	
6	26/04/18 16:26	RELEASE VOUCHER	 Load PDF	
7	26/04/18 16:26	RENTAL RECEIPT	 Load PDF	
8	26/04/18 16:26	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKB1508E (Insd veh)	Model:	HONDA CIVIC 1.8 L (A)
	SDB6673K (TP veh)		
Date of Accident:	04/04/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	4,673.10
Final Repair Cost	:	\$	3,103.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	700.00 7 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	3,805.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hock Wah Motor Workshop Pte Ltd	:	\$ 3,805.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

26 Apr
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18006354/UJA3S2
Date: 26/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100301745
 Claimant Vehicle No : SDB6673K Insured Vehicle No : SKB1508E
 Date of Loss: 04/04/2018 Nature of Claim: TP Claim No: 8515928646SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDB6673K**
 Make & Model: HONDA CIVIC, 1.8 L (A) Engine No: R18A11014665
 Reg. Date: 02/03/2006 (Man. Year: 2006) Chassis No: JHMFD16306S204411
 Colour: Silver Odometer: 158837 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,987.38	1,683.54	303.84	15.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,960.00	420.00	17.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,367.38	3,643.54	723.84	16.57
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,367.38	2,900.00	1,467.38	33.60
+ GST 7.00/7.00% (S\$)	305.72	203.00	102.72	33.60
Nett Amount (S\$)	4,673.10	3,103.00	1,570.10	33.60
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,805.00		

INSPECTION

Date of Assignment: 06/04/2018
 Date Inspected: 06/04/2018 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 2008/2010/2012
 Singapore 489977
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID HINGE LH	Repair	48.60 FL	*- FL
2	1		*BOOTLID HINGE RH	Repair	48.60 FL	*- FL
3	1		*BOOTLID EMBLEM	Necessary	24.10 FL	*24.10 FL
4	1		*BOOTLID LOGO - 1.6	Necessary	22.70 FL	*22.70 FL
5	1		*BOOTLID LOGO - CIVIC	Necessary	28.80 FL	*28.80 FL
6	1		*BOOTLID LOGO - I-VTEC	Necessary	33.50 FL	*33.50 FL
7	1		*BOOTLID REFLECTOR RH	Cracked	145.90 FL	*145.90 FL
8	1		*BOOTLID REFLECTOR LH	Not Necessary	145.90 FL	*- FL
9	1		*BOOTLID INNER LOCK	Twisted	181.90 FL	*181.90 FL
10	1		*END PANEL	Badly Dented	300.80 FL	*300.80 FL
11	1		*END PANEL TOP GARNISH	Twisted	56.10 FL	*56.10 FL
12	3		*END PANEL TOP GARNISH CLIP	Not Necessary	11.70 FL	*- FL
13	1		*TAILLAMP O/S	Cracked	226.22 FL	*226.22 FL
14	1		*BOOTLID RUBBER	Twisted	97.60 FL	*97.60 FL
15	1		*REAR BUMPER	Distorted	638.00 FL	*638.00 FL
16	1		*REAR BUMPER RETAINER RH	Bent	17.00 FL	*17.00 FL
17	1		*REAR BUMPER RETAINER LH	Necessary	17.00 FL	*17.00 FL
18	4		*REAR BUMPER CLIP	Necessary	14.80 FL	*14.80 FL
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Bent	30.00 FS	*20.00 FS
21	1		*REAR NUMBER PLATE HOLDER	Bent	30.00 FS	*20.00 FS
22	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
23	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,399.22	2,044.42
- List Item Discount on L Items 20.00/20.00% (\$\$)	411.84	360.88
Total Parts (\$\$)	1,987.38	1,683.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS.	New	1,000.00	900.00
2	SPRAY PAINT ON THE AFFECTED AREAS.	New	1,000.00	900.00
3	ANTI-RUST COATING.	New	150.00	80.00
4	ANTI-RUST COATING. (NPA)	New	0.00	0.00
5	WIRING.	New	80.00	30.00
6	TO REMOVE & REFIT REVERSE SENSOR.	New	150.00	50.00
Gross Labour Cost (S\$)			2,380.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >