

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1173362Z
 AU SOON LANG
 NO

SINGAPORE
 TEL : FAX :
 PH : 9
 ATTN :

ESTIMATE BILL

Number : EB00004795
 Date : 05/04/2018
 Case No : AD00009655
 Vehicle No : SDB6673K
 Chassis: JHMFD16306S204411
 Year of Mfr 2006
 Policy No
 Model : HONDA CIVIC

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED SEVENTY-THREE AND CENTS TEN ONLY			Less Excess		0.00
			SUBTOTAL		4,367.38
			GST 7.00%		305.72
			TOTAL		4,673.10

Date of accident : 04/04/2018 07:10 AM. Place : JUNCTION OF UPP EAST COAST RD & BEDOK SOUTH AVE 1

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE