

summary ✓
after print ✓

21002100

ASS. REC. BY:

REF: CS/EQI18006357/89d36

Special Instruction:

Surveyor: Sebastian
Menner

ASSIGNMENT (Office)

From (Person): Joel Goh of EQI Date/Time: 5/4/18 @ 4:31pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 9663E Insured: _____

at Workshop n/s: Elite Automotive Tel: 93882885/8136 4741/6339 737

of 280 woodlands Ind. Prk E5 #01-17

Policy No: DMPPHQ17-004513 Claim No: DM18HO00761-JG

Sum Insured: _____ Excess: \$ 300.00

Make of Veh: _____ D.O.A. 21/03/2018
(Client's Record)

CA / REA / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 8:48am 06/4/18 Person Contacted: Christy Vehicle: IN / UT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKH 9663E - X</u>
<u>09/4/18 @</u>	<u>3:36pm revert to Joel Goh via Menner.</u>
<u>13/4/18 @</u>	<u>3:39pm Joel Goh informed C/A at LS @ 9500 & EX @ \$300 via Menner.</u>
<u>16/4/18 @</u>	<u>1:12pm informed Christy C/A not more than LS @ 9500 & EX: \$300 by email.</u>
<u>26/4/18 @</u>	<u>12:33pm confirmed with Christy LS @ 5500, 6 days by email.</u>
	<u>(Ref B)</u>

REF: EQI

ASSIGNMENT

From

Date: 06/04/18

Estimated Cost

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SKH 9663E

at Workshop mis: Elite Automotive

at 280 woodlands Ind Prk E5 #01-17

Insured:

Policy No:

Claims No:

Sum Insured:


Excess: \$ 300.00

(Client's Record)

Make of Veh:

After 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKH 9663E

Yr Regn: 17/9/2012

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Camry

CC 1998

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 211012

T/Radio: Insured / Std / NI / NA

Eng No:

C/No: MKR053BK Y104003188

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ NR / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 24/3/18

D.O.I: 6/4/18

Survey held at: Elite

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 JUL 2018

Case/Time: File Pass to?

126/7 1/18

Date/Time: File Return to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1 S - RT \$1

2 Photo

3 Chair

4

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Insp (\$)☐ : Weekend (\$)

Report Format:

PCR-00

Lump Sum / I.B.T.S

5800

300

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18006357/Sqd3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 06-04-2018		
		Code : EQI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SKH 9663E	
Policy No.	Coverage (\$)		0.00	
Claim No. DM18HO00761-JG	Excess (\$)		300.00	
Assign From MERIMEN (JOEL GOH)	Assign Date		06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 24/03/2018	Inspection Date		06/04/2018	
Survey held at	ELITE AM PTE. LTD. 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST @ WOODLANDS, 757322 WOODLANDS			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Sendback Est	05 Apr 2018 14:02 S\$20,526.15	05 Apr 2018 16:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	PRECAST STEEL FIXERS PTE LTD, Co. Reg. No.: 200617696Z, Tel: +6598559251			
Vehicle Reg. No.:	SKH9663E	Date of Loss:	24/03/2018 16:00 - :59 [66 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / DM18HO00761-JG	Policy/Cover Note No.:	DMPHQ17-004513 (Comprehensive) Coverage: 01/04/2017 - 31/03/2018	
		Excess:	S\$300.00	
Repairer:	Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands, 757322 Woodlands - Tel: 9388 2885/8136 4741/63397378			
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2018]			
Driver/Custodian:	CHAN KOK JIN (56 / Male), NRIC: S2511081A, Tel: +6598559251			
Adj Asg. Remarks:	EXCESS: \$300.00 AFTER 50% DISCOUNT			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Elite AM <eliteamclaim@gmail.com>
Sent: Thursday, 26 July 2018 12:33 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: Re: VEHICLE SKH 9663E (DOA: 24/03/18)

Hi Shiau Chan,

Good day! We accept the offer.Thanks!

Regards,

Christy

On Wed, 25 Jul 2018, 15:45 Shiau Chan (LKKAUTO), <siewsc@lkkauto.com> wrote:

Dear Christy,

WITHOUT PREJUDICE

Offer Lump Sum \$5,800.00 before excess \$300.00 & GST and 6 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 16 April 2018 1:12 PM

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 16 April 2018 1:12 PM
To: 'Elite AM'
Cc: SUR
Subject: RE: VEHICLE SKH 9663E (DOA: 24/03/18)

Dear Christy,

As instructed by our client EQI Insurance, please proceed to repair the insured vehicle **SKH 9663E** at repair cost not more Lump Sum \$9,500.00 (Excess \$300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Apr 2018 16:16	Cim Veh Model Changed	(201714) TOYOTA CAMRY 2.0 (A).	[R] Lim Wee Kiang
2	03 Apr 2018 16:16	Cim Created	Reg No: SKH9663E. Policy No: DMPPHQ17-004513. Acct Date: 2018/03/24. Claim Type: OD. Insurer: EQ Insurance Company Ltd (HQ). Workshop: Elite Automotive Pte Ltd (HQ)	[R] Lim Wee Kiang
3	05 Apr 2018 14:02	Cim Submitted	20526.15.	[R] Lim Wee Kiang
4	05 Apr 2018 16:31	Cim Registration Modified	Excess: -> 300.00.	[I] Joel Goh
5	05 Apr 2018 16:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):EXCESS: \$300.00 AFTER 50% DISCOUNT	[I] Joel Goh
6	05 Apr 2018 16:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/16	[I] Joel Goh
7	05 Apr 2018 16:31	Adj Mandate Set	Approved:0.00,	[I] Joel Goh
8	06 Apr 2018 08:26	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	06 Apr 2018 10:31	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen	[A] Nivitha Govindasamy
10	09 Apr 2018 15:25	Adj Rpt Initiated		[A] SHIAU CHAN
11	09 Apr 2018 15:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/16	[A] SHIAU CHAN
12	09 Apr 2018 15:36	Adj Mandate Request	Cur,Req:11870.15:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	13 Apr 2018 15:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/16. Mandate Remarks: OD AUTHORISED UP TO \$9,500.00 BEFORE EXCESS OF \$300.00	[I] Joel Goh
14	13 Apr 2018 15:38	Adj Mandate Set	Approved:9500.00:OD AUTHORISED UP TO \$9,500.00 BEFORE EXCESS OF \$300.00 Reinsp:Adj decides.	[I] Joel Goh

Date From



Date To



Audit Type None

Go

ACTIVITY

[06/04/2018 08:51] Nivitha Govindasamy:
Vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1766156	03/04/2018 16:16	Motor	Elite Automotive Pte Ltd(HQ)	Elite Automotive Pte Ltd (HQ)	SKH9663E		xx.xx
1771147	09/04/2018 15:25	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKH9663E		10.70

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 09 Apr 2018

Preliminary Advice

Vehicle No	: SKH9663E	Accident Date	: 24/03/2018
Make	: TOYOTA CAMRY	Policy No.	: DMPPHQ17-004513
Assignment Date	: 05/04/2018	Excess	: S\$300.00
Date of Inspection	: 06/04/2018	Est. Duration of Repair	: 6.00
Inspection At	: ELITE AUTOMOTIVE PTE LTD (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-17, HARVEST@WOODLANDS SINGAPORE 757322		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,526.15
Revised Amount	:S\$	4,474.00
Check Items (Estimated)	:S\$	7,396.15
Total	:S\$	11,870.15

Lump Sum Repair	:S\$	9,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	55,470.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,530.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7696Z
Vehicle Details	
Vehicle No.:	SKH9663E
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	1AZE249377
Chassis No.:	MR053BK5104003188
Maximum Power Output:	109.0 kW (146 bhp)
Open Market Value:	\$23,475.00
Original Registration Date:	17 Sep 2012
First Registration Date:	17 Sep 2012
Transfer Count:	0
Actual ARF Paid:	\$23,475.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2022
PARF Rebate Amount:	\$16,432.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$88,002.00
COE Rebate Amount:	\$39,038.00
Total Rebate Amount:	\$55,470.00

The information contained herein is correct as at 09 Apr 2018

OK

MV 67K.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKH9663E
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	CAMRY 2.0 AUTO
Chassis No. :	MR053BK5104003188
Propellant :	Petrol
Engine No. :	1AZE249377
Engine Capacity :	1998 cc
Maximum Power Output :	109.0 kW (146 bhp)
Maximum Laden Weight :	2000 kg
Unladen Weight :	1445 kg
Year Of Manufacture :	2012
Original Registration Date :	17 Sep 2012
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$88,002.00
COE Expiry Date :	16 Sep 2022
Road Tax Expiry Date :	16 Sep 2018
PARF Eligibility Expiry Date :	16 Sep 2022
Inspection Due Date :	16 Sep 2019
Intended Transfer Date :	09 Apr 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

- Reckless Cyclists
- Insufficient cash card driver today I met
- Tyre pressure

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Only 5 Months Old, Lexus RX200 Turbo, Price Negotiable!



Almost New! Mileage 6,000km,
5 Years Warranty! In House
Finance, High Trade In,
Speedo Motoring, StarAd



Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

Camry 2.0A

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Camry 2.0A	Any	Any	2012	Any	Any	Any	Available
	Toyota Camry 2.0A	\$67,800	\$12,720 /yr	05-Sep-2012	1,998 cc	-	Luxury	Available
Promotion Interest Rate As Low As 1.99%! Extremely Reliable Luxurious Sedan And Practical Boot Space Up To 440L! Humongous Interior, More Than What Is Needed To Fill Up With 5 Adults! With It's 2 Tone... Dickson Automobile Posted: 11-Mar-2018 Tags: 2012 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$69,800	\$13,790 /yr	25-Jun-2012	1,998 cc	89,000 km	Luxury	Available
Very Well Maintained. Beautiful Paint Work, Original Condition. Call Now For Enquires And Viewing Today! Posted: 07-Mar-2018 Tags: 2012 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$69,800	\$14,320 /yr	30-Apr-2012	1,998 cc	116,299 km	Luxury	Available
Just Arrived! 1 Owner Car, Very Well Maintained. High Loan With High Trade In. Price Negotiable. Call Now! Posted: 12-Feb-2018 Tags: 2012 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Camry 2.0A, Camry 2.0A Singapore, used Camry 2.0A Singapore, used Camry 2.0A, used vehicles Singapore or even buy used Camry 2.0A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/03/2018 20:17
Date Of Accident	24/03/2018 16:50
Exact Location Of Accident	SLE(CTE) BEFORE TPE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH9663E
Insured/Policyholder	
Name Of Registered Owner	PRECAST STEEL FIXERS PTE LTD
Co Reg No	200617696Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98569251
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-004513
Cover Note Number	

Driver

Name of Driver	CHAN KOK JIN
NRIC No	S2511081A
Date Of Birth	17/08/1961
Occupation	INDOOR
Date Of Driving Pass	29/06/1985
Driving Experience	32 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98569251
Fax Number	
Contact Number	
Email Address	CHAN@TSSCONSTRUCTION.COM.SG

Address 125 KEW CRESCENT SINGAPORE 466162

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was traveling along SLE(CTE) on the 2nd lane from the right. Lane on the right lane was closed for construction work. Car SJR2335H in front of me made a sudden braking. I managed to brake but could not stop on time and collided onto the rear of car SJR2335H. There is a taxi SHD9749Z in front of car SJR2335H. I was not certain if car SJR2335H had collided onto taxi SHD9749Z. Damages to my car were on the front portion. I suspect my undercarriage had liquid leakage. No injuries were involved.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR2335H

Vehicle Make/Model/Colour TOYOTA/WISH 1.8X A

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TAN

NRIC/Passport Number

Contact Number 96323682

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD9749Z
Vehicle Make/Model/Colour	RENAULT/LATITUDE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	CHAI
NRIC/Passport Number	
Contact Number	96518254
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

REPORTING OFFICER

IMPORTANT NOTES

1. This report is intended for use as evidence in the event of a claim against the Insurer(s).
2. This report must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as factual and accurate as possible. Any willful misrepresentation or withholding of material facts may render the Insurer(s) liable to repudiate the claim.
4. The facts and circumstances of this loss to Insurers' convenience is not an admission of policy liability on the part of Insurers' convenience.
5. Any fines levied may be referred to the Police for investigation.
6. The report will be forwarded by the Insurer(s) to the GAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the completion of this report to the Insurer(s), you hereby consent to the issuing of this report to the Insurer(s) and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information"; and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicles involved in this accident (all Insurer(s) who have insured vehicles involved in this Accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) collectively the "Purposes";
 - (c) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (d) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Bin Pabla

Policyholder's Signature / Date & Time

Driver's Signature (If driver is NOT the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was traveling along SLE(CTE) on the 2nd lane from the right. Lane on the right lane was closed for construction work. Car SJR2335H in front of me made a sudden braking. I managed to brake but could not stop on time and collided onto the rear of car SJR2335H. There is a taxi SHD9749Z in front of car SJR2335H. I was not certain if car SJR2335H had collided onto taxi SHD9749Z.

Damages to my car were on the front portion. I suspect my undercarriage had liquid leakage. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time:

24 March 2018 at 7:39 PM

Date/Time:

24 March 2018 at 7:39 PM

Elite Automotive Pte Ltd (Co.Reg.No:201700196D)
 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands
 Singapore 757322

Tel: 9388 2885/8136 4741/63397378 Fax: 63397475 Email: elite.automotive13@gmail.com

INSURER: EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ17-004513	Date of Loss:	24/03/2018
Vehicle Reg. No.:	SKH9663E	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PRECAST STEEL FIXERS PTE LTD	Contact No:	+6598559251
Driver:	CHAN KOK JIN		
Make/Model:	TOYOTA CAMRY, 2.0 (A)	Vehicle Reg. Date:	17/09/2012
Vehicle Colour:	SILVER		
Engine No:	1AZE249377	Chassis No:	MR053BK5104003188
Odometer:	210811 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	ELITE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	17,136.15
Miscellaneous Items	60.00
Labour	3,330.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	20,526.15
- Excess (S\$)	600.00
(S\$)	19,926.15
+ GST 7.00% (S\$)	1,394.83
Nett Amount (S\$)	21,320.98

This claim is handled by: LIM WEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2018)

Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKH9663E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ✓ BT	0.00	0.00	*380.00 F
2	2		*BONNET HINGE ✓ BT	0.00	0.00	*100.00 F
3	1		*BONNET LOCK ✓ BT	0.00	0.00	*80.00 F
4	1		*BONNET INSULATION	0.00	0.00	*180.00 F (XNN)
5	10		*BONNET INSULATION CLIPS	0.00	0.00	*30.00 F (NEC)
6	1		*RHS FRONT FENDER R	0.00	0.00	*200.00 F
7	1		*RHS FRONT FENDER SPLASH SHIELD ✓ Defect	0.00	0.00	*120.00 F
8	10		*RHS FRONT FENDER SPLASH SHIELD CLIPS ✓ NEC	0.00	0.00	*30.00 F
9	1		*LHS FRONT FENDER R	0.00	0.00	*200.00 F
10	1		*LHS FRONT FENDER SPLASH SHIELD ✓ Defect	0.00	0.00	*120.00 F
11	10		*LHS FRONT FENDER SPLASH SHIELD CLIPS ✓ NEC	0.00	0.00	*30.00 F
12	1		*BONNET MOULDING ✓ BT	0.00	0.00	*120.00 F
13	1		*FRONT GRILLE ✓ CRK	0.00	0.00	*200.00 F
14	1		*FRONT GRILLE EMBLEM ✓ NEC	0.00	0.00	*50.00 F
15	2		*HEADLAMP LH SCR RH ? ✓ CR	0.00	0.00	*900.00 F
16	2		*HEADLAMP RETAINER ? XNN	0.00	0.00	*56.00 F
17	1		*FRONT BUMPER ✓ CRK	0.00	0.00	*280.00 F
18	1		*FRONT BUMPER REINFORCEMENT ? ✓ VDP	0.00	0.00	*190.00 F
19	10		*FRONT BUMPER CLIPS ✓ NEC	0.00	0.00	*30.00 F
20	1		*FRONT BUMPER AIR GRILLE ? ✓ CR	0.00	0.00	*80.00 F
21	2		*FRONT BUMPER SIDE RETAINER ? ✓ PE	0.00	0.00	*90.00 F
22	1		*FRONT BUMPER FOAM/SPONGE ✓ CRK	0.00	0.00	*60.00 F
23	1		*FRONT LOCK BRACKET ? ✓ BT	0.00	0.00	*80.00 F
24	1		*FRONT SUPPORT PANEL ? ✓ PE	0.00	0.00	*280.00 F
25	1		*FRONT TOP PANEL ? ✓ BT	0.00	0.00	*180.00 F
26	1		*FRONT TOP PANEL COVER ? ✓ PE	0.00	0.00	*150.00 F
27	10		*FRONT TOP PANEL COVER CLIPS ? ✓ NEC	0.00	0.00	*30.00 F
28	1		*FRONT TOP PANEL AIR DUCT ? ✓ TR	0.00	0.00	*120.00 F
29	1		*FRONT BUMPER RETAINER ? XNN	0.00	0.00	*45.00 F
30	1		*A/C CONDENSER C/W RECEIVER DRYER ? ✓ BT	0.00	0.00	*550.00 F
31	1		*A/C HIGH PRESSURE HOSE ? XNN	0.00	0.00	*280.00 F
32	1		*A/C SUCTION HOSE ? XNN	0.00	0.00	*250.00 F
33	1		*A/C COOLING HOSE ? XNN	0.00	0.00	*200.00 F
34	1		*RADIATOR ? XNN	0.00	0.00	*650.00 F
35	2		*RADIATOR TOP MOUNTING ? XNN	0.00	0.00	*40.00 F
36	2		*RADIATOR TOP MOUNTING BRACKET ? XNN	0.00	0.00	*50.00 F
37	1		*RADIATOR RESERVE TANK ? XNN	0.00	0.00	*150.00 F

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
38	1		*ALTERNATOR X nn	0.00	0.00	*650.00 F
39	1		*ALTERNATOR BEARING X nn	0.00	0.00	*90.00 F
40	1		*FAN BELT X nn	0.00	0.00	*110.00 F
41	1		*FUSE BOX ASSY X nn	0.00	0.00	*250.00 F
42	1		*RADIATOR FAN COWLING ? X nn	0.00	0.00	*120.00 F
43	1		*RADIATOR ELECTRIC FAN ASSY ? X nn	0.00	0.00	*250.00 F
44	1		*EXHAUST MANIFOLD COVER X nn	0.00	0.00	*350.00 F
45	1		*A/C ELECTRIC FAN ASSY ? X nn	0.00	0.00	*350.00 F
46	1		*WINDSCREEN WASHER TANK ? X nn	0.00	0.00	*120.00 F
47	1		*ABS PUMP X nn	0.00	0.00	*4,530.00 F
48	2		*FRONT FENDER TOP COVER X nn	0.00	0.00	*160.00 F
49	1		*FRONT NUMBER PLATE BASE GARNISH ✓ B7	0.00	0.00	*90.00 F
50	2		*FRONT FOG LAMP ? X nn	0.00	0.00	*360.00 F
51	2		*FRONT FOG LAMP COVER ? X nn	0.00	0.00	*160.00 F
52	1		*FRONT TOW HOOK COVER ? X nn	0.00	0.00	*25.00 F
53	2		*FRONT FENDER NAME PLATE (EMBLEM) ✓ NFE	0.00	0.00	*120.00 F
54	1		*RADIATOR COOLANT ? ✓ ncc	0.00	0.00	*25.00 F
55	2		*HEADLAMP PANEL ? X nsp	0.00	0.00	*560.00 F

F=Franchise part.

Sub Total (S\$)	14,901.00
+ Margin on L,N Items 15.00% (S\$)	2,235.15
Total Parts (S\$)	17,136.15

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE C/W HOLDER ✓ RT	45 60.00
Sub Total (S\$)			60.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Labour charges to remove & install front end attachments & fittings to enable repairs; to cut, replace & weld front panellings as listed above; to straighten & repairs RHS & LHS front fender inner panels wheelhousings and front body member; to replace damaged parts as listed above	New	900 1,500.00
2	To spary painting on:- Bonnet (inner & outer), RHS & LHS front fenders, fenders inner panels & wheelhousings front bumper and front panellings	New	900 1,400.00
3	To remove & replace A/C condenser C/W receiver dryer & A/C hoses; to vacuum & charge up gas	New	80 150.00
4	To remove & replace radiator & electric fans; to pressurize cooling system	New	60 80.00
5	To remove & replace both headlamps; to check electrical wirings & lights functions, including focus headlights	New	30 50.00
6	To remove, check and calibrate electrical system after accident repairs	New	100 150.00
Gross Labour Cost (S\$)			3,330.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >


 6/4/18
 Sebastian
 6/4/18
 - Excess : 4300
 - Repair
 - Lump Sum Repair
 - Question Made Item Photo
 - Photo After Paint
 90036121

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.yong@lkkauto.com

Elite Automotive Pte Ltd (Co.Reg.No:201700196D)

280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands

Singapore 757322

Tel: 9388 2885/8136 4741/63397378 Fax: 63397475 Email: elite.automotive13@gmail.com

INSURER: EQ Insurance Company Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ17-004513	Date of Loss:	24/03/2018
Vehicle Reg. No.:	SKH9663E	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PRECAST STEEL FIXERS PTE LTD	Contact No:	+6598559251
Driver:	CHAN KOK JIN		
Make/Model:	TOYOTA CAMRY, 2.0 (A)	Vehicle Reg. Date:	17/09/2012
Vehicle Colour:	SILVER		
Engine No:	1AZE249377	Chassis No:	MR053BK5104003188
Odometer:	210811 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	ELITE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	17,136.15
Miscellaneous Items	60.00
Labour	3,330.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	20,526.15
- Excess (S\$)	600.00
(S\$)	19,926.15
+ GST 7.00% (S\$)	1,394.83
Nett Amount (S\$)	21,320.98

This claim is handled by: LIM WEE KIANGGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2018)

Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKH9663E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ✓ BT	0.00	0.00	*380.00 F
2	2		*BONNET HINGE ✓ BT	0.00	0.00	*100.00 F
3	1		*BONNET LOCK ✓ BT	0.00	0.00	*80.00 F
4	1		*BONNET INSULATION X NE	0.00	0.00	*180.00 F
5	10		*BONNET INSULATION CLIPS ✓ NE	0.00	0.00	*30.00 F
6	1		*RHS FRONT FENDER R	0.00	0.00	*200.00 F
7	1		*RHS FRONT FENDER SPLASH SHIELD ✓ Defect	0.00	0.00	*120.00 F
8	10		*RHS FRONT FENDER SPLASH SHIELD CLIPS ✓ NE	0.00	0.00	*30.00 F
9	1		*LHS FRONT FENDER R	0.00	0.00	*200.00 F
10	1		*LHS FRONT FENDER SPLASH SHIELD ✓ Defect	0.00	0.00	*120.00 F
11	10		*LHS FRONT FENDER SPLASH SHIELD CLIPS ✓ NE	0.00	0.00	*30.00 F
12	1		*BONNET MOULDING ✓ BT	0.00	0.00	*120.00 F
13	1		*FRONT GRILLE ✓ CR	0.00	0.00	*200.00 F
14	1		*FRONT GRILLE EMBLEM ✓ NE	0.00	0.00	*50.00 F
15	2		*HEADLAMP LH SCR RH ✓ CR	0.00	0.00	*900.00 F
16	2		*HEADLAMP RETAINER ? X NSP	0.00	0.00	*56.00 F
17	1		*FRONT BUMPER ✓ CR	0.00	0.00	*280.00 F
18	1		*FRONT BUMPER REINFORCEMENT ? ✓ DT	0.00	0.00	*190.00 F
19	10		*FRONT BUMPER CLIPS ✓ NE	0.00	0.00	*30.00 F
20	1		*FRONT BUMPER AIR GRILLE ? ✓ CR	0.00	0.00	*80.00 F
21	2		*FRONT BUMPER SIDE RETAINER ? ✓ Defect	0.00	0.00	*90.00 F
22	1		*FRONT BUMPER FOAM/SPONGE ✓ CR	0.00	0.00	*60.00 F
23	1		*FRONT LOCK BRACKET ? ✓ BT	0.00	0.00	*80.00 F
24	1		*FRONT SUPPORT PANEL ? ✓ Defect	0.00	0.00	*280.00 F
25	1		*FRONT TOP PANEL ? ✓ DT	0.00	0.00	*180.00 F
26	1		*FRONT TOP PANEL COVER ? ✓ Defect	0.00	0.00	*150.00 F
27	10		*FRONT TOP PANEL COVER CLIPS ? ✓ NE	0.00	0.00	*30.00 F
28	1		*FRONT TOP PANEL AIR DUCT ? ✓ TN	0.00	0.00	*120.00 F
29	1		*FRONT BUMPER RETAINER ? X	0.00	0.00	*45.00 F
30	1		*A/C CONDENSER C/W RECEIVER DRYER ? ✓ BT	0.00	0.00	*550.00 F
31	1		*A/C HIGH PRESSURE HOSE ? X	0.00	0.00	*280.00 F
32	1		*A/C SUCTION HOSE ? X	0.00	0.00	*250.00 F
33	1		*A/C COOLING HOSE ? X	0.00	0.00	*200.00 F
34	1		*RADIATOR ? X	0.00	0.00	*650.00 F
35	2		*RADIATOR TOP MOUNTING ? X	0.00	0.00	*40.00 F
36	2		*RADIATOR TOP MOUNTING BRACKET ? X	0.00	0.00	*50.00 F
37	1		*RADIATOR RESERVE TANK ? X	0.00	0.00	*150.00 F

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
38	1		*ALTERNATOR X	0.00	0.00	*650.00 F
39	1		*ALTERNATOR BEARING X	0.00	0.00	*90.00 F
40	1		*FAN BELT X	0.00	0.00	*110.00 F
41	1		*FUSE BOX ASSY X	0.00	0.00	*250.00 F
42	1		*RADIATOR FAN COWLING ? X	0.00	0.00	*120.00 F
43	1		*RADIATOR ELECTRIC FAN ASSY ? X	0.00	0.00	*250.00 F
44	1		*EXHAUST MANIFOLD COVER X	0.00	0.00	*350.00 F
45	1		*A/C ELECTRIC FAN ASSY ? X	0.00	0.00	*350.00 F
46	1		*WINDSCREEN WASHER TANK ? X	0.00	0.00	*120.00 F
47	1		*ABS PUMP X	0.00	0.00	*4,530.00 F
48	2		*FRONT FENDER TOP COVER X	0.00	0.00	*160.00 F
49	1		*FRONT NUMBER PLATE BASE GARNISH ✓ B7	0.00	0.00	*90.00 F
50	2		*FRONT FOG LAMP ? X	0.00	0.00	*360.00 F
51	2		*FRONT FOG LAMP COVER ? X	0.00	0.00	*160.00 F
52	1		*FRONT TOW HOOK COVER ? X	0.00	0.00	*25.00 F
53	2		*FRONT FENDER NAME PLATE (EMBLEM) ✓ NE	0.00	0.00	*120.00 F
54	1		*RADIATOR COOLANT ? ✓ NRC	0.00	0.00	*25.00 F
55	2		*HEADLAMP PANEL ? X NSP	0.00	0.00	*560.00 F

F=Franchise part.

Sub Total (S\$)	14,901.00
+ Margin on L,N Items 15.00% (S\$)	2,235.15
Total Parts (S\$)	17,136.15

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE C/W HOLDER ✓ 87	45 60.00
Sub Total (S\$)			60.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Labour charges to remove & install front end attachments & fittings to enable repairs; to cut, replace & weld front panellings as listed above; to straighten & repairs RHS & LHS front fender inner panels wheelhousings and front body member; to replace damaged parts as listed above	New	900 1,500.00
2	To spary painting on:- Bonnet (inner & outer), RHS & LHS front fenders, fenders inner panels & wheelhousings front bumper and front panellings	New	900 1,400.00
3	To remove & replace A/C condenser C/W receiver dryer & A/C hoses; to vacuum & charge up gas	New	80 ? 150.00
4	To remove & replace radiator & electric fans; to pressurize cooling system	New	60 ? 80.00
5	To remove & replace both headlamps; to check electrical wirings & lights functions, including focus headlights	New	30 50.00
6	To remove, check and calibrate electrical system after accident repairs	New	100 ? 150.00
Gross Labour Cost (S\$)			3,330.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6 days

Sebastian

6/4/18

- Excess : \$ 300
- Revert
- Long Sum Repair
- Question Mark Item Photo
- Photo After Paint

90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Sendback Est	05 Apr 2018 14:02 \$20,526.15	05 Apr 2018 16:31 Edit Adj Rpt	\$5,800.00 Edit Estimates	\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: PRECAST STEEL FIXERS PTE LTD, Co. Reg. No.: 200617696Z, Tel: +6598559251									
Vehicle Reg. No.: SKH9663E		Date of Loss: 24/03/2018 16:00 - :59 [66 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DM18HO00761-JG		Policy/Cover Note No.: DMPPHQ17-004513 (Comprehensive) Coverage: 01/04/2017 - 31/03/2018							
		Excess: S\$300.00							
Repairer: Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands, 757322 Woodlands - Tel: 9388 2885/8136 4741/63397378									
Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 16/04/2018]									
Driver/Custodian: CHAN KOK JIN (56 / Male), NRIC: S2511081A, Tel: +6598559251									
Adj Asg. Remarks: EXCESS: \$300.00 AFTER 50% DISCOUNT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
EQT_HQ (13/04/2018): Alert - Adj Mandate Approved (\$9500.00) - SKH9663E - Claim Handler: Joel Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKH9663E (DM18HO00761-JG)
OD
Mar 24 2018 4:00PM
[PRECAST STEEL FIXERS PTE LTD]
Elite Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Elite Automotive Pte Ltd (HQ)		Thumbnail	Print					
1	05/04/18 14:02	Repairer Estimates			Load HTML					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	09/04/18 15:35	Adjuster Immediate Advice			Load HTML					
Photos/Images							3 per page		☒	
No	Finalized On	Elite Automotive Pte Ltd (HQ)		Thumbnail	Print					
1	06/04/18 09:47	Accident Photo			Load JPG	☒				
2	06/04/18 09:47	Accident Photo			Load JPG	☒				
3	06/04/18 09:47	Accident Photo			Load JPG	☒				
4	06/04/18 09:47	Accident Photo			Load JPG	☒				
5	06/04/18 09:47	Accident Photo			Load JPG	☒				
6	06/04/18 09:47	Accident Photo			Load JPG	☒				
7	06/04/18 09:47	Accident Photo			Load JPG	☒				
8	06/04/18 09:47	Accident Photo			Load JPG	☒				
9	06/04/18 09:47	Accident Photo			Load JPG	☒				
10	06/04/18 09:47	Accident Photo			Load JPG	☒				
11	06/04/18 09:47	Accident Photo			Load JPG	☒				
12	06/04/18 09:47	Accident Photo			Load JPG	☒				
13	06/04/18 09:47	Accident Photo			Load JPG	☒				
14	06/04/18 09:47	Accident Photo			Load JPG	☒				
15	06/04/18 09:47	Accident Photo			Load JPG	☒				
16	06/04/18 09:47	Accident Photo			Load JPG	☒				
17	06/04/18 09:47	Accident Photo			Load JPG	☒				
18	06/04/18 09:47	Accident Photo			Load JPG	☒				
19	06/04/18 09:47	Accident Photo			Load JPG	☒				
20	06/04/18 09:47	Accident Photo			Load JPG	☒				
21	06/04/18 09:47	Accident Photo			Load JPG	☒				
22	06/04/18 09:47	Accident Photo			Load JPG	☒				
23	06/04/18 09:47	Accident Photo			Load JPG	☒				
24	06/04/18 09:47	Accident Photo			Load JPG	☒				
25	06/04/18 09:47	Accident Photo			Load JPG	☒				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	09/04/18 15:37	General View			Load JPG	☒				
2	09/04/18 15:37	General View			Load JPG	☒				
3	09/04/18 15:37	General View			Load JPG	☒				
4	09/04/18 15:37	General View			Load JPG	☒				
5	09/04/18 15:37	General View			Load JPG	☒				
6	09/04/18 15:37	General View			Load JPG	☒				
7	09/04/18 15:37	General View			Load JPG	☒				
8	09/04/18 15:37	General View			Load JPG	☒				

Assessment Reports			1 per page	☒
No	Finalized On	Elite Automotive Pte Ltd (HQ)	Thumbnail	Print
9	09/04/18 15:37	General View		☒
10	09/04/18 15:37	General View		☒
11	09/04/18 15:37	General View		☒
12	09/04/18 15:37	General View		☒
13	09/04/18 15:37	General View		☒
14	09/04/18 15:37	General View		☒
15	09/04/18 15:37	General View		☒
16	09/04/18 15:37	General View		☒
17	09/04/18 15:37	General View		☒
18	09/04/18 15:37	General View		☒
19	09/04/18 15:37	General View		☒
20	09/04/18 15:37	General View		☒
21	09/04/18 15:37	General View		☒
22	09/04/18 15:37	General View		☒
23	09/04/18 15:37	General View		☒
24	09/04/18 15:37	General View		☒
25	09/04/18 15:37	General View		☒
26	09/04/18 15:37	General View		☒
27	09/04/18 15:37	General View		☒
28	09/04/18 15:37	General View		☒
29	09/04/18 15:37	General View		☒
30	09/04/18 15:37	General View		☒
31	09/04/18 15:37	General View		☒
32	09/04/18 15:37	General View		☒
33	09/04/18 15:37	General View		☒
34	09/04/18 15:37	General View		☒
35	09/04/18 15:37	General View		☒
36	09/04/18 15:37	General View		☒
37	09/04/18 15:37	General View		☒
38	09/04/18 15:37	General View		☒
39	09/04/18 15:37	General View		☒
40	09/04/18 15:37	General View		☒
41	09/04/18 15:37	General View		☒
42	09/04/18 15:37	General View		☒
43	09/04/18 15:37	General View		☒
44	09/04/18 15:37	General View		☒
45	09/04/18 15:37	General View		☒
46	09/04/18 15:37	General View		☒
47	09/04/18 15:37	General View		☒
48	09/04/18 15:37	General View		☒
49	09/04/18 15:37	General View		☒
50	09/04/18 15:37	General View		☒
51	09/04/18 15:37	General View		☒
52	09/04/18 15:37	General View		☒
53	09/04/18 15:37	General View		☒
54	09/04/18 15:37	General View		☒
55	09/04/18 15:37	General View		☒
56	09/04/18 15:37	General View		☒
57	09/04/18 15:37	General View		☒
58	09/04/18 15:37	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	Elite Automotive Pte Ltd (HQ)	Thumbnail	Print
59	09/04/18 15:37	Odometer Reading	 Load JPG	☒
60	09/04/18 15:37	General View	 Load JPG	☒
61	09/04/18 15:37	Chassis Number	 Load JPG	☒
62	09/04/18 15:37	General View	 Load JPG	☒
63	09/04/18 15:37	General View	 Load JPG	☒
64	09/04/18 15:37	General View	 Load JPG	☒
65	09/04/18 15:37	General View	 Load JPG	☒
66	09/04/18 15:37	General View	 Load JPG	☒
67	09/04/18 15:37	General View	 Load JPG	☒
68	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
69	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
70	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
71	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
72	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
73	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
74	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
75	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
76	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
77	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
78	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
79	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
80	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
81	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
82	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
83	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
84	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
85	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
86	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
87	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
88	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
89	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
90	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
91	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
92	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
93	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
94	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
95	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
96	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
97	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
98	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
99	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
100	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
101	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
102	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
103	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
104	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
105	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
106	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
107	26/07/18 14:22	Reinspection Photo	 Load JPG	☒
108	26/07/18 14:22	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	Elite Automotive Pte Ltd (HQ)	Thumbnail	Print
109	26/07/18 14:22	Reinspection Photo		☒
110	26/07/18 14:22	Reinspection Photo		☒
111	26/07/18 14:22	Reinspection Photo		☒
112	26/07/18 14:22	Reinspection Photo		☒
113	26/07/18 14:22	Reinspection Photo		☒
114	26/07/18 14:22	Reinspection Photo		☒
115	26/07/18 14:22	Reinspection Photo		☒
116	26/07/18 14:22	Reinspection Photo		☒
117	26/07/18 14:22	Reinspection Photo		☒
118	26/07/18 14:22	Reinspection Photo		☒
119	26/07/18 14:22	Reinspection Photo		☒
120	26/07/18 14:22	Reinspection Photo		☒
121	26/07/18 14:22	Reinspection Photo		☒
122	26/07/18 14:22	Reinspection Photo		☒
123	26/07/18 14:22	Reinspection Photo		☒
124	26/07/18 14:22	Reinspection Photo		☒
125	26/07/18 14:22	Reinspection Photo		☒
126	26/07/18 14:22	Reinspection Photo		☒
127	26/07/18 14:22	Reinspection Photo		☒
128	26/07/18 14:22	Reinspection Photo		☒
129	26/07/18 14:22	Reinspection Photo		☒
130	26/07/18 14:22	Reinspection Photo		☒
131	26/07/18 14:22	Reinspection Photo		☒
132	26/07/18 14:22	Reinspection Photo		☒
133	26/07/18 14:22	Reinspection Photo		☒
134	26/07/18 14:22	Reinspection Photo		☒
135	26/07/18 14:22	Reinspection Photo		☒
136	26/07/18 14:22	Reinspection Photo		☒
137	26/07/18 14:22	Reinspection Photo		☒
138	26/07/18 14:22	Reinspection Photo		☒
139	26/07/18 14:22	Reinspection Photo		☒
140	26/07/18 14:22	Reinspection Photo		☒
141	26/07/18 14:22	Reinspection Photo		☒
142	26/07/18 14:22	Reinspection Photo		☒
143	26/07/18 14:22	Reinspection Photo		☒
144	26/07/18 14:22	Reinspection Photo		☒
145	26/07/18 14:22	Reinspection Photo		☒
Documentation			1 per page	
No	Finalized On	Elite Automotive Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 09:41	ACCIDENT REPORT (PAGE 1)		
2	06/04/18 09:41	ACCIDENT REPORT (PAGE 2)		
3	06/04/18 09:41	ACCIDENT REPORT (PAGE 3)		
4	06/04/18 09:41	ACCIDENT REPORT (PAGE 4)		
5	06/04/18 09:41	ACCIDENT REPORT (PAGE 5)		
6	06/04/18 09:41	Claimant's NRIC		☒
7	06/04/18 09:41	Claimant's NRIC		☒
8	06/04/18 09:41	Driver's Driving License		☒
9	06/04/18 09:41	Driver's Driving License		☒
10	06/04/18 09:41	Certificate of Insurance		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 15:38	ESTIMATE		

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)					
Show Remarks To: ☐ Repairer ☐ Handling Insurer					
Note: Remarks are private unless you show it to other parties.					

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ18006357/NQD3E2

Date: 06/08/2018

REFERENCE

Insured/Claimant: PRECAST STEEL FIXERS PTE LTD Policy No: DMPPHQ17-004513

Date of Loss: 24/03/2018

Nature of Claim: OD

Claim No: DM18HO00761-JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH9663E

Make & Model: TOYOTA CAMRY, 2.0 (A)

Engine No: 1AZE249377

Reg. Date: 17/09/2012 (Man. Year: 2012)

Chassis No: MR053BK5104003188

Colour: Silver

Odometer: 211012 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$67,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,136.15	5,192.25	11,943.90	69.70
Miscellaneous Items	60.00	45.00	15.00	25.00
Labour	3,330.00	2,070.00	1,260.00	37.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,526.15	7,307.25	13,218.90	64.40
Approved Total (Overridden) (S\$)		5,800.00		
- Excess (S\$)	600.00	300.00	300.00	50.00
(S\$)	19,926.15	5,500.00	14,426.15	72.40
+ GST 7.00/7.00% (S\$)	1,394.83	385.00	1,009.83	72.40
Nett Amount (S\$)	21,320.98	5,885.00	15,435.98	72.40

INSPECTION

Date of Assignment: 05/04/2018 Present Location:

Elite Automotive Pte Ltd (HQ)

Date Inspected: 06/04/2018 Inspected At:

280 Woodlands Industrial Park E5, #01-17,
Harvest@Woodlands
Singapore 757322

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2018)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH9663E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	380.00 F	*380.00 F
2	2		*BONNET HINGE (WCP)	Bent	100.00 F	*100.00 F
3	1		*BONNET LOCK (WCP)	Jammed	80.00 F	*80.00 F
4	1		*BONNET INSULATION (WCP)	Not Necessary	180.00 F	*- F
5	10		*BONNET INSULATION CLIPS (WCP)	Necessary	30.00 F	*30.00 F
6	1		*RHS FRONT FENDER (WCP)	Repair	200.00 F	*- F
7	1		*RHS FRONT FENDER SPLASH SHIELD (WCP)	Deformed	120.00 F	*120.00 F
8	10		*RHS FRONT FENDER SPLASH SHIELD CLIPS (WCP)	Necessary	30.00 F	*30.00 F
9	1		*LHS FRONT FENDER (WCP)	Repair	200.00 F	*- F
10	1		*LHS FRONT FENDER SPLASH SHIELD (WCP)	Deformed	120.00 F	*120.00 F
11	10		*LHS FRONT FENDER SPLASH SHIELD CLIPS (WCP)	Necessary	30.00 F	*30.00 F
12	1		*BONNET MOULDING (WCP)	Bent	120.00 F	*120.00 F
13	1		*FRONT GRILLE (WCP)	Cracked	200.00 F	*200.00 F
14	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	50.00 F	*50.00 F
15	2		*HEADLAMP (WCP)	Scratched	900.00 F	*900.00 F
16	2		*HEADLAMP RETAINER (WCP)	No such part	56.00 F	*- F
17	1		*FRONT BUMPER (WCP)	Cracked	280.00 F	*280.00 F
18	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	190.00 F	*190.00 F
19	10		*FRONT BUMPER CLIPS (WCP)	Necessary	30.00 F	*30.00 F
20	1		*FRONT BUMPER AIR GRILLE (WCP)	Cracked	80.00 F	*80.00 F
21	2		*FRONT BUMPER SIDE RETAINER (WCP)	Deformed	90.00 F	*90.00 F
22	1		*FRONT BUMPER FOAM/SPONGE (WCP)	Cracked	60.00 F	*60.00 F
23	1		*FRONT LOCK BRACKET (WCP)	Bent	80.00 F	*80.00 F
24	1			Deformed	280.00 F	*280.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT SUPPORT PANEL (WCP)			
25	1		*FRONT TOP PANEL (WCP)	Bent	180.00 F	*180.00 F
26	1		*FRONT TOP PANEL COVER (WCP)	Deformed	150.00 F	*150.00 F
27	10		*FRONT TOP PANEL COVER CLIPS (WCP)	Necessary	30.00 F	*30.00 F
28	1		*FRONT TOP PANEL AIR DUCT (WCP)	Torn	120.00 F	*120.00 F
29	1		*FRONT BUMPER RETAINER (WCP)	Not Necessary	45.00 F	*- F
30	1		*A/C CONDENSER C/W RECEIVER DRYER (WCP)	Bent	550.00 F	*550.00 F
31	1		*A/C HIGH PRESSURE HOSE (WCP)	Not Necessary	280.00 F	*- F
32	1		*A/C SUCTION HOSE (WCP)	Not Necessary	250.00 F	*- F
33	1		*A/C COOLING HOSE (WCP)	Not Necessary	200.00 F	*- F
34	1		*RADIATOR (WCP)	Not Necessary	650.00 F	*- F
35	2		*RADIATOR TOP MOUNTING (WCP)	Not Necessary	40.00 F	*- F
36	2		*RADIATOR TOP MOUNTING BRACKET (WCP)	Not Necessary	50.00 F	*- F
37	1		*RADIATOR RESERVE TANK (WCP)	Not Necessary	150.00 F	*- F
38	1		*ALTERNATOR (WCP)	Not Necessary	650.00 F	*- F
39	1		*ALTERNATOR BEARING (WCP)	Not Necessary	90.00 F	*- F
40	1		*FAN BELT (WCP)	Not Necessary	110.00 F	*- F
41	1		*FUSE BOX ASSY (WCP)	Not Necessary	250.00 F	*- F
42	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	120.00 F	*- F
43	1		*RADIATOR ELECTRIC FAN ASSY (WCP)	Not Necessary	250.00 F	*- F
44	1		*EXHAUST MANIFOLD COVER (WCP)	Not Necessary	350.00 F	*- F
45	1		*A/C ELECTRIC FAN ASSY (WCP)	Not Necessary	350.00 F	*- F
46	1		*WINDSCREEN WASHER TANK (WCP)	Not Necessary	120.00 F	*- F
47	1		*ABS PUMP (WCP)	Not Necessary	4,530.00 F	*- F
48	2		*FRONT FENDER TOP COVER (WCP)	Not Necessary	160.00 F	*- F
49	1		*FRONT NUMBER PLATE BASE GARNISH (WCP)	Bent	90.00 F	*90.00 F
50	2		*FRONT FOG LAMP (WCP)	Not Necessary	360.00 F	*- F
51	2		*FRONT FOG LAMP COVER (WCP)	Not Necessary	160.00 F	*- F
52	1		*FRONT TOW HOOK COVER (WCP)	Not Necessary	25.00 F	*- F
53	2		*FRONT FENDER NAME PLATE (EMBLEM) (WCP)	Necessary	120.00 F	*120.00 F
54	1		*RADIATOR COOLANT (WCP)	Necessary	25.00 F	*25.00 F
55	2		*HEADLAMP PANEL (WCP)	No such part	560.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Sub Total (S\$)					14,901.00	4,515.00
+ Margin on L,N Items 15.00/15.00% (S\$)					2,235.15	677.25
Total Parts (S\$)					17,136.15	5,192.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT NUMBER PLATE C/W HOLDER (BENT)	60.00	45.00
Sub Total (\$\$)			60.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Labour charges to remove & install front end attachments & fittings to enable repairs; to cut, replace & weld front panellings as listed above; to straighten & repairs RHS & LHS front fender inner panels wheelhousings and front body member; to replace damaged parts as listed above	New	1,500.00	900.00
2	To spary painting on:- Bonnet (inner & outer), RHS & LHS front fenders, fenders inner panels & wheelhousings front bumper and front panellings	New	1,400.00	900.00
3	To remove & replace A/C condenser C/W receiver dryer & A/C hoses; to vacuum & charge up gas	New	150.00	80.00
4	To remove & replace radiator & electric fans; to pressurize cooling system	New	80.00	60.00
5	To remove & replace both headlamps; to check electrical wirings & lights functions, including focus headlights	New	50.00	30.00
6	To remove, check and calibrate electrical system after accident repairs	New	150.00	100.00
Gross Labour Cost (\$\$)			3,330.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >