

ASS. REC. BY:

REF: CS/ICS18006364/R/qd362

Special Instruction:

Surveyor
Mehmen

Rasul

ASSIGNMENT (Office)

From (Person): Janice Goh

of

ECICS

Date/Time:

6/4/18 @ 9:25am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 4116G

Insured:

at Workshop m/s

Borneo Motors

Tel:

9336 6875

of

No. 2 Pandan Crescent

Policy No:

MPC18A00053000

Claim No:

DMPC1800122H

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A. 01/04/2018

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:50am @ 6/4/18

Person Contacted:

Sashi

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
09/4/18 @ 4.29pm	SKZ 4116G - NA/CTI 18 006032/13 Revert to Janice Goh by email.
10/4/18 @ 4.22am	Janice Goh informed C/A by email.
10/4/18 @ 4.23am	Informed Shashi C/A & Ex: # 10 by email.
	Final Rq \$17584.70, 5 days later \$5603.80, 247.7

D.O.A: 1/04/2018

Signature: *Rashid*

REF: ECICS

34542

ASSIGNMENT

From: Date: 06/04/18

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKZ 4116 G
at Workshop m/s Borneo Motors
of No. 2 Pandan Crescent

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$600.00


(Client's Record)

Make of Veh:

sashi @ 9336 6875

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 82K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ 4116 G Yr Regn: 2016 Jan

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 c.c 1598

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 47575 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053REH104543763

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MICY OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 01/04/18

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 06/04/18

BORNEO MOTOR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report

1) 16/8 final

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1) S + RS SI

2) Photos

3) Others

4)

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

MEP-00

17584.70

450

10

460




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18006364/R1qd3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987 & nbsp; & nbsp;		Date : 06-04-2018		
		Code : ICS		
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SKZ 4116G	
	Policy No.	Coverage (\$)	0.00	
	Claim No. DMPC1800122H	Excess (\$)	0.00	
	Assign From JANICE GOH	Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 01/04/2018	Inspection Date	06/04/2018	
	Survey held at BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Friday, 6 April 2018 9:25 AM
To: Shashi PTCBC; assignments@lkkauto.com
Cc: ECICS Claims
Subject: RE: SKZ4116G OD CLAIM
Attachments: 04042018145723-0001.pdf

Dear Shashi

Thank you for your email.
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange OD survey.
Policy excess \$600.00.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.****

-----Original Message-----

From: Shashi PTCBC [<mailto:Shashitharan@borneomotors.com.sg>]
Sent: Wednesday, 4 April, 2018 2:58 PM
To: ECICS Claims
Subject: FW: SKZ4116G OD CLAIM
Importance: High

Hi

Kindly arrange to survey the above mentioned vehicle .

Thanks
Shashi
Motor Claim Assessor

-----Original Message-----

From: Shashitharan@borneomotors.com.sg [mailto:Shashitharan@borneomotors.com.sg]

Sent: Wednesday, April 4, 2018 2:57 PM

To: Shashi PTCBC

Subject: SKZ4116G OD CLAIM

Sent by: B051776 [Shashitharan@borneomotors.com.sg]

Number of Images: 8

Attachment File Type: PDF

Device Name: ApeosPort-V C2276

Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 April 2018 11:23 AM
To: Shashi PTCBC
Cc: SUR
Subject: VEHICLE SKZ 4116G (DOA: 01/04/2018)

Dear Shashi,

As instructed by our client ECICS Insurance , please proceed to repair the insured vehicle **SKZ 4116G (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 10 April 2018 11:22 AM
To: Shiau Chan (LKKAUTO); Admin-D (LKKAUTO); ECICS Claims
Cc: SUR
Subject: RE: SKZ4116G OD CLAIM

Dear Shiau

Please proceed authorise repair if damage is consistent.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.**

-----Original Message-----

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 9 April, 2018 4:29 PM
To: Janice Goh Siew Geok (ECICS, Claims); Admin-D (LKKAUTO); ECICS Claims
Cc: SUR
Subject: RE: SKZ4116G OD CLAIM

Dear Janice,

Enclosed herewith preliminary advice of SKZ 4116G.
We have not authorise repair.

Kindly advise on authorisation.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]
Sent: Friday, 6 April 2018 2:37 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; ECICS Claims <claims@ecics.com.sg>
Subject: RE: SKZ4116G OD CLAIM

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Apr 2018

Preliminary Advice

Vehicle No	: SKZ4116G	Accident Date	: 01/04/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC18A00053000
Assignment Date	: 09/04/2018	Excess	: S\$0.00
Date of Inspection	: 06/04/2018	Est. Duration of Repair	: 5
Inspection At	: BORNEO MOTORS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,801.90
Revised Amount	:S\$	9,067.80
Check Items (Estimated)	:S\$	9,947.00
Total	:S\$	19,014.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	49,712.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,288.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 9 April 2018 4:29 PM
To: 'Janice Goh Siew Geok (ECICS, Claims)'; Admin-D (LKKAuto); ECICS Claims
Cc: SUR
Subject: RE: SKZ4116G OD CLAIM
Attachments: CSICS18006364R1qd3.pdf

Dear Janice,

Enclosed herewith preliminary advice of SKZ 4116G.
We have not authorise repair.

Kindly advise on authorisation.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]
Sent: Friday, 6 April 2018 2:37 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; ECICS Claims <claims@ecics.com.sg>
Subject: RE: SKZ4116G OD CLAIM

Dear Nivitha

Our claim no is DMPC1800122H.
Thank you!

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.**

-----Original Message-----

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 6 April, 2018 9:59 AM
To: ECICS Claims



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DMPC1800122H

Date: 09th April 2018

Our Ref: CS/ICS18006364/R1qd3

The Motor Claims Department
ECICS Limited

Attn: Janice

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKZ 4116G .


We thank you for the instruction on 06/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/04/2018 at the premises of M/s BORNEO MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>22,801.90</u> .
Revised Estimate Amount	: S\$ <u>9,067.80</u> .
"Check" Items Amount	: S\$ <u>9,947.00</u> .
Market Value	: S\$ <u>82,000.00</u> .
Salvage Value	: S\$ <u>49,712.00</u> .
Nett Value	: S\$ <u>32,288.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

We have not authorize repair.

Yours faithfully

MOHD RASUL
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3454Z
Vehicle Details	
Vehicle No.:	SKZ4116G
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX546099
Chassis No.:	MR053REH104543763
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$35,021.00
Total Rebate Amount:	\$49,712.00

The information contained herein is correct as at 09 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 16:10
Date Of Accident	01/04/2018 14:20
Exact Location Of Accident	BRADDELL ROAD ENTRY TO LOR. 6 TOA PAYOH SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ4116G
Insured/Policyholder	
Name Of Registered Owner	JEYAKUMAR S/O RAMASAMY DHARMALINGAM
NRIC No	S1183454Z
Email Address	DARMAINDREN@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-93390625
Alternative Phone No	OFFICE-62502774

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 L CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00053000
Cover Note Number	

Driver

Name of Driver	DARMAINDREN S/O JEYAKUMAR
NRIC No	S9128055H
Date Of Birth	25/07/1991
Occupation	INDOOR
Date Of Driving Pass	27/06/2012
Driving Experience	5 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93390625
Fax Number	
Contact Number	OFFICE-62502774
Email Address	DARMAINDREN@OUTLOOK.COM

Address	BLK 154 LORONG 2 TOA PAYOH #19-614
Postcode	310154
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR8829X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG1202S
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 02/04/2018
2pm



Reporting Centre Personnel's Signature
Name: TAN KIAN ANN
NRIC/FIN No.: S1549534J


Sketch Plan #2 Pg. 1

SKETCH PLAN

Car A: SKZ4116G

Car B: SGR 8879X

Car C: GBG 1202S



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident occurred at the slip road exit from Braddell Road to Toa Payoh Lor 6 road, opposite Blk 216 (Sy 310216), at 2.20pm on 01/04/2018. It was raining heavily at the moment, therefore visibility was compromised. As I exit Braddell road via the slip road into Toa Payoh Lor 6, I was on lane 2. At that point of time, due to congestion, I switched over to lane 1 at point Z. At that moment, as I proceeded down lane 1, car B had applied a sudden break. My immediate reaction was to jam break too, but unfortunately it was not on time. My car (Car A), had collided into the back of ~~Car B~~, car B and car B rolled forward and contacted Car C. At that moment all three of us switched on our hazard lights and exited the car to take photos of the damages. All cars were still operational. Therefore we moved out to block 213 (Sy 310213), to further access the damages.

My Car, Car A had obtained damages to the front. No injuries. Car B, damages to front and rear of the vehicle and no injuries. Car C, damage to rear with no injuries.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 02/04/2018
2pm

Reporting Centre Personnel's Signature
Name: TAN KIAN ANN
NRIC/FIN No.: S1549534J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 27 Jun 2012

NP 428A

Licence No: S9128055H

3914408

NRIC No: S9128055H

Date of issue: 03-08-2006

APT BLK 154 LORONG 2 TOA PAYOH #19-814
SINGAPORE 310154

NRIC No: S9128055H Date: 04/12/2014

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S9128055H

Name: DARMAINDREN S/O JEYAKUMAR

Birth Date: 25 Jul 1991

Issue Date: 27 Jun 2012

002081756E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9128055H

Name: DARMAINDREN S/O JEYAKUMAR

ஜெ தர்மேந்திரன்

Race: INDIAN

Date of birth: 25-07-1991

Country of birth: SINGAPORE

Sex: M

S9128055H



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Jeyakumar S/O Ramasamy Dharme 154 Lorong 2 Toa Payoh #19-614 Singapore 310154 Mobile: 93827472
	Document No	
	Document Date	
	0	
	04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/01/2016	SKZ4116G	0	30271 :60D/SKZ4116G/03041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104543763	1ZRX546099	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC18A00053000 ACC DATE:01/04/18 DRIVE IN:03/04/18 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				100.00
3	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP				154.00
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				308.00
5	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				616.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
7	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				3080.00
8	B	BP-RES RESRPAY ACC AFF AREA				2530.00
9	1	S53112-02630 GRILLE, RADIATOR LWR	1.00	165.00		165.00
10	2	S52119-02955 COVER, FR BUMPER	1.00	514.90		514.90
11	3	S52115-02270 SUPPORT, FR BUMPER RH	1.00	83.30		83.30
12	4	S52116-02270 SUPPORT, FR BUMPER LH	1.00	83.30		83.30
13	5	S52611-02310 ABSORBER, FR BUMPER	1.00	79.70		79.70
14	6	S52161-0K040 PIECE, RR BUMPER	10.00	3.90		39.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623279

TO SECURITY GUARD

3623279

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 04/04/2018
TIME 14:46

VEHICLE NO SKZ4116G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Cô Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Jeyakumar S/O Ramasamy Dharma 154 Lorong 2 Toa Payoh #19-614 Singapore 310154 Mobile: 93827472
	Document No 0	
	Document Date 04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/01/2016	SKZ4116G	0	30271 :60D/SKZ4116G/03041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104543763	12RX546099	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	7	S53100-02760	1.00	625.00		CRA 625.00 ✓
16	8	S53301-02310	1.00	1213.10		RA 1213.10 ✓
17	9	T90467-09050	6.00	2.30		M 13.80 ✓
18	0	S53802-02220	1.00	877.10		SUX 877.10 ✓
19	1	S53801-02240	1.00	877.10		SUX 877.10 ✓
20	2	S53510-02671	1.00	131.10		RA 131.10 ✓
21	3	S53420-02360	1.00	57.00		XU 57.00 ✓
22	4	S53410-02360	1.00	57.00		XU 57.00 ✓
23	5	S53208-02210	1.00	145.20		RA 145.20 ✓
24	6	S53201-02370	1.00	1097.10		RA 1097.10 ✓
25	7	S75311-02190	1.00	46.30		M 46.30 ✓
26	8	S75444-02A20	1.00	34.40		RA 34.40 ✓
27	9	S75444-02700	1.00	34.40		SUX 34.40 ✓
28	0	S81150-02F51	1.00	2907.40		CRA 2907.40 ✓
29	1	S81110-02F51	1.00	2907.40		CRA 2907.40 ✓
30	2	S85315-02630	1.00	183.60		XU 183.60 ✓
31	3	S88450-02350	1.00	1507.40		RA 1507.40 ✓
32	4	S16410-0D390	1.00	1800.20		SUX 1800.20 ✓
33	5	S16712-0D150	1.00	85.00		SUX 85.00 ✓
34	6	S16711-0T101	1.00	249.10		SUX 249.10 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
<div>LKK Auto Consultants</div> <div>Please acknowledge receipt of vehicle</div> <div>the Repairer of the following:</div> <div><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed</div>		Parts	15,813.90	GST 7.00%
		Labour	6,888.00	Less
		Materials	100.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			22,801.90	1,596.13
			0.00	24,398.03

PLEASE TEAR ALONG PERFORATED LINE

3623280

3623280

TO SECURITY GUARD

Signature:

DATE

04/04/2018

PLEASE ALLOW THE UNDERMENTIONED

TIME

14:46

VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SKZ4116G

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Lt

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Jeyakumar S/O Ramasamy Dharma 154 Lorong 2 Toa Payoh #19-614 Singapore 310154 Mobile: 93827472	
		Document No		
		Document Date		
		0		
		17/04/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/01/2016	SKZ4116G	41812	30271 :60D/SKZ4116G/030411

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
MR053REH104543763	12RX546099	60	Shashitharan	10/04/2018	8.00	17/04/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC18A00053000 ACC DATE:01/04/18 DRIVE IN:03/04/18 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)	E33			100.00
3	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP	*			154.00
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS	18			308.00
5	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR	18			616.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
7	B	BP-LAB REPL ACC AFF PARTS AND PANEL	36			2464.00
		STRAIGHTEN AND REALIGN ACC AFF AREA including replacement of support				
8	B	BP-RES RESRPAY ACC AFF AREA	*			2024.00
9	V	EXC Excess element of insurance repair to be paidby the insured party	88			-600.00
10	1	S52119-02955 COVER, FR BUMPER	1.00	514.90		514.90
11	2	S52115-02270 SUPPORT, FR BUMPER RH	1.00	83.30		83.30
12	3	S52116-02270 SUPPORT, FR BUMPER LH	1.00	83.30		83.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3622450

TO SECURITY GUARD

3622450

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2018
TIME 14:45

VEHICLE NO SKZ4116G

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICBCICS	Mr Jeyakumar S/O Ramasamy Dharma 154 Lorong 2 Toa Payoh #19-614 Singapore 310154 Mobile: 93827472
	Document No 0	
	Document Date 17/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ S2	ZRE171R	22/01/2016	SKZ4116G	41812	30271	60D/SKZ4116G/03041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104543763	12RX546099	60	Shashitharan	10/04/2018	8.00	17/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	4	S52611-02310 ABSORBER, FR BUMPER	1.00	79.70		79.70
14	5	S52161-0K040 PIECE, RR BUMPER	10.00	3.90		39.00
15	6	S53100-02760 GRILLE, RADIATOR	1.00	625.00		625.00
16	7	S53301-02310 HOOD SUB-ASSY	1.00	1213.10		1213.10
17	8	T90467-09050 CLIP	6.00	2.30		13.80
18	9	S75444-02A20 PLATE, LUGGAGE	1.00	34.40		34.40
19	0	S81110-02F51 HEADLAMP ASSY, RH HG	1.00	2907.40		2907.40
20	1	S53510-02671 LOCK ASSY, HOOD	1.00	131.10		131.10
21	2	S53208-02210 SUPPORT SUB-ASSY, HO	1.00	145.20		145.20
22	3	S53201-02370 SUPPORT SUB-ASSY	1.00	1097.10		1097.10
23	4	S81150-02F51 HEADLAMP ASSY, LH HG	1.00	2907.40		2907.40
24	5	S88450-02350 CONDENSER ASSY	1.00	1507.40		1507.40
25	6	S52131-02190 REINFORCEMENT, FR	1.00	386.60		386.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	16,984.70
	Please acknowledge receipt of vehicle	Parts 11,768.70	GST 7.00%	1,188.93
		Labour 5,716.00	Less	0.00
		Materials 100.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	18,173.63

PLEASE TEAR ALONG PERFORATED LINE

3622451

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2018
TIME 14:45

VEHICLE NO SKZ4116G

CUSTOMER


SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2018 16:06 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	S\$17,584.70 Edit Estimates	S\$17,584.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	JEYAKUMAR S/O RAMASAMY DHARMALINGAM, ID: S1183454Z, Email: DARMAINDREN@OUTLOOK.COM								
Vehicle Reg. No.:	SKZ4116G	Date of Loss:	01/04/2018 14:00 - :59 [26 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	MPC18A00053000 (Comprehensive)						
		Excess:							
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/04/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS 		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ4116G



















































OD









Apr 1 2018 2:00PM

[JEYAKUMAR S/O RAMASAMY DHARMALINGAM]

Borneo Motors (S) Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	10/04/18 11:02	Adjuster Immediate Advice
		1 Load HTM <input type="checkbox"/>
Photos/Images		3 per page <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	10/04/18 11:04	Odometer Reading
2	10/04/18 11:04	Chassis Number
3	10/04/18 11:04	General View
4	10/04/18 11:04	General View
5	10/04/18 11:04	General View
6	10/04/18 11:04	General View
7	10/04/18 11:04	General View
8	10/04/18 11:04	General View
9	10/04/18 11:04	General View
10	10/04/18 11:04	General View
11	10/04/18 11:04	General View
12	10/04/18 11:04	General View
13	10/04/18 11:04	General View
14	10/04/18 11:04	General View
15	10/04/18 11:04	General View
16	10/04/18 11:04	General View
17	10/04/18 11:04	General View
18	10/04/18 11:04	General View
19	10/04/18 11:04	General View
20	10/04/18 11:04	General View
21	10/04/18 11:04	General View
22	10/04/18 11:04	General View
23	10/04/18 11:04	General View
24	10/04/18 11:04	General View
25	10/04/18 11:04	General View
26	10/04/18 11:04	General View
27	10/04/18 11:04	General View
28	10/04/18 11:04	General View
29	10/04/18 11:04	General View
30	10/04/18 11:04	General View
31	10/04/18 11:04	General View
32	10/04/18 11:04	General View
33	10/04/18 11:04	General View
34	10/04/18 11:04	General View
35	10/04/18 11:04	General View
		1 Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/04/18 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	16/08/18 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18006364/R1QD3E2

Date: 16/08/2018

REFERENCE

Insured/Claimant: JEYAKUMAR S/O RAMASAMY DHARMALINGAM

Policy No: MPC18A00053000

Date of Loss: 01/04/2018

Nature of Claim: OD

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ4116G

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZR546099

Reg. Date: 22/01/2016 (Man. Year: 2015)

Chassis No: MR053REH104543763

Colour: Grey

Odometer: 47575 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$82,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,500.50	12,018.70	4,481.80	27.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,688.00	5,566.00	1,122.00	16.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,188.50	17,584.70	5,603.80	24.17
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	22,588.50	16,984.70	5,603.80	24.81
+ GST 7.00/7.00% (S\$)	1,581.20	1,188.93	392.27	24.81
Nett Amount (S\$)	24,169.70	18,173.63	5,996.07	24.81

INSPECTION

Date of Assignment: 06/04/2018

Date Inspected: 06/04/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ4116G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REGN PLATE (PO#)	Missing	100.00 FS	*100.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*GRILLE, RADIATOR LWR	Serviceable	165.00 FS	*- FS
4	1		*COVER, FR BUMPER	Deformed	514.90 FS	*514.90 FS
5	1		*SUPPORT, FR BUMPER RH	Necessary	83.30 FS	*83.30 FS
6	1		*SUPPORT, FR BUMPER LH	Necessary	83.30 FS	*83.30 FS
7	1		*ABSORBER, FR BUMPER	Deformed	79.70 FS	*79.70 FS
8	10		*PIECE, RR BUMPER	Necessary	39.00 FS	*39.00 FS
9	1		*GRILLE, RADIATOR	Cracked	625.00 FS	*625.00 FS
10	1		*HOOD SUB-ASSY	Bent	1,213.10 FS	*1,213.10 FS
11	6		*CLIP	Necessary	13.80 FS	*13.80 FS
12	1		*FENDER SUB-ASSY, LH	Serviceable	877.10 FS	*- FS
13	1		*FENDER SUB-ASSY, RH	Serviceable	877.10 FS	*- FS
14	1		*LOCK ASSY, HOOD	Bent	131.10 FS	*131.10 FS
15	1		*HINGE ASSY, HOOD, LH	Serviceable	57.00 FS	*- FS
16	1		*HINGE ASSY, HOOD RH	Serviceable	57.00 FS	*- FS
17	1		*SUPPORT SUB-ASSY, HO	Bent	145.20 FS	*145.20 FS
18	1		*SUPPORT SUB-ASSY	Bent	1,097.10 FS	*1,097.10 FS
19	1		*RADIATOR GRILLE EMBLEM	Not Necessary	46.30 FS	*- FS
20	1		*PLATE, LUGGAGE COMPT	Necessary	34.40 FS	*34.40 FS
21	1		*PLATE, LUGGAGE COMPT	Serviceable	34.40 FS	*- FS
22	1		*HEADLAMP ASSY, LH	Cracked	2,907.40 FS	*2,907.40 FS
23	1		*JAR, WASHER, A	Serviceable	183.60 FS	*- FS
24	1		*A/C CONDENSER ASSY	Bent	1,507.40 FS	*1,507.40 FS
25	1		*RADIATOR ASSY	Serviceable	1,800.20 FS	*- FS
26	1		*RADIATOR SHROUD NO 2	Serviceable	85.00 FS	*- FS
27	1		*SHROUD, FAN	Serviceable	249.10 FS	*- FS
28	1		*REINFORCEMENT, FR	Bent	386.60 FS	*386.60 FS
29	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
30	1		*HEADLAMP ASSY, RH	Cracked	2,907.40 FS	*2,907.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	16,500.50	12,018.70
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	154.00	154.00
2	R/I AIRCOND PIPE VACUUM AND REGAS	New	308.00	308.00
3	RESET ECU UPON COMPLETION OF REPAIR	New	616.00	616.00
4	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	3,080.00	2,464.00
5	RESPRAY ACC AFF AREA	New	2,530.00	2,024.00
Gross Labour Cost (S\$)			6,688.00	5,566.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >