

Rasul

REF: ASM(AXA)

C/S/ASM 18006365/R4d352

2049D

ASSIGNMENT

From:

Date: 6/4/18

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLC 4051T

at Workshop no: Hin Lung Workshop

or Blk 1008, Blk Merah Lane 3 #01-20

Insured:

Policy No:

Claims No:

Sum insured:

Excess: \$400.00

(Client's Record)

Make of Veh:

3:30pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

70K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% J Val: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

SLC 4051T

Yr Regn:

2016 May

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

mitsubishi attage 12 cc 1193

Colour:

MAROON

A/C Insured / Std / NI / NA

Sp. Reading:

033053

T/Ratio: Insured / Std / NI / NA

Eng No:

C/No:

MMBSTA13AHH060343

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 185/55R15
R: 1"

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A:

27/03/18

D.O.A:

06/04/18

Survey held at:

Hin Lung

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

(Red

Finalised part by Part \$3,485/- (2079.46%)

Submit final report / hard copy to insurance. Date 10/4/2019

Attach Discharge voucher and Tax invoice.

12/4/19 RECEIVED 2 APR 2018 1st close date 16/5/18, reopen ref only J.

Date/Time: File Pass to:

☐

: Preli. Report

2014 Typist

☒

: Final Report

Date/Time: File Return to:

Days Of Repair:

9

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photo:

Notes:

TOTAL:

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Needing: \$

Report Format:

OD

Lump Sum / I.B.I. \$

M

200

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X.

Your Ref:
Our Ref : 1528/04/18
M/s : AXA INSURANCE PTE LTD
8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811

Page: 1
Date: 05/04/2018

Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SLC4051T - ATTRAGE-1.2 CVT (A) 0
INSURED : SEAH SEOW PEA
DATE OF ACCIDENT : 27/03/2018
POLICY NO : GA1999687

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID ✓	1 @ 350.00	350.00	✓
2	REAR BOOT LID WEATHERSTRIP ✓	1 @ 55.00	55.00	✓
3	REAR BOOT MOULDING	1 @ 165.00	165.00	XSVL
4	REAR BOOT EMBLEM	1 @ 18.00	18.00	ne ✓
5	REAR BOOT LOGO "ATTRAGE"	1 @ 32.00	32.00	ne ✓
6	REAR BOOT LOGO "MIVEC"	1 @ 26.00	26.00	ne ✓
7	REAR BOOT HINGE RH & LH	2 @ 65.00	130.00	XSVL
8	REAR BOOT LOCK ✓	1 @ 90.00	90.00	PT ✓
9	REAR BOOT CATCH	1 @ 25.00	25.00	XSVL
10	REAR RH FENDER	1 @ 420.00	420.00	R
11	REAR WINDSCREEN SEALANT	1 @ 32.00	32.00	XSVL
12	TAIL LIGHT UNIT RH & LH	2 @ 145.00	290.00	? XSVL
13	REAR BUMPER ✓	1 @ 290.00	290.00	PT ✓
14	REAR BUMPER CLIP ✓	10 @ 2.00	20.00	ne ✓
15	REAR BUMPER SIDE RETAINER RH & LH	2 @ 20.00	40.00	ne ✓
16	REAR BUMPER REFLECTOR RH & LH	2 @ 18.00	36.00	? XSVL
17	REAR END PANEL ✓	1 @ 245.00	245.00	PT ✓
18	REAR END PANEL GARNISH ✓	1 @ 50.00	50.00	PT ✓
19	REAR END PANEL GARNISH CLIP ✓	8 @ 2.50	20.00	ne ✓
20	SPARE TYRE BOARD ✓	1 @ 140.00	140.00	CR - 120
21	SPARE TYRE WELL/PANEL	1 @ 680.00	680.00	R
22	REVERSE SENSOR (1 SET) ✓	1 @ 200.00	200.00	cut ✓ S/N 200
Total			3,354.00	

LABOUR CHARGES

- 1 REMOVE AND REPAIR REAR BOOT, REAR BUMPER, REAR RH FENDER, REINFORCEMENT, TAIL LIGHTS, REAR END PANEL & ETC.,

800
1,600.00 ~~800~~

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 1528/04/18

Page: 2
Date: 05/04/2018

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

- AND REPLACEMENT OF PARTS FOR THE EFFECTED AREAS.
- 2 SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.
 - 3 CHECK WIRING & PROPER FUNCTIONING.
 - 4 REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.
 - 5 REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR.

S\$ S\$ S\$

~~1,200.00~~ 1000

~~40.00~~
~~150.00~~ 60

120.00 X

1900

Nett Total Before GST

6,464.00

Yours faithfully,



(Workshop Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL

Hp 90010068

9 days

P/P

06/04/18 @ 1530

Authorized

Resurvey by paint

EXCESS: 400

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

TAX INVOICE

M/s AXA INSURANCE PTE LTD
8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
ATTN: MISS YVONNE ANG

INVOICE NO.: OD514
Acc/Rep Date: 27/03/2018
Policy No.: GA1999687
Model: ATTRAGE-1.2 CVT (A)
Veh Reg. No.: SLC4051T
Invoice Date: 02/04/2019 Page: 1

REPLACEMENT OF PARTS		
1	REAR BOOT LID	350.00
1	REAR BOOT LID WEATHERSTRIP	90.00
1	REAR BOOT EMBLEM	18.00
1	REAR BOOT LOGO "ATTRAGE"	32.00
1	REAR BOOT LOGO "MIVEC"	26.00
1	REAR BOOT LOCK	100.00
2	TAIL LIGHT UNIT RH & LH	300.00
1	REAR BUMPER	350.00
10	REAR BUMPER CLIP	20.00
2	REAR BUMPER SIDE RETAINER RH & LH	40.00
1	REAR END PANEL	250.00
1	REAR END PANEL GARNISH	45.00
8	REAR END PANEL GARNISH CLIP	20.00
1	SPARE TYRE BOARD	120.00
SUB-TOTAL		1,761.00
*SPECIAL NETT		
1	REVERSE SENSOR (1 SET)	200.00
LABOUR CHARGES		
REMOVE AND REPAIR REAR BOOT, REAR BUMPER, REAR RH FENDER, REINFORCEMENT, TAIL LIGHTS, REAR END PANEL & ETC. AND REPLACEMENT OF PARTS FOR THE EFFECTED AREAS.		800.00
SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.		1,000.00
CHECK WIRING & PROPER FUNCTIONING.		40.00
REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.		60.00
Nett Total Before GST		3,861.00

(Three Thousand Eight Hundred Sixty-One Only)

HIN LUNG WORKSHOP
(Workshop Manager)

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

TAX INVOICE

M/S AXA INSURANCE PTE LTD
8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
ATTN: MISS YVONNE ANG

INVOICE NO. : OD514
Acc/Rep Date: 27/03/2018
Policy No. : GA1999687
Model : ATTRAGE-1.2 CVT (A)
Veh Reg. No.: SLC4051T
Invoice Date: 09/04/2019 Page: 1

REPLACEMENT OF PARTS

1	REAR BOOT LID	350.00
1	REAR BOOT LID WEATHERSTRIP	90.00
1	REAR BOOT LOCK	100.00
1	REAR BUMPER	350.00
10	REAR BUMPER CLIP	20.00
2	REAR BUMPER SIDE RETAINER RH & LH	40.00
1	REAR END PANEL	250.00
1	REAR END PANEL GARNISH	45.00
8	REAR END PANEL GARNISH CLIP	20.00
1	SPARE TYRE BOARD	120.00

SUB-TOTAL 1,385.00

*SPECIAL NETT
1 REVERSE SENSOR (1 SET) 200.00

LABOUR CHARGES

REMOVE AND REPAIR REAR BOOT, REAR BUMPER, REAR RH FENDER, REINFORCEMENT, TAIL LIGHTS, REAR END PANEL & ETC. AND REPLACEMENT OF PARTS FOR THE EFFECTED AREAS. 800.00
SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT. 1,000.00
CHECK WIRING & PROPER FUNCTIONING. 40.00
REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR. 60.00

Nett Total Before GST 3,485.00
LESS EXCESS (CLAIM NO.: S8M00CUY) 400.00

Nett Total Before GST 3,085.00
Add GST @ 7% 215.95

Nett Total After GST 3,300.95

(Three ThousandThree Hundred and Cents Ninety-Five Only)


HIN LUNG WORKSHOP
(Workshop Manager)



redefining / insurance

SATISFACTION VOUCHER / WORKSHOP'S WARRANTY

To: AXA Insurance Pte Ltd

I/We Seah Seow Pea hereby confirm that I/we have taken delivery of my/our vehicle of registration number 3LC4051T from the Workshop, Messrs Hin Lue Workshop and that all necessary and reasonable repairs arising from the accident involving my/our vehicle that occurred on 27/3/2018 have been effected to my/our entire satisfaction. Save for my/our rights under the Warranty set out below, I/we confirm that I/we have no further claims against the Workshop in respect of such repairs.

I/We hereby authorise my/our insurer, AXA Insurance Pte Ltd, to pay the costs of such repairs (less the excess) which amounts to S\$ _____ directly to the said Workshop and I/we confirm that such payment shall wholly discharge any and all liability on the part of AXA Insurance Pte Ltd to indemnify me/ us for all damage to my/our said vehicle arising from the said accident.

Dated: 3/5/18

Signature of the Policyholder or duly authorized representative and company stamp where applicable.

WORKSHOP'S WARRANTY

Subject to provisions (a) to (d) below, the repairs effected to the abovementioned vehicle are warranted good by the Workshop for twelve (12) months from the date of this Satisfaction Voucher and during this period, rectification of repairs effected by the Workshop which prove to be faulty shall be undertaken by the Workshop free of charge.

This Warranty shall be inapplicable to:

- (a) faults arising out of abnormal usage of the vehicle;
- (b) faults due to attempts to correct any defect in the repairs effected by the Workshop or the mishandling of rectification work to the vehicle by persons other than the Workshop;
- (c) manufacturing defects in any parts replaced that could not reasonably have been detected by the Workshop at the time the repairs were effected;
- (d) faults or defects arising out of normal wear and tear, misuse, neglect, accident, flood, acts of God, or use in violation of the specifications relevant to the vehicle.

Signature and stamp of the Workshop



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 720672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 100307741M



Wiper (Model 1000) Original Wiper blades (Japan) Made in Japan
Front / Made in Germany
Spark plug (Japan) / Spark plug (Japan) Made in Japan

HIN LUNG WORKSHOP*
BLK 1008 BUKIT MERAH LANE 3
#01-20

SINGAPORE 159722
TEL: 68583000 FAX: 64760075
ATTN: SUSAN / FREDDY 98323236.

TAX INVOICE : AR201804-11549
DATE : 20/04/2018
CUSTOMER ID : HIN004
VEH REG. NO. : SLC4051T
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
①	J15920A203 A13AATTRAGE	PANEL, TRUNK LID	CC CC11-C-07A	1	350.00	350.00
②	J18330A851 A13A	TAIL LAMP LH	CC CC11-A-06C	1	150.00	150.00
③	J18330A852 A13A	TAIL LAMP RH	CC CC11-C-06D	1	150.00	150.00
④	J16410C750 A13A	FACE, RR BUMPER	CC CC11-C-01D	1	350.00	350.00
⑤	J15281A631 A13A	PANEL, RR END	CC CC11-P-01A	1	250.00	250.00
⑥	J17240A172XA A13A	TRIM, RR END	CC CC11-D-05B	1	45.00	45.00

SUB-TOTAL : 1,295.00
ADD GST 7.00 % 90.65

E & O E TOTAL AMOUNT SGD: 1,385.65

[P] 20/04/2018 3:17:41PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[R] 20/04/2018 3:08:15PM

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGAI KADUT AVE SINGAPORE 720672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 196307741M



Dept Direct 8411 9791 16741 9808




Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808



Dept Direct 8411 9791 16741 9808

Arrange By	Unit
	166

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400

10YR 5A	1.40000 400
10YR 5A	1.40000 400





日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 726672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 19607741M



Wiper blade: NRB (Nippon Wiper blade, Siper (Made in Korea)
Forn (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

HIN LUNG WORKSHOP*
BLK 1008 BUKIT MERAH LANE 3
#01-20

SINGAPORE 159722
TEL: 68583000 FAX: 64760075
ATTN: SUSAN / FREDDY: 98323236

TAX INVOICE : AR201804-13794
DATE : 25/04/2018
CUSTOMER ID : HIN004
VEH REG. NO. : SLC4051T
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

Qty	W/OCKID	DESCRIPTION	SkLec	QTY	UNIT PRICE	AMOUNT
1	UMU000368 A03A,Z23W CY2 CY4	GROMMET, TAIL LAMP	TA PL3-N1-020	1	2.50	2.50
2	UMU000283 A03A,A13ACY2 CY4	GROMMET, TAIL LAMP	TA PL3-N1-02N	1	2.50	2.50
3	J17646A265 A13A	BOARD, TRUNK ROOM FLOOR	TA PL3-P1-1AR	1	120.00	120.00

SUB-TOTAL	125.00
ADD GST 7.00%	8.75
TOTAL AMOUNT SGD	133.75

[P] 25/04/2018 11:20:27AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).


[P] 25/04/2018 11:15:59AM

215115 11/20/2018-087 Dkt: 0001

JAE Auto Pte Ltd

Sales Executive: NIN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRN	DISC QUANTY	SALV AGE%	PART PRICE(NT)	ACTION (PARTS)	REMOVE
		1	1			REAR BOOT LID			Bent	350				350	Approve	
		2	1			REAR BOOT LID WEATHERSTRIP			Necessary	90				90	Reviewing	
		3	1			REAR BOOT MOULDING			Serviceable	0	0	0	0	0	Deny	
		4	1			REAR BOOT EMBLEM			Serviceable	0	0	0	0	0	Deny	
		5	1			REAR BOOT LOGO "ATTRAGE"			Serviceable	0	0	0	0	0	Deny	
		6	1			REAR BOOT LOGO "MIVEC"			Serviceable	0	0	0	0	0	Deny	
		7	2			REAR BOOT HINGE RH & LH			Serviceable	0	0	0	0	0	Deny	
		8	1			REAR BOOT LOCK			Bent	100				100	Reviewing	
		9	1			REAR BOOT CATCH			Serviceable	0	0	0	0	0	Deny	
		10	1			REAR RH FENDER			Repair	0	0	0	0	0	Deny	
		11	1			REAR WINDSCREEN SEALANT			Serviceable	0	0	0	0	0	Deny	

 **SERVICE REQUESTS** **MESSAGES** **CLAIMS**

		PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1	REMOVE AND REPAIR REAR BOOT, REAR BUMPER, REAR RH FENDER, REINFORCEMENT, TAIL LIGHTS, REAR END PANEL & ETC., AND REPLACEMENT OF PARTS FOR THE EFFECTED AREAS.	800	0	0	Approve	
		2		1000	0	0	Approve	
		3		40	0	0	Approve	
		4		60	0	0	Approve	
		5		0	0	0	Deny	

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Approve		9	
		2	SET REVERSE SENSOR	Approve	200	CUT	

- SERVICE REQUESTS
- MESSAGES
- CLAIMS

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount	\$3,085.00	Claim Amount	\$3,085.00
CATEGORY	ESTIMATE	REVISED AMOUNT	
Spare Parts	\$1,376.00	\$1,385.00	
Labour	\$1,900.00	\$1,900.00	
Miscellaneous	\$200.00	\$200.00	
Excess	-\$400.00	-\$400.00	