

ASS. REC. BY:

REF:

TM1 / CC3/TM218006367/Kvb2

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 389M

Yr Regn:

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c

1995

Colour

n. white / R

A/C:

Insured / Std / NI / NA

Sp. Reading

325131

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF/AB215/MC 282897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti 215/60R16

W/M / R/M

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

3.13/18

D.O.A. 5.4/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14 File pass to Corbush

11 Lr @ 3000 3773.59 (Red 41, 773.48, 920)

SHD 389M

CC3/ATM17013676/Kwb3

QL 17860 - x

DUA: 1107A

6/4/18

Email GIA to TM1

RECEIVED 9 APR 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

6/4 - typist

Days Of Repair:

2

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

250

Transportation:

10

S + RS \$

Photos

Others

TOTAL

260

Report Format:

merimen

Lump Sum / I.B.I. (\$

3773.59



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/TMI18006367/Kvb

20 MCCALLUM STREET #09-01

TOKIO MARINE CENTRESINGAPORE 069046

Date : 06-04-2018



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 1786D	Veh. Inspected	SHD 389M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/03/2018	Inspection Date	05/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Apr 2018		06 Apr 2018 14:37 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CLARENCE CHAW, ID: S7802885H		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD389M	Date of Loss:	31/03/2018 21:00 - :59
Claim Type:	TP / M1801799	Policy/Cover Note No.:	MU001800 (Comprehensive) Coverage: 16/02/2017 - 15/02/2019
Vehicle Reg. No. (Insured):	SLL1786D	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/04/2018]		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 April 2018 12:26 PM
To: motorclaims@tokiomarine.com.sg
Cc: priscilla@tokiomarine.com.sg; 'Too Joon Hwa'; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 31/3/2018, SHD 389M (TP VEHICLE), SLL 1786D (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir,

Please be informed that we had inspected the vehicle SHD 389M M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111 on 5/4/2018

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD389M
Vehicle to be Exported:	Yes
Intended De-registration Date:	03 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003061
Chassis No.:	VF1ABL15AUC282697
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$28,724.00
Total Rebate Amount:	\$43,722.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/04/2018 09:35
Date Of Accident	31/03/2018 21:30
Exact Location Of Accident	OUTRAM ROAD SLIP ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD389M
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	ANG GEOK BENG
NRIC No	S7038932J
Date Of Birth	07/11/1970
Occupation	OUTDOOR
Date Of Driving Pass	11/10/2005
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82555178
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 503 HOUGANG AVENUE 8 #10-722
Postcode	530503
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180401/2025

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL1786D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ANG GEOK BENG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD389M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

px see attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180401/2025

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180401/2025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/04/2018 11:38		Vide Report No.:		Station Diary No.: 91	
Informant's Particulars					
Name of Informant: ANG GEOK BENG			Address: APT BLK 503 HOUGANG AVENUE 8 #10-722 SINGAPORE 530503		
ID Type / ID No.: NRIC NO / S7038932J			Contact No.: Home/Office: Mobile: 82555178		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 07/11/1970	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 31/03/2018 21:30	Type of Location: Sliproad
Location: Along Road 1 OUTRAM ROAD				
Slip road along Outram Road towards CTE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD389M	Car	RENAULT	Atitude	Red	Slightly Damaged	0
SLL1786D	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180401/2025

2 of 3

Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

Report No. T/20180401/2025

CONTINUATION OF REPORT

Driver			
Name	ANG GEOK BENG	ID No.	S7038932J
Related Vehicle	SHD389M (Car)	Contact No.	82555178
Hospital/Clinic	POW FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	01/04/2018	Date Discharge	01/04/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 31 Mar 2018 at About 9.30pm, I was driving my vehicle, SHD389M, along Outram Road (direction towards Chinatown) on the left most lane. I stopped at the slip road leading towards CTE as there were pedestrians crossing the zebra crossing. Suddenly, I felt an impact coming from behind my vehicle. As I was stepping out to make a check, I saw the car that had collided onto my vehicle (SLL1786D) driving off. My vehicle sustained a dent on the bumper. Due to the collision, I felt stiffness on the rear of my neck when turning my head and also lower back pain. I sought medical attention at POW Family Clinic & Surgery and was given 4 days of MC. I do not have any in-car camera installed.



**SINGAPORE
POLICE FORCE**



T/20180401/2025

3 of 3

Report No. T/20180401/2025

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Insp A LEE HIANG HAO

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

01/04/2018 11:38

Officer In Charge Of Case:

TP / HRT /

SSI GOH GEOK LYE

Contact No.: 65476148

Classification Of Case:

Authentication Stamp

NP168



Signature:

SN 085

Singapore Police Force

Trans-cab Auto Services Pte Ltd

AAD1804-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 2010196266

SHD 389M

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Insurer:

SHD 389M

VF1ABL15AUC282697

RENAULT

LATITUDE

31.3.2018

TOKIO MARINE**PART****LIST**

1	1 BUMPER COVER REAR	\$	Bu 1,108.46	—
2	1 BUMPER LOWER REAR	\$	nd/n/s 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	Sn 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	Sn 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	Sn 44.99	X
6	1 BUMPER REFLECTOR RH	\$	cm 43.61	—
7	1 BUMEP R BRACKET SIDE LH REAR	\$	Sn 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	Sn 44.99	X
9	1 BUMPER REFLECTOR LH	\$	Sn 43.61	X
10	1 BUMPER BEAM REAR	\$	B 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	R 225.95	} X
12	1 BUMPER BEAM BRACKET RH REAR	\$	R 225.95	
13	1 BOOT REAR	\$	R 2,872.68	
14	1 BOOT FINISHER	\$	Sn 470.06	
15	1 BOOT WHEATERSTRIP	\$	Sn 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	Sn 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	Sn 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	na 225.36	
19	1 BOOT BADGE	\$	na 225.36	
20	1 BOOT STRUT LH	\$	Sn 276.08	
21	1 BOOT STRUT RH	\$	Sn 276.08	
22	1 BOOT HINGE LH	\$	R 367.84	
23	1 BOOT HINGE RH	\$	R 367.84	
24	1 BOOT INNER TRIM	\$	Sn 586.45	
25	1 BOOT SWITCH	\$	Sn 168.13	
26	1 BOOT LOCK	\$	R 202.67	
27	1 BOOT LOCK CATCH	\$	R 74.40	
28	2 LICENCE PLATE LAMP	\$	Sn 50.52	
29	2 BOOT RUBBER PLUG	\$	Sn 221.81	

Trans-cab Auto Services Pte Ltd**AAD1804-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

30	1 FENDER PANEL INNER TRIM REAR LH	\$	Sm 671.45	}
31	1 FENDER PANEL REAR LH	\$	R 3,299.13	
32	1 WHEELARCH REAR LH	\$	Sm 543.47	
33	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm 671.45	
34	1 FENDER PANEL REAR RH	\$	R 3,299.13	
35	1 WHEELARCH REAR RH	\$	Sm 543.47	
36	1 TAILLAMP RH	\$	Sm 552.55	
37	1 TAILLAMP PANEL RH	\$	R 986.70	
38	1 TAILLAMP LH	\$	Sm 552.55	
39	1 TAILLAMP PANEL LH	\$	R 986.70	
40	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77	
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56	
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88	
43	1 SPARE WHEEL PANEL TRIM	\$	Sm 612.21	
44	1 EXHAUST REAR	\$	R 7,489.05	
45	1 EXHAUST CAP REAR	\$	R 230.49	

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET PARKING AID	\$	Short 700.00	✓
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMEP R BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMEP R RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMEP R BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMEP R RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	X
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	X
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	X

Trans-cab Auto Services Pte Ltd**AAD1804-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00	}
17 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
19 1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
20 1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
21 2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
22 1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00	
25 1 SPARE TYRE	\$	<i>sn</i> 330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 34,507.07****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	<i>2200</i> 4,500.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2000</i> 4,200.00
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1804-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

To transfer of rear luggage floor panel fittings,
attachment and perform water seepage test. \$ *nn* 170.00 X

To supply and re-do rear luggage floor panel
insulation padding. \$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and
perform water seepage test. \$ *nn* 380.00 X

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 X

TOTAL \$ 11,040.00

Over All Total \$ 45,547.07

(LUMP SUM)

Repair Days

15 Days
2 days

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18006367/KVBN2

Date: 10/04/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU001800
Claimant Vehicle No :	SHD389M	Insured Vehicle No :	SLL1786D
Date of Loss:	31/03/2018	Nature of Claim:	TP
		Claim No:	M1801799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD389M	Engine No:	M9R8839C003061
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC282697
Reg. Date:	10/06/2016 (Man. Year: 2015)	Odometer:	325131 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,507.05	3,293.59	31,213.46	90.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,040.00	480.00	10,560.00	95.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	45,547.05	3,773.59	41,773.46	91.71
+ GST 7.00/7.00% (S\$)	3,188.29	264.15	2,924.14	91.71
Nett Amount (S\$)	48,735.34	4,037.74	44,697.60	91.71

INSPECTION

Date of Assignment:	06/04/2018	
Date Inspected:	05/04/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD389M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
34	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
39	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
41	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
42	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*-FL
44	1		*EXHAUST REAR	Repair	7,489.05 FL	*-FL
45	1		*EXHAUST CAP REAR	Repair	230.49 FL	*-FL
46	1		*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
47	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
49	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
50	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
51	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
52	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
53	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
54	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
55	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS
56	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
57	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
58	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
59	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
60	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS
61	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*-FS
62	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
63	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
64	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
65	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
66	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
67	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
68	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
69	1		*SPARE TRYE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*-FS
70	1		*SPARE TYRE	Serviceable	330.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,093.94	3,563.43
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,586.89	269.84
Total Parts (\$\$)	34,507.05	3,293.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (\$\$)			11,040.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >