

ASS. REC. BY:

REF: CS/FCI18006370/Sqd3/12

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 05/04/2018 @ 4:10pm

Estimated Cost: Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 9402J Insured: SHA 6596H

at Workshop m/s TC Autoclinic Tel: 67038515 / 96450023

of 25 Leng Kee Rd

Policy No: B-18088936MFSH Claim No: D18002643 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 0104/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4:29pm @ 5/4/18 Person Contacted: shawn H.O.D. Endorsement:

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 9402J - CC3/AIG/17022632/Tle q3s2 D.O.A: 7/10/17
	SHA 6596H - CS/FCI/16013864/Gtbc2 D.O.A: 23/7/16
12/4/18 @ 5:10pm	revised to Karen Tan by email.
14/5/18 @ 10:24am	Sebastian Analised Shawn final fig @ 4310.80 by email. (Red @ 7781.12, 35%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. SK59402J Yr Regn: 15/5/2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai C.C. 1997Colour: White A/C: Insured / Std / NI / NASp. Reading: 27341 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STN1-BHJ-1141267870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 1/4/18 D.O.I. 10/4/18Survey held at TC AutocareDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 MAY 2018

Date/Time File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time File Return to?

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: 145Transportation: 50

) \$ + RS. \$

) Photos

) Others

TOTAL

223

Report Format: TLLump Sum / I.B.I. (\$) 4310.80Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

MOTOR SURVEY ASSIGNMENT

Date	03-04-2018	Our Ref No. D18002643MFSH
Accident Date	01-04-2018	Claim Type. Third Party
Insured Vehicle	SHA6596H	Third Party Vehicle. SKS9402J
Survey Location	25 LENG KEE ROAD	4-29pm
Contact Person.	SHAWN CHUA	
Contact No.	67038515/ 96450023	Fax No. 64795019
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR - EST. COR - \$6,591.92	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TC AUTOCLINIC PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236604)



PRI Documents



Close



PRI Header Details

Claim No	D18002643MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TC AUTOCLINIC
Workshop Name	TC AUTOCLINIC PTE LTD (Contact Person : SHAWN CHUA)	Survey Location & Contact Details	25 LENG KEE ROAD Mobile: 96450023 , Phone: 67038515 , Fax: 64795015 EmailId: SHAWNCHUA@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR - EST. COR -		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA6596H	TP Vehicle No	SKS9402J
PRI Recieved Date	05-04-2018 05:24:23 PM	Surveyor Appointed Date	05-04-2018 04:09:57 PM	Surveyor Accept Date	05-04-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Sebastian Yeang (LKK Auto)
Sent: Thursday, 24 May 2018 9:42 AM
To: Shiau Chan (LKKAuto)
Subject: FW: SKS9402J Finalized Claim
Attachments: SKS_9402_J_ESTIMATE_REPLY.pdf

FYI

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sebastian Yeang (LKK Auto)
Sent: Monday, 14 May 2018 10:04 AM
To: 'Shawn Chua'
Cc: Shiau Chan
Subject: RE: SKS9402J Finalized Claim

Dear Shawn

Please refer to the attachment for the finalization.

Thank You

CS/FCI18006370/Sqd3

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua [<mailto:shawnychua@tanchong.com>]
Sent: Saturday, 12 May 2018 9:59 AM
To: Sebastian Yeang (LKK Auto)
Subject: SKS9402J Finalized Claim

MS First Capital Ref: **D18002643MFSH**
Our Ref: **SKS9402J**

Good morning.

Attached is **SKS9402J** finalized claim.

Kindly reply so that I can close the case soon.

Thank you very much for your time & assistance.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 12 April 2018 5:08 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002643MFSH/1
Attachments: CSFCI18006370Sqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKS 9402J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 6 April 2018 9:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002643MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 5 April 2018 4:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002643MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002643MFSH

Date: 12 April 2018

Our Ref: CS/FCI18006370/Sqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 9402J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/04/2018 at the premises of M/s TC AUTOCLINIC, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,591.92</u>
Revised Estimate Amount	: S\$ <u>4,310.80</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Yours faithfully

Sebastian
Automotive Assessor

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 083/IC/TCAC/CCR/2018
DATE : 02-APR-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR EGIN O'DONOVAN
ADDRESS : 259 GREENWOOD AVE

S(286875)
TELEPHONE NO : 98437027/82000552

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100466489-01000
VEHICLE NO : SKS9402J
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20335833W
CHASSIS NO : SJNFBAJ11U1267870
MILEAGE : 27132 KM
DATE IN : 02/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 01/04/2018

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS9402J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	✓
2 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100
3 ZZ/001	RENEW FRONT LEFT FENDER, TRIM, FRONT LEFT DOOR, MOULDINGS, TAPES, HINGES, SIDE SILL, PANELS & REPAIR	1560.00	1170
4 ZZ/002	TRANSFER FRONT LEFT DOOR COMPONENTS TO FACILITATE REPAIR	120.00	✓
5 ZZ/003	RESPRAY FRONT LEFT FENDER, FRONT LEFT DOOR, LEFT SILL, B-PILLAR ETC	1250.00	750
6 ZZ/004	QC, RETUNE & CONSULT CHECK		
7 ZZ/005	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES		3370.00	

Sebastian.
10/4/18.

- Part by part repair.
- Photo Before Paint.

90036121

sebastianyeap@lkkauto.com

5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS9402J

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	BOTTOM HINGE ✓ BT	82421-4EAOA	56.10	✓
2	TOP HINGE ✓ BT	82420-4EAOA	56.10	✓
3	LOWER DOOR MOULDING ✓ Deform	80871-4EAOA	323.60	✓
4	FENDER TRIM ✓ cut	63811-4EAOA	483.00	✓
5	DOOR LOWER PARTING SEAL ✓ ✓ NEC	80839-4EAOA	70.40	✓
6	TOP DOOR MOULDING ✓ NEC	80283-4EA1A	100.70	✓
7	CENTRE DOOR MOULDING ✓ NEC	80821-4EAOA	188.90	✓
8	B-PILLAR TAPE ✓ NEC	80813-4EAOA	29.90	✓
9	FRONT LEFT DOOR ✓ DT	H0101-HVOMA	1104.80	✓
10	LEFT OUTER SILL R	G6415-HVOMB	991.20	✓
11	FRONT LEFT FENDER R	F3101-4EAMB	622.70	✓
SUB TOTAL			4027.40	0.00 0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			805.48	0.00 0.00
GRAND TOTAL			3221.92	0.00 0.00
OVERALL TOTAL			3221.92	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKS9402J

TOTAL LABOUR CHARGES	3370.00
TOTAL SPARE PARTS CHARGES	3221.92
GRAND TOTAL	6591.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 083/IC/TCAC/CCR/2018
DATE : 02-APR-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR EOTN O'DONOVAN
ADDRESS : 259 GREENWOOD AVE
S(286875)
TELEPHONE NO : 98437027/82000552

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100466489-01000
VEHICLE NO : SKS9402J
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20335833W
CHASSIS NO : SJNFB AJ11U1267870
MILEAGE : 27132 KM
DATE IN : 02/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 01/04/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS9402J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	240.00 ✓
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100.00 ✓
3	ZZ/001	RENEW FRONT LEFT FENDER TRIM, FRONT LEFT DOOR, TAPES MOULDINGS, HINGES ETC. REPAIR LEFT FENDER & SILL	1560.00	1170.00 ✓
4	ZZ/002	TRANSFER FRONT LEFT DOOR COMPONENTS TO FACILITATE REPAIR	120.00	120.00 ✓
5	ZZ/003	RESPRAY FRONT LEFT FENDER, FRONT LEFT DOOR, LEFT SILL, B-PILLAR ETC	1250.00	750.00 ✓
6	ZZ/004	QC, RETUNE & CONSULT CHECK		
7	ZZ/005	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3370.00	2380.00 ✓

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS9402J

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	BOTTOM HINGE BT	B2421-4EADA	56.10		OK
2	TOP HINGE BT	B2420-4EADA	56.10		OK
3	LOWER DOOR MOULDING Defain	B0871-4EADA	323.60		OK
4	FENDER TRIM C.F.	63811-4EADA	483.00		OK
5	DOOR LOWER PARTING SEAL N/C	B0839-4EADA	70.40		OK
6	TOP DOOR MOULDING N/C	B0283-4EA1A	100.70		OK
7	CENTRE DOOR MOULDING N/C	B0821-4EADA	188.90		OK
8	B-PILLAR TAPE N/C	B0813-4EADA	29.90		OK
9	FRONT LEFT DOOR DT	H0101-HVQMA	1104.80		OK
10	LEFT OUTER SILL K	G6415-HVQMB	991.20		X
11	FRONT LEFT FENDER R	F3101-4EAMB	622.70		X
SUB TOTAL			2413.50	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			482.70	0.00	0.00
GRAND TOTAL			1930.80	0.00	0.00
OVERALL TOTAL			1930.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO. SKS9402J

NETT ITEM	2413.50
LESS 20.00%	-482.70
NETT AMOUNT	1930.80
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	2380.00
TOTAL SPARE PARTS CHARGES	1930.80
TOTAL CHARGES	4310.80
ADD 7 % GST	301.76
GRAND TOTAL	4612.56

Sebastian

14/5/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006370/Sqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6596H	Veh. Inspected	SKS 9402J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002643MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFBAJ11U1267870	Colour	WHITE	
Odometer	27341	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	CONTINENTAL	7 mm	
L/H Front Tyre	225/45 R19	CONTINENTAL	7 mm	
R/H Rear Tyre	225/45 R19	CONTINENTAL	7 mm	
L/H Rear Tyre	225/45 R19	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2018	Inspection Date	10/04/2018	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9402J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOTTOM HINGE (N)	BENT	56.10	56.10
1	TOP HINGE (N)	BENT	56.10	56.10
1	LOWER DOOR MOULDING (N)	DEFORMED	323.60	323.60
1	FENDER TRIM (N)	CUT	483.00	483.00
1	DOOR LOWER PARTING SEAL (N)	NECESSARY	70.40	70.40
1	TOP DOOR MOULDING (N)	NECESSARY	100.70	100.70
1	CENTRE DOOR MOULDING (N)	NECESSARY	188.90	188.90
1	B-PILLAR TAPE (N)	NECESSARY	29.90	29.90
1	FRONT LEFT DOOR (N)	DENTED	1,104.80	1,104.80
1	LEFT OUTER SILL (N)	TO REPAIR SEE LABOUR	991.20	-
1	FRONT LEFT FENDER (N)	TO REPAIR SEE LABOUR	622.70	-
	LESS 20% DISCOUNT		-805.48	-482.70
			3,221.92	1,930.80
	LABOUR			
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		240.00	240.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		200.00	100.00
	RENEW FRONT LEFT FENDER, TRIM, FRONT LEFT DOOR, MOULDINGS, TAPES, HINGES, SIDE SILL PANELS & REPAIR. INCLUSIVE OF THE REPAIR OF LEFT OUTER SILL AND FRONT LEFT FENDER.		1,560.00	1,170.00
	TRANSFER FRONT LEFT DOOR COMPONENTS TO FACILITATE REPAIR.		120.00	120.00
	RESPRAY FRONT LEFT FENDER, FRONT LEFT DOOR, LEFT SILL, B-PILLAR ETC.		1,250.00	750.00
	-		-	-
	-		-	-
	-		-	-
			3,370.00	2,380.00
	GRAND TOTAL		6,591.92	4,310.80

Report Ref No. CS/FCI18006370/Sqd3n2



RECOMMENDED COST OF REPAIRS			4,310.80
-----------------------------	--	--	----------

Report Ref No. CS/FCI18006370/Sqd3n2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.