

REF:

NS/ZNC18006375/Svb2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SHB 668T

Yr Regn:

19/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4

C.C. 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

25705

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK153E4805579722

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 17x65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

4/4/13

D.O.I.

5/4/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 668T - NS / TIT09004962 / ZW

DIN: 001809

THX/04/18/2018

SW 3014H - X

LKR

NTW

23/4/18 Sebastian confirmed \$ 741.25 (Red) 2279.55, 7519

SLV 3014H

RECEIVED 24 APR 2018

Gate/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

2

1)

☐ : Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

24/4 - typist

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

741.25

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

160

35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006375/Svb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 06-04-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 3014H	Veh. Inspected	SHB 668T	
Policy No.	5096979944	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/04/2018	Inspection Date	05/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 23 April 2018 1:41 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: RE: SHB668T

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Monday, 23 April 2018 9:34 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: RE: SHB668T

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi
Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 17 April 2018 6:41 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: SHB668T

Hi Sebastian,

Attached herewith the repair estimate of SHB 668T having Case No: TAX/04/18/2018.

There is no change to the approved amount of \$741.25 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 17 April 2018 5:29 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0991340-002	COMFORT TRANSPORTATION PTE LTD	SH 7013A	SJL 3277S
2	MT/0990420-002	COMFORT TRANSPORTATION PTE LTD	SHC 1833X	GBG 6935C
3	MT/0991001-002	COMFORT TRANSPORTATION PTE LTD	SHB 4181D	SJF 4165G
4	MT/0987576-002	SMRT TAXIS	SHB 5490E	SGN 2724A
5	MT/0988974-002	SMRT TAXIS	SHF 474P	SKP 1761R
6	MT/0988606-002	SMRT TAXIS	SHF 287M	SHD 1850R
7	MT/0988375-002	SMRT TAXIS	SHB 5737U	SKZ 9804X
8	MT/0991050-002	COMFORT TRANSPORTATION PTE LTD	SHD 6647D	SLM 4176P
9	MT/0991603-001	COMFORT TRANSPORTATION PTE LTD	SH 9594B	SJF 8421R
10	MT/0989297-002	SMRT TAXIS	SHB 5445L	GZ 8719M
11	MT/0989010-002	SMRT TAXIS	SHB 668T	SLV 3014H
12	MT/0988555-002	SMRT TAXIS	SHB 5515T	SLS 2028R
13	MT/0981124-002	SMRT BUSES	SMB 8039Y	SJC 8146B
14	MT/0991610-001	COMFORT TRANSPORTATION PTE LTD	SHC 8728X	GBG 2031L
15	MT/0991074-002	COMFORT TRANSPORTATION PTE LTD	SHC 2948S	GZ 1977E
16	MT/0990979-002	COMFORT TRANSPORTATION PTE LTD	SHD 6658Y	FBK 791T
17	MT/0990696-002	COMFORT TRANSPORTATION PTE LTD	SHD 4138U	PC 2948Y
18	MT/0990960-002	COMFORT TRANSPORTATION PTE LTD	SHD 4928G	YP 6440T

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5096979944	GLIDERS AUTO TRADING	53375166K	GFT	drivo CLASSIC	SLV3014H	SLV3014H	27/12/2017	

SMRT Accident Vehicle Repair Estimates

G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB668T
 Ref. No : TAX/04/18/2018
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : VINCENT LIM CHENG CHUAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/04/2018 11:30:00 AM
 Accident Reported Date / Time : 04/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095366
 Special Instruction to ARC, if any :
 SLV3014H
 Prepared Date : 04/04/2018 03:25:32 PM



Signature
 6/4/18

Selection
 5/4/18.

- Part by part repair.
- Question Mark Item
- Photo
- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU803579722

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 1,493.68	1,493.68
Other Charges	: 260.00	0.00
TOTAL	: 2,649.68	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 04/04/2018 04:48:05 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 04:48:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	260.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
TOTAL MATERIALS								1,493.70	1,493.68	
TOTAL MATERIALS(Discounted)							1,493.68	1,493.68		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 15:18
Date Of Accident	04/04/2018 11:30
Exact Location Of Accident	ORCHARD ROAD TOWARDS PARAGON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB668T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	VINCENT LIM CHENG CHUAN
NRIC No	S0109917E
Date Of Birth	08/04/1954
Occupation	OUTDOOR
Date Of Driving Pass	05/09/2014
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	04-50
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : SUNNY GOH
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG ORCHARD ROAD TOWARDS PARAGON WITH ONE PASSENGER (MALE CHINESE) ON BOARD AS ALL THE VEHICLES AHEAD HAD STOPPED. WHEN THE FRONT VEHICLE STARTED TO MOVE, I STARTED TO MOVE SLOWLY AND SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLV3014H HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV3014H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	GOH CHEE WAH
NRIC/Passport Number	S6903721F
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

Orchard Road towards Paragon



A - 5HB 668 T

B- SLV 3014 +)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 103–110

Driver's Signature
(If driver is not the policyholder)

Date & Time:

4/4/18 10:44pm.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)

Date & Time:
4/4/18
14.44 pm.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

4/4/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB668T
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8287697
Chassis No.:	JTDKB3FU803579722
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,873.00
Total Rebate Amount:	\$36,623.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Apr 2018

OK



747

7-4-18/09:04

7-4-18/13:04

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

5-4-18/13:04

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB668T
 Ref. No : TAX/04/18/2018
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : VINCENT LIM CHENG CHUAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/04/2018 11:30:00 AM
 Accident Reported Date / Time : 04/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle Issued? : No
 Accident Repair Job Card No : 000024095366

Special Instruction to ARC, if any :

SLV3014H NTUC P/P

BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang @lkkauto.com HP:90036121

Prepared Date : 04/04/2018 03:25:32 PM



Recording Camera

☐☒

Radio Antenna

☐☒1st witness

Date

5-4-18

2nd witness

Date

QC 7/4/18 10:43 PM

Vehicle to Wega Date In:	6/4/18	Towing:	
Time In:	-	Driver:	747
Wega Job No:	04/0225		2018
Vehicle sent to SMRT Date In:	1-4-2018	Towing:	
Time In:	10-20	Driver:	
Received by (SMRT):	[Signature]		

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU803579722

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	338.00	200.00
Total Spray Painting Charges	558.00	200.00
Total Material Charges	550.35	311.25
Other Charges	260.00	30.00
TOTAL	1,706.35 3020.80	741.25
Lum Sum Total	0.00	0.00
No. of Repair Days	3.00	2.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	04/04/2018 04:48:05 PM	05/04/2018 01:04:14 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 04:48:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0306

Invoice No :

Quotation Date : 13/4

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	200.00
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	558.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	260.00	30.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	100.00	0.00	Replace	Repair	No <i>R</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <i>✓</i>
5246247030			PAD, RR BUMPER, RH & LH, 1	<i>0</i> 1	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5246247020			PAD, RR BUMPER, RH & LH, 2	<i>0</i> 2	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5246247010			PAD, RR BUMPER, RH & LH, 3	<i>0</i> 3	3.80	25.00	0.00	Replace	Not given	No <i>X</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH	<i>0</i> 2	11.00	25.00	0.00	Replace	Not given	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>S</i>	No <i>✓</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Check	No <i>X</i>
5257647040			RETAINER, RR BUMPER, LH	0	111.50	25.00	0.00	Replace	Not given	No <i>X</i>
5257547040			RETAINER, RR BUMPER, RH	0	112.70	25.00	0.00	Replace	Not given	No <i>X</i>
5245347010			GUARD, RR BUMPER, LOWER	0	558.30	25.00	0.00	Replace	Not given	No <i>X</i>
5246147010			PAD, RR BUMPER, CTR	<i>0</i> 3	2.20	25.00	0.00	Replace	Not given	No <i>X</i>
TOTAL MATERIALS							550.35	311.25		
TOTAL MATERIALS(Discounted)							550.35	311.25		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Sebastian
23/4/18

311.25 /
+ 200.00 /
+ 230.00 /

741.25 /

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006375/Svbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 02-05-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 3014H	Veh. Inspected	SHB 668T
Policy No.	5096979944	Coverage (\$)	0.00
Claim No.	MT/0989010-002	Excess (\$)	0.00
Assign From		Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803579722	Colour	MAROON
Odometer	25703	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/04/2018	Inspection Date	05/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 668T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	CLIPS PIECE,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD RR BUMPER RH & LH,1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD RR BUMPER RH & LH,2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD RR BUMPER RH & LH,3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL RR BUMPER ARM RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	RETAINER RR BUMPER LH	NOT NECESSARY	111.50	-
1	RETAINER RR BUMPER RH	NOT NECESSARY	112.70	-
1	GUARD,RR BUMPER LOWER	NOT NECESSARY	558.30	-
3	PAD,RR BUMPER CTR @\$2.20	NOT NECESSARY	6.60	-
1	COVER,RR BUMPER ASSY	TO REPAIR	423.90	-
			1,891.60	311.25
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			538.00	230.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			558.00	200.00
TO WASH AND VACUUM.		NOT NECESSARY	60.00	-
			1,156.00	430.00
GRAND TOTAL			3,047.60	741.25
RECOMMENDED COST OF REPAIRS (CONFIRMED)				741.25

Report Ref No. NS/INC18006375/Svbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.